

## P2 Bridge Preservation - Replacement/Rehab Projects

### 2011-13 Bien Priority Array

(Sorted by Priority Number)

11-13 #	Bridge Number	Bridge Name	Mile post	Region	Length	Future work Description
1	002/005N	SNOHOMISH RIVER BRIDGE	0.18	Northwest	2,980	Rehabilitate Bridge
1	002/006N	EBEY ISLAND VIADUCT	0.75	Northwest	6,923	Rehabilitate Bridge
2	097/106	SATUS CR 2ND CROSSING	45.84	South Central	133	Replace Bridge
3	303/004A	MANETTE BRIDGE CS1841	1.47	Olympic	1,573	Replace Bridge
4	010/143	BRISTOL FILL	90.10	South Central	430	Replace Deck
5	005/670W	STILLAGUAMISH R	209.35	Northwest	859	Replace Deck
6	090/322S	SR 261 OC	221.95	Eastern	169	Replace Bridge
7	090/322N	SR 261 OC	221.95	Eastern	169	Replace Bridge
8	097/020	SATUS CR	30.80	Southwest	101	Replace Bridge
9	101/354	MCDONNELL CR	258.21	Olympic	179	Replace Bridge
10	548/010	DAKOTA CR	11.54	Northwest	182	Replace Bridge
11	241/005	MABTON-SUNNYSIDE #650	1.34	South Central	521	Replace Bridge
12	167/020E	PUYALLUP R	6.40	Olympic	477	Replace Bridge
13	302/105	PURDY BR	15.65	Olympic	550	Replace Bridge
14	012/720	WHETSTONE CR	372.57	South Central	21	Replace Bridge
15	022/007	SLOUGH OF YAKIMA R	1.39	South Central	115	Replace Bridge
16	012/012S	WISHKAH R HERON CS1415	0.08	Olympic	235	Rehabilitate Bridge
17	107/006	SLOUGH	7.79	Olympic	279	Replace Bridge
18	107/005	SLOUGH	7.59	Olympic	294	Replace Bridge
19	508/012	S FK NEWAUKUM R	13.65	Southwest	197	Replace Bridge
20	300/001	MISSION CR	0.28	Olympic	51	Replace Bridge
21	506/106	LACAMAS CR	8.05	Southwest	170	Replace Bridge
22	508/025	CREEK - west	24.08	Southwest	26	Replace Bridge
23	508/023	ALDER CR	22.65	Southwest	88	Replace Bridge
24	005/036E	E FK LEWIS R	18.21	Southwest	852	Replace Bridge

Total Number of Bridges = 25



## P2 Bridge Preservation - Replacement/Rehab Projects

### 2011-13 Bien Priority Array

(Sorted by Bridge Number)

11-13 #	Bridge Number	Bridge Name	Mile post	Region	Length	Future work Description
1	002/005N	SNOHOMISH RIVER BRIDGE	0.18	Northwest	2,980	Rehabilitate Bridge
1	002/006N	EBEY ISLAND VIADUCT	0.75	Northwest	6,923	Rehabilitate Bridge
24	005/036E	E FK LEWIS R	18.21	Southwest	852	Replace Bridge
5	005/670W	STILLAGUAMISH R	209.35	Northwest	859	Replace Deck
4	010/143	BRISTOL FILL	90.10	South Central	430	Replace Deck
16	012/012S	WISHKAH R HERON CS1415	0.08	Olympic	235	Rehabilitate Bridge
14	012/720	WHETSTONE CR	372.57	South Central	21	Replace Bridge
15	022/007	SLOUGH OF YAKIMA R	1.39	South Central	115	Replace Bridge
7	090/322N	SR 261 OC	221.95	Eastern	169	Replace Bridge
6	090/322S	SR 261 OC	221.95	Eastern	169	Replace Bridge
8	097/020	SATUS CR	30.80	Southwest	101	Replace Bridge
2	097/106	SATUS CR 2ND CROSSING	45.84	South Central	133	Replace Bridge
9	101/354	MCDONNELL CR	258.21	Olympic	179	Replace Bridge
18	107/005	SLOUGH	7.59	Olympic	294	Replace Bridge
17	107/006	SLOUGH	7.79	Olympic	279	Replace Bridge
12	167/020E	PUYALLUP R	6.40	Olympic	477	Replace Bridge
11	241/005	MABTON-SUNNYSIDE #650	1.34	South Central	521	Replace Bridge
20	300/001	MISSION CR	0.28	Olympic	51	Replace Bridge
13	302/105	PURDY BR	15.65	Olympic	550	Replace Bridge
3	303/004A	MANETTE BRIDGE CS1841	1.47	Olympic	1,573	Replace Bridge
21	506/106	LACAMAS CR	8.05	Southwest	170	Replace Bridge
19	508/012	S FK NEWAUKUM R	13.65	Southwest	197	Replace Bridge
23	508/023	ALDER CR	22.65	Southwest	88	Replace Bridge
22	508/025	CREEK - west	24.08	Southwest	26	Replace Bridge
10	548/010	DAKOTA CR	11.54	Northwest	182	Replace Bridge

Total Number of Bridges = 25



# 2011-13 Bien P2 Bridge Replacements/Rehab Candidate

Bridge Number: 2 / 5N	Structure ID 0008266B	Bridge Name: SNOHOMISH RIVER BRIDGE	Milepost: 0.18	Region: Northwest
Year Built / YR Widened: 1968	Bridge Type: SG CBox CS		Number of Main/Appr span 5 / 33	Sufficiency Rating: 67.12
Bridge Width (curb-curb): 30.0 ft	Bridge Length: 2,980 ft	Max Span: 204 ft	<b>Bridge Deck View</b>	
Average Daily Traffic: 32,660	Truck% 8%	Number of Lanes: 2	NHS: YES	
Vertical Clearance: NA	Detour Length (miles): 2		Appr Rdway Width: 30.0 ft	
Design Load: HS 20	HS: 1.15	Load Restricted Bridge? <input type="checkbox"/>		
Op Rating: 58.00	A1: 1.97	BL Load:		
Inv Rating: 35.00	A2: 1.51	CL-8 Load:		
	A3: 1.48	SA Load:		
<b>Bridge Inspection Information</b>			<b>Bridge Profile View</b>	
Date Inspected: 8/9/2008	Structr Adequacy: 5			
Superstr Code: 5	Safe Load: 5			
Substr Code: 6	Deck Geometry: 4			
Deck Code: 6	Underclearance: 8			
Scour: 5	Waterway: 8			
<b>Proposed Bridge Replacement Information</b>				
New Bridge Width:	ft.	Bridge \$'s:		
New Bridge Length:	ft.	Total \$'s:		
Priority Array #:	1			
PIN Number:	100205E			
WIN Number:		Repl/Rehab Year:		
Contract Number:		Ad Date:	8/9/2010	
<p>Bridge 2/5N has 15 spans of precast concrete girder (PRC) units near Home Acres Road (piers 18 to 33) in need of rehabilitation. There are 6 units across the width of the bridge in each span.</p> <p>These PRC units were designed with a 1 inch concrete cover around the main reinforcing steel in the stem. Some of these units have rebar that is corroding causing the concrete cover to crack and debond.</p>				



# 2011-13 Bien P2 Bridge Replacements/Rehab Candidate

Bridge Number: 2 / 6N	Structure ID 0008378E	Bridge Name: EBEY ISLAND VIADUCT	Milepost: 0.75	Region: Northwest
Year Built / YR Widened: 1968	Bridge Type: PRCB PCG		Number of Main/Appr span 1 / 178	Sufficiency Rating: 23.35 SD
Bridge Width (curb-curb): 30.0 ft	Bridge Length: 6,923 ft	Max Span: 82 ft	<b>Bridge Deck View</b>	
Average Daily Traffic: 34,331	Truck% 8%	Number of Lanes: 2	NHS: YES	
Vertical Clearance: NA	Detour Length (miles): 2		Appr Rdway Width: 30.0 ft	
Design Load: HS 20	HS: 0.84	Load Restricted Bridge? <input checked="" type="checkbox"/>		
Op Rating: 27.00	A1: 1.06	BL Load: 20,000		
Inv Rating: 17.00	A2: 1.12	CL-8 Load: 21,000		
	A3: 1.30	SA Load:		
<b>Bridge Inspection Information</b>			<b>Bridge Profile View</b>	
Date Inspected: 7/12/2008	Structr Adequacy: 4			
Superstr Code: 4	Safe Load: 5			
Substr Code: 6	Deck Geometry: 4			
Deck Code: 6	Underclearance: 4			
Scour: 8	Waterway: 8			
<b>Proposed Bridge Replacement Information</b>				
New Bridge Width:	ft.	Bridge \$'s:		
New Bridge Length:	ft.	Total \$'s:		
Priority Array #:	1			
PIN Number:	100205E			
WIN Number:	A00205C	Repl/Rehab Year:	2010	
Contract Number:		Ad Date:	8/9/2010	
<b>THIS BRIDGE IS CLASSIFIED "SD" DUE TO A SUPERSTRUCTURE CONDITION.</b>				
<p>Bridge 2/6N has 170 spans of precast concrete girder (PRC) units. These units were designed with a 1 inch concrete cover around the main reinforcing steel in the stem. There are 4 - #10 reinforcing bars located at the bottom of the stems. An in-depth inspection was performed in 1986. Approximately 82% of the T-beam spans have cracks parallel to the #10 bars in the stem. Approximately 34% of the spans have moderate to severe cracking with the main #10 bars exposed. Eight spans of bridge 2/6N were repaired in 1999 (Contract 5550). The deck was repaired and overlaid with an ACP w/membrane in 2001 (C#6157).</p> <p>The concrete superstructure of the bridge from span 60 to bridge 2/7N limits (121 spans) was repaired in 2007 as part of contract 7304. The next project will repair the remaining deteriorated spans 1 to 60.</p>				



# 2011-13 Bien P2 Bridge Replacements/Rehab Candidate

Bridge Number: 5 / 36E	Structure ID 0002473A	Bridge Name: E FK LEWIS R	Milepost: 18.21	Region: Southwest
Year Built / YR Widened: 1936	Bridge Type: STrus CTB	Number of Main/Appr span 1 / 12	Sufficiency Rating: 30.35 SD	
Bridge Width (curb-curb): 48.0 ft	Bridge Length: 852 ft	Max Span: 248 ft	<p align="center"><b>Bridge Deck View</b></p> 	
Average Daily Traffic: 33,747	Truck% 35%	Number of Lanes: 3		
Vertical Clearance: 17 FT 02 in	Detour Length (miles): 2	Appr Rdway Width: 52.0 ft		<p align="center"><b>Bridge Profile View</b></p> 
Design Load: H 15	HS: 0.70	Load Restricted Bridge? <input checked="" type="checkbox"/>		
Op Rating: 31.00	A1: 1.02	BL Load: 20,000		
Inv Rating: 18.00	A2: 1.06	CL-8 Load: 20,000		
	A3: 1.16	SA Load: 35,500		
<b>Bridge Inspection Information</b>				
Date Inspected: 8/18/2009	Structr Adequacy: 4			
Superstr Code: 4	Safe Load: 5			
Substr Code: 6	Deck Geometry: 4			
Deck Code: 6	Underclearance: 3			
Scour: 3	Waterway: 8			
<b>Proposed Bridge Replacement Information</b>				
New Bridge Width: 48 ft.	Bridge \$'s:			
New Bridge Length: 860 ft.	Total \$'s:			
Priority Array #: 24				
PIN Number:				
WIN Number:	Repl/Rehab Year: 2020			
Contract Number:	Ad Date:			
<p>THIS BRIDGE IS CLASSIFIED "SD" BASED ON THE SUPERSTRUCTURE CODE.                  Many of the steel stringers have cracks. A repair project for the cracked stringers was completed by contract in 2006.                  There are 48 locations with bolts, drilled holes, or welded plates. Some of the stringer ends at the floorbeam connections are showing laminar rust and starting to lift the deck off the stringer top flanges. Approximately 8% section loss typical.</p> <p>This bridge was added to the Bridge Replacement Priority Array due to the existing load restrictions and it is cost prohibitive to rehabilitate the bridge to meet current truck load standards.</p>				



# 2011-13 Bien P2 Bridge Replacements/Rehab Candidate

Bridge Number: 5 / 670W		Structure ID 0001652A		Bridge Name: STILLAGUAMISH R		Milepost: 209.35		Region: Northwest			
Year Built / YR Widened: 1933		Bridge Type: STrus CTB		Number of Main/Appr span 3 / 5		Sufficiency Rating: 44.56 SD					
Bridge Width (curb-curb): 48.0 ft		Bridge Length: 859 ft		Max Span: 200 ft		<b>Bridge Deck View</b> 					
Average Daily Traffic: 39,247		Truck% 13%	Number of Lanes: 3	NHS: YES							
Vertical Clearance: 16 FT 05 in		Detour Length (miles): 2		Appr Rdway Width: 58.0 ft							
Design Load: H 15		HS: 1.04	Load Restricted Bridge? <input type="checkbox"/>								
Op Rating: 35.00		A1: 1.38	BL Load:								
Inv Rating: 21.00		A2: 1.52	CL-8 Load:								
		A3: 1.64	SA Load:								
<b>Bridge Inspection Information</b>						<b>Bridge Profile View</b> 					
Date Inspected: #####		Structr Adequacy: 4									
Superstr Code: 5		Safe Load: 5									
Substr Code: 6		Deck Geometry: 4									
Deck Code: 4		Underclearance: 2									
Scour: 3		Waterway: 8									
<b>Proposed Bridge Replacement Information</b>											
New Bridge Width:		ft.	Bridge \$'s:								
New Bridge Length:		ft.	Total \$'s:								
Priority Array #:		5									
PIN Number:											
WIN Number:		Repl/Rehab Year:		2013							
Contract Number:		Ad Date:									

**THIS BRIDGE IS CLASSIFIED "SD" BASED ON THE DECK CONDITION.**  
 A modified concrete overlay was applied in 1992. The length of the 3 truss spans is 606 feet. Transverse hairline cracks in most panel points. Soffit: Transverse and map cracking in soffit, some were leaching or had rust stains throughout all steel truss spans of bridge; see photos #5 and #21. Some movement in the deck was observed under heavy traffic in areas of all truss spans, most notably between Panel Points L0 and L1. There are exposed rusty transverse bars with section loss, up to 6 ft. in length with 2" deep spalls; Some areas of delaminated and honeycombed concrete were observed between the stringers. Spalls, up to 10 ft. long, and longitudinal cracks were observed along the east edge of the deck. Spalls were also observed at the interface of the floorbeams and deck. A future project will replace the concrete deck on the three steel truss spans.



# 2011-13 Bien P2 Bridge Replacements/Rehab Candidate

Bridge Number: 10 / 143	Structure ID 0002222A	Bridge Name: BRISTOL FILL	Milepost: 90.10	Region: South Central
Year Built / YR Widened: 1937	Bridge Type: SB	Number of Main/Appr span 15 / 0	Sufficiency Rating: 41.75 SD	
Bridge Width (curb-curb): 24.0 ft	Bridge Length: 430 ft	Max Span: 33 ft	<b>Bridge Deck View</b>	
Average Daily Traffic: 1,115	Truck% 11%	Number of Lanes: 2	NHS: No	
Vertical Clearance: NA	Detour Length (miles): 34	Appr Rdway Width: 34.0 ft		
Design Load: H 15	HS: 0.97	Load Restricted Bridge? <input type="checkbox"/>		
Op Rating: 32.00	A1: 1.52	BL Load:		
Inv Rating: 19.00	A2: 1.46	CL-8 Load:		
	A3: 1.62	SA Load:		
<b>Bridge Inspection Information</b>			<b>Bridge Profile View</b>	
Date Inspected: 6/16/2009	Structr Adequacy: 4			
Superstr Code: 5	Safe Load: 5			
Substr Code: 6	Deck Geometry: 4			
Deck Code: 3	Underclearance: 9			
Scour: N	Waterway: 9			
<b>Proposed Bridge Replacement Information</b>				
New Bridge Width:	ft.	Bridge \$'s:		
New Bridge Length:	ft.	Total \$'s:		
Priority Array #:	4			
PIN Number:				
WIN Number:	Repl/Rehab Year:	2012		
Contract Number:	Ad Date:			
<p><b>THIS BRIDGE IS CLASSIFIED "SD" BASED ON THE DECK CONDITION.</b>                  Deck replacement is needed based on the 80% delams found when the ACP was removed during contract 6286 in May, 2002. The cement appears to be breaking down in the concrete deck allowing aggregate to debond.</p> <p>There is 8700 sq.ft. in Condition State 3 due to the chain drag survey completed in 2002, see Element 376. Map cracking and heavy leaching with stalactites in soffit dripping down on to the stringers and columns. Areas of rock pockets scattered throughout the soffit of the deck. Many areas of efflorescence and light pattern cracks near the floorbeams throughout.</p>				



# 2011-13 Bien P2 Bridge Replacements/Rehab Candidate

Bridge Number: 12 / 12S	Structure ID 000000LM	Bridge Name: WISHKAH R HERON CS1415		Milepost: 0.08	Region: Olympic
Year Built / YR Widened: 1949	Bridge Type: SSwS SG		Number of Main/Appr span 2 / 1	Sufficiency Rating: 45.97 SD	
Bridge Width (curb-curb): 28.0 ft	Bridge Length: 235 ft	Max Span: 93 ft		<b>Bridge Deck View</b> 	
Average Daily Traffic: 13,707	Truck% 12%	Number of Lanes: 2	NHS: YES		
Vertical Clearance: NA	Detour Length (miles): 2		Appr Rdway Width: 30.0 ft		
Design Load: H 20	HS: 1.21	Load Restricted Bridge? <input type="checkbox"/>			
Op Rating: 64.00	A1: 1.41	BL Load:			
Inv Rating: 39.00	A2: 1.42	CL-8 Load:			
	A3: 1.71	SA Load:			
<b>Bridge Inspection Information</b>				<b>Bridge Profile View</b> 	
Date Inspected: 5/20/2009	Structr Adequacy: 4				
Superstr Code: 5	Safe Load: 5				
Substr Code: 4	Deck Geometry: 3				
Deck Code: 4	Underclearance: 9				
Scour: 5	Waterway: 8				
<b>Proposed Bridge Replacement Information</b>					
New Bridge Width:	ft.	Bridge \$'s:			
New Bridge Length:	ft.	Total \$'s:			
Priority Array #:	16				
PIN Number:					
WIN Number:	Repl/Rehab Year:				
Contract Number:	Ad Date:				
<p><b>THE BRIDGE IS CLASSIFIED "SD" DUE TO THE SUBSTRUCTURE CONDITION.</b>                  This is a steel swing span bridge that was built with untreated timber piles. The bridge sags during operation due to additional weight added after the grid deck was replaced in 1990.</p> <p>A previous review has determined that the center pier should be reinforced with four new shaft foundations to reinforce this bridge against future seismic activity.</p>					



# 2011-13 Bien P2 Bridge Replacements/Rehab Candidate

Bridge Number: 12 / 720	Structure ID 0000307A	Bridge Name: WHETSTONE CR	Milepost: 372.57	Region: South Central
Year Built / YR Widened: 1919	Bridge Type: CS		Number of Main/Appr span 2 / 0	Sufficiency Rating: 30.99 SD
Bridge Width (curb-curb): 25.7 ft	Bridge Length: 21 ft	Max Span: 10 ft	<b>Bridge Deck View</b>	
Average Daily Traffic: 2,538	Truck% 18%	Number of Lanes: 2	NHS: YES	
Vertical Clearance: NA	Detour Length (miles): 11		Appr Rdway Width: 37.0 ft	
Design Load: Unknown	HS: 0.56	Load Restricted Bridge? <input type="checkbox"/>		
Op Rating: 33.00	A1: 1.00	BL Load:		
Inv Rating: 20.00	A2: 1.00	CL-8 Load:		
	A3: 1.00	SA Load:		
<b>Bridge Inspection Information</b>			<b>Bridge Profile View</b>	
Date Inspected: 2/25/2009	Structr Adequacy: 4			
Superstr Code: 7	Safe Load: 5			
Substr Code: 4	Deck Geometry: 2			
Deck Code: 7	Underclearance: 9			
Scour: 5	Waterway: 6			
<b>Proposed Bridge Replacement Information</b>				
New Bridge Width: 40 ft.	Bridge \$'s:			
New Bridge Length: 40 ft.	Total \$'s:			
Priority Array #: 14				
PIN Number:				
WIN Number:	Repl/Rehab Year:			
Contract Number:	Ad Date:			

THIS BRIDGE IS CLASSIFIED "SD" DUE TO THE SUBSTRUCTURE CODE.

Calculations show the bridge to be scour critical. Very old bridge with 2 feet of ACP over the bridge deck. The channel is almost all silted in which makes it difficult to inspect under the bridge. The waterway opening is too restrictive and allows water over the approach roadway during high flows. The 1996 flood flow water splashed over concrete rail at upstream side.

This bridge has been added to the 2009-11 P2 Bridge Replacement Priority Array.



# 2011-13 Bien P2 Bridge Replacements/Rehab Candidate

Bridge Number: 22 / 7	Structure ID 0001942A	Bridge Name: SLOUGH OF YAKIMA R	Milepost: 1.39	Region: South Central
Year Built / YR Widened: 1935	Bridge Type: CTB		Number of Main/Appr span 3 / 0	Sufficiency Rating: 40.22SD
Bridge Width (curb-curb): 24.0 ft	Bridge Length: 115 ft	Max Span: 50 ft	<b>Bridge Deck View</b>	
Average Daily Traffic: 7,905	Truck% 9%	Number of Lanes: 2	NHS: YES	
Vertical Clearance: NA	Detour Length (miles): 13		Appr Rdway Width: 30.0 ft	
Design Load: H 15	HS: 0.90	Load Restricted Bridge? <input type="checkbox"/>		
Op Rating: 37.00	A1: 1.23	BL Load:		
Inv Rating: 22.00	A2: 1.14	CL-8 Load:		
	A3: 1.25	SA Load:		
<b>Bridge Inspection Information</b>			<b>Bridge Profile View</b>	
Date Inspected: 5/7/2009	Structr Adequacy: 5			
Superstr Code: 7	Safe Load: 5			
Substr Code: 5	Deck Geometry: 2			
Deck Code: 4	Underclearance: 9			
Scour: 3	Waterway: 5			
<b>Proposed Bridge Replacement Information</b>				
New Bridge Width: 40 ft.	Bridge \$'s:			
New Bridge Length: 120 ft.	Total \$'s:			
Priority Array #: 15				
PIN Number:				
WIN Number:	Repl/Rehab Year:			
Contract Number:	Ad Date:			
<p>A Nickel funded project to widen SR 22 between I-82 and McDonald Road in Toppenish, almost totally within the Yakama Nation Reservation. Safety improvements include widening the lanes and shoulders, flattening the slope, and installing guardrail. Design on this safety improvement project will begin in late 2007. Construction is scheduled to begin in 2009, and be completed in 2011.</p> <p>The Yakima River Bridge and the Slough Bridge have been excluded from this project due to the cost of replacement.</p>				



# 2011-13 Bien P2 Bridge Replacements/Rehab Candidate

Bridge Number: 90 / 322N	Structure ID 0005761B	Bridge Name: SR 261 OC	Milepost: 221.95	Region: Eastern	
Year Built / YR Widened: 1952	Bridge Type: CVS	Number of Main/Appr span 3 / 0	Sufficiency Rating: 45.01 SD		
Bridge Width (curb-curb): 31.7 ft	Bridge Length: 169 ft	Max Span: 66 ft	<b>Bridge Deck View</b> 		
Average Daily Traffic: 7,800	Truck% 28%	Number of Lanes: 2			NHS: YES
Vertical Clearance: NA	Detour Length (miles): Appr Rdway Width: 2 40.0 ft				
Design Load: HS 15	HS: 1.25	Load Restricted Bridge? <input type="checkbox"/>			
Op Rating: 36.00	A1: 1.75	BL Load:			
Inv Rating: 22.00	A2: 1.59	CL-8 Load:			
	A3: 1.63	SA Load:			
<b>Bridge Inspection Information</b>			<b>Bridge Profile View</b> 		
Date Inspected: #####	Structr Adequacy: 4				
Superstr Code: 4	Safe Load: 5				
Substr Code: 6	Deck Geometry: 2				
Deck Code: 7	Underclearance: 8				
Scour: N	Waterway: 9				
<b>Proposed Bridge Replacement Information</b>					
New Bridge Width: 40 ft.	Bridge \$'s:				
New Bridge Length: 175 ft.	Total \$'s:				
Priority Array #: 7					
PIN Number:					
WIN Number:	Repl/Rehab Year:				
Contract Number:	Ad Date:				

**THIS BRIDGE IS CLASSIFIED "SD" BASED ON THE SUPERSTRUCTURE CONDITION.**

Superstructure is coded as a "4" due to the longitudinal rusty cracks in the soffit of the hollow slab. note Top of slab covered with ACP. Edge of slab Leaching at slab to barrier interface. Vertical and diagonal hairline cracks on both edges of slab. Longitudinal crack in edge of slab at the NW corner approximately 15 ft. long. Soffit. Longitudinal cracks in soffit. Leaching along longitudinal joint at bottom centerline of slab in all spans. Longitudinal rust stained and leaching cracks, almost the full lengths of Span 1 and Span 2 (Photos #4 and #5). The northeast corner of Span 3 has a spall 4" x 4" x 1/2" deep.

This bridge has been added to the 2009-11 P2 Program Replacement List.



# 2011-13 Bien P2 Bridge Replacements/Rehab Candidate

Bridge Number: 90 / 322S	Structure ID 0005761A	Bridge Name: SR 261 OC	Milepost: 221.95	Region: Eastern
Year Built / YR Widened: 1958	Bridge Type: CVS	Number of Main/Appr span 3 / 0	Sufficiency Rating: 39.68 SD	
Bridge Width (curb-curb): 31.7 ft	Bridge Length: 169 ft	Max Span: 66 ft	<b>Bridge Deck View</b>	
Average Daily Traffic: 8,026	Truck% 28%	Number of Lanes: 2	NHS: YES	
Vertical Clearance: NA	Detour Length (miles): 2	Appr Rdway Width: 40.0 ft		
Design Load: HS 20	HS: 0.79	Load Restricted Bridge? <input type="checkbox"/>		
Op Rating: 32.00	A1: 1.07	BL Load:		
Inv Rating: 19.00	A2: 1.10	CL-8 Load:		
	A3: 1.10	SA Load:		
<b>Bridge Inspection Information</b>			<b>Bridge Profile View</b>	
Date Inspected: 8/11/2008	Structr Adequacy: 4			
Superstr Code: 4	Safe Load: 5			
Substr Code: 6	Deck Geometry: 2			
Deck Code: 7	Underclearance: 8			
Scour: N	Waterway: 9			
<b>Proposed Bridge Replacement Information</b>				
New Bridge Width: 40 ft.	Bridge \$'s:			
New Bridge Length: 175 ft.	Total \$'s:			
Priority Array #: 6				
PIN Number:				
WIN Number:	Repl/Rehab Year:			
Contract Number:	Ad Date:			
<p><b>THIS BRIDGE IS CLASSIFIED "SD" BASED ON THE SUPERSTRUCTURE and DECK CONDITION.</b>                  Superstructure is coded as a "4" due to the longitudinal rusty cracks in the soffit of the hollow slab.                  Top of slab covered with ACP, see note 801. Edge of slab longitudinal crack, approximately 20 ft. long in north edge of Span 1; crack starts near west abutment. Another rust stained crack that is approximately 8 ft. long along north edge of the slab in Span 1. Vertical cracks in edges of the deck. 2005 interim inspection: There were no apparent changes to the overall delamination characteristics. All spans have a rusty leaching crack about 12" from the north edge. Transverse leaching cracks, some are rust stained. Random small spalls in the bottom of the slab, some are rust stained. A 4" diameter x 1/2" deep rust stained spall at the south end of Span 1 near midspan. There is a 25ft. long delamination with a rusty area on the north face of Span 3.</p> <p>This bridge has been added to the 2009-11 P2 Program Replacement List.</p>				



# 2011-13 Bien P2 Bridge Replacements/Rehab Candidate

Bridge Number: 97 / 20	Structure ID 0006113A	Bridge Name: SATUS CR	Milepost: 30.80	Region: Southwest	
Year Built / YR Widened: 1959	Bridge Type: CVS	Number of Main/Appr span 3 / 0	Sufficiency Rating: 20.25 SD		
Bridge Width (curb-curb): 38.0 ft	Bridge Length: 101 ft	Max Span: 40 ft	<p align="center"><b>Bridge Deck View</b></p> 		
Average Daily Traffic: 3,917	Truck% 26%	Number of Lanes: 2			NHS: YES
Vertical Clearance: NA	Detour Length (miles): 45	Appr Rdway Width: 45.0 ft			
Design Load: HS 20	HS: 0.71	Load Restricted Bridge? <input type="checkbox"/>			
Op Rating: 33.00	A1: 1.00	BL Load:			
Inv Rating: 19.00	A2: 0.98	CL-8 Load:			
	A3: 1.04	SA Load:			
<p align="center"><b>Bridge Inspection Information</b></p> Date Inspected: 7/15/2009      Structr Adequacy: 4 Superstr Code: 4                      Safe Load: 5 Substr Code: 5                         Deck Geometry: 5 Deck Code: 3                          Underclearance: 9 Scour: 3                                 Waterway: 6			<p align="center"><b>Bridge Profile View</b></p> 		
<p align="center"><b>Proposed Bridge Replacement Information</b></p> New Bridge Width: 40 ft.      Bridge \$'s: New Bridge Length: 120 ft.      Total \$'s: Priority Array #: 8 PIN Number: WIN Number:                      Repl/Rehab Year: Contract Number:                      Ad Date:					
<p>THE BRIDGE IS CLASSIFIED "SD" DUE TO A SUPERSTRUCTURE AND DECK CONDITION.</p> <p>This is a cast-in-place hollow concrete slab. The bridge was constructed with little or no cover over the top mat of steel reinforcing in the deck. The top surface of the slab was first overlaid with a membrane and asphalt in 1974. The deck was repaired extensively and overlaid with asphalt in 1989. The bottom side of the slab has significant cracking with rust staining.</p> <p>Bridge Replacement is warranted since there is no cost effect way of addressing the bridge scour problem and the concrete slab deterioration.</p> <p>This bridge has been added to the 2009-11 P2 Program Replacement List.</p>					



# 2011-13 Bien P2 Bridge Replacements/Rehab Candidate

Bridge Number: 97 / 106	Structure ID 0002689B	Bridge Name: SATUS CR 2ND CROSSING	Milepost: 45.84	Region: South Central
Year Built / YR Widened: 1942	Bridge Type: SRB TTC	Number of Main/Appr span 1 / 4	Sufficiency Rating: 42.48 SD	
Bridge Width (curb-curb): 29.6 ft	Bridge Length: 133 ft	Max Span: 60 ft	<b>Bridge Deck View</b>	
Average Daily Traffic: 3,253	Truck% 29%	Number of Lanes: 2	NHS: YES	
Vertical Clearance: NA	Detour Length (miles): 63	Appr Rdway Width: 32.0 ft		
Design Load: H 15	HS: 1.10	Load Restricted Bridge? <input checked="" type="checkbox"/>		
Op Rating: 40.00	A1: 1.35	BL Load: 20,500		
Inv Rating: 27.00	A2: 1.48	CL-8 Load: 20,500		
	A3: 1.64	SA Load: 42,000		
<b>Bridge Inspection Information</b>			<b>Bridge Profile View</b>	
Date Inspected: 4/14/2008	Structr Adequacy: 5			
Superstr Code: 6	Safe Load: 5			
Substr Code: 5	Deck Geometry: 4			
Deck Code: 4	Underclearance: 9			
Scour: 3	Waterway: 3			
<b>Proposed Bridge Replacement Information</b>				
New Bridge Width: 36 ft.	Bridge \$'s: \$1,700,000			
New Bridge Length: 180 ft.	Total \$'s: \$5,982,400			
Priority Array #: 2				
PIN Number: 509703L				
WIN Number: E09703L	Repl/Rehab Year: 2011			
Contract Number:	Ad Date: 10/15/2010			
<b>THE BRIDGE IS CLASSIFIED "SD" DUE TO A DECK CONDITION.</b>				
<p>The waterway opening under the bridge is very restricted. Region maintenance typically removes drift debris every spring.</p> <p>The steel beams have areas of rust blooms and top flange rust. The timber sawn girders 1M, 2J and 2L have a horizontal split in the web for approx 1/2 length near mid span. Three feet of east end of pier no. 2 timber cap has a 1 inch shell (Red Tagged). Pier 5 cap under stringer "D" has center rot. Four feet of east end of pier 6 cap has center rot.</p> <p>Bridge Replacement project currently scheduled to go to contract in October 2010.</p>				



# 2011-13 Bien P2 Bridge Replacements/Rehab Candidate

Bridge Number: 101 / 354		Structure ID 0002437A		Bridge Name: MCDONNELL CR		Milepost: 258.21		Region: Olympic	
Year Built / YR Widened: 1939		Bridge Type: TTC		Number of Main/Appr span 9 / 0		Sufficiency Rating: 18.91 SD			
Bridge Width (curb-curb): 28.0 ft		Bridge Length: 179 ft		Max Span: 36 ft		<b>Bridge Deck View</b> 			
Average Daily Traffic: 18,956		Truck% 10%	Number of Lanes: 2	NHS: YES					
Vertical Clearance: NA		Detour Length (miles): 13		Appr Rdway Width: 40.0 ft					
Design Load: H 15		HS: 1.38	Load Restricted Bridge? <input type="checkbox"/>						
Op Rating: 50.00		A1: 1.68	BL Load:						
Inv Rating: 31.00		A2: 1.85	CL-8 Load:						
		A3: 2.04	SA Load:						
<b>Bridge Inspection Information</b>									
Date Inspected: 6/28/2009		Structr Adequacy: 3							
Superstr Code: 7		Safe Load: 5							
Substr Code: 3		Deck Geometry: 2							
Deck Code: 6		Underclearance: 9							
Scour: 3		Waterway: 8							
<b>Proposed Bridge Replacement Information</b>									
New Bridge Width: 40 ft.		Bridge \$'s:							
New Bridge Length: 185 ft.		Total \$'s:							
Priority Array #: 9									
PIN Number:									
WIN Number:		Repl/Rehab Year:							
Contract Number:		Ad Date:							
<b>Bridge Profile View</b> 									
<p><b>THIS BRIDGE IS CLASSIFIED "SD" DUE TO A SUBSTRUCTURE / SCOUR CONDITION.</b></p> <p>Substructure rated a 3 based on embedment depths of piles at Piers 5 through 8 being five foot or less. There are also yellow tagged caps and previously red tag piles that now have helper piles. Even before scour is considered, the pile tips of Piers 5 - 8 are only 4 to 7 ft below the ground surface. If the banks erode and the stream reaches Piers 4 or 9, they will be undermined. Scour code changed from 2 to 3 by HDR 2/24/2004. SCOUR - Pile 9D is 1'-9" from embankment and Pile 9E is 1'-0" from embankment.</p>									



# 2011-13 Bien P2 Bridge Replacements/Rehab Candidate

Bridge Number: 107 / 5	Structure ID 0004381A	Bridge Name: SLOUGH		Milepost: 7.59	Region: Olympic
Year Built / YR Widened: 1953	Bridge Type: TTC		Number of Main/Appr span 16 / 0	Sufficiency Rating: 36.79 SD	
Bridge Width (curb-curb): 22.4 ft	Bridge Length: 294 ft	Max Span: 19 ft		<b>Bridge Deck View</b> 	
Average Daily Traffic: 4,113	Truck% 17%	Number of Lanes: 2	NHS: No		
Vertical Clearance: NA	Detour Length (miles): 40		Appr Rdway Width: 28.0 ft		
Design Load: HS 15	HS: 1.27	Load Restricted Bridge? <input checked="" type="checkbox"/>			
Op Rating: 46.00	A1: 1.51	BL Load: 20,000			
Inv Rating: 32.00	A2: 1.65	CL-8 Load:			
	A3: 1.83	SA Load: 40,000			
<b>Bridge Inspection Information</b>				<b>Bridge Profile View</b> 	
Date Inspected: 5/20/2008	Structr Adequacy: 4				
Superstr Code: 6	Safe Load: 5				
Substr Code: 4	Deck Geometry: 2				
Deck Code: 6	Underclearance: 9				
Scour: 5	Waterway: 6				
<b>Proposed Bridge Replacement Information</b>					
New Bridge Width: 40 ft.	Bridge \$'s:				
New Bridge Length: 295 ft.	Total \$'s:				
Priority Array #: 18					
PIN Number: 310708A					
WIN Number: C10708D	Repl/Rehab Year: 2008				
Contract Number:	Ad Date: 1/7/2008				
<p><b>THIS BRIDGE IS CLASSIFIED "SD" DUE TO A SUBSTRUCTURE CONDITION.</b>                  Substructure coded a "4" due to extensive rot in piles and caps. This bridge was added to the Bridge Replacement Priority Array in 1990.</p> <p>There are 28 of the 48 interior timber piles that are "Yellow Tagged" due to splits or rot within 3 inches of their center. The timber cap @ piers 8 and 11 are "Red Tagged" and have a 1 inch shell in selected locations. The new replacement bridge will be a prestressed concrete hollow slab. The Bridge\$'s include: \$1,640,000 for the new bridge, \$310,000 for the detour bridge, \$140,000 for the soldier pile walls at the ends of the new bridge.</p>					



# 2011-13 Bien P2 Bridge Replacements/Rehab Candidate

Bridge Number: 107 / 6	Structure ID 0004381B	Bridge Name: SLOUGH	Milepost: 7.79	Region: Olympic
Year Built / YR Widened: 1953	Bridge Type: TTC		Number of Main/Appr span 15 / 0	Sufficiency Rating: 36.79 SD
Bridge Width (curb-curb): 22.5 ft	Bridge Length: 279 ft	Max Span: 19 ft	<b>Bridge Deck View</b>	
Average Daily Traffic: 4,113	Truck% 17%	Number of Lanes: 2	NHS: No	
Vertical Clearance: NA	Detour Length (miles): 40		Appr Rdway Width: 28.0 ft	
Design Load: HS 15	HS: 1.26	Load Restricted Bridge? <input checked="" type="checkbox"/>		
Op Rating: 45.00	A1: 1.50	BL Load:	21,000	
Inv Rating: 32.00	A2: 1.64	CL-8 Load:		
	A3: 1.82	SA Load:	41,000	
<b>Bridge Inspection Information</b>			<b>Bridge Profile View</b>	
Date Inspected: 5/20/2008	Structr Adequacy: 4			
Superstr Code: 6	Safe Load: 5			
Substr Code: 4	Deck Geometry: 2			
Deck Code: 6	Underclearance: 9			
Scour: 5	Waterway: 8			
<b>Proposed Bridge Replacement Information</b>				
New Bridge Width: 40 ft.	Bridge \$'s:			
New Bridge Length: 280 ft.	Total \$'s:			
Priority Array #: 17				
PIN Number: 310708A				
WIN Number: C10708D	Repl/Rehab Year: 2008			
Ad Date: 1/7/2008				
Contract Number:				
<p><b>THIS BRIDGE IS CLASSIFIED "SD" DUE A SUBSTRUCTURE CONDITION.</b> Substructure coded a "4" due to extensive rot in piles and caps.</p> <p>There are 5 of the 40 interior timber piles that are "Yellow Tagged" due to splits and have been temporarily repaired with steel rings. The new replacement bridge will be a prestressed concrete hollow slab. The Bridge\$'s include: \$1,640,000 for the new bridge, \$310,000 for the detour bridge, \$140,000 for the soldier pile walls at the ends of the new bridge.</p> <p>The Bridge PS&amp;E has been completed.</p>				



# 2011-13 Bien P2 Bridge Replacements/Rehab Candidate

Bridge Number: 167 / 20E	Structure ID 0003960A	Bridge Name: PUYALLUP R	Milepost: 6.40	Region: Olympic
Year Built / YR Widened: 1925 / 1951	Bridge Type: STrus TTC PRCB		Number of Main/Appr span 1 / 5	Sufficiency Rating: 33.04 SD
Bridge Width (curb-curb): 21.0 ft	Bridge Length: 477 ft	Max Span: 371 ft	<b>Bridge Deck View</b>	
Average Daily Traffic: 17,936	Truck% 5%	Number of Lanes: 2	NHS: YES	
Vertical Clearance: 18 FT 07 in	Detour Length (miles): Appr Rdway Width: 2 24.0 ft		<b>Bridge Profile View</b> 	
Design Load: H 15	HS: 0.69	Load Restricted Bridge? <input checked="" type="checkbox"/>		
Op Rating: 28.00	A1: 0.93	BL Load:		
Inv Rating: 17.00	A2: 0.97	CL-8 Load:		
	A3: 1.07	SA Load:		
<b>Bridge Inspection Information</b>				
Date Inspected: 7/12/2009	Structr Adequacy: 2			
Superstr Code: 5	Safe Load: 5			
Substr Code: 6	Deck Geometry: 2			
Deck Code: 5	Underclearance: 2			
Scour: 7	Waterway: 8			
<b>Proposed Bridge Replacement Information</b>				
New Bridge Width: 75 ft.	Bridge \$'s:			
New Bridge Length: 480 ft.	Total \$'s: \$45,000,000			
Priority Array #: 12				
PIN Number:				
WIN Number:	Repl/Rehab Year:			
Contract Number:	Ad Date:			
THIS BRIDGE IS CLASSIFIED "SD" DUE TO THE STRUCTURAL ADEQUACY CODE.				



# 2011-13 Bien P2 Bridge Replacements/Rehab Candidate

Bridge Number: 241 / 5	Structure ID 08336200	Bridge Name: MABTON-SUNNYSIDE #650	Milepost: 1.34	Region: South Central
Year Built / YR Widened: 1954	Bridge Type: CBOX	Number of Main/Appr span 5 / 0	Sufficiency Rating: 10.84 SD	
Bridge Width (curb-curb): 24.0 ft	Bridge Length: 521 ft	Max Span: 114 ft	<b>Bridge Deck View</b>	
Average Daily Traffic: 4,150	Truck% 5%	Number of Lanes: 2	NHS: No	
Vertical Clearance: NA	Detour Length (miles): 19	Appr Rdway Width: 32.0 ft		
Design Load: HS 20	HS: 0.43	Load Restricted Bridge? <input checked="" type="checkbox"/>		
Op Rating: 13.00	A1: 0.58	BL Load:		
Inv Rating: 8.00	A2: 0.51	CL-8 Load:		
	A3: 0.57	SA Load:		
<b>Bridge Inspection Information</b>			<b>Bridge Profile View</b>	
Date Inspected: #####	Structr Adequacy: 2			
Superstr Code: 5	Safe Load: 0			
Substr Code: 6	Deck Geometry: 2			
Deck Code: 7	Underclearance: 9			
Scour: 5	Waterway: 8			
<b>Proposed Bridge Replacement Information</b>				
New Bridge Width: 40 ft.	Bridge \$'s:			
New Bridge Length: 525 ft.	Total \$'s:			
Priority Array #: 11				
PIN Number:				
WIN Number:	Repl/Rehab Year:			
Contract Number:	Ad Date:			



**THIS BRIDGE IS CLASSIFIED "SD" DUE TO THE STRUCTURAL ADEQUACY CODE.**

The capacity of the bridge to carry vehicular traffic is low because of its age and poor shear strength design. This bridge is currently load posted with the following ratings - Truck 14 tons , Truck/Semitrailer 18 tons , Truck/Trailer 22 tons. This bridge was built by Yakima County and transferred to the Department in 1992. It was designed for HS-15 loads but used design standards that resulted in very light shear reinforcement and low shear capacity. The cracking in the girder webs is evidence of this low shear capacity.



# 2011-13 Bien P2 Bridge Replacements/Rehab Candidate

Bridge Number: 300 / 1	Structure ID 0007342A	Bridge Name: MISSION CR	Milepost: 0.28	Region: Olympic
Year Built / YR Widened: 1963	Bridge Type: TS		Number of Main/Appr span 3 / 0	Sufficiency Rating: 32.72SD
Bridge Width (curb-curb): 26.0 ft	Bridge Length: 51 ft	Max Span: 17 ft	<b>Bridge Deck View</b>	
Average Daily Traffic: 6,584	Truck% 5%	Number of Lanes: 2	NHS: No	
Vertical Clearance: NA	Detour Length (miles): 50		Appr Rdway Width: 28.0 ft	
Design Load: HS 20	HS: 1.05	Load Restricted Bridge? <input type="checkbox"/>		
Op Rating: 38.00	A1: 1.32	BL Load:		
Inv Rating: 28.00	A2: 1.39	CL-8 Load:		
	A3: 1.60	SA Load:		
<b>Bridge Inspection Information</b>			<b>Bridge Profile View</b>	
Date Inspected: 3/5/2008	Structr Adequacy: 4			
Superstr Code: 7	Safe Load: 5			
Substr Code: 4	Deck Geometry: 2			
Deck Code: 7	Underclearance: 9			
Scour: 3	Waterway: 6			
<b>Proposed Bridge Replacement Information</b>				
New Bridge Width: 40 ft.	Bridge \$'s:			
New Bridge Length: 60 ft.	Total \$'s:			
Priority Array #: 20				
PIN Number:				
WIN Number:	Repl/Rehab Year:			
Contract Number:	Ad Date:			
<p><b>THIS BRIDGE IS CLASSIFIED "SD" BASED ON A SUBSTRUCTURE / SCOUR CONDITION.</b>                  This is a 3 span Treated Timber bridge built in 1963 with 2 intermediate piers in the waterway. The intermediate pierwalls are on spread footings. Bridge has been closed due to scour failure in the past.</p> <p>Substructure coded a "4" due to scour where Pier 3 has previously experienced settlement. A Scour report says The calculated scour depth is well below the bottom of the foundations shown on the original layout sheet and notes in the file indicate the bridge has experienced a failure due to scour in 1966 and was repaired. The previous recommend scour repair of riprap placement around the piers has been completed.</p> <p>This bridge has been added to the P2 Program Replacement List for the 2009-11 biennium.</p>				



# 2011-13 Bien P2 Bridge Replacements/Rehab Candidate

Bridge Number: 302 / 105	Structure ID 000000JQ	Bridge Name: PURDY BR	Milepost: 15.65	Region: Olympic
Year Built / YR Widened: 1936 / 1966	Bridge Type: CBOX		Number of Main/Appr span 5 / 0	Sufficiency Rating: 23.45 SD
Bridge Width (curb-curb): 20.0 ft	Bridge Length: 550 ft	Max Span: 190 ft	<b>Bridge Deck View</b>	
Average Daily Traffic: 21,346	Truck% 3%	Number of Lanes: 2	NHS: No	
Vertical Clearance: NA	Detour Length (miles): 50		Appr Rdway Width: 26.0 ft	
Design Load: H 15	HS: 0.88	Load Restricted Bridge? <input checked="" type="checkbox"/>		
Op Rating: 37.00	A1: 1.21	BL Load: 19,500		
Inv Rating: 22.00	A2: 1.09	CL-8 Load:		
	A3: 1.06	SA Load: 32,500		
<b>Bridge Inspection Information</b>			<b>Bridge Profile View</b>	
Date Inspected: 6/22/2008	Structr Adequacy: 4			
Superstr Code: 6	Safe Load: 5			
Substr Code: 4	Deck Geometry: 2			
Deck Code: 5	Underclearance: 9			
Scour: 5	Waterway: 8			
<b>Proposed Bridge Replacement Information</b>				
New Bridge Width: 40 ft.	Bridge \$'s:			
New Bridge Length: 550 ft.	Total \$'s:			
Priority Array #: 13				
PIN Number:				
WIN Number:	Repl/Rehab Year:			
Contract Number:	Ad Date:			



**THIS BRIDGE IS CLASSIFIED "SD" DUE TO THE SUBSTRUCTURE CODE.**  
 The capacity of the bridge to carry vehicular traffic is low because of its age and poor shear strength design.

Substructure coded "4" based on Piers 3 and 4 pier walls heavily spalled in all four corners with rebar that is corroded through and missing, and other areas where exposed rebar is heavily corroded and covered with marine life. The pier walls are box structures with interior voids, and the corner spalls have reduced the wall thickness in areas from 16" to about 7" thick. The reduced wall thickness near and below the water surface increases the likelihood of local failure of the submerged pier walls.



# 2011-13 Bien P2 Bridge Replacements/Rehab Candidate

Bridge Number: 303 / 4A	Structure ID 0003531A	Bridge Name: MANETTE BRIDGE	CS1841	Milepost: 1.47	Region: Olympic
Year Built / YR Widened: 1930 / 1949	Bridge Type: STrus SG SRB		Number of Main/Appr span 1 / 12	Sufficiency Rating: 16.80 SD	
Bridge Width (curb-curb): 18.4 ft	Bridge Length: 1,573 ft	Max Span: 243 ft		<p style="text-align: center;"><b>Bridge Deck View</b></p> 	
Average Daily Traffic: 7,300	Truck% 3%	Number of Lanes: 2	NHS: YES		
Vertical Clearance: 14 FT 07 in	Detour Length (miles): 5		Appr Rdway Width: 22.0 ft		
Design Load: HS 15	HS: 1.03	Load Restricted Bridge? <input checked="" type="checkbox"/>			
Op Rating: 37.00	A1: 1.23	BL Load:			
Inv Rating: 22.00	A2: 1.33	CL-8 Load:			
	A3: 1.49	SA Load:			
<b>Bridge Inspection Information</b>					
Date Inspected: 11/17/2008	Structr Adequacy: 2				
Superstr Code: 4	Safe Load: 3				
Substr Code: 4	Deck Geometry: 2				
Deck Code: 5	Underclearance: 9				
Scour: 3	Waterway: 8				
<b>Proposed Bridge Replacement Information</b>					
New Bridge Width: 54 ft.	Bridge \$'s:				
New Bridge Length: 1,550 ft.	Total \$'s: \$82,854,344				
Priority Array #: 3					
PIN Number: 330311A					
WIN Number: C30311A	Repl/Rehab Year: 2010				
Contract Number:	Ad Date: 3/1/2010				
<p><b>THIS BRIDGE IS CLASSIFIED "SD" DUE TO A SUBSTRUCTURE CONDITION.</b>          This bridge was added to the Priority Array in 1990 as a bridge rehabilitation project.          A review of information obtained during the rehab contracts determined that further rehabilitation of the concrete in the piers is not feasible thus, this bridge is in need of replacement.</p> <p>Core testing of the substructure concrete in the piers indicates the presence of alkali-silica reaction. Bridge Inspections indicate continuing deterioration in the underwater footings. The footings at pier 5 was repaired under Contract 4038 in 1992. The footings at piers 4 and 6 were repaired under Contract 4658 in 1995. A decision was made in 1993 to complete necessary repairs until the bridge could be replaced.</p>					
<b>Bridge Profile View</b>					
					



# 2011-13 Bien P2 Bridge Replacements/Rehab Candidate

Bridge Number: 506 / 106	Structure ID 0003928A	Bridge Name: LACAMAS CR	Milepost: 8.05	Region: Southwest
Year Built / YR Widened: 1951	Bridge Type: TTC		Number of Main/Appr span 9 / 0	Sufficiency Rating: 41.84 SD
Bridge Width (curb-curb): 24.0 ft	Bridge Length: 170 ft	Max Span: 19 ft	<b>Bridge Deck View</b>	
Average Daily Traffic: 1,956	Truck% 12%	Number of Lanes: 2	NHS: No	
Vertical Clearance: NA	Detour Length (miles): 11		Appr Rdway Width: 30.0 ft	
Design Load: H 15	HS: 0.84	Load Restricted Bridge? <input checked="" type="checkbox"/>		
Op Rating: 30.00	A1: 0.99	BL Load:	16,500	
Inv Rating: 19.00	A2: 1.08	CL-8 Load:	21,000	
	A3: 1.20	SA Load:	41,000	
<b>Bridge Inspection Information</b>			<b>Bridge Profile View</b>	
Date Inspected: 5/7/2009	Structr Adequacy: 4			
Superstr Code: 5	Safe Load: 5			
Substr Code: 4	Deck Geometry: 4			
Deck Code: 3	Underclearance: 9			
Scour: 5	Waterway: 8			
<b>Proposed Bridge Replacement Information</b>				
New Bridge Width: 40 ft.	Bridge \$'s:			
New Bridge Length: 175 ft.	Total \$'s:			
Priority Array #: 21				
PIN Number: 450607A				
WIN Number: D50607A	Repl/Rehab Year: 2015			
Contract Number:	Ad Date:			
<p><b>THIS BRIDGE IS CLASSIFIED "SD" DUE TO A DECK AND SUBSTRUCTURE CONDITION.</b>                  This bridge was added to the Bridge Replacement Priority Array in 2000.</p> <p>The Bridge Inspection Report says the deck has a 6" thick ACP overlay has many cracks and patches. Many timber lams in deck (3"x4") have center rot starting from the North edge and continuing 2' to 8' into the deck. The Stringer 10 has been replaced; Stringer 20 and 30 are Red Tagged and have 2" and 1/2" shell on 5" section under scupper. The Piles are checked, weathered, and split. Pile 3D has a 2" shell and a 6" rot pocket near the top (Y.T.); Pile 4D has a 1/4" wide check - 16 feet long; Pile 6D has a 2" shell with a 4" rot pocket ranging from 6' - 15' from the ground and has bug borer holes throughout (Y.T.); Pile 7D has a 2" shell with 4" rot pocket along the top 6 feet (Y.T.).</p> <p>P2 Bridge Replacement funding will likely be available in 2013-15.</p>				



# 2011-13 Bien P2 Bridge Replacements/Rehab Candidate

Bridge Number: 508 / 12	Structure ID 000000IJ	Bridge Name: S FK NEWAUKUM R	Milepost: 13.65	Region: Southwest
Year Built / YR Widened: 1930	Bridge Type: STrus TTC		Number of Main/Appr span 1 / 7	Sufficiency Rating: 27.89 SD
Bridge Width (curb-curb): 20.0 ft	Bridge Length: 197 ft	Max Span: 90 ft	<b>Bridge Deck View</b>	
Average Daily Traffic: 1,652	Truck% 14%	Number of Lanes: 2	NHS: No	
Vertical Clearance: NA	Detour Length (miles): 23		Appr Rdway Width: 26.0 ft	
Design Load: Unknown	HS: 0.79	Load Restricted Bridge? <input checked="" type="checkbox"/>		
Op Rating: 37.00	A1: 1.09	BL Load:	16,000	
Inv Rating: 22.00	A2: 0.91	CL-8 Load:	18,000	
	A3: 0.91	SA Load:	34,000	
<b>Bridge Inspection Information</b>			<b>Bridge Profile View</b>	
Date Inspected: 2/27/2008	Structr Adequacy:	4		
Superstr Code: 5	Safe Load:	2		
Substr Code: 5	Deck Geometry:	2		
Deck Code: 3	Underclearance:	9		
Scour: 3	Waterway:	8		
<b>Proposed Bridge Replacement Information</b>				
New Bridge Width: 40 ft.	Bridge \$'s:			
New Bridge Length: 200 ft.	Total \$'s:			
Priority Array #: 19				
PIN Number:				
WIN Number:	Repl/Rehab Year:	2015		
Contract Number:	Ad Date:			
<p><b>THIS BRIDGE IS CLASSIFIED "SD" BASED ON THE DECK CONDITION.</b>                  The ACP was removed in 2001 as part of contract 6020. The concrete deck is very deteriorated and has over 60% delaminations.</p> <p>There is 15% section loss in the floorbeam webs near the connections to the truss, and 10% section loss in the bottom flanges near the ends. Exterior stringers: Top flanges up to 15% section loss and bottom flanges up to 30% section loss. Worst case is Stringer 7-1A near north truss panel point L1 with about 10 ft. of bottom flange showing laminar rusting and 30% section loss. Floor system lateral bracing between L4-L5 is bent 4" over 9 ft.</p>				



# 2011-13 Bien P2 Bridge Replacements/Rehab Candidate

Bridge Number: 508 / 23	Structure ID 000000CQ	Bridge Name: ALDER CR	Milepost: 22.65	Region: Southwest
Year Built / YR Widened: 1937	Bridge Type: TTT		Number of Main/Appr span 3 / 0	Sufficiency Rating: 49.01 SD
Bridge Width (curb-curb): 19.6 ft	Bridge Length: 88 ft	Max Span: 29 ft	<b>Bridge Deck View</b>	
Average Daily Traffic: 1,331	Truck% 14%	Number of Lanes: 2	NHS: No	
Vertical Clearance: NA	Detour Length (miles): 50		Appr Rdway Width: 21.0 ft	
Design Load: Unknown	HS: 1.03	Load Restricted Bridge? <input type="checkbox"/>		
Op Rating: 37.00	A1: 1.29	BL Load:		
Inv Rating: 26.00	A2: 1.31	CL-8 Load:		
	A3: 1.58	SA Load:		
<b>Bridge Inspection Information</b>			<b>Bridge Profile View</b>	
Date Inspected: 2/27/2008	Structr Adequacy: 5			
Superstr Code: 6	Safe Load: 5			
Substr Code: 5	Deck Geometry: 2			
Deck Code: 3	Underclearance: 9			
Scour: 5	Waterway: 8			
<b>Proposed Bridge Replacement Information</b>				
New Bridge Width: 38 ft.	Bridge \$'s:			
New Bridge Length: 95 ft.	Total \$'s:			
Priority Array #: 23				
PIN Number: 450804A				
WIN Number: D50804A	Repl/Rehab Year:			
Contract Number:	Ad Date:			



**THIS BRIDGE IS CLASSIFIED "SD" DUE TO A DECK, SUPER AND SUBSTRUCTURE CONDITION.**

The inspection report indicates the timber deck was repaired in 1993 by maintenance forces. During the repair the timber deck was found to have many rotten areas. The maintenance forces indicated that more areas will need to be repaired in the future. There are numerous pot holes in the existing ACP. Column 2D is red tagged due to rot found in the bottom 4'. Column 3D has a helper column next to the original column.

P2 Bridge Replacement funding will likely be available in 2015-17.



# 2011-13 Bien P2 Bridge Replacements/Rehab Candidate

Bridge Number: 508 / 25		Structure ID 000000JV		Bridge Name: CREEK		Milepost: 24.08		Region: Southwest		
Year Built / YR Widened: 1937		Bridge Type: TTC		Number of Main/Appr span 1 / 0		Sufficiency Rating: 53.00 FO				
Bridge Width (curb-curb): 19.7 ft		Bridge Length: 26 ft		Max Span: 24 ft		<b>Bridge Deck View</b>				
Average Daily Traffic: 1,331		Truck% 14%	Number of Lanes: 2		NHS: No					
Vertical Clearance: NA		Detour Length (miles): 50		Appr Rdway Width: 20.0 ft						
Design Load: Unknown		HS: 1.14	Load Restricted Bridge? <input checked="" type="checkbox"/>							
Op Rating: 41.00		A1: 1.29	BL Load: 18,000							
Inv Rating: 28.00		A2: 1.37	CL-8 Load: 21,500							
		A3: 1.57	SA Load: 39,000							
<b>Bridge Inspection Information</b>					<b>Bridge Profile View</b>					
Date Inspected: 10/20/2009		Structr Adequacy: 5								
Superstr Code: 6		Safe Load: 5								
Substr Code: 5		Deck Geometry: 2								
Deck Code: 6		Underclearance: 9								
Scour: 3		Waterway: 3								
<b>Proposed Bridge Replacement Information</b>										
New Bridge Width: 36 ft.		Bridge \$'s:								
New Bridge Length: 30 ft.		Total \$'s:								
Priority Array #: 22										
PIN Number: 450807A										
WIN Number: D50807A		Repl/Rehab Year:								
Contract Number:		Ad Date:								
<p><b>THIS BRIDGE IS CLASSIFIED "SD" DUE TO A DECK, SUPER AND SUBSTRUCTURE CONDITION.</b></p> <p>The ACP is breaking up in the east bound lane with open alligator cracking. Water leaks through the deck before it can run off the bridge. The deck planks are wet, spongy and starting to rot in the area of the breaking up ACP. There are 12 lines of stringers, most of them are wet. Most stringers are mud stained with weather checks in a few locations. The north section of the timber cap @ Pier 2 has a 1.5 inch shell over pile 2A and a 1 inch shell over pile 2C. It has been red tagged and needs to be replaced. Pile 1A is wet, soft and punky. Pile 1B has a vertical split on the NW corner with surface insect infestation. Pile 1D has a vertical split on the south face with surface insect rot up to 1/2 inch deep. Pile 2E is red tagged today with a 1.5 inch shell.</p> <p>P2 Bridge Replacement funding will likely be available in 2011-13.</p>										



# 2011-13 Bien P2 Bridge Replacements/Rehab Candidate

Bridge Number: 548 / 10	Structure ID 08061500	Bridge Name: DAKOTA CR	Milepost: 11.54	Region: Northwest	
Year Built / YR Widened: 1930 / 1951	Bridge Type: SRB TTC	Number of Main/Appr span 1 / 4	Sufficiency Rating: 34.67 SD		
Bridge Width (curb-curb): 23.7 ft	Bridge Length: 182 ft	Max Span: 80 ft	<p align="center"><b>Bridge Deck View</b></p> 		
Average Daily Traffic: 7,152	Truck% 14%	Number of Lanes: 2			NHS: No
Vertical Clearance: NA	Detour Length (miles): 3	Appr Rdway Width: 27.0 ft			
Design Load: H 15	HS: 0.44	Load Restricted Bridge? <input checked="" type="checkbox"/>			
Op Rating: 24.00	A1: 0.60	BL Load: 21,500			
Inv Rating: 14.00	A2: 0.53	CL-8 Load: 21,500			
	A3: 0.54	SA Load:			
<b>Bridge Inspection Information</b>					
Date Inspected: 7/22/2009	Structr Adequacy: 2				
Superstr Code: 5	Safe Load: 0				
Substr Code: 5	Deck Geometry: 2				
Deck Code: 6	Underclearance: 9				
Scour: 5	Waterway: 8				
<b>Proposed Bridge Replacement Information</b>					
New Bridge Width: 40 ft.	Bridge \$'s:				
New Bridge Length: 190 ft.	Total \$'s:				
Priority Array #: 10					
PIN Number: 154816A					
WIN Number: A54816A	Repl/Rehab Year: 2010				
Contract Number:	Ad Date:				
<p><b>THIS BRIDGE IS CLASSIFIED "SD" DUE TO THE STRUCTURAL ADEQUACY CODE.</b></p> <p>The ownership of this bridge was transferred from Whatcom County to the state as part of the 1992 Route Jurisdictional Transfer.</p> <p>This bridge has a posted 15 ton weight limit due to the design of the steel and timber girders. The steel beams are rusty with some pitted areas. There are two yellow tagged piles in the treated timber approach spans.</p>					
<p align="center"><b>Bridge Profile View</b></p> 					



## P2 Bridge Preservation - Bridge Repair

### 2011-13 Bien Priority Array

(Sorted by Priority Number)

11-13 #	Bridge Number	Bridge Name	Region	Repair Description	Bridge Item\$'s
1	167/38	24TH ST E OVER SR 167	Olympic	Replace damaged PCG	\$500,000
1	2/39	ANDERSON CR	Northwest	Replace East side Br Rail	\$200,000
1	16/110E	TACOMA NARROWS	Olympic	Replace Finger Exp Jnt at Tower #4	\$300,000
2	16/110E	TACOMA NARROWS	Olympic	Replace Maintenance Traveler	\$3,000,000
3	5/104W	DIKE ACCESS RD & RR	Southwest	Replace Steel Exp Joint	\$104,000
4	395/40	PIONEER MEM. BR	South Central	Replace Exp Joint	\$470,000
5	5/537S	EB LANES I-5 OC	Northwest	Repair Conc Box Girder	\$100,000
6	5/537S	EB LANES I-5 OC	Northwest	Replace Exp Jnt	\$40,000
7	5/535E	NB VIADUCT STA 2032	Northwest	Replace Exp Jnt	\$50,000
8	5/536N-W	NB I5 to WB W SEA FRW	Northwest	Replace Exp Jnt	\$15,000
9	5/537E-S	E-S RAMP BR	Northwest	Replace Exp Jnt	\$120,000
10	5/537N	S-E RAMP WB LANES	Northwest	Replace Exp Jnt	\$42,000
11	5/537N-W	N-6TH RAMP BRIDGE	Northwest	Replace Exp Jnt	\$63,000
12	5/538E	NB VIADUCT STA 2075	Northwest	Replace Exp Jnt	\$140,000
13	5/543E	KING-JACKSON ST OC	Northwest	Replace Exp Jnt	\$58,000
14	5/543NCD	NBCD KING JACKSON S	Northwest	Replace Exp Jnt	\$113,000
15	5/543SCD	SBCD KING JACKSON S	Northwest	Replace Exp Jnt	\$150,000
16	5/543W	KING-JACKSON ST OC	Northwest	Replace Exp Jnt	\$56,000
17	5/545NCD	NBCD VIADUCT STA 219	Northwest	Replace Exp Jnt	\$96,000
18	5/545SCD	SBCD VIADUCT STA 219	Northwest	Replace Exp Jnt	\$180,000
19	5/562E	NB LANES VIADUCT	Northwest	Replace Exp Jnt	\$90,000
20	104/5.1	HOOD CANAL-W.A. BUG	Olympic	Replace 18 anchor cables	\$3,000,000
21	90/25N	HOMER M. HADLEY	Northwest	Replace 10 Anchor Cables	\$2,430,000
22	90/25S	LACEY V. MURROW BR	Northwest	Replace 10 Anchor Cables	\$2,430,000
23	5/232W	SKOOKUMCHUCK R	Southwest	Repair damage Truss	\$716,705
24	5/647E	UNION SLOUGH	Northwest	Replace Exp Jnt	\$120,000
25	5/647W	UNION SLOUGH	Northwest	Replace Exp Jnt	\$120,000
26	5/648W	STEAMBOAT SLOUGH	Northwest	Replace Exp Jnt	\$144,000
27	5/650E	EBEY SL BN RY SR 529	Northwest	Replace Exp Jnt	\$900,000
28	5/650W	EBEY SL BN RY SR 529	Northwest	Replace Exp Jnt	\$470,000
29	5/342W-S	MCALLISTER CR	Olympic	Repair Concrete Columns	\$200,000
30	18/9	NP RY OC	Northwest	Replace Exp Jnts @ 6 locations	\$250,000
31	18/9	NP RY OC	Northwest	Replace and Paint Steel Hanger and Pin asse	\$309,750



## P2 Bridge Preservation - Bridge Repair

### 2011-13 Bien Priority Array

(Sorted by Priority Number)

11-13 #	Bridge Number	Bridge Name	Region	Repair Description	Bridge Item\$'s
32	90/10W-S	I-5 OC, W-S RAMP	Northwest	Replace Exp Joints	\$164,000
33	90/540N	HANGMAN CR	Eastern	Repair deteriorated conc in CBOX	\$150,000
34	90/540S	HANGMAN CR	Eastern	Repair deteriorated conc in CBOX	\$100,000
35	405/70E	SR 522 OC SAMMAMISH	Northwest	Replace Exp Joints	\$100,000
36	405/70N-E	N-E RAMP SAMMAMISH	Northwest	Replace Exp Joints	\$34,500
37	405/70N-W	N-W RAMP SAMMAMISH	Northwest	Replace Exp Joints	\$60,000
38	405/70S-E	S-E RAMP BR	Northwest	Replace Exp Joints	\$25,000
39	405/70W	SR 522 OC SAMMAMISH	Northwest	Replace Exp Joints	\$100,000
40	5/102E	SR 503 OC	Southwest	Replace Exp Jnt	\$27,900
41	5/102W	SR 503 OC	Southwest	Replace Exp Jnt	\$27,900
42	153/16	METHOW R	North Central	Concrete Bridge Rail	\$190,000
43	153/17	METHOW R	North Central	Concrete Bridge Rail	\$125,000
44	90/25N	HOMER M. HADLEY	Northwest	Replace 10 Anchor Cables	\$2,430,000
45	101/269	FULTON CR	Olympic	Repair Concrete Columns	\$320,000
46	101/432E	KENNEDY CR	Olympic	Repair Concrete Columns	\$720,000
47	101/432W	KENNEDY CR	Olympic	Repair Concrete Columns	\$720,000
48	167/32E	VALLEY AVE & UPRR O'	Olympic	Replace Expansion Joint	\$100,000
49	290/4.7E-E	3RD AVE & E-E RAMP O	Eastern	Repair deteriorated Conc	\$200,000
50	395/40	PIONEER MEM. BR	South Central	Replace Exp Joint	\$156,675
51	5/570	LAKE WASH SHIP CANA	Northwest	Replace Exp Jnt	\$360,000
52	20/204	DECEPTION PASS	Northwest	Replace deteriorated steel truss braces	\$250,000
53	90/40N	EAST CHANNEL-LK WAS	Northwest	Install new seals in Modular Joints	\$75,000
54	167/40E	8TH ST E O'XING	Olympic	Repair Bridge Rail	\$25,000
55	195/24	S FK PALOUSE R CT HO	Eastern	Repair deteriorated Conc	\$100,000
56	410/31	WHITE R (STUCK R)	Olympic	Replace Exp Joints	\$108,000
57	500/6	I-205 OC	Southwest	Replace Exp Joints	\$111,000
58	12/12N	WISHKAH R CS1413	Olympic	Rehab deteriorated Conc	\$100,000
59	18/17S	GREEN R (NEELEY BRID	Northwest	Repair cracking in steel stringers	\$250,000
60	90/180	COLUMBIA R VANTAG	South Central	Repl poured rubber in deck jnts	\$168,000
61	20/207	CANOE PASS	Northwest	Replace deteriorated steel truss braces	\$200,000
62	90/545E-E	FOURTH-E RAMP	Eastern	Repair deteriorated conc in CBOX	\$200,000
63	107/4	CHEHALIS R	Olympic	Replace Timber Deck	\$1,600,000
64	409/10	JULIA BUTLER HANSEN	Southwest	Replace Timber Deck	\$1,500,000



## P2 Bridge Preservation - Bridge Repair

### 2011-13 Bien Priority Array

(Sorted by Priority Number)

11-13 #	Bridge Number	Bridge Name	Region	Repair Description	Bridge Item\$'s
65	529/15E	UNION SL	Northwest	Repair deteriorated concrete columns	\$3,000,000
66	529/15E	UNION SL	Northwest	Repair deteriorated concrete columns	\$3,000,000
67	530/124	N FK STILLAGUAMISH R	Northwest	Repair cracks in steel elements	\$200,000
68	12/512S	SNAKE RIVER AT BURBA	South Central	Repair cracks in Steel Stringers	\$400,000
69	99/507E	SR 599 OC	Northwest	Replace Exp Jnt	\$74,000
70	99/507S-S	PACIFIC HWY OC	Northwest	Replace Exp Jnt	\$95,000
71	99/507W	S 116TH PL OC	Northwest	Replace Exp Jnt	\$54,000
72	99/508	PACIFIC HWY OC	Northwest	Replace Exp Jnt	\$113,500
73	101/115N-W	N-W RAMP	Olympic	Replace Exp Jnt	\$40,000
74	4/230	COWLITZ R-P CRAWFOR	Southwest	Steel Truss Deck Joints	\$54,600
75	5/553	I-5 OC, DENNY WAY	Northwest	Replace Exp Jnt	\$42,000
76	6/118	CHEHALIS R ADNA	Southwest	Replace Exp Jnt	\$40,000
77	9/360	JOHNSON CR	Northwest	Add Sheet Pile Wall	\$100,000
78	12/306	INDIAN CR	Southwest	Replace Conc Bridge Rail	\$45,000
79	2/601	STEVENS CR UPPER X-I	Eastern	Replace Bridge Rail	\$25,000
80	12/713	NP RY OC	South Central	Replace Conc Bridge Rail	\$110,000
81	12/915	SNAKE R CLARKSTON	South Central	Bridge Rail	\$300,000
82	21/321	W FK SAN POIL	Eastern	Replace Conc Bridge Rail	\$50,000
83	21/323	SAN POIL R	Eastern	Replace Conc Bridge Rail	\$50,000
84	26/2SP	N FK PALOUSE-WEST W	Eastern	Replace Conc Bridge Rail	\$50,000
85	90/332	I-90 OC, TOKIO RD	Eastern	Replace Expansion Joint	\$80,000
86	195/27	N FK PALOUSE R	Eastern	Concrete Bridge Railing	\$96,000
87	5/40W	LEWIS R	Southwest	Steel Truss Repair	\$250,000
88	20/651	BONAPARTE CR	North Central	Replace Bridge Rail	\$250,000

Total Number of Bridges = 90

Totals \$ = \$36,294,530



## P2 Bridge Preservation - Bridge Repair

### 2011-13 Bien Priority Array

(Sorted by Bridge Number)

11-13 #	Bridge Number	Bridge Name	Region	Repair Description	Bridge Item\$'s
1	2/39	ANDERSON CR	Northwest	Replace East side Br Rail	\$200,000
79	2/601	STEVENS CR UPPER X-I	Eastern	Replace Bridge Rail	\$25,000
74	4/230	COWLITZ R-P CRAWFOR	Southwest	Steel Truss Deck Joints	\$54,600
87	5/40W	LEWIS R	Southwest	Steel Truss Repair	\$250,000
40	5/102E	SR 503 OC	Southwest	Replace Exp Jnt	\$27,900
41	5/102W	SR 503 OC	Southwest	Replace Exp Jnt	\$27,900
3	5/104W	DIKE ACCESS RD & RR	Southwest	Replace Steel Exp Joint	\$104,000
23	5/232W	SKOOKUMCHUCK R	Southwest	Repair damage Truss	\$716,705
29	5/342W-S	MCALLISTER CR	Olympic	Repair Concrete Columns	\$200,000
7	5/535E	NB VIADUCT STA 2032	Northwest	Replace Exp Jnt	\$50,000
8	5/536N-W	NB I5 to WB W SEA FRW	Northwest	Replace Exp Jnt	\$15,000
9	5/537E-S	E-S RAMP BR	Northwest	Replace Exp Jnt	\$120,000
10	5/537N	S-E RAMP WB LANES	Northwest	Replace Exp Jnt	\$42,000
11	5/537N-W	N-6TH RAMP BRIDGE	Northwest	Replace Exp Jnt	\$63,000
5	5/537S	EB LANES I-5 OC	Northwest	Repair Conc Box Girder	\$100,000
6	5/537S	EB LANES I-5 OC	Northwest	Replace Exp Jnt	\$40,000
12	5/538E	NB VIADUCT STA 2075	Northwest	Replace Exp Jnt	\$140,000
13	5/543E	KING-JACKSON ST OC	Northwest	Replace Exp Jnt	\$58,000
14	5/543NCD	NBCD KING JACKSON S	Northwest	Replace Exp Jnt	\$113,000
15	5/543SCD	SBCD KING JACKSON S	Northwest	Replace Exp Jnt	\$150,000
16	5/543W	KING-JACKSON ST OC	Northwest	Replace Exp Jnt	\$56,000
17	5/545NCD	NBCD VIADUCT STA 219	Northwest	Replace Exp Jnt	\$96,000
18	5/545SCD	SBCD VIADUCT STA 219	Northwest	Replace Exp Jnt	\$180,000
75	5/553	I-5 OC, DENNY WAY	Northwest	Replace Exp Jnt	\$42,000
19	5/562E	NB LANES VIADUCT	Northwest	Replace Exp Jnt	\$90,000
51	5/570	LAKE WASH SHIP CANA	Northwest	Replace Exp Jnt	\$360,000
24	5/647E	UNION SLOUGH	Northwest	Replace Exp Jnt	\$120,000
25	5/647W	UNION SLOUGH	Northwest	Replace Exp Jnt	\$120,000
26	5/648W	STEAMBOAT SLOUGH	Northwest	Replace Exp Jnt	\$144,000
27	5/650E	EBEY SL BN RY SR 529	Northwest	Replace Exp Jnt	\$900,000
28	5/650W	EBEY SL BN RY SR 529	Northwest	Replace Exp Jnt	\$470,000
76	6/118	CHEHALIS R ADNA	Southwest	Replace Exp Jnt	\$40,000
77	9/360	JOHNSON CR	Northwest	Add Sheet Pile Wall	\$100,000



## P2 Bridge Preservation - Bridge Repair

### 2011-13 Bien Priority Array

(Sorted by Bridge Number)

11-13 #	Bridge Number	Bridge Name	Region	Repair Description	Bridge Item\$'s
58	12/12N	WISHKAH R CS1413	Olympic	Rehab deteriorated Conc	\$100,000
78	12/306	INDIAN CR	Southwest	Replace Conc Bridge Rail	\$45,000
68	12/512S	SNAKE RIVER AT BURBA	South Central	Repair cracks in Steel Stringers	\$400,000
80	12/713	NP RY OC	South Central	Replace Conc Bridge Rail	\$110,000
81	12/915	SNAKE R CLARKSTON	South Central	Bridge Rail	\$300,000
1	16/110E	TACOMA NARROWS	Olympic	Replace Finger Exp Jnt at Tower #4	\$300,000
2	16/110E	TACOMA NARROWS	Olympic	Replace Maintenance Traveler	\$3,000,000
30	18/9	NP RY OC	Northwest	Replace Exp Jnts @ 6 locations	\$250,000
31	18/9	NP RY OC	Northwest	Paint Steel Hanger and Pin asse	\$309,750
59	18/17S	GREEN R (NEELEY BRID	Northwest	Repair cracking in steel stringers	\$250,000
52	20/204	DECEPTION PASS	Northwest	Replace deteriorated steel truss braces	\$250,000
61	20/207	CANOE PASS	Northwest	Replace deteriorated steel truss braces	\$200,000
88	20/651	BONAPARTE CR	North Central	Replace Bridge Rail	\$250,000
82	21/321	W FK SAN POIL	Eastern	Replace Conc Bridge Rail	\$50,000
83	21/323	SAN POIL R	Eastern	Replace Conc Bridge Rail	\$50,000
84	26/2SP	N FK PALOUSE-WEST W	Eastern	Replace Conc Bridge Rail	\$50,000
32	90/10W-S	I-5 OC, W-S RAMP	Northwest	Replace Exp Joints	\$164,000
21	90/25N	HOMER M. HADLEY	Northwest	Replace 10 Anchor Cables	\$2,430,000
44	90/25N	HOMER M. HADLEY	Northwest	Replace 10 Anchor Cables	\$2,430,000
22	90/25S	LACEY V. MURROW BR	Northwest	Replace 10 Anchor Cables	\$2,430,000
53	90/40N	EAST CHANNEL-LK WAS	Northwest	Install new seals in Modular Joints	\$75,000
60	90/180	COLUMBIA R VANTAG	South Central	Repl poured rubber in deck jnts	\$168,000
85	90/332	I-90 OC, TOKIO RD	Eastern	Replace Expansion Joint	\$80,000
33	90/540N	HANGMAN CR	Eastern	Repair deteriorated conc in CBOX	\$150,000
34	90/540S	HANGMAN CR	Eastern	Repair deteriorated conc in CBOX	\$100,000
62	90/545E-E	FOURTH-E RAMP	Eastern	Repair deteriorated conc in CBOX	\$200,000
69	99/507E	SR 599 OC	Northwest	Replace Exp Jnt	\$74,000
70	99/507S-S	PACIFIC HWY OC	Northwest	Replace Exp Jnt	\$95,000
71	99/507W	S 116TH PL OC	Northwest	Replace Exp Jnt	\$54,000
72	99/508	PACIFIC HWY OC	Northwest	Replace Exp Jnt	\$113,500
73	101/115N-W	N-W RAMP	Olympic	Replace Exp Jnt	\$40,000
45	101/269	FULTON CR	Olympic	Repair Concrete Columns	\$320,000
46	101/432E	KENNEDY CR	Olympic	Repair Concrete Columns	\$720,000



## P2 Bridge Preservation - Bridge Repair

### 2011-13 Bien Priority Array

(Sorted by Bridge Number)

11-13 #	Bridge Number	Bridge Name	Region	Repair Description	Bridge Item\$'s
47	101/432W	KENNEDY CR	Olympic	Repair Concrete Columns	\$720,000
20	104/5.1	HOOD CANAL-W.A. BUG	Olympic	Replace 18 anchor cables	\$3,000,000
63	107/4	CHEHALIS R	Olympic	Replace Timber Deck	\$1,600,000
42	153/16	METHOW R	North Central	Concrete Bridge Rail	\$190,000
43	153/17	METHOW R	North Central	Concrete Bridge Rail	\$125,000
48	167/32E	VALLEY AVE & UPRR O'	Olympic	Replace Expansion Joint	\$100,000
1	167/38	24TH ST E OVER SR 167	Olympic	Replace damaged PCG	\$500,000
54	167/40E	8TH ST E O'XING	Olympic	Repair Bridge Rail	\$25,000
55	195/24	S FK PALOUSE R CT HO	Eastern	Repair deteriorated Conc	\$100,000
86	195/27	N FK PALOUSE R	Eastern	Concrete Bridge Railing	\$96,000
49	290/4.7E-E	3RD AVE & E-E RAMP O	Eastern	Repair deteriorated Conc	\$200,000
4	395/40	PIONEER MEM. BR	South Central	Replace Exp Joint	\$470,000
50	395/40	PIONEER MEM. BR	South Central	Replace Exp Joint	\$156,675
35	405/70E	SR 522 OC SAMMAMISH	Northwest	Replace Exp Joints	\$100,000
36	405/70N-E	N-E RAMP SAMMAMISH	Northwest	Replace Exp Joints	\$34,500
37	405/70N-W	N-W RAMP SAMMAMISH	Northwest	Replace Exp Joints	\$60,000
38	405/70S-E	S-E RAMP BR	Northwest	Replace Exp Joints	\$25,000
39	405/70W	SR 522 OC SAMMAMISH	Northwest	Replace Exp Joints	\$100,000
64	409/10	JULIA BUTLER HANSEN	Southwest	Replace Timber Deck	\$1,500,000
56	410/31	WHITE R (STUCK R)	Olympic	Replace Exp Joints	\$108,000
57	500/6	I-205 OC	Southwest	Replace Exp Joints	\$111,000
65	529/15E	UNION SL	Northwest	Repair deteriorated concrete columns	\$3,000,000
66	529/15E	UNION SL	Northwest	Repair deteriorated concrete columns	\$3,000,000
67	530/124	N FK STILLAGUAMISH R	Northwest	Repair cracks in steel elements	\$200,000
Total Number of Bridges = 90				Totals \$ =	\$36,294,530



# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 2 / 39	Structure ID 0001706C	Bridge Name: ANDERSON CR	Milepost: 34.25	Region: Northwest
Year Built / YR Widened: 1933	Bridge Type: CTB	Bridge Length: 93 ft	Bridge Width (curb-curb): 25.0 ft	Sufficiency Rating: 59.57 FO
Average Daily Traffic: 6,364	Truck%	Freight Route	Num of Lanes: 2	
Date Inspected:	Structr Adequacy:	Superstr Code:	Safe Load:	Scour:
BMS Element Num: <b>331</b>	BMS Element Descr: <b>Concrete Bridge Rail</b>			
BMS Element Quantity: <b>93</b>				
Project Number:	2011-13 Priority#:	<b>1</b>		
Repair Year: <b>2011</b>	2009-11 Priority#:			
CPMS Ad Date:	Bridge \$'s:	<b>\$300,000</b>		
	Repair Total\$'s:	<b>\$600,000</b>		



**Repair Description:**

Replace damaged concrete balluster rail

**COMMENTS**

The concrete bridge rail was damaged in Dec 2009 by a Truck impact. NW Region Bridge Maintenance Crews removed the damaged rail and added a temporary thrie beam on H-Beam posts.

The costs and details for the concrete bridge rail replacement should be similar to those used on Us 2 Deep Creek bridge (contract 7568) in 2008.

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 2 / 601	Structure ID 0003168A	Bridge Name: STEVENS CR UPPER X-ING	Milepost: 267.23	Region: Eastern
Year Built / YR Widened: 1946	Bridge Type: CS	Bridge Length: 23 ft	Bridge Width (curb-curb): 36.0 ft	Sufficiency Rating: 91.06
Average Daily Traffic: 6,105	Truck% 10%	Freight Route	Num of Lanes: 2	
Date Inspected: 8/9/2006	Structr Adequacy: 6	Superstr Code: 6	Safe Load: 5	
Substr Code: 6	Scour: 8	BMS Element Num: 331		
BMS Element Descr: Concrete Bridge Rail		BMS Element Quantity: 46		
Project Number:	2011-13 Priority#: 79	Repair Year:	2009-11 Priority#: 91	
CPMS Ad Date:	Bridge \$'s: \$25,000	Repair Total\$'s: \$50,000		
<b>Repair Description:</b> Replace deteriorated concrete balluster rail				
<b>COMMENTS</b>				
<p>The concrete bridge rails are deteriorated with exposed reinforcing steel. The bridge rails need to be replaced with a new Thrie Beam and steel H-Posts.</p> <p>The costs and details for the concrete bridge rail replacement should be similar to those used on SR 153 bridges (contract 7229) in 2007.</p>				

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 4 / 230		Structure ID 0003717A		Bridge Name: COWLITZ R-P CRAWFORD BR		Milepost: 61.08		Region: Southwest	
Year Built / YR Widened: 1951		Bridge Type: STrus CTB		Bridge Length: 1,710 ft		Bridge Width (curb-curb): 56.0 ft		Sufficiency Rating: 40.98	
Average Daily Traffic: 28,026		Truck% 4%		Freight Route		Num of Lanes: 4			
Date Inspected: 9/11/2006		Structr Adequacy: 5		Superstr Code: 6		Safe Load: 5			
Substr Code: 5		Scour: 5		BMS Element Num: 402		BMS Element Descr: <b>Poured Joint Filler</b>			
BMS Element Quantity: 728		Project Number:		2011-13 Priority#: 74		Repair Year:			
CPMS Ad Date:		Bridge \$'s: \$54,600		Repair Total\$'s: \$109,200					
									
<b>Repair Description:</b> Replace joint material in panel joints in Steel Truss span.									
<b>COMMENTS</b>									
Bridge item\$ based on \$75 / ft , Total Project\$ based on \$150 / ft.									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 5 / 40W		Structure ID 0002559A		Bridge Name: LEWIS R		Milepost: 19.83		Region: Southwest	
Year Built / YR Widened: 1940		Bridge Type: STrus CTB		Bridge Length: 1,310 ft		Bridge Width (curb-curb): 48.0 ft		Sufficiency Rating: 46.09FO	
Average Daily Traffic: 33,747		Truck% 21%		Freight Route		Num of Lanes: 3			
Date Inspected: 9/21/2009		Structr Adequacy: 3		Superstr Code: 5		Safe Load: 5			
Substr Code: 7		Scour: 5		BMS Element Num:		BMS Element Descr: <b>Steel Truss</b>			
BMS Element Quantity: 0		Project Number:		2011-13 Priority#: 87		2009-11 Priority#:			
Repair Year: 2020		CPMS Ad Date:		Bridge \$'s: \$250,000		Repair Total\$'s: \$500,000			
		<p><b>Repair Description:</b> Repair sways damaged from overheight truck</p>							
<p><b>COMMENTS</b></p>									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 5 / 102E		Structure ID 0007064A		Bridge Name: SR 503 OC		Milepost: 21.08		Region: Southwest			
Year Built / YR Widened: 1963		Bridge Type: PCB		Bridge Length: 168 ft		Bridge Width (curb-curb): 45.0 ft		Sufficiency Rating: 75.54 FO			
Average Daily Traffic: 23,154		Truck% 21%		Freight Route T1		Num of Lanes: 3					
Date Inspected: 10/27/2005		Structr Adequacy: 7		Superstr Code: 7		Safe Load: 5					
Substr Code: 7		Scour: N									
BMS Element Num: 415		BMS Element Descr: <b>Exp Jnt - Rubber Bolt Down</b>									
BMS Element Quantity: 186 Feet											
Project Number:		2011-13 Priority#:		40							
Repair Year: 2016		2009-11 Priority#:		44							
CPMS Ad Date:		Bridge \$'s:		\$93,000							
		Repair Total\$'s:		\$279,000							
											
<b>Repair Description:</b> Replace the rubber bolt down expansion joints.											
<b>COMMENTS</b>											
The rubber bolt down expansion joints were added to this bridge in 1983. These expansion joints are deteriorated and need to be replaced.											
Bridge Item cost based on \$500 / ft. Total project cost based on \$1,500 / ft.											

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 5 / 102W		Structure ID 0007064B		Bridge Name: SR 503 OC		Milepost: 21.08		Region: Southwest			
Year Built / YR Widened: 1963		Bridge Type: PCB		Bridge Length: 168 ft		Bridge Width (curb-curb): 45.0 ft		Sufficiency Rating: 75.54 FO			
Average Daily Traffic: 23,154		Truck% 21%		Freight Route T1		Num of Lanes: 3					
Date Inspected: 10/27/2005		Structr Adequacy: 7		Superstr Code: 7		Safe Load: 5					
Substr Code: 7		Scour: N									
BMS Element Num: 415		BMS Element Descr: <b>Exp Jnt - Rubber Bolt Down</b>									
BMS Element Quantity: 186 Feet											
Project Number:		2011-13 Priority#:		41							
Repair Year: 2016		2009-11 Priority#:		45							
CPMS Ad Date:		Bridge \$'s:		\$93,000							
		Repair Total\$'s:		\$279,000							
											
<b>Repair Description:</b>											
Replace the rubber bolt down expansion joints.											
<b>COMMENTS</b>											
The rubber bolt down expansion joints were added to this bridge in 1983. These expansion joints are deteriorated and need to be replaced.											
Bridge Item cost based on \$500 / ft. Total project cost based on \$1,500 / ft.											

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 5 / 104W		Structure ID 0008952A		Bridge Name: DIKE ACCESS RD & RR OC		Milepost: 22.72		Region: Southwest	
Year Built / YR Widened: 1972		Bridge Type: SG		Bridge Length: 675 ft		Bridge Width (curb-curb): 52.0 ft		Sufficiency Rating: 91.27	
Average Daily Traffic: 27,077		Truck% 24%		Freight Route T1		Num of Lanes: 3			
Date Inspected: 3/20/2005		Structr Adequacy: 6		Superstr Code: 6		Safe Load: 5			
Substr Code: 7		Scour: N		BMS Element Num: 414		BMS Element Descr: Steel Plate Exp Jnt with Bolts			
BMS Element Quantity: 104		Project Number:		2011-13 Priority#: 3		2009-11 Priority#: 6			
Repair Year: 2012		CPMS Ad Date:		Bridge \$'s: \$208,000		Repair Total\$'s: \$520,000		 	
<b>Repair Description:</b> Replace steel plate expansion joints at both ends of the bridge.									
<b>COMMENTS</b>									
The sliding steel plate joints are held in place with springs and bolts. The south abutment joint has its anchorage straps sheared off in the right lane and has been temporarily repaired. The north abutment joint headers have been patched with UREfast.									
Bridge Item cost based on \$2,000 / ft. Total project cost based on \$5,000 / ft.									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 5 / 232W		Structure ID 0011757B		Bridge Name: SKOOKUMCHUCK R		Milepost: 82.28		Region: Southwest	
Year Built / YR Widened: 1951		Bridge Type: STrus CTB		Bridge Length: 252 ft		Bridge Width (curb-curb): 31.0 ft		Sufficiency Rating: 62.20	
Average Daily Traffic: 34,200		Truck%: 20%		Freight Route:		Num of Lanes: 2			
Date Inspected: 6/28/2008		Structr Adequacy: 5		Superstr Code: 5		Safe Load: 5			
Substr Code: 6		Scour: 3		BMS Element Num:		BMS Element Descr:			
BMS Element Quantity: 0		Project Number:		2011-13 Priority#: 23		2009-11 Priority#:			
Repair Year: 2014		CPMS Ad Date:		Bridge \$'s: \$540,000		Repair Total\$'s: \$1,000,000			
									
<b>Repair Description:</b> Repair the damaged steel truss									
<b>COMMENTS</b>									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 5 / 342W-S		Structure ID 0008100H		Bridge Name: MCALLISTER CR		Milepost: 114.09		Region: Olympic	
Year Built / YR Widened: 1968		Bridge Type: CS		Bridge Length: 168 ft		Bridge Width (curb-curb): 23.0 ft		Sufficiency Rating: 84.57	
Average Daily Traffic: 830		Truck% 2%		Freight Route T1		Num of Lanes: 1			
Date Inspected: 7/27/2006		Structr Adequacy: 5		Superstr Code: 7		Safe Load: 5			
Substr Code: 5		Scour: 8		BMS Element Num: 227		BMS Element Descr: Concrete Submerged Pile/Column			
BMS Element Quantity: 8		Project Number:		2011-13 Priority#: 29		2009-11 Priority#: 32			
Repair Year: 2016		CPMS Ad Date:		Bridge \$'s: \$200,000		Repair Total\$'s: \$350,000		 	
<b>Repair Description:</b>		Repair salt water deteriorated columns @ piers 2 & 4.		<b>COMMENTS</b>		The columns are showing signs of corrosion in the reinforcing steel. Repair with fiberglass jackets.			

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 5 / 535E		Structure ID 0007816A		Bridge Name: NB VIADUCT STA 2032		Milepost: 162.19		Region: Northwest	
Year Built / YR Widened: 1966 / 1992		Bridge Type: PCB		Bridge Length: 901 ft		Bridge Width (curb-curb): 76.0 ft		Sufficiency Rating: 87.81	
Average Daily Traffic: 98,250		Truck% 7%		Freight Route T1		Num of Lanes: 5			
Date Inspected: 11/6/2006		Structr Adequacy: 7		Superstr Code: 7		Safe Load: 5			
Substr Code: 7		Scour: N							
BMS Element Num: 408		BMS Element Descr: Exp Jnt - Steel Sliding Plate				BMS Element Quantity: 304 Feet			
Project Number:		2011-13 Priority#:		7					
Repair Year: 2012		2009-11 Priority#:		14					
CPMS Ad Date:		Bridge \$'s:		\$456,000					
		Repair Total\$'s:		\$760,000					
									
<b>Repair Description:</b> Replace the Steel Sliding Plate expansion joints.									
<b>COMMENTS</b>									
Sections of the existing steel sliding plate expansion joints have failed and have been replaced with a poured rubber joint. These expansion joints need to be replaced.									
There are four (4) expansion joint locations (Piers 1, 4, 7, 10)									
Bridge Item cost based on \$1,500 / ft. Total project cost based on \$2,500 / ft.									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 5 / 536N-W		Structure ID 0007741G		Bridge Name: N-W RAMP I-5 OC		Milepost: 162.98		Region: Northwest	
Year Built / YR Widened: 1967		Bridge Type: CBOX		Bridge Length: 1,722 ft		Bridge Width (curb-curb): 21.0 ft		Sufficiency Rating: 78.89	
Average Daily Traffic: 3,086		Truck% 5%		Freight Route T1		Num of Lanes: 1			
Date Inspected: 10/26/2006		Structr Adequacy: 6		Superstr Code: 6		Safe Load: 5			
Substr Code: 7		Scour: N							
BMS Element Num: 408		BMS Element Descr: Exp Jnt - Steel Sliding Plate				BMS Element Quantity: 150 Feet			
Project Number:		2011-13 Priority#: 8		Repair Year: 2012		2009-11 Priority#: 15			
CPMS Ad Date:		Bridge \$'s: \$150,000		Repair Total\$'s: \$375,000					
									
<b>Repair Description:</b> Replace the Steel Sliding Plate expansion joints.									
<b>COMMENTS</b>									
Sections of the existing steel sliding plate expansion joints have failed and have been replaced with a poured rubber joint. These expansion joints need to be replaced.									
The steel sliding plate has been removed from the expansion joints in spans 2, 13, and 17 creating an open joint.									
Bridge Item cost based on \$1,000 / ft. Total project cost based on \$2,500 / ft.									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 5 / 537E-S		Structure ID 0007741N		Bridge Name: E-S RAMP BR		Milepost: 162.99		Region: Northwest	
Year Built / YR Widened: 1967		Bridge Type: CBox		Bridge Length: 1,206 ft		Bridge Width (curb-curb): 21.0 ft		Sufficiency Rating: 96.86	
Average Daily Traffic: 7,505		Truck% 5%		Freight Route T1		Num of Lanes: 1			
Date Inspected: 8/23/2006		Structr Adequacy: 6		Superstr Code: 6		Safe Load: 5		Substr Code: 7	
BMS Element Num: 408		BMS Element Descr: Exp Jnt - Steel Sliding Plate							
BMS Element Quantity: 120									
Project Number:		2011-13 Priority#:		9					
Repair Year: 2012		2009-11 Priority#:		16					
CPMS Ad Date:		Bridge \$'s:		\$120,000					
		Repair Total\$'s:		\$300,000					

No Photo Available

**Repair Description:**

Replace steel plate expansion joints

**COMMENTS**

Sections of the existing steel sliding plate expansion joints have failed and need to be replaced.  
 Bridge Item cost based on \$1,000 / ft. Total project cost based on \$2,500 / ft.

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 5 / 537N	Structure ID 0007741R	Bridge Name: S-E RAMP WB LANES	Milepost: 163.00	Region: Northwest
Year Built / YR Widened: 1967	Bridge Type: CBOX	Bridge Length: 2,885 ft	Bridge Width (curb-curb): 28.0 ft	Sufficiency Rating: 27.54 SD
Average Daily Traffic: 79,346	Truck% 7%	Freight Route T1	Num of Lanes: 2	
Date Inspected: 5/9/2006	Structr Adequacy: 4	Superstr Code: 5	Safe Load: 5	
Substr Code: 7	Scour: N			
BMS Element Num: 408	BMS Element Descr: Exp Jnt - Steel Sliding Plate			
BMS Element Quantity: 369 feet				
Project Number: 100562S	2011-13 Priority#: 10			
Repair Year: 2012	2009-11 Priority#: 17			
CPMS Ad Date:	Bridge \$'s: \$553,500			
	Repair Total\$'s: \$922,500			
				
<b>Repair Description:</b> Replace the existing steel sliding plate expansion joints.				
<b>COMMENTS</b>				
The original steel sliding plate expansion joints are breaking up and in need of replacement. There are ten (10) expansion joint locations (Pier 1, span 5, span 8, span 11, span 15, span 18, span 22, span 26, span 30, span 34)				
Bridge Item cost based on \$1,500 / ft. Total project cost based on \$2,500 / ft.				

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 5 / 537N-W		Structure ID 0007741H		Bridge Name: N-6TH RAMP BRIDGE		Milepost: 162.98		Region: Northwest	
Year Built / YR Widened: 1967		Bridge Type: CBox		Bridge Length: 720 ft		Bridge Width (curb-curb): 21.0 ft		Sufficiency Rating: 96.65	
Average Daily Traffic: 8,243		Truck% 30%		Freight Route T1		Num of Lanes: 1			
Date Inspected: 5/9/2006		Structr Adequacy: 6		Superstr Code: 6		Safe Load: 5		Substr Code: 7	
Scour: N									
BMS Element Num: 408		BMS Element Descr: <b>Exp Jnt - Steel Sliding Plate</b>							
BMS Element Quantity: 63									
Project Number:		2011-13 Priority#: 11							
Repair Year: 2012		2009-11 Priority#: 18							
CPMS Ad Date:		Bridge \$'s: \$63,000							
		Repair Total\$'s: \$157,500							






**Repair Description:**  
Replace the existing steel sliding plate expansion joints.

**COMMENTS**

The original steel sliding plate expansion joints are breaking up and in need of replacement.

Bridge Item cost based on \$1,000 / ft. Total project cost based on \$2,500 / ft.

Bridge Number: 5 / 537S	Structure ID 0007741T	Bridge Name: EB LANES I-5 OC	Milepost: 163.00	Region: Northwest
Year Built / YR Widened: 1966	Bridge Type: CBOX	Bridge Length: 1,793 ft	Bridge Width (curb-curb): 28.0 ft	Sufficiency Rating: 32.00SD
Average Daily Traffic: 30,000	Truck% 30%	Freight Route T1	Num of Lanes: 2	
Date Inspected: 11/6/2006	Structr Adequacy: 4	Superstr Code: 4	Safe Load: 5	
Substr Code: 7	Scour: N			
BMS Element Num: 105	BMS Element Descr: <b>Concrete Box Girder</b>			
BMS Element Quantity: 600 feet				
Project Number: 100562S	2011-13 Priority#: 5			
Repair Year: 2012	2009-11 Priority#: 12			
CPMS Ad Date:	Bridge \$'s:			
	Repair Total\$'s:	\$500,000		



**Repair Description:**

Repair delaminated concrete areas on the bottom side of the bottom slab.

**COMMENTS**

The expansion joints allow water and contaminants to flow onto the bottom slab of the Concrete Box superstructure which has caused delaminations in the concrete from the reinforcing steel.

The 10/5/2002 Bridge Inspection recorded the BMS states for Element 105 Concrete Box Girder to be: Condition State 2 = 700LF, Condition State 3 = 500LF, Condition State 4 = 100LF.

Total cost estimated @ \$500,000 until a thorough review can be done.

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 5 / 537S	Structure ID 0007741T	Bridge Name: EB LANES I-5 OC	Milepost: 163.00	Region: Northwest
Year Built / YR Widened: 1966	Bridge Type: CBOX	Bridge Length: 1,793 ft	Bridge Width (curb-curb): 28.0 ft	Sufficiency Rating: 32.00SD
Average Daily Traffic: 30,000	Truck% 30%	Freight Route T1	Num of Lanes: 2	
Date Inspected: 11/6/2006	Structr Adequacy: 4	Superstr Code: 4	Safe Load: 5	
Substr Code: 7	Scour: N			
BMS Element Num: 408	BMS Element Descr: Exp Jnt - Steel Sliding Plate			
BMS Element Quantity: 300 Feet				
Project Number: 100562S	2011-13 Priority#: 6			
Repair Year: 2012	2009-11 Priority#: 13			
CPMS Ad Date:	Bridge \$'s: \$450,000			
	Repair Total\$'s: \$750,000			
				
<b>Repair Description:</b> Replace the steel sliding plate expansion joints.				
<b>COMMENTS</b>				
The original steel sliding plate expansion joints are breaking up and allowing water and contaminants to flow onto the bottom slab of the Concrete Box superstructure. This has caused delaminations in the concrete from the reinforcing steel.				
There are seven (7) expansion joint locations (East Abutment, Span 4, Span 7, Span 11, Span 14, Span 17, Span 21).				
Bridge Item cost based on \$1,500 / ft. Total project cost based on \$2,500 / ft.				

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 5 / 538E		Structure ID 0007741C		Bridge Name: NB VIADUCT STA 2075		Milepost: 162.98		Region: Northwest			
Year Built / YR Widened: 1966 / 1992		Bridge Type: CS		Bridge Length: 872 ft		Bridge Width (curb-curb): 57.7 ft		Sufficiency Rating: 77.49			
Average Daily Traffic: 79,346		Truck% 7%		Freight Route T1		Num of Lanes: 4					
Date Inspected: 11/7/2006		Structr Adequacy: 5		Superstr Code: 6		Safe Load: 5					
Substr Code: 7		Scour: N									
BMS Element Num: 408		BMS Element Descr: <b>Exp Jnt - Steel Sliding Plate</b>									
BMS Element Quantity: 140 Feet											
Project Number:		2011-13 Priority#: 12		Repair Year: 2012		2009-11 Priority#: 19					
CPMS Ad Date:		Bridge \$'s: \$140,000		Repair Total\$'s: \$350,000							
<h2>No Photo Available</h2>					<h2>No Photo Available</h2>						
<b>Repair Description:</b> Replace the steel sliding plate expansion joints at 4 locations.											
<b>COMMENTS</b>											
Sections of the existing steel sliding plate expansion joints are loose. These expansion joints need to be replaced.  Bridge Item cost based on \$1,000 / ft. Total project cost based on \$2,500 / ft.											

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 5 / 543E		Structure ID 0007504A		Bridge Name: KING-JACKSON ST OC		Milepost: 164.41		Region: Northwest	
Year Built / YR Widened: 1965 / 1992		Bridge Type: CBox		Bridge Length: 706 ft		Bridge Width (curb-curb): 58.8 ft		Sufficiency Rating: 67.31	
Average Daily Traffic: 79,500		Truck% 5%		Freight Route T1		Num of Lanes: 4			
Date Inspected: 8/24/2006		Structr Adequacy: 5		Superstr Code: 6		Safe Load: 4			
Substr Code: 7		Scour: N							
BMS Element Num: 408		BMS Element Descr: Exp Jnt - Steel Sliding Plate				BMS Element Quantity: 58			
Project Number:		2011-13 Priority#: 13		Repair Year: 2012		2009-11 Priority#: 20			
CPMS Ad Date:		Bridge \$'s: \$58,000		Repair Total\$'s: \$145,000					
					<p style="text-align: center; font-size: 2em; font-weight: bold; transform: rotate(-5deg);">No Photo Available</p>				
<p><b>Repair Description:</b> Replace the steel sliding plate expansion joints at 1 locations.</p>									
<b>COMMENTS</b>									
<p>Sections of the existing steel sliding plate expansion joints are loose. These expansion joints need to be replaced.</p> <p>Bridge Item cost based on \$1,000 / ft. Total project cost based on \$2,500 / ft.</p>									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 5 / 543NCD		Structure ID 0007504C		Bridge Name: NBCD KING JACKSON ST OC		Milepost: 164.41		Region: Northwest	
Year Built / YR Widened: 1965		Bridge Type: CBox		Bridge Length: 709 ft		Bridge Width (curb-curb): 48.0 ft		Sufficiency Rating: 56.17 FO	
Average Daily Traffic: 61,357		Truck% 10%		Freight Route T1		Num of Lanes: 4			
Date Inspected: 8/24/2006		Structr Adequacy: 5		Superstr Code: 7		Safe Load: 5			
Substr Code: 7		Scour: N		BMS Element Num: 408		BMS Element Descr: Exp Jnt - Steel Sliding Plate			
BMS Element Quantity: 113		Project Number:		2011-13 Priority#: 14		2009-11 Priority#: 21			
Repair Year: 2012		CPMS Ad Date:		Bridge \$'s: \$113,000		Repair Total\$'s: \$282,500			
									
<p><b>Repair Description:</b> Replace the steel sliding plate expansion joints.</p>									
<p><b>COMMENTS</b></p>									
<p>Sections of the existing steel sliding plate expansion joints are loose. These expansion joints need to be replaced.</p> <p>Bridge Item cost based on \$1,000 / ft. Total project cost based on \$2,500 / ft.</p>									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 5 / 543SCD		Structure ID 0007504D		Bridge Name: SBCD KING JACKSON ST OC		Milepost: 164.41		Region: Northwest			
Year Built / YR Widened: 1965		Bridge Type: CBox		Bridge Length: 709 ft		Bridge Width (curb-curb): 60.0 ft		Sufficiency Rating: 64.81			
Average Daily Traffic: 73,582		Truck% 55%		Freight Route T1		Num of Lanes: 4					
Date Inspected: 8/24/2006		Structr Adequacy: 5		Superstr Code: 6		Safe Load: 5					
Substr Code: 7		Scour: N									
BMS Element Num: 408		BMS Element Descr: Exp Jnt - Steel Sliding Plate									
BMS Element Quantity: 150											
Project Number:		2011-13 Priority#: 15		Repair Year: 2012		2009-11 Priority#: 22					
CPMS Ad Date:		Bridge \$'s: \$150,000		Repair Total\$'s: \$375,000							
											
<b>Repair Description:</b> Replace the steel sliding plate expansion joints.											
<b>COMMENTS</b>											
Sections of the existing steel sliding plate expansion joints are loose. These expansion joints need to be replaced.  Bridge Item cost based on \$1,000 / ft. Total project cost based on \$2,500 / ft.											

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 5 / 543W		Structure ID 0007504B		Bridge Name: KING-JACKSON ST OC		Milepost: 164.41		Region: Northwest			
Year Built / YR Widened: 1965 / 1992		Bridge Type: CBox		Bridge Length: 712 ft		Bridge Width (curb-curb): 55.8 ft		Sufficiency Rating: 92.55			
Average Daily Traffic: 79,500		Truck% 5%		Freight Route T1		Num of Lanes: 3					
Date Inspected: 8/24/2006		Structr Adequacy: 6		Superstr Code: 6		Safe Load: 5					
Substr Code: 7		Scour: N									
BMS Element Num: 408		BMS Element Descr: Exp Jnt - Steel Sliding Plate									
BMS Element Quantity: 56											
Project Number:		2011-13 Priority#: 16		Repair Year: 2012		2009-11 Priority#: 23					
CPMS Ad Date:		Bridge \$'s: \$56,000		Repair Total\$'s: \$140,000							
											
<p><b>Repair Description:</b> Replace the steel sliding plate expansion joints.</p>											
<b>COMMENTS</b>											
<p>Sections of the existing steel sliding plate expansion joints are loose. These expansion joints need to be replaced.</p> <p>Bridge Item cost based on \$1,000 / ft. Total project cost based on \$2,500 / ft.</p>											


# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 5 / 545NCD		Structure ID 0007110F		Bridge Name: NBCD VIADUCT STA 2195		Milepost: 165.69		Region: Northwest	
Year Built / YR Widened: 1964		Bridge Type: CBox		Bridge Length: 702 ft		Bridge Width (curb-curb): 32.0 ft		Sufficiency Rating: 79.42	
Average Daily Traffic: 29,230		Truck% 5%		Freight Route T1		Num of Lanes: 2			
Date Inspected: 10/23/2005		Structr Adequacy: 5		Superstr Code: 6		Safe Load: 5			
Substr Code: 7		Scour: N		BMS Element Num: 408		BMS Element Descr: Exp Jnt - Steel Sliding Plate			
BMS Element Quantity: 96		Project Number: 2011-13 Priority#: 17		Repair Year: 2012		2009-11 Priority#: 24			
CPMS Ad Date:		Bridge \$'s: \$96,000		Repair Total\$'s: \$240,000					
									
<b>Repair Description:</b> Replace the steel sliding plate expansion joints.									
<b>COMMENTS</b>									
Sections of the existing steel sliding plate expansion joints are loose. These expansion joints need to be replaced.  Bridge Item cost based on \$1,000 / ft. Total project cost based on \$2,500 / ft.									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 5 / 545SCD	Structure ID 0007110G	Bridge Name: SBCD VIADUCT STA 2195	Milepost: 165.71	Region: Northwest
Year Built / YR Widened: 1964 / 1991	Bridge Type: CB <sub>ox</sub>	Bridge Length: 806 ft	Bridge Width (curb-curb): 44.9 ft	Sufficiency Rating: 67.67 FO
Average Daily Traffic: 73,582	Truck% 5%	Freight Route T1	Num of Lanes: 3	
Date Inspected: 10/11/2005	Structr Adequacy: 6	Superstr Code: 6	Safe Load: 5	
Substr Code: 7	Scour: N			
BMS Element Num: 406	BMS Element Descr: Comp Seal w/ Steel Header			
BMS Element Quantity: 180				
Project Number:	2011-13 Priority#:	18		
Repair Year: 2012	2009-11 Priority#:	25		
CPMS Ad Date:	Bridge \$'s:	\$180,000		
	Repair Total\$'s:	\$450,000		
				
<b>Repair Description:</b> Replace expansion joints at 4 locations.				
<b>COMMENTS</b>				
Sections of the existing steel sliding plate expansion joints have been repaired by Region Maintenance crews. These expansion joints need to be replaced.				
Bridge Item cost based on \$1,000 / ft. Total project cost based on \$2,500 / ft.				

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 5 / 553		Structure ID 0006635B		Bridge Name: I-5 OC, DENNY WAY		Milepost: 166.06		Region: Northwest	
Year Built / YR Widened: 1962		Bridge Type: CBox		Bridge Length: 321 ft		Bridge Width (curb-curb): 42.0 ft		Sufficiency Rating: 69.37 FO	
Average Daily Traffic: 24,000		Truck% 5%		Freight Route		Num of Lanes: 4			
Date Inspected: 10/12/2005		Structr Adequacy: 7		Superstr Code: 7		Safe Load: 5			
Substr Code: 7		Scour: N		BMS Element Num: 415		BMS Element Descr: Rubber bolt down exp jnt			
BMS Element Quantity: 42		Project Number:		2011-13 Priority#: 75		Repair Year:			
CPMS Ad Date:		2009-11 Priority#: 86		Bridge \$'s: \$42,000		Repair Total\$'s: \$84,000			
									
<b>Repair Description:</b> Replace the expansion joint on the east end of the bridge									
<b>COMMENTS</b>									
Sections of the existing expansion joint are broken. This expansion joint needs to be replaced.  Bridge Item cost based on \$1,000 / ft. Total project cost based on \$2,500 / ft.									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 5 / 562E		Structure ID 0006800B		Bridge Name: NB LANES VIADUCT		Milepost: 166.98		Region: Northwest			
Year Built / YR Widened: 1963		Bridge Type: CTB		Bridge Length: 381 ft		Bridge Width (curb-curb): 66.0 ft		Sufficiency Rating: 83.22			
Average Daily Traffic: 108,000		Truck% 5%		Freight Route T1		Num of Lanes: 4					
Date Inspected: 12/7/2005		Structr Adequacy: 6		Superstr Code: 7		Safe Load: 5					
Substr Code: 6		Scour: N									
BMS Element Num: 408		BMS Element Descr: <b>Exp Jnt - Steel Sliding Plate</b>									
BMS Element Quantity: 90											
Project Number:		2011-13 Priority#:		19							
Repair Year: 2012		2009-11 Priority#:		26							
CPMS Ad Date:		Bridge \$'s:		\$90,000							
		Repair Total\$'s:		\$225,000							
					<h2>No Photo Available</h2>						
<b>Repair Description:</b> Replace the steel sliding plate expansion joints.											
<b>COMMENTS</b>											
Sections of the existing steel sliding plate expansion joints have been repaired by Region Maintenance crews. These expansion joints need to be replaced.											
Bridge Item cost based on \$1,000 / ft. Total project cost based on \$2,500 / ft.											

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 5 / 570		Structure ID 0006080A		Bridge Name: LAKE WASH SHIP CANAL		Milepost: 169.63		Region: Northwest	
Year Built / YR Widened: 1962		Bridge Type: STrus CBox CS		Bridge Length: 4,429 ft		Bridge Width (curb-curb): 174.0 ft		Sufficiency Rating: 53.99FO	
Average Daily Traffic: 200,000		Truck% 6%		Freight Route T1		Num of Lanes: 12			
Date Inspected: 9/10/2005		Structr Adequacy: 3		Superstr Code: 6		Safe Load: 4			
Substr Code: 7		Scour: 8		BMS Element Num: 402		BMS Element Descr: Poured Joints			
BMS Element Quantity: 3,600		Project Number:		2011-13 Priority#: 51		Repair Year:			
CPMS Ad Date:		2009-11 Priority#: 60		Bridge \$'s: \$360,000		Repair Total\$'s: \$500,000			
									
<b>Repair Description:</b> Replace poured joint sealant in deck joints of the lower deck express lanes.									
<b>COMMENTS</b>									
There are deck joints at 60 locations in the Steel Truss span. The poured joint sealant needs to be replaced to prevent water leakage and corrosion of the supporting steel elements. The roadway width is 60 feet.									
The bridge item cost is estimated to be \$100 per foot of joint									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 5 / 647E		Structure ID 0008226B		Bridge Name: UNION SLOUGH		Milepost: 197.09		Region: Northwest	
Year Built / YR Widened: 1968		Bridge Type: PCB CTB		Bridge Length: 396 ft		Bridge Width (curb-curb): 48.0 ft		Sufficiency Rating: 86.56	
Average Daily Traffic: 55,401		Truck% 8%		Freight Route T1		Num of Lanes: 3			
Date Inspected: 10/28/2005		Structr Adequacy: 6		Superstr Code: 7		Safe Load: 5			
Substr Code: 6		Scour: 8							
BMS Element Num: 415		BMS Element Descr: <b>Exp Jnt - Rubber Bolt down</b>				BMS Element Quantity: 240 Feet			
Project Number:		2011-13 Priority#:		24					
Repair Year: 2012		2009-11 Priority#:		27					
CPMS Ad Date:		Bridge \$'s:		\$120,000					
		Repair Total\$'s:		\$360,000					
									
<p><b>Repair Description:</b> Replace the Rubber Bolt Down expansion joints.</p>									
<p><b>COMMENTS</b></p>									
<p>The rubber bolt down expansion joints were installed in 1985 along with the modified concrete overlay. These joints have been repaired many times by Region Maintenance.</p>									
<p>Bridge Item cost based on \$500 / ft. Total project cost based on \$1,500 / ft.</p>									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 5 / 647W		Structure ID 0008226C		Bridge Name: UNION SLOUGH		Milepost: 197.09		Region: Northwest			
Year Built / YR Widened: 1968		Bridge Type: PCB CTB		Bridge Length: 396 ft		Bridge Width (curb-curb): 48.0 ft		Sufficiency Rating: 84.56			
Average Daily Traffic: 55,401		Truck% 8%		Freight Route T1		Num of Lanes: 3					
Date Inspected: 10/28/2005		Structr Adequacy: 6		Superstr Code: 7		Safe Load: 5					
Substr Code: 6		Scour: 8									
BMS Element Num: 415		BMS Element Descr: <b>Exp Jnt - Rubber Bolt down</b>									
BMS Element Quantity: 240 Feet											
Project Number:		2011-13 Priority#:		25							
Repair Year: 2012		2009-11 Priority#:		28							
CPMS Ad Date:		Bridge \$'s:		\$120,000							
		Repair Total\$'s:		\$360,000							
											
<p><b>Repair Description:</b> Replace the Rubber Bolt Down expansion joints.</p>											
<p><b>COMMENTS</b></p>											
<p>The rubber bolt down expansion joints were installed in 1985 along with the modified concrete overlay. These joints have been repaired many times by Region Maintenance.</p>											
<p>Bridge Item cost based on \$500 / ft. Total project cost based on \$1,500 / ft.</p>											

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 5 / 648W		Structure ID 0008226E		Bridge Name: STEAMBOAT SLOUGH		Milepost: 197.90		Region: Northwest	
Year Built / YR Widened: 1968		Bridge Type: PCG		Bridge Length: 1,026 ft		Bridge Width (curb-curb): 48.0 ft		Sufficiency Rating: 81.14	
Average Daily Traffic: 63,000		Truck% 8%		Freight Route T1		Num of Lanes: 3			
Date Inspected: 4/22/2006		Structr Adequacy: 6		Superstr Code: 6		Safe Load: 5			
Substr Code: 7		Scour: 7							
BMS Element Num: 412		BMS Element Descr: Strip Seal Expansion Joint				BMS Element Quantity: 96			
Project Number:		2011-13 Priority#:		26					
Repair Year: 2012		2009-11 Priority#:		29					
CPMS Ad Date:		Bridge \$'s:		\$144,000					
		Repair Total\$'s:		\$240,000					
									
<b>Repair Description:</b> Replace strip seal expansion joint at two locations.									
<b>COMMENTS</b>									
Sections of the existing steel sliding plate expansion joints have failed and need to be replaced.  Bridge item cost based on \$1,500 per foot. Total project cost based on \$2,500 per foot.									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 5 / 650E		Structure ID 0008400A		Bridge Name: EBEY SL BN RY SR 529 OC		Milepost: 198.50		Region: Northwest	
Year Built / YR Widened: 1969		Bridge Type: PCG		Bridge Length: 2,062 ft		Bridge Width (curb-curb): 60.0 ft		Sufficiency Rating: 74.72 FO	
Average Daily Traffic: 52,500		Truck% 8%		Freight Route T1		Num of Lanes: 4			
Date Inspected: 12/3/2006		Structr Adequacy: 5		Superstr Code: 7		Safe Load: 5		Substr Code: 6	
Scour: 3		BMS Element Num: 416		BMS Element Descr: <b>Modular Expansion Joint</b>					
BMS Element Quantity: 360									
Project Number:		2011-13 Priority#: 27							
Repair Year: 2014		2009-11 Priority#: 30							
CPMS Ad Date:		Bridge \$'s: \$900,000							
		Repair Total\$'s: \$1,800,000							





**Repair Description:**  
Replace Modular Expansion Joints and strip seal joints.

**COMMENTS**

Sections of the existing steel sliding plate expansion joints have failed and need to be replaced.

Bridge Item cost based on \$1,500 / ft. Total project cost based on \$3,000 / ft.

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 5 / 650W	Structure ID 0004196A	Bridge Name: EBEY SL BN RY SR 529 OC	Milepost: 198.51	Region: Northwest
Year Built / YR Widened: 1954 / 1968	Bridge Type: SG CTB	Bridge Length: 1,920 ft	Bridge Width (curb-curb): 54.0 ft	Sufficiency Rating: 70.10
Average Daily Traffic: 52,500	Truck% 8%	Freight Route T1	Num of Lanes: 4	
Date Inspected: 12/3/2006	Structr Adequacy: 6	Superstr Code: 6	Safe Load: 5	
Substr Code: 7	Scour: 5	BMS Element Num: <b>415</b>		
BMS Element Descr: <b>Exp Jnt - Rubber Bolt down</b>		BMS Element Quantity: <b>924</b>		
Project Number:	2011-13 Priority#:	<b>28</b>		
Repair Year: 2014	2009-11 Priority#:	<b>31</b>		
CPMS Ad Date:	Bridge \$'s:	<b>\$470,000</b>		
	Repair Total\$'s:	<b>\$1,386,000</b>		
				
<b>Repair Description:</b> Replace the Rubber Bolt Down expansion joints.				
<b>COMMENTS</b>				
The rubber bolt down expansion joints were installed in 1985 along with the modified concrete overlay. These joints have been repaired many times by Region Maintenance.				
Bridge Item cost based on \$500 / ft. Total project cost based on \$1,500 / ft.				

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 6 / 118		Structure ID 0008757A		Bridge Name: CHEHALIS R ADNA		Milepost: 46.59		Region: Southwest	
Year Built / YR Widened: 1971		Bridge Type: SG		Bridge Length: 406 ft		Bridge Width (curb-curb): 40.0 ft		Sufficiency Rating: 95.31	
Average Daily Traffic: 5,663		Truck% 10%		Freight Route		Num of Lanes: 2			
Date Inspected: 5/23/2007		Structr Adequacy: 7		Superstr Code: 7		Safe Load: 5			
Substr Code: 7		Scour: 3		BMS Element Num: 414		BMS Element Descr: Steel Plate Exp Jnt			
BMS Element Quantity: 80		Project Number:		2011-13 Priority#: 76		Repair Year:			
CPMS Ad Date:		2009-11 Priority#: 87		Bridge \$'s: \$40,000		Repair Total\$'s: \$240,000			
									
<b>Repair Description:</b> Rehabilitate the expansion joints.									
<b>COMMENTS</b>									
Remove and replace the bolts that attach the steel sliding plate expansion joint.  Bridge Item cost based on \$500 / ft. Total project cost based on \$3,000 / ft.									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 9 / 360		Structure ID 0006578A		Bridge Name: JOHNSON CR		Milepost: 97.81		Region: Northwest	
Year Built / YR Widened: 1961		Bridge Type: CST		Bridge Length: 104 ft		Bridge Width (curb-curb): 28.0 ft		Sufficiency Rating: 75.51 FO	
Average Daily Traffic: 12,662		Truck%:		Freight Route:		Num of Lanes: 2			
Date Inspected: 4/18/2007		Structr Adequacy: 6		Superstr Code: 7		Safe Load: 5			
Substr Code: 6		Scour: 4		BMS Element Num: 215		BMS Element Descr: Concrete Abutment			
BMS Element Quantity: 56		Project Number:		2011-13 Priority#: 77		Repair Year:			
CPMS Ad Date:		2009-11 Priority#: 88		Bridge \$'s: \$100,000		Repair Total\$'s: \$350,000			
									
<b>Repair Description:</b> Add a sheet pile wall around the abutments to contain the approach roadway embankment.									
<b>COMMENTS</b>									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 12 / 12N		Structure ID 0002311A		Bridge Name: WISHKAH R CS1413		Milepost: 0.08		Region: Olympic			
Year Built / YR Widened: 1925 / 2003		Bridge Type: BAS ST CTB CS		Bridge Length: 363 ft		Bridge Width (curb-curb): 27.0 ft		Sufficiency Rating: 42.98			
Average Daily Traffic: 7,500		Truck% 12%		Freight Route		Num of Lanes: 2					
Date Inspected: 6/6/2005		Structr Adequacy: 4		Superstr Code: 5		Safe Load: 5					
Substr Code: 5		Scour: 3		BMS Element Num: 110		BMS Element Descr: Concrete Girder					
BMS Element Quantity: 0		Project Number:		2011-13 Priority#: 58		Repair Year:				2009-11 Priority#: 68	
CPMS Ad Date:		Bridge \$'s:		Repair Total\$'s: \$100,000							
											
<b>Repair Description:</b> Rehabilitate deteriorated concrete elements.											
<b>COMMENTS</b>											

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 12 / 306		Structure ID 0002513A		Bridge Name: INDIAN CR		Milepost: 159.01		Region: Southwest	
Year Built / YR Widened: 1939		Bridge Type: CTB		Bridge Length: 139 ft		Bridge Width (curb-curb): 24.0 ft		Sufficiency Rating: 79.09	
Average Daily Traffic: 1,788		Truck% 21%		Freight Route		Num of Lanes: 2			
Date Inspected: 9/5/2006		Structr Adequacy: 6		Superstr Code: 7		Safe Load: 5			
Substr Code: 6		Scour: 3		BMS Element Num: 331		BMS Element Descr: Concrete Bridge Rail			
BMS Element Quantity: 278		Project Number:		2011-13 Priority#: 78		Repair Year:			
CPMS Ad Date:		Bridge \$'s: \$45,000		Repair Total\$'s: \$100,000					
<b>Repair Description:</b> Replace the deteriorated concrete bridge rails.									
<b>COMMENTS</b>									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 12 / 512S	Structure ID 0012800A	Bridge Name: SNAKE RIVER AT BURBANK	Milepost: 294.51	Region: South Central
Year Built / YR Widened: 1986	Bridge Type: ST PCB	Bridge Length: 1,780 ft	Bridge Width (curb-curb): 38.0 ft	Sufficiency Rating: 82.45
Average Daily Traffic: 7,063	Truck%	Freight Route	Num of Lanes: 2	
Date Inspected: 5/2/2006	Structr Adequacy: 5	Superstr Code: 5	Safe Load: 5	
Substr Code: 5	Scour: 3	BMS Element Num: <b>356</b>		
BMS Element Descr: <b>Steel Cracking</b>		BMS Element Quantity: 11		
Project Number:	2011-13 Priority#: 68	Repair Year:	2009-11 Priority#: 78	
CPMS Ad Date:	Bridge \$'s: \$400,000	Repair Total\$'s: \$600,000		
				
<b>Repair Description:</b> Repair cracking in stringers.				
<b>COMMENTS</b>				
As of 10/2005 this problem is in a "No Action" status. A mitigation plan should be established.				


# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 12 / 713		Structure ID 0001687B		Bridge Name: NP RY OC		Milepost: 367.73		Region: South Central	
Year Built / YR Widened: 1933		Bridge Type: CTB		Bridge Length: 269 ft		Bridge Width (curb-curb): 26.0 ft		Sufficiency Rating: 68.43 FO	
Average Daily Traffic: 3,118		Truck% 15%		Freight Route		Num of Lanes: 2			
Date Inspected: 3/6/2007		Structr Adequacy: 6		Superstr Code: 6		Safe Load: 5			
Substr Code: 6		Scour: N		BMS Element Num: 331		BMS Element Descr: Concrete Bridge Rail			
BMS Element Quantity: 538 Feet		Project Number: 2011-13 Priority#: 80		Repair Year: 2009-11 Priority#: 92		Bridge \$'s: \$110,000			
CPMS Ad Date:		Repair Total\$'s: \$220,000							
<b>Repair Description:</b> Replace the deteriorated concrete bridge rails.									
<b>COMMENTS</b>									
The existing concrete rail is deteriorated. Maintenance has covered the top rail with sheet metal.  The construction details and costs should be similar to those on bridge 26/285 (C#6567) completed in 2003.									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 12 / 915		Structure ID 0002348A		Bridge Name: SNAKE R CLARKSTON		Milepost: 434.10		Region: South Central	
Year Built / YR Widened: 1939		Bridge Type: SL ST CTB		Bridge Length: 1,432 ft		Bridge Width (curb-curb): 40.0 ft		Sufficiency Rating: 44.20SD	
Average Daily Traffic: 20,518		Truck%: 2%		Freight Route		Num of Lanes: 4			
Date Inspected: 7/25/2006		Structr Adequacy: 5		Superstr Code: 6		Safe Load: 5			
Substr Code: 5		Scour: 3		BMS Element Num: 331		BMS Element Descr: Concrete Bridge Rail			
BMS Element Quantity: 922 Feet		Project Number: 501212P		2011-13 Priority#: 81		Repair Year: 2009-11 Priority#: 93			
CPMS Ad Date:		Bridge \$'s: \$300,000		Repair Total\$'s: \$600,000				 	
<p><b>Repair Description:</b> Replace the deteriorated concrete bridge rail on the approach spans and repair the concrete end posts.</p>									
<b>COMMENTS</b>									
<p>The concrete bridge rail is deteriorated with many areas of exposed reinforcing steel. The concrete end posts are exfoliated and severely cracked.</p>									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 16 / 110E	Structure ID 0003418A	Bridge Name: TACOMA NARROWS	Milepost: 7.28	Region: Olympic
Year Built / YR Widened: 1949	Bridge Type: SSusS SG CTB	Bridge Length: 5,978 ft	Bridge Width (curb-curb): 46.3 ft	Sufficiency Rating: 39.88 FO
Average Daily Traffic: Truck% 48,000	Freight Route T1	Num of Lanes: 4		
Date Inspected:	Structr Adequacy:			
Superstr Code:	Safe Load:			
Substr Code:	Scour:			
BMS Element Num:	BMS Element Descr:			
BMS Element Quantity:				
Project Number:	2011-13 Priority#:	1		
Repair Year: 2012	2009-11 Priority#:			
CPMS Ad Date:	Bridge \$'s:			
	Repair Total\$'s:	\$500,000		



### Repair Description:

Replace Expansion Joint and supports at Tower 4


### COMMENTS

The support system for the steel supporting the Finger Expansion Joint at Tower 4 is deteriorated and in need of replacement.

Total cost estimated @ \$500,000 until a thorough review can be done.

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 16 / 110E		Structure ID 0003418A		Bridge Name: TACOMA NARROWS		Milepost: 7.28		Region: Olympic	
Year Built / YR Widened: 1949		Bridge Type: SSusS SG CTB		Bridge Length: 5,978 ft		Bridge Width (curb-curb): 46.3 ft		Sufficiency Rating: 39.88 FO	
Average Daily Traffic: Truck% 48,000		Freight Route T1		Num of Lanes: 4					
Date Inspected:		Structr Adequacy:							
Superstr Code:		Safe Load:							
Substr Code:		Scour:							
BMS Element Num:									
BMS Element Descr:									
BMS Element Quantity:									
Project Number:		2011-13 Priority#:		2					
Repair Year: 2012		2009-11 Priority#:							
CPMS Ad Date:		Bridge \$'s:							
		Repair Total\$'s:		\$3,500,000					
 <p><b>FIGURE 1- Maintenance Traveler</b></p>									
<p><b>Repair Description:</b> Replace Maintenance Traveler</p>									
<p><b>COMMENTS</b></p>									
<p>The Top traveler and rail is 70 years old and in need of replacement. There are sections of the rail track at the towers that is deteriorating. Bridge Maintenance crews use this traveler system to perform maintenance on the bridge.</p> <p>Total cost estimated @ \$3,500,000 until a thorough review can be done.</p>									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 18 / 9	Structure ID 0005082A	Bridge Name: NP RY OC	Milepost: 3.82	Region: Northwest
Year Built / YR Widened: 1956 / 1975	Bridge Type: CB <sub>o</sub> x	Bridge Length: 1,151 ft	Bridge Width (curb-curb): 69.2 ft	Sufficiency Rating: 86.26
Average Daily Traffic: 44,000	Truck% 6%	Freight Route T1	Num of Lanes: 5	
Date Inspected: 12/20/2005	Structr Adequacy: 6	Superstr Code: 6	Safe Load: 5	
Substr Code: 7	Scour: N			
BMS Element Num: 415	BMS Element Descr: <b>Rubber Bolt Down exp joints</b>			
BMS Element Quantity: 413				
Project Number: Repair Year: 2016	2011-13 Priority#: 2009-11 Priority#:	30 33		
CPMS Ad Date:	Bridge \$'s: Repair Total\$'s:	\$309,750 \$619,500		
				
<b>Repair Description:</b> Replace Expansion Joints at 6 locations.				
<b>COMMENTS</b>				
The rubber bolt down expansion joints are deteriorated. Maintenance has removed and replaced sections of the expansion joint.  Bridge Item cost based on \$750 / ft. Total project cost based on \$1,500 / ft.				


# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 18 / 9	Structure ID 0005082A	Bridge Name: NP RY OC	Milepost: 3.82	Region: Northwest
Year Built / YR Widened: 1956 / 1975	Bridge Type: CB <sub>OX</sub>	Bridge Length: 1,151 ft	Bridge Width (curb-curb): 69.2 ft	Sufficiency Rating: 86.26
Average Daily Traffic: 44,000	Truck% 6%	Freight Route T1	Num of Lanes: 5	
Date Inspected: 12/20/2005	Structr Adequacy: 6	Superstr Code: 6	Safe Load: 5	
Substr Code: 7	Scour: N			
BMS Element Num: 161	BMS Element Descr: Steel Hanger Assembly			
BMS Element Quantity: 58				
Project Number: 2011-13 Priority#: 31				
Repair Year: 2016	2009-11 Priority#: 34			
CPMS Ad Date:	Bridge \$'s: \$250,000			
	Repair Total\$'s: \$450,000			
				
<b>Repair Description:</b> Clean and Paint Steel Hanger and Pin assembly.				
<b>COMMENTS</b>				
The existing pins and hangers are rusty. They need to be cleaned and painted with an epoxy rust penetrating sealer.				
Use a lump sum bridge Item cost of \$4,000 for each or say \$250,000. Use \$200,000 for Region items. Use \$450,000 for total.				

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 18 / 17S		Structure ID 0006066B		Bridge Name: GREEN R (NEELEY BRIDGE)		Milepost: 6.62		Region: Northwest	
Year Built / YR Widened: 1959		Bridge Type: STrus CBox		Bridge Length: 371 ft		Bridge Width (curb-curb): 29.5 ft		Sufficiency Rating: 37.45SD	
Average Daily Traffic: 22,000		Truck%: 10%		Freight Route: T1		Num of Lanes: 2			
Date Inspected: 8/8/2006		Structr Adequacy: 5		Superstr Code: 5		Safe Load: 5			
Substr Code: 5		Scour: 4		BMS Element Num: 356		BMS Element Descr: Steel Stringer			
BMS Element Quantity: 16		Project Number: 2011-13 Priority#: 59		Repair Year: 2009-11 Priority#: 69		CPMS Ad Date: Bridge \$'s: Repair Total\$'s: \$500,000			
		<h2>No Photo Available</h2>							
<b>Repair Description:</b> Address cracking in 15 steel stringers.									
<b>COMMENTS</b>									
Repair cope cracks at the following locations: Stringer 1A at Floorbeam 1 , Stringer 1E at Floorbeam 1 , Stringer 2E at Floorbeam 1 , Stringer 3A at Floorbeam 2 , Stringer 3E at Floorbeam 2 , Stringer 4A at Floorbeam 3 , Stringer 4A at Floorbeam 4 , Stringer 5A at Floorbeam 5 , Stringer 6A at Floorbeam 6 , Stringer 6E at Floorbeam 6 , Stringer 7A at Floorbeam 6 , Stringer 7E at Floorbeam 6 , Stringer 7A at Floorbeam 7 , Stringer 8A at Floorbeam 7 , Stringer 8E at Floorbeam 7 .									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 20 / 204		Structure ID 0001929A		Bridge Name: DECEPTION PASS		Milepost: 41.81		Region: Northwest	
Year Built / YR Widened: 1935		Bridge Type: STrus CTB		Bridge Length: 976 ft		Bridge Width (curb-curb): 22.0 ft		Sufficiency Rating: 47.72 FO	
Average Daily Traffic: 14,000		Truck% 6%		Freight Route		Num of Lanes: 2			
Date Inspected: 3/29/2007		Structr Adequacy: 5		Superstr Code: 5		Safe Load: 5		Substr Code: 7	
BMS Element Num: 131		BMS Element Descr: <b>Steel Deck Truss</b>							
BMS Element Quantity: 0									
Project Number:		2011-13 Priority#: 52		Repair Year:		2009-11 Priority#: 61		CPMS Ad Date:	
		Bridge \$'s:		Repair Total\$'s: \$500,000					






**Repair Description:**  
Replace corroded secondary braces.

**COMMENTS**

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 20 / 207		Structure ID 0001929B		Bridge Name: CANOE PASS		Milepost: 42.04		Region: Northwest	
Year Built / YR Widened: 1935		Bridge Type: SA CTB		Bridge Length: 511 ft		Bridge Width (curb-curb): 22.0 ft		Sufficiency Rating: 48.21 FO	
Average Daily Traffic: 14,000		Truck% 6%		Freight Route		Num of Lanes: 2			
Date Inspected: 4/11/2007		Structr Adequacy: 5		Superstr Code: 6		Safe Load: 5			
Substr Code: 7		Scour: 9		BMS Element Num: 131		BMS Element Descr: <b>Steel Deck Truss</b>			
BMS Element Quantity: 0		Project Number:		2011-13 Priority#: 61		Repair Year:			
CPMS Ad Date:		2009-11 Priority#: 71		Bridge \$'s: \$200,000		Repair Total\$'s: \$400,000			
									
<b>Repair Description:</b> Replace corroded secondary braces.									
<b>COMMENTS</b>									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 20 / 651		Structure ID 0001738A		Bridge Name: BONAPARTE CR		Milepost: 262.83		Region: North Central			
Year Built / YR Widened: 1933		Bridge Type: CA CS		Bridge Length: 118 ft		Bridge Width (curb-curb): 24.0 ft		Sufficiency Rating: 46.48			
Average Daily Traffic: Truck%		Freight Route		Num of Lanes: 2							
Date Inspected: 3/17/2007		Structr Adequacy:		Superstr Code: 6						Safe Load:	
Substr Code: 5		Scour:		BMS Element Num: 331						BMS Element Descr: Concrete Bridge Rail	
BMS Element Quantity: 236		Project Number:		2011-13 Priority#: 88						Repair Year:	
CPMS Ad Date:		2009-11 Priority#: 999		Bridge \$'s:		Repair Total\$'s: \$700,000					
											
<p><b>Repair Description:</b> Replace Bridge Rail and repair concrete braces that support the bridge rail.</p>											
<p><b>COMMENTS</b></p>											

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 21 / 321		Structure ID 0001622A		Bridge Name: W FK SAN POIL		Milepost: 145.62		Region: Eastern	
Year Built / YR Widened: 1932		Bridge Type: CTB		Bridge Length: 42 ft		Bridge Width (curb-curb): 24.0 ft		Sufficiency Rating: 73.32	
Average Daily Traffic: 207		Truck% 8%		Freight Route		Num of Lanes: 2			
Date Inspected: 9/12/2006		Structr Adequacy: 6		Superstr Code: 7		Safe Load: 5			
Substr Code: 6		Scour: 3		BMS Element Num: 331		BMS Element Descr: Concrete Bridge Rail			
BMS Element Quantity: 84		Project Number:		2011-13 Priority#: 82		Repair Year:			
CPMS Ad Date:		2009-11 Priority#: 94		Bridge \$'s: \$50,000		Repair Total\$'s: \$100,000			
<p><b>Repair Description:</b> Replace the deteriorated concrete bridge rails.</p>									
<p><b>COMMENTS</b></p>									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 21 / 323		Structure ID 000000HN		Bridge Name: SAN POIL R		Milepost: 148.45		Region: Eastern	
Year Built / YR Widened: 1927		Bridge Type: CTB		Bridge Length: 61 ft		Bridge Width (curb-curb): 20.4 ft		Sufficiency Rating: 4.98SD	
Average Daily Traffic: 643		Truck% 7%		Freight Route		Num of Lanes: 2			
Date Inspected: 9/13/2006		Structr Adequacy: 3		Superstr Code: 7		Safe Load: 5			
Substr Code: 3		Scour: 3		BMS Element Num: 331		BMS Element Descr: Concrete Bridge Rail			
BMS Element Quantity: 122		Project Number:		2011-13 Priority#: 83		Repair Year:			
CPMS Ad Date:		2009-11 Priority#: 95		Bridge \$'s: \$50,000		Repair Total\$'s: \$100,000			
<p><b>Repair Description:</b> Replace the deteriorated concrete bridge rails.</p>									
<p><b>COMMENTS</b></p>									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 26 / 2SP		Structure ID 0002385B		Bridge Name: N FK PALOUSE-WEST WYE		Milepost: 38.50		Region: Eastern	
Year Built / YR Widened: 1938		Bridge Type: CTB		Bridge Length: 114 ft		Bridge Width (curb-curb): 26.0 ft		Sufficiency Rating: 61.45FO	
Average Daily Traffic: 9,105		Truck% 9%		Freight Route		Num of Lanes: 2			
Date Inspected: 10/24/2006		Structr Adequacy: 5		Superstr Code: 6		Safe Load: 5			
Substr Code: 6		Scour: 8		BMS Element Num: 331		BMS Element Descr: Concrete Bridge Rail			
BMS Element Quantity: 228 Feet		Project Number:		2011-13 Priority#: 84		Repair Year:			
CPMS Ad Date:		Bridge \$'s: \$50,000		Repair Total\$'s: \$100,000					
<b>Repair Description:</b> Replace the deteriorated concrete bridge rails.									
<b>COMMENTS</b>									
The concrete bridge rail is deteriorated.									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 90 / 10W-S		Structure ID 0007565B		Bridge Name: I-5 OC, W-S RAMP		Milepost: 2.40		Region: Northwest			
Year Built / YR Widened: 1965 / 1988		Bridge Type: CBox		Bridge Length: 1,245 ft		Bridge Width (curb-curb): 20.5 ft		Sufficiency Rating: 79.11 FO			
Average Daily Traffic: 13,247		Truck% 5%		Freight Route T1		Num of Lanes: 1					
Date Inspected: 7/11/2005		Structr Adequacy: 6		Superstr Code: 6		Safe Load: 5					
Substr Code: 7		Scour: N									
BMS Element Num: 408		BMS Element Descr: Steel Sliding Plate									
BMS Element Quantity: 164											
Project Number:		2011-13 Priority#: 32		Repair Year: 2016		2009-11 Priority#: 35					
CPMS Ad Date:		Bridge \$'s: \$164,000		Repair Total\$'s: \$410,000							
											
<b>Repair Description:</b> Replace Expansion Joints											
<b>COMMENTS</b>											
Sections of the existing steel sliding plate expansion joints have failed and need to be replaced.  Bridge Item cost based on \$1,000 / ft. Total project cost based on \$2,500 / ft.											

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 90 / 25N	Structure ID 0012271A	Bridge Name: HOMER M. HADLEY	Milepost: 4.24	Region: Northwest
Year Built / YR Widened: 1989	Bridge Type: CFP POBX SBOX	Bridge Length: 9,559 ft	Bridge Width (curb-curb): 92.0 ft	Sufficiency Rating: 71.79 FO
Average Daily Traffic: Truck% 57,401	Freight Route T1	Num of Lanes: 7		
Date Inspected: 5/31/2005	Structr Adequacy: 6			
Superstr Code: 6	Safe Load: 5			
Substr Code: 7	Scour: 8			
BMS Element Num: <b>148</b> BMS Element Descr: <b>Floating Bridge - Anchor Cable</b> BMS Element Quantity: 10				
Project Number:	2011-13 Priority#:	21		
Repair Year: 2014	2009-11 Priority#:	9		
CPMS Ad Date:	Bridge \$'s:	\$1,500,000		
	Repair Total\$'s:	\$2,000,000		
				
<b>Repair Description:</b> Replace 10 anchor cables.				
<b>COMMENTS</b>				
The Bridge Office recommends the following 10 anchor cable be replaced in the 2013-15 biennium: L1n , L2n , L3n , L4n , L5n , L6n , Fn , Jn , Os , Ys				
Bridge Item cost uses \$150,000 for install and cost of each cable ...\$150k x 10 = \$1.5m Use \$500,000 to develop PS&E and construction engineering and contingencies.				

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 90 / 25N		Structure ID 0012271A		Bridge Name: HOMER M. HADLEY		Milepost: 4.24		Region: Northwest	
Year Built / YR Widened: 1989		Bridge Type: CFP PTCBox SBox		Bridge Length: 9,559 ft		Bridge Width (curb-curb): 92.0 ft		Sufficiency Rating: 71.79 FO	
Average Daily Traffic: 61,500		Truck% 0%		Freight Route T1		Num of Lanes: 7			
Date Inspected: 5/31/2005		Structr Adequacy: 6		Superstr Code: 6		Safe Load: 5			
Substr Code: 7		Scour: 8		BMS Element Num: 148		BMS Element Descr: Floating Bridge - Anchor Cable			
BMS Element Quantity: 10		Project Number:		2011-13 Priority#: 44		2009-11 Priority#: 52			
Repair Year: 2016		CPMS Ad Date:		Bridge \$'s: \$2,430,000		Repair Total\$'s: \$2,700,000			
<b>Repair Description:</b> Replace 10 anchor cables									
<b>COMMENTS</b>									
There are 9 (out of a total of 53) anchor cables that were installed in 1983. These need to be replaced in the 2013-15 biennium.  Bridge Item cost uses \$250,000 for install of each cable and \$20,000 cable cost...\$270k x 9 = \$2.43m Use \$300,000 to develop PS&E and construction engineering and contingencies.									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 90 / 25S		Structure ID 000000KN		Bridge Name: LACEY V. MURROW BR		Milepost: 4.24		Region: Northwest	
Year Built / YR Widened: 1940 / 1992		Bridge Type: CFP SA ST CBOX S		Bridge Length: 8,981 ft		Bridge Width (curb-curb): 52.0 ft		Sufficiency Rating: 90.80	
Average Daily Traffic: Truck%		Freight Route		Num of Lanes:					
57,401 4%		T1		3					
Date Inspected: 6/5/2007		Structr Adequacy: 6							
Superstr Code: 7		Safe Load: 5							
Substr Code: 6		Scour: 8							
BMS Element Num: 148		BMS Element Descr: <b>Floating Bridge - Anchor Cable</b>							
BMS Element Quantity: 10									
Project Number:		2011-13 Priority#: 22							
Repair Year: 2014		2009-11 Priority#: 10							
CPMS Ad Date:		Bridge \$'s: \$1,500,000							
		Repair Total\$'s: \$2,000,000							
									
<b>Repair Description:</b>									
Replace 10 anchor cables.									
<b>COMMENTS</b>									
Recommendation from consultant hired by the Bridge Preservation Office recommends the following anchor cable be replaced: Es , Js , Ks , L1n , L2n , L3n , Ls , Ns , Ps									
Bridge Item cost uses \$250,000 for install of each cable and \$20,000 cable cost...\$270k x 9 = \$2.4m Use \$300,000 to develop PS&E and construction engineering and contingencies.									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 90 / 40N		Structure ID 0011490A		Bridge Name: EAST CHANNEL-LK WASH		Milepost: 8.48		Region: Northwest	
Year Built / YR Widened: 1981		Bridge Type: WSBox		Bridge Length: 2,224 ft		Bridge Width (curb-curb): 80.0 ft		Sufficiency Rating: 69.37 FO	
Average Daily Traffic: 67,000		Truck% 0%		Freight Route		Num of Lanes: 5			
Date Inspected: 10/30/2006		Structr Adequacy: 4		Superstr Code: 6		Safe Load: 5			
Substr Code: 7		Scour: 8		BMS Element Num: 416		BMS Element Descr: <b>Modular Expansion Joint</b>			
BMS Element Quantity: 160		Project Number:		2011-13 Priority#: 53		Repair Year:			
CPMS Ad Date:		2009-11 Priority#: 62		Bridge \$'s: \$75,000		Repair Total\$'s: \$150,000			
									
<b>Repair Description:</b> Replace Glands in Modular expansion joints in westbound lanes.									
<b>COMMENTS</b>									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 90 / 180		Structure ID 0006533A		Bridge Name: COLUMBIA R VANTAGE		Milepost: 137.19		Region: South Central	
Year Built / YR Widened: 1962		Bridge Type: STrus SG		Bridge Length: 2,504 ft		Bridge Width (curb-curb): 56.0 ft		Sufficiency Rating: 44.71	
Average Daily Traffic: 11,916		Truck% 26%		Freight Route T1		Num of Lanes: 4			
Date Inspected: 7/11/2007		Structr Adequacy: 5		Superstr Code: 5		Safe Load: 5			
Substr Code: 6		Scour: 3		BMS Element Num: 402		BMS Element Descr: Poured Joint Filler			
BMS Element Quantity: 2,240		Project Number:		2011-13 Priority#: 60		Repair Year:			
CPMS Ad Date:		2009-11 Priority#: 70		Bridge \$'s: \$168,000		Repair Total\$'s: \$336,000			
<h2>No Photo Available</h2>									
<p><b>Repair Description:</b> Replace poured joint filler in all transverse joints.</p>									
<p><b>COMMENTS</b></p>									
<p>Bridge Item repair cost based on \$75 / ft. Total Project cost based on \$150 / ft.</p>									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 90 / 332		Structure ID 0005783D		Bridge Name: I-90 OC, TOKIO RD		Milepost: 231.23		Region: Eastern	
Year Built / YR Widened: 1958		Bridge Type: PCG		Bridge Length: 225 ft		Bridge Width (curb-curb): 26.0 ft		Sufficiency Rating: 96.15	
Average Daily Traffic: 250		Truck% 25%		Freight Route		Num of Lanes: 2			
Date Inspected: 9/26/2006		Structr Adequacy: 6		Superstr Code: 6		Safe Load: 5			
Substr Code: 6		Scour: N		BMS Element Num: 409		BMS Element Descr: Steel Sliding Exp Joint			
BMS Element Quantity: 160		Project Number:		2011-13 Priority#: 85		Repair Year:			
CPMS Ad Date:		2009-11 Priority#: 97		Bridge \$'s: \$80,000		Repair Total\$'s: \$160,000			
									
<b>Repair Description:</b> Replace Expansion Joints									
<b>COMMENTS</b>									
Bridge Item cost based on \$500 / ft. Total project cost based on \$1,000 / ft.									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 90 / 540N		Structure ID 0006579B		Bridge Name: HANGMAN CR		Milepost: 279.49		Region: Eastern	
Year Built / YR Widened: 1963		Bridge Type: CBOX		Bridge Length: 1,222 ft		Bridge Width (curb-curb): 44.0 ft		Sufficiency Rating: 67.56	
Average Daily Traffic: 24,152		Truck% 13%		Freight Route T1		Num of Lanes: 3			
Date Inspected: 9/21/2005		Structr Adequacy: 5		Superstr Code: 6		Safe Load: 5			
Substr Code: 5		Scour: 7		BMS Element Num: 105		BMS Element Descr: Concrete Box Girder			
BMS Element Quantity: 2		Project Number:		2011-13 Priority#: 33		2009-11 Priority#: 36			
Repair Year: 2016		CPMS Ad Date:		Bridge \$'s: \$150,000		Repair Total\$'s: \$300,000			
									
<p><b>Repair Description:</b> Remove loose concrete, clean rusty steel and apply a patching material and sealer.</p>									
<p><b>COMMENTS</b></p>									
<p>The strip seal expansion joints over the interior hinges were replaced in 1999. Shortly after the expansion joints were replaced the gap in the hinged area closed.</p> <p>Use assumed costs of \$150,000 and \$300,000 until better estimates are developed.</p>									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 90 / 540S		Structure ID 0006579B		Bridge Name: HANGMAN CR		Milepost: 279.49		Region: Eastern	
Year Built / YR Widened: 1963		Bridge Type: CBOX		Bridge Length: 1,222 ft		Bridge Width (curb-curb): 44.0 ft		Sufficiency Rating: 67.56	
Average Daily Traffic: 24,152		Truck% 13%		Freight Route T1		Num of Lanes: 3			
Date Inspected: 9/21/2005		Structr Adequacy: 5		Superstr Code: 6		Safe Load: 5			
Substr Code: 5		Scour: 7							
BMS Element Num: 105		BMS Element Descr: Concrete Box Girder				BMS Element Quantity: 2			
Project Number:		2011-13 Priority#:		34					
Repair Year: 2016		2009-11 Priority#:		37					
CPMS Ad Date:		Bridge \$'s:		\$150,000					
		Repair Total\$'s:		\$300,000					
									
<p><b>Repair Description:</b> Remove loose concrete, clean rusty steel and apply a patching material and sealer.</p>									
<p><b>COMMENTS</b></p>									
<p>The strip seal expansion joints over the interior hinges were replaced in 1999. Shortly after the expansion joints were replaced the gap in the hinged area closed.</p> <p>Use assumed costs of \$150,000 and \$300,000 until better estimates are developed.</p>									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 90 / 545E-E		Structure ID 0008322D		Bridge Name: FOURTH-E RAMP		Milepost: 280.54		Region: Eastern	
Year Built / YR Widened: 1967		Bridge Type: CBox		Bridge Length: 79 ft		Bridge Width (curb-curb): 25.0 ft		Sufficiency Rating: 96.57	
Average Daily Traffic: 4,590		Truck% 5%		Freight Route T1		Num of Lanes: 1			
Date Inspected: 8/24/2005		Structr Adequacy: 6		Superstr Code: 6		Safe Load: 5			
Substr Code: 6		Scour: N		BMS Element Num: 215		BMS Element Descr: Concrete Abutment			
BMS Element Quantity: 25		Project Number:		2011-13 Priority#: 62		Repair Year:			
CPMS Ad Date:		2009-11 Priority#: 72		Bridge \$'s: \$200,000		Repair Total\$'s: \$300,000			
Repair Description:		Remove delaminated concrete, clean rusty rebar and apply new patching material.		COMMENTS					

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 99 / 507E		Structure ID 0007967A		Bridge Name: SR 599 OC		Milepost: 22.94		Region: Northwest	
Year Built / YR Widened: 1966		Bridge Type: PCB		Bridge Length: 263 ft		Bridge Width (curb-curb): 23.0 ft		Sufficiency Rating: 76.96FO	
Average Daily Traffic: 4,973		Truck% 6%		Freight Route		Num of Lanes: 1			
Date Inspected: 5/10/2006		Structr Adequacy: 5		Superstr Code: 6		Safe Load: 5			
Substr Code: 6		Scour: N		BMS Element Num: 415		BMS Element Descr: Exp Jnt - Rubber Bolt Down			
BMS Element Quantity: 160 feet		Project Number: 2011-13 Priority#: 69		Repair Year: 2009-11 Priority#: 80		Bridge \$'s: \$74,000			
CPMS Ad Date:		Repair Total\$'s: \$222,000		CPMS Ad Date:		Repair Total\$'s: \$222,000			
									
<b>Repair Description:</b> Replace 160 LF of rubber bolt down expansion joint.									
<b>COMMENTS</b>									
The rubber bolt down expansion joints are deteriorated. Maintenance has removed and replaced sections of the expansion joint. The new Expansion Joint will be RCS with Polyester Concrete headers. Bridge Item cost based on \$500 / ft. Total project cost based on \$1,500 / ft.									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 99 / 507S-S		Structure ID 0007967D		Bridge Name: PACIFIC HWY OC		Milepost: 22.94		Region: Northwest	
Year Built / YR Widened: 1966		Bridge Type: PCB		Bridge Length: 236 ft		Bridge Width (curb-curb): 38.0 ft		Sufficiency Rating: 81.78 FO	
Average Daily Traffic: 16,961		Truck% 6%		Freight Route		Num of Lanes: 2			
Date Inspected: 5/10/2006		Structr Adequacy: 6		Superstr Code: 7		Safe Load: 5			
Substr Code: 7		Scour: N		BMS Element Num: 415		BMS Element Descr: Exp Jnt - Rubber Bolt Down			
BMS Element Quantity: 190 feet		Project Number: 2011-13 Priority#: 70		Repair Year: 2009-11 Priority#: 81		Bridge \$'s: \$95,000			
CPMS Ad Date:		Repair Total\$'s: \$285,000							
				<p><b>Repair Description:</b> Replace 190 LF of rubber bolt down expansion joint.</p>					
<b>COMMENTS</b>									
<p>The rubber bolt down expansion joints are deteriorated. Maintenance has removed and replaced sections of the expansion joint.</p> <p>The new Expansion Joint will be RCS with Polyester Concrete headers.</p> <p>Bridge Item cost based on \$500 / ft. Total project cost based on \$1,500 / ft.</p>									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 99 / 507W		Structure ID 0007967C		Bridge Name: S 116TH PL OC		Milepost: 22.94		Region: Northwest	
Year Built / YR Widened: 1966		Bridge Type: PCB		Bridge Length: 196 ft		Bridge Width (curb-curb): 23.0 ft		Sufficiency Rating: 81.20 FO	
Average Daily Traffic: 2,447		Truck% 6%		Freight Route		Num of Lanes: 1			
Date Inspected: 5/10/2006		Structr Adequacy: 6		Superstr Code: 7		Safe Load: 5			
Substr Code: 7		Scour: N		BMS Element Num: 415		BMS Element Descr: Exp Jnt - Rubber Bolt Down			
BMS Element Quantity: 108 feet		Project Number: 2011-13 Priority#: 71		Repair Year: 2009-11 Priority#: 82		Bridge \$'s: \$54,000			
CPMS Ad Date:		Repair Total\$'s: \$162,000							
		<h2 style="font-size: 2em; opacity: 0.5;">No Photo Available</h2>							
<b>Repair Description:</b> Replace 108 LF of rubber bolt down expansion joint.									
<b>COMMENTS</b>									
The rubber bolt down expansion joints are deteriorated. Maintenance has removed and replaced sections of the expansion joint. The new Expansion Joint will be RCS with Polyester Concrete headers. Bridge Item cost based on \$500 / ft. Total project cost based on \$1,500 / ft.									

Bridge Number: 99 / 508		Structure ID 0007967B		Bridge Name: PACIFIC HWY OC		Milepost: 22.94		Region: Northwest	
Year Built / YR Widened: 1966		Bridge Type: PCB		Bridge Length: 248 ft		Bridge Width (curb-curb): 52.0 ft		Sufficiency Rating: 79.25 FO	
Average Daily Traffic: 19,960		Truck% 6%		Freight Route		Num of Lanes: 3			
Date Inspected: 5/10/2006		Structr Adequacy: 6		Superstr Code: 6		Safe Load: 5			
Substr Code: 6		Scour: N		BMS Element Num: 415		BMS Element Descr: Exp Jnt - Rubber Bolt Down			
BMS Element Quantity: 227		Project Number:		2011-13 Priority#: 72		Repair Year:			
CPMS Ad Date:		2009-11 Priority#: 83		Bridge \$'s: \$113,500		Repair Total\$'s: \$340,500			
									
<p><b>Repair Description:</b> Replace 227 LF of rubber bolt down expansion joint.</p>									
<p><b>COMMENTS</b></p>									
<p>The rubber bolt down expansion joints are deteriorated. Maintenance has removed and replaced sections of the expansion joint. The new Expansion Joint will be RCS with Polyester Concrete headers.</p> <p>Bridge Item cost based on \$500 / ft. Total project cost based on \$1,500 / ft.</p>									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 101 / 115N-W		Structure ID 0012643A		Bridge Name: N-W RAMP		Milepost: 83.12		Region: Olympic	
Year Built / YR Widened: 1985		Bridge Type: SG		Bridge Length: 1,456 ft		Bridge Width (curb-curb): 20.0 ft		Sufficiency Rating: 96.26	
Average Daily Traffic: 4,623		Truck% 0%		Freight Route		Num of Lanes: 1			
Date Inspected: 6/7/2005		Structr Adequacy: 6		Superstr Code: 7		Safe Load: 5			
Substr Code: 6		Scour: N		BMS Element Num: 415		BMS Element Descr: Bolt Down Panel - Molded Rubbe			
BMS Element Quantity: 80 LF		Project Number: 2011-13 Priority#: 73		Repair Year: 2009-11 Priority#: 84		Bridge \$'s: \$40,000			
CPMS Ad Date:		Repair Total\$'s: \$120,000							
		<p style="text-align: center; font-size: 2em; font-weight: bold;">No Photo Available</p>							
<p><b>Repair Description:</b> Replace bolt down panels expansion joint system.</p>									
<p><b>COMMENTS</b></p>									
<p>The rubber bolt down expansion joints are deteriorated. The new Expansion Joint will be RCS with Polyester Concrete headers. Bridge Item cost based on \$500 / ft. Total project cost based on \$1,500 / ft.</p>									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 101 / 269		Structure ID 0000987A		Bridge Name: FULTON CR		Milepost: 313.55		Region: Olympic	
Year Built / YR Widened: 1926		Bridge Type: CTB		Bridge Length: 127 ft		Bridge Width (curb-curb): 24.0 ft		Sufficiency Rating: 46.21 FO	
Average Daily Traffic: 2,063		Truck% 17%		Freight Route		Num of Lanes: 2			
Date Inspected: 7/12/2006		Structr Adequacy: 5		Superstr Code: 7		Safe Load: 5			
Substr Code: 5		Scour: 3		BMS Element Num: 227		BMS Element Descr: Concrete Submerged Column			
BMS Element Quantity: 8		Project Number:		2011-13 Priority#: 45		2009-11 Priority#: 54			
Repair Year: 2016		CPMS Ad Date:		Bridge \$'s: \$320,000		Repair Total\$'s: \$600,000		 	
<b>Repair Description:</b> Repair and encase section of concrete columns exposed to saltwater.									
<b>COMMENTS</b>									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 101 / 432E		Structure ID 0006383B		Bridge Name: KENNEDY CR		Milepost: 356.17		Region: Olympic	
Year Built / YR Widened: 1960		Bridge Type: CVS		Bridge Length: 129 ft		Bridge Width (curb-curb): 28.0 ft		Sufficiency Rating: 66.79 FO	
Average Daily Traffic: 8,357		Truck% 7%		Freight Route		Num of Lanes: 2			
Date Inspected: 7/25/2006		Structr Adequacy: 5		Superstr Code: 6		Safe Load: 5			
Substr Code: 5		Scour: 3		BMS Element Num: 227		BMS Element Descr: Concrete Submerged Column			
BMS Element Quantity: 18		Project Number:		2011-13 Priority#: 46		2009-11 Priority#: 55			
Repair Year: 2016		CPMS Ad Date:		Bridge \$'s: \$720,000		Repair Total\$'s: \$1,080,000			
<p><b>Repair Description:</b> Clean and encase concrete columns</p>									
<p><b>COMMENTS</b></p> <p>Need to get current pictures of the columns.</p>									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 101 / 432W		Structure ID 0006383A		Bridge Name: KENNEDY CR		Milepost: 356.17		Region: Olympic	
Year Built / YR Widened: 1960		Bridge Type: CVS		Bridge Length: 129 ft		Bridge Width (curb-curb): 28.0 ft		Sufficiency Rating: 57.77 FO	
Average Daily Traffic: 8,357		Truck% 7%		Freight Route		Num of Lanes: 2			
Date Inspected: 7/24/2006		Structr Adequacy: 5		Superstr Code: 7		Safe Load: 5			
Substr Code: 5		Scour: 3		BMS Element Num: 227		BMS Element Descr: Concrete Submerged Column			
BMS Element Quantity: 18		Project Number:		2011-13 Priority#: 47		2009-11 Priority#: 56			
Repair Year: 2016		CPMS Ad Date:		Bridge \$'s: \$720,000		Repair Total\$'s: \$1,080,000			
<h2>No Photo Available</h2>					<h2>No Photo Available</h2>				
<b>Repair Description:</b> Clean and encase concrete columns									
<b>COMMENTS</b>									
Need to get current pictures of the columns.									

Bridge Number: 104 / 5.1	Structure ID 0011964A	Bridge Name: HOOD CANAL-WEST HALF	Milepost: 13.93	Region: Olympic
Year Built / YR Widened: 1982	Bridge Type: CFP PCG STRus	Bridge Length: 4,245 ft	Bridge Width (curb-curb): 28.0 ft	Sufficiency Rating: 47.98
Average Daily Traffic: 13,327	Truck%:	Detour (miles):	Num of Lanes: 2	
Date Inspected:	Superstr Code:	Substr Code:	Structr Adequacy:	Safe Load:
			Scour:	
BMS Element Num: <b>148</b>		BMS Element Descr: <b>Floating Bridge - Anchor Cable</b>		
BMS Element Quantity: <b>18 Each</b>				
Project Number:	2009-11 Priority#:	53		
Repair Year: <b>2014</b>	2011-13 Priority#:	20		
CPMS Ad Date:	Bridge \$'s:	\$5,040,000		
	Repair Total\$'s:	\$5,891,760		
				
<b>Repair Description:</b>				
Replace 18 anchor cables and purchase 1 spare cable.				
<b>COMMENTS</b>				
The bridge has 24 anchor cables that are 3 inches in diameter, of which 18 are 29 years old. These 18 should be programmed for replacement when they reach 30 years old. This project also needs to include the purchase of 1 spare cable in case of a need to replace a cable by an emergency. Cables - An, As, Bs, Dn, Fs, Gn, Gs, Hn, Hs, Jn, Js, L1n, L1s, L2s, Mn, Ms.				
Bridge Item estimate (\$250,000 installation + \$30,000 materials) per cable x 18 cables. = \$5,040,000. Total cost = \$5,891,760				



# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 107 / 4		Structure ID 0005827A		Bridge Name: CHEHALIS R		Milepost: 6.83		Region: Olympic	
Year Built / YR Widened: 1958		Bridge Type: ST CBOX TTT		Bridge Length: 1,302 ft		Bridge Width (curb-curb): 26.0 ft		Sufficiency Rating: 40.45SD	
Average Daily Traffic: 4,392		Truck% 16%		Freight Route		Num of Lanes: 2			
Date Inspected: 3/19/2007		Structr Adequacy: 5		Superstr Code: 6		Safe Load: 5			
Substr Code: 5		Scour: 3		BMS Element Num: 31		BMS Element Descr: Timber Deck			
BMS Element Quantity: 20,226 SF		Project Number: 2011-13 Priority#: 63		Repair Year: 2009-11 Priority#: 73		Bridge \$'s: \$1,600,000			
CPMS Ad Date:		Repair Total\$'s: \$3,200,000							
<b>Repair Description:</b> Remove and replace the timber deck and bridge rails on the timber approach span.									
<b>COMMENTS</b>									
The timber deck has many areas that are deteriorated as evident by the failure in the ACP overlay. The Olympic Region Maintenance office indicates that they have repaired the timber deck in many areas. Four patched areas have replaced 4 deck planks with one 12" x 4" timber. Most spans between the timber piers have cracks in the ACP.									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 153 / 16		Structure ID 0003507A		Bridge Name: METHOW R		Milepost: 16.85		Region: North Central	
Year Built / YR Widened: 1939 / 1949		Bridge Type: CTB		Bridge Length: 454 ft		Bridge Width (curb-curb): 24.0 ft		Sufficiency Rating: 38.67	
Average Daily Traffic: 865		Truck%: 12%		Freight Route		Num of Lanes: 2			
Date Inspected: 9/27/2006		Structr Adequacy: 4		Superstr Code: 6		Safe Load: 5			
Substr Code: 5		Scour: 3		BMS Element Num: 331		BMS Element Descr: Concrete Bridge Rail			
BMS Element Quantity: 908 LF		Project Number:		2011-13 Priority#: 42		2009-11 Priority#: 50			
Repair Year: 2016		Bridge \$'s: \$190,000		Repair Total\$'s: \$275,000		CPMS Ad Date:			
					<p style="text-align: center; font-size: 2em; font-weight: bold; transform: rotate(-5deg);">No Photo Available</p>				
<p><b>Repair Description:</b></p> <p>Remove the concrete baluster bridge rails and replace with a new Thrie Beam rail. Add a new metal pedestrian rail to the sidewalk.</p>									
<p><b>COMMENTS</b></p> <p>The concrete balluster bridge rails are deteriorated with exposed reinforcing steel.</p> <p>The costs and details for the concrete bridge rail replacement should be similar to those used on bridge 153/20 (16315) in 2002.</p>									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 153 / 17		Structure ID 0002450E		Bridge Name: METHOW R		Milepost: 18.91		Region: North Central	
Year Built / YR Widened: 1939		Bridge Type: CTB		Bridge Length: 302 ft		Bridge Width (curb-curb): 24.0 ft		Sufficiency Rating: 49.87	
Average Daily Traffic: 865		Truck% 12%		Freight Route		Num of Lanes: 2			
Date Inspected: 9/27/2006		Structr Adequacy: 5		Superstr Code: 6		Safe Load: 5			
Substr Code: 5		Scour: 5		BMS Element Num: 331		BMS Element Descr: Concrete Bridge Rail			
BMS Element Quantity: 604 LF		Project Number:		2011-13 Priority#: 43		Repair Year: 2016			
CPMS Ad Date:		2009-11 Priority#: 51		Bridge \$'s: \$125,000		Repair Total\$'s: \$185,000			
									
<b>Repair Description:</b> Remove the concrete baluster bridge rails and replace with a new Thrie Beam rail. Add a new metal pedestrian rail to the sidewalk.									
<b>COMMENTS</b>									
The concrete balluster bridge rails are deteriorated with exposed reinforcing steel.  The costs and details for the concrete bridge rail replacement should be similar to those used on bridge 153/20 (16315) in 2002.									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 167 / 32E		Structure ID 0009075D		Bridge Name: VALLEY AVE & UPRR O'XIN		Milepost: 7.22		Region: Olympic	
Year Built / YR Widened: 1973		Bridge Type: PCG		Bridge Length: 925 ft		Bridge Width (curb-curb): 50.5 ft		Sufficiency Rating: 94.49	
Average Daily Traffic: 26,125		Truck% 8%		Freight Route		Num of Lanes: 2			
Date Inspected: 12/12/2006		Structr Adequacy: 7		Superstr Code: 7		Safe Load: 5			
Substr Code: 7		Scour: N		BMS Element Num: 409		BMS Element Descr: Steel Sliding Plate Exp Joint			
BMS Element Quantity: 100		Project Number:		2011-13 Priority#: 48		Repair Year:			
CPMS Ad Date:		2009-11 Priority#: 57		Bridge \$'s: \$100,000		Repair Total\$'s: \$250,000			
									
<b>Repair Description:</b> Replace Expansion joints @ piers 4 and 6.									
<b>COMMENTS</b> Bridge Item cost based on \$1,000 / ft. Total project cost based on \$2,500 / ft.									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 167 / 38		Structure ID 0016597A		Bridge Name: 24TH ST E OVER SR 167		Milepost: 9.61		Region: Olympic	
Year Built / YR Widened: 2004		Bridge Type: PCG		Bridge Length: 382 ft		Bridge Width (curb-curb): 69.8 ft		Sufficiency Rating: 48.22	
Average Daily Traffic: 8,832		Truck% 		Freight Route 		Num of Lanes: 5			
Date Inspected: 11/12/2008		Structr Adequacy: 3		Superstr Code: 3		Safe Load: 5			
Substr Code: 7		Scour: 5							
BMS Element Num: 115		BMS Element Descr: Prestress Concrete Girder		BMS Element Quantity: 134					
Project Number:		2011-13 Priority#: 1		Repair Year: 2011		2009-11 Priority#:			
CPMS Ad Date:		Bridge \$'s: \$500,000		Repair Total\$'s: \$800,000					
									
<b>Repair Description:</b> Replace the south outside prestress girder over the north bound lanes.									
<b>COMMENTS</b>									
The south outside prestress girder over the north bound lanes was damaged by a truck impact on Dec 16 2009. The Bridge Preservation Office has determined that this girder cannot be repaired and needs to be replaced.									


# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 167 / 40E		Structure ID 0010558A		Bridge Name: 8TH ST E O'XING		Milepost: 10.62		Region: Olympic	
Year Built / YR Widened: 1977		Bridge Type: PCG		Bridge Length: 185 ft		Bridge Width (curb-curb): 38.0 ft		Sufficiency Rating: 91.36	
Average Daily Traffic: 26,125		Truck% 8%		Freight Route		Num of Lanes: 2			
Date Inspected: 12/5/2005		Structr Adequacy: 7		Superstr Code: 7		Safe Load: 5			
Substr Code: 7		Scour: N		BMS Element Num: 331		BMS Element Descr: Concrete Bridge Rail			
BMS Element Quantity: 56		Project Number:		2011-13 Priority#: 54		Repair Year:			
CPMS Ad Date:		2009-11 Priority#: 64		Bridge \$'s: \$25,000		Repair Total\$'s: \$50,000			
									
<p><b>Repair Description:</b> Replace 56 feet of bridge rail.</p>									
<p><b>COMMENTS</b></p>									
<p>Southeast six sections of bridge rail has severe exfoliation of top 1 foot, and requires repair/replacement. Also, Northwest end section has severe exfoliation of top 1 foot, and requires repair/replacement. -- (Revised the priority to 2 from 4 per GCS. RLS 12/19/05).</p>									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 195 / 24		Structure ID 000000BI		Bridge Name: S FK PALOUSE R CT HOUSE		Milepost: 38.09		Region: Eastern	
Year Built / YR Widened: 1923		Bridge Type: CTB		Bridge Length: 228 ft		Bridge Width (curb-curb): 56.0 ft		Sufficiency Rating: 31.00 FO	
Average Daily Traffic: Truck%		Freight Route		Num of Lanes:					
11,386				4					
Date Inspected: 10/25/2006		Structr Adequacy: 3							
Superstr Code: 5		Safe Load: 5							
Substr Code: 6		Scour: 8							
BMS Element Num: 110									
BMS Element Descr: Concrete Girder									
BMS Element Quantity: 2,000									
Project Number:		2011-13 Priority#: 55							
Repair Year:		2009-11 Priority#: 65							
CPMS Ad Date:		Bridge \$'s:							
		Repair Total\$'s: \$200,000							
									
<p><b>Repair Description:</b></p> <p>Patch all spalls on the girders, edge beams, and the deck soffit that have exposed rebar. Remove all the loose concrete, clean all the rust off the exposed rebars and concrete grout patch the spall areas.</p>									
<p align="center"><b>COMMENTS</b></p> <p>Active corrosion spalling in the bottom flange of the girders.</p>									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 195 / 27		Structure ID 0001542A		Bridge Name: N FK PALOUSE R		Milepost: 38.50		Region: Eastern	
Year Built / YR Widened: 1931		Bridge Type: CTB		Bridge Length: 240 ft		Bridge Width (curb-curb): 26.0 ft		Sufficiency Rating: 69.15 FO	
Average Daily Traffic: 9,105		Truck% 9%		Freight Route		Num of Lanes: 2			
Date Inspected: 10/26/2006		Structr Adequacy: 6		Superstr Code: 6		Safe Load: 5			
Substr Code: 6		Scour: 8		BMS Element Num: 331		BMS Element Descr: Concrete Bridge Railing			
BMS Element Quantity: 480 LF		Project Number: 2011-13 Priority#: 86		Repair Year: 2009-11 Priority#: 98		Bridge \$'s: \$96,000			
CPMS Ad Date:		Repair Total\$'s: \$200,000							
<p><b>Repair Description:</b> Remove the concrete baluster bridge rails and replace with a new Thrie Beam rail.</p>									
<b>COMMENTS</b>									
<p>The existing concrete rail is cracked and deteriorated.</p> <p>Bridge Item \$ estimate based on \$200 per ft , Total Project \$ estimate based on \$400 per ft.</p>									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 290 / 4.7E-W		Structure ID 0008774C		Bridge Name: 3RD AVE & E-E RAMP OC		Milepost: 1.18		Region: Eastern	
Year Built / YR Widened: 1971		Bridge Type: CBox		Bridge Length: 518 ft		Bridge Width (curb-curb): 38.0 ft		Sufficiency Rating: 87.02	
Average Daily Traffic: 9,000		Truck%		Freight Route		Num of Lanes: 2			
Date Inspected: 9/25/2006		Structr Adequacy: 5		Superstr Code: 5		Safe Load: 5			
Substr Code: 6		Scour: N		BMS Element Num: 105		BMS Element Descr: Concrete Box			
BMS Element Quantity: 10		Project Number:		2011-13 Priority#: 49		Repair Year:			
CPMS Ad Date:		2009-11 Priority#: 58		Bridge \$'s:		Repair Total\$'s: \$400,000			
									
<b>Repair Description:</b> Remove delaminated concrete, clean rusty steel and apply new patching material.									
<b>COMMENTS</b>									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 395 / 40		Structure ID 0004195A		Bridge Name: PIONEER MEM. BR		Milepost: 18.59		Region: South Central	
Year Built / YR Widened: 1954 / 1986		Bridge Type: STrus SG PCS		Bridge Length: 2,521 ft		Bridge Width (curb-curb): 63.3 ft		Sufficiency Rating: 59.21 FO	
Average Daily Traffic: 42,446		Truck%: 7%		Freight Route: T1		Num of Lanes: 4			
Date Inspected: 10/26/2006		Structr Adequacy: 5		Superstr Code: 6		Safe Load: 5			
Substr Code: 6		Scour: 3		BMS Element Num: 416		BMS Element Descr: Modular Expansion Joint			
BMS Element Quantity: 188		Project Number:		2011-13 Priority#: 4		2009-11 Priority#: 7			
Repair Year: 2012		CPMS Ad Date:		Bridge \$'s: \$470,000		Repair Total\$'s: \$940,000			
									
<p><b>Repair Description:</b> Replace modular expansion joints @ 3 locations installed in 1986.</p>									
<p><b>COMMENTS</b></p>									
<p>The SC Region has noted recurring failure with the modular expansion joints on the Blue Bridge. The bolts holding the longitudinal bars to the support bars either shear off or become loose and back out due to wear, age, and obsolete design. Current design on similar joint requires almost twice as many support bars significantly reducing strain on the longitudinal bars. Repairs require the closure of all lanes, either north or south depending on the joint being repaired. The repairs require a UBIT to access the bottom of the joint. Current repair costs are between \$12-20,000 per repair. Since 1992 when the problem was first discovered 8 repairs have been required at the 4 joints. Bridge Item cost based on \$2,500 / ft. Total project cost based on \$5,000 / ft.</p>									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 395 / 40		Structure ID 0004195A		Bridge Name: PIONEER MEM. BR		Milepost: 18.59		Region: South Central	
Year Built / YR Widened: 1954 / 1986		Bridge Type: STrus SG PCS		Bridge Length: 2,521 ft		Bridge Width (curb-curb): 63.3 ft		Sufficiency Rating: 59.21 FO	
Average Daily Traffic: 42,446		Truck%: 7%		Freight Route:		Num of Lanes: 4			
Date Inspected: 10/26/2006		Structr Adequacy: 5		Superstr Code: 6		Safe Load: 5			
Substr Code: 6		Scour: 3		BMS Element Num: 402		BMS Element Descr: Poured Joint Filler			
BMS Element Quantity: 2,089		Project Number:		2011-13 Priority#: 50		Repair Year:			
CPMS Ad Date:		Bridge \$'s: \$156,675		Repair Total\$'s: \$313,350		2009-11 Priority#: 59			
									
<b>Repair Description:</b> Replace poured joint filler in joints through the arch span.									
<b>COMMENTS</b> Bridge Item cost based on \$75 / ft. Total project cost based on \$150 / ft.									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 405 / 70E		Structure ID 0008382A		Bridge Name: SR 522 OC SMMAMISH R		Milepost: 23.53		Region: Northwest			
Year Built / YR Widened: 1968		Bridge Type: CBox		Bridge Length: 1,352 ft		Bridge Width (curb-curb): 40.0 ft		Sufficiency Rating: 69.28 FO			
Average Daily Traffic: 67,000		Truck% 5%		Freight Route T1		Num of Lanes: 3					
Date Inspected: 9/28/2006		Structr Adequacy: 6		Superstr Code: 6		Safe Load: 5					
Substr Code: 7		Scour: 5									
BMS Element Num: 415		BMS Element Descr: <b>Exp Jnt - Rubber Bolt down</b>									
BMS Element Quantity: 200											
Project Number:		2011-13 Priority#:		35							
Repair Year: 2016		2009-11 Priority#:		39							
CPMS Ad Date:		Bridge \$'s:		\$100,000							
		Repair Total\$'s:		\$300,000							
											
<b>Repair Description:</b>											
Replace all rubber bolt down expansion joints. There are rubber bolt down expansion joints at 5 separate locations on the bridge.											
<b>COMMENTS</b>											
These expansion joints were installed in 1985 with the existing concrete overlay. Many sections of the joints are missing or have been repaired by Region Maintenance crews.											
Bridge Item cost based on \$500 / ft. Total project cost based on \$1,500 / ft.											

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 405 / 70N-E		Structure ID 0008382C		Bridge Name: N-E RAMP SMMAMISH R		Milepost: 23.53		Region: Northwest			
Year Built / YR Widened: 1968		Bridge Type: CB <sub>ox</sub>		Bridge Length: 709 ft		Bridge Width (curb-curb): 23.0 ft		Sufficiency Rating: 85.23			
Average Daily Traffic: 15,791		Truck% 5%		Freight Route T1		Num of Lanes: 1					
Date Inspected: 4/18/2006		Structr Adequacy: 6		Superstr Code: 6		Safe Load: 5					
Substr Code: 7		Scour: 5									
BMS Element Num: 415		BMS Element Descr: <b>Exp Jnt - Rubber Bolt down</b>									
BMS Element Quantity: 69											
Project Number:		2011-13 Priority#:		36							
Repair Year: 2016		2009-11 Priority#:		40							
CPMS Ad Date:		Bridge \$'s:		\$34,500							
		Repair Total\$'s:		\$103,500							
											
<p><b>Repair Description:</b> Replace all rubber bolt down expansion joints. There are rubber bolt down expansion joints at 3 separate locations on the bridge.</p>											
<p><b>COMMENTS</b></p>											
<p>These expansion joints were installed in 1985 with the existing concrete overlay. Many sections of the joints are missing or have been repaired by Region Maintenance crews.</p> <p>Bridge Item cost based on \$500 / ft. Total project cost based on \$1,500 / ft.</p>											

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 405 / 70N-W		Structure ID 0008382D		Bridge Name: N-W RAMP SAMMAMISH R		Milepost: 23.53		Region: Northwest			
Year Built / YR Widened: 1968		Bridge Type: CBox		Bridge Length: 1,469 ft		Bridge Width (curb-curb): 24.0 ft		Sufficiency Rating: 90.25 FO			
Average Daily Traffic: 6,569		Truck% 5%		Freight Route T1		Num of Lanes: 1					
Date Inspected: 9/28/2006		Structr Adequacy: 6		Superstr Code: 6		Safe Load: 5					
Substr Code: 7		Scour: 5									
BMS Element Num: 415		BMS Element Descr: <b>Exp Jnt - Rubber Bolt down</b>									
BMS Element Quantity: 120											
Project Number:		2011-13 Priority#:		37							
Repair Year: 2016		2009-11 Priority#:		41							
CPMS Ad Date:		Bridge \$'s:		\$60,000							
		Repair Total\$'s:		\$180,000							
											
<p><b>Repair Description:</b> Replace all rubber bolt down expansion joints. There are rubber bolt down expansion joints at 5 separate locations on the bridge.</p>											
<p><b>COMMENTS</b></p>											
<p>These expansion joints were installed in 1985 with the existing concrete overlay. Many sections of the joints are missing or have been repaired by Region Maintenance crews.</p> <p>Bridge Item cost based on \$500 / ft. Total project cost based on \$1,500 / ft.</p>											


# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 405 / 70S-E		Structure ID 0008382E		Bridge Name: S-E RAMP BR		Milepost: 23.53		Region: Northwest	
Year Built / YR Widened: 1968		Bridge Type: CB <sub>OX</sub>		Bridge Length: 433 ft		Bridge Width (curb-curb): 25.0 ft		Sufficiency Rating: 95.16FO	
Average Daily Traffic: 8,568		Truck% 5%		Freight Route T1		Num of Lanes: 1			
Date Inspected: 10/19/2005		Structr Adequacy: 6		Superstr Code: 6		Safe Load: 5			
Substr Code: 7		Scour: N							
BMS Element Num: 415		BMS Element Descr: <b>Exp Jnt - Rubber Bolt down</b>				BMS Element Quantity: 50			
Project Number:		2011-13 Priority#:		38					
Repair Year: 2016		2009-11 Priority#:		42					
CPMS Ad Date:		Bridge \$'s:		\$25,000					
		Repair Total\$'s:		\$75,000					
									
<p><b>Repair Description:</b> Replace all rubber bolt down expansion joints. There are rubber bolt down expansion joints at 2 separate locations on the bridge.</p>									
<p align="center"><b>COMMENTS</b></p> <p>These expansion joints were installed in 1985 with the existing concrete overlay. Many sections of the joints are missing or have been repaired by Region Maintenance crews.</p> <p>Bridge Item cost based on \$500 / ft. Total project cost based on \$1,500 / ft.</p>									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 405 / 70W		Structure ID 0008382B		Bridge Name: SR 522 OC SAMMAMISH R		Milepost: 23.53		Region: Northwest			
Year Built / YR Widened: 1968		Bridge Type: CB <sub>o</sub> x		Bridge Length: 1,410 ft		Bridge Width (curb-curb): 34.5 ft		Sufficiency Rating: 56.99FO			
Average Daily Traffic: 67,000		Truck% 5%		Freight Route T1		Num of Lanes: 3					
Date Inspected: 9/27/2006		Structr Adequacy: 5		Superstr Code: 7		Safe Load: 5					
Substr Code: 7		Scour: 5									
BMS Element Num: 415		BMS Element Descr: <b>Exp Jnt - Rubber Bolt down</b>									
BMS Element Quantity: 192											
Project Number:		2011-13 Priority#:		39							
Repair Year: 2016		2009-11 Priority#:		43							
CPMS Ad Date:		Bridge \$'s:		\$100,000							
		Repair Total\$'s:		\$288,000							
											
<b>Repair Description:</b>											
Replace all rubber bolt down expansion joints. There are rubber bolt down expansion joints at 5 separate locations on the bridge.											
<b>COMMENTS</b>											
These expansion joints were installed in 1985 with the existing concrete overlay. Many sections of the joints are missing or have been repaired by Region Maintenance crews.											
Bridge Item cost based on \$500 / ft. Total project cost based on \$1,500 / ft.											

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 409 / 10	Structure ID 0002377A	Bridge Name: JULIA BUTLER HANSEN BR	Milepost: 2.92	Region: Southwest
Year Built / YR Widened: 1938 / 1987	Bridge Type: ST PCB SG CTB	Bridge Length: 2,615 ft	Bridge Width (curb-curb): 20.0 ft	Sufficiency Rating: 40.45 FO
Average Daily Traffic: Truck% 2,200	Freight Route	Num of Lanes: 2		
Date Inspected: 12/15/2005	Structr Adequacy: 5			
Superstr Code: 6	Safe Load: 5			
Substr Code: 5	Scour: 5			
BMS Element Num: <b>31</b> BMS Element Descr: <b>Timber Deck</b> BMS Element Quantity: 25,348				
Project Number:	2011-13 Priority#:	<b>64</b>		
Repair Year:	2009-11 Priority#:	<b>74</b>		
CPMS Ad Date:	Bridge \$'s:	<b>\$1,500,000</b>		
	Repair Total\$'s:	<b>\$3,000,000</b>		
				
<b>Repair Description:</b> Replace timber deck on steel truss span.				
<b>COMMENTS</b>				
The Southwest Region Maintenance bridge crews adding steel plates over deteriorated areas in the deck as part of an asphalt repaving project.				


# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 410 / 31	Structure ID 0008746A	Bridge Name: WHITE R (STUCK R)	Milepost: 8.99	Region: Olympic
Year Built / YR Widened: 1971	Bridge Type: PCG CBox	Bridge Length: 442 ft	Bridge Width (curb-curb): 102.0 ft	Sufficiency Rating: 86.46
Average Daily Traffic: 44,586	Truck% 7%	Freight Route	Num of Lanes: 6	
Date Inspected: 8/31/2005	Structr Adequacy: 6	Superstr Code: 6	Safe Load: 5	
Substr Code: 7	Scour: 8			
BMS Element Num: 415	BMS Element Descr: <b>Exp Jnt - Rubber Bolt down</b>			
BMS Element Quantity: 216				
Project Number: 2011-13 Priority#: 56				
Repair Year: 2009-11 Priority#: 66				
CPMS Ad Date: Bridge \$'s: \$108,000				
Repair Total\$'s: \$216,000				
				
<b>Repair Description:</b> Replace rubber bolt down expansion joints.				
<b>COMMENTS</b>				
Bridge Item cost based on \$500 / ft. Total project cost based on \$1,000 / ft.				

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 500 / 6		Structure ID 0009214B		Bridge Name: I-205 OC		Milepost: 4.77		Region: Southwest				
Year Built / YR Widened: 1973		Bridge Type: PTCBox PCG			Bridge Length: 408 ft		Bridge Width (curb-curb): 114.0 ft		Sufficiency Rating: 66.44 FO			
Average Daily Traffic: 38,737		Truck% 5%	Freight Route		Num of Lanes: 7							
Date Inspected: 10/24/2005		Structr Adequacy: 4			Superstr Code: 7					Safe Load: 5		
Substr Code: 7		Scour: N			BMS Element Num: 415					BMS Element Descr: Exp Joint - Rubber Bolt Down		
BMS Element Quantity: 222		Project Number:		2011-13 Priority#: 57		Repair Year:				2009-11 Priority#: 67		
CPMS Ad Date:		Bridge \$'s: \$111,000		Repair Total\$'s: \$222,000								
												
<b>Repair Description:</b> Replace expansion joints.												
<b>COMMENTS</b>												
Bridge Item cost based on \$500 / ft. Total project cost based on \$1,000 / ft.												

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 529 / 15E		Structure ID 0004562A		Bridge Name: UNION SL		Milepost: 5.12		Region: Northwest	
Year Built / YR Widened: 1954		Bridge Type: CTB		Bridge Length: 633 ft		Bridge Width (curb-curb): 28.0 ft		Sufficiency Rating: 55.16FO	
Average Daily Traffic: 11,816		Truck% 5%		Freight Route		Num of Lanes: 2			
Date Inspected: 7/19/2005		Structr Adequacy: 5		Superstr Code: 7		Safe Load: 5			
Substr Code: 5		Scour: 5		BMS Element Num: 227		BMS Element Descr: Concrete Submerged Pile/Column			
BMS Element Quantity: 44		Project Number:		2011-13 Priority#: 65		Repair Year:			
CPMS Ad Date:		2009-11 Priority#: 75		Bridge \$'s: \$3,000,000		Repair Total\$'s: \$3,300,000			
<p><b>Repair Description:</b> Repair deteriorated columns.</p>									
<p><b>COMMENTS</b></p>									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 529 / 15W		Structure ID 0000965B		Bridge Name: UNION SL		Milepost: 5.13		Region: Northwest	
Year Built / YR Widened: 1927		Bridge Type: CTB		Bridge Length: 581 ft		Bridge Width (curb-curb): 24.0 ft		Sufficiency Rating: 40.43SD	
Average Daily Traffic: 11,816		Truck% 5%		Freight Route		Num of Lanes: 2			
Date Inspected: 7/21/2005		Structr Adequacy: 4		Superstr Code: 5		Safe Load: 5			
Substr Code: 4		Scour: 5		BMS Element Num: 227		BMS Element Descr: Concrete Submerged Pile/Column			
BMS Element Quantity:		Project Number:		2011-13 Priority#: 66		Repair Year:			
CPMS Ad Date:		Bridge \$'s: \$3,000,000		Repair Total\$'s: \$3,300,000					
<b>Repair Description:</b> Repair deteriorated columns.									
<b>COMMENTS</b>									
A review of the condition of these columns and a visual inspection indicate that a repair is not required at this time. Monitor condition.									

# Bridge Preservation Program (P2)

# Bridge Repair Form

Bridge Number: 530 / 124		Structure ID 0007733A		Bridge Name: N FK STILLAGUAMISH R		Milepost: 28.78		Region: Northwest	
Year Built / YR Widened: 1966		Bridge Type: SA PCB		Bridge Length: 377 ft		Bridge Width (curb-curb): 26.0 ft		Sufficiency Rating: 55.27 FO	
Average Daily Traffic: 3,729		Truck%: 13%		Freight Route:		Num of Lanes: 2			
Date Inspected: 5/20/2007		Structr Adequacy: 5		Superstr Code: 5		Safe Load: 5			
Substr Code: 7		Scour: 7		BMS Element Num: 356		BMS Element Descr: Steel Stringer			
BMS Element Quantity: 12		Project Number:		2011-13 Priority#: 67		Repair Year:			
CPMS Ad Date:		2009-11 Priority#: 77		Bridge \$'s: \$200,000		Repair Total\$'s: \$400,000			
		<p><b>Repair Description:</b> Repair cracking in stringers.</p>		<b>COMMENTS</b>		Some cracks have been previously repaired by the Region Maintenance.			

## P2 Bridge Preservation - Concrete Deck Repair / Overlay Projects

2011-13 Bien Priority Array

(Sorted by Priority Number)



11-13 #	Bridge Number	Bridge Name	Mile post	Region	Bridge Item\$'s	Total\$'s
2	395/545	COLUMBIA R KETTLE FALLS	241.49	Eastern	\$700,000	\$2,000,000
3	90/78N	SR 18 OC	25.66	Northwest	\$133,768	\$225,400
4	90/156S	DRY CR	104.71	South Central	\$307,153	\$782,092
5	90/126S	BIG CR	75.36	South Central	\$169,830	\$431,146
6	90/150S	TANEUM CR	97.27	South Central	\$144,662	\$414,750
7	90/316N	N PAHA PACKARD RD OC	215.24	Eastern	\$133,685	\$421,509
8	90/156N	DRY CR	104.71	South Central	\$307,153	\$782,092
9	90/120N	YAKIMA R	71.26	South Central	\$487,840	\$1,059,942
10	82/213S	CHANDLER CANAL BRIDGE	81.86	South Central	\$139,798	\$438,075
11	82/110S	EAST SELAH OC	29.02	South Central	\$220,444	\$548,041
12	261/120	TUCANNON R	10.27	South Central	\$151,642	\$469,802
13	12/329	COWICHE CR	199.21	South Central	\$208,720	\$565,887
14	6/123	CHEHALIS R RIVERSIDE	50.94	Southwest	\$205,992	\$347,096
15	5/534S-W	S-W RAMP LUCILE ST OC	161.28	Northwest	\$378,017	\$1,017,057
16	5/534A	N-W RAMP AIRPORT W. OC	161.27	Northwest	\$606,335	\$1,631,347
17	5/534N-W	N-W RAMP RR OC	161.27	Northwest	\$13,442	\$366,660
18	5/536N-W	NB I5 to WB W SEA FRWY	162.98	Northwest	\$815,174	\$2,057,887
19	90/540N	HANGMAN CR	279.49	Eastern	\$1,176,683	\$2,364,939
20	90/540S	HANGMAN CR	279.49	Eastern	\$1,176,683	\$2,364,939
21	203/106	SKYKOMISH R	23.20	Northwest	\$576,380	\$1,223,083
22	90/126N	BIG CR	75.36	South Central	\$104,217	\$312,783
23	90/140N	YAKIMA R	86.20	South Central	\$307,153	\$782,092
24	90/150N	TANEUM CR	97.27	South Central	\$144,662	\$414,750
25	90/152N	WEST SIDE CANAL	100.55	South Central	\$74,931	\$248,640
26	90/152S	WEST SIDE CANAL	100.55	South Central	\$80,910	\$264,904
27	90/162N	WILSON CR	109.13	South Central	\$197,935	\$553,218
28	290/2W-W	2ND AVE OC	0.07	Eastern	\$314,298	\$716,661
29	97/6	SWALE CR	8.08	Southwest	\$110,978	\$330,290
30	195/52	MILW RR OC (CMSTP&P)	63.30	Eastern	\$187,314	\$516,517
31	195/49	PINE CR #1	62.98	Eastern	\$324,233	\$818,149
32	128/10	SNAKE R - RED WOLF BR	0.22	South Central	\$906,946	\$2,102,466
33	9/315	N FK NOOKSACK R U S	78.87	Northwest	\$422,917	\$929,726
34	110/15	BOGACHIEL RIVER	8.64	Olympic	\$191,197	\$572,688
35	82/217	I-82 OC, WINE COUNTRY RD	36.45	South Central	\$398,245	\$1,119,916



## P2 Bridge Preservation - Concrete Deck Repair / Overlay Projects

2011-13 Bien Priority Array

(Sorted by Priority Number)



11-13 #	Bridge Number	Bridge Name	Mile post	Region	Bridge Item\$'s	Total\$'s
36	18/17S	GREEN R (NEELEY BRIDGE)	6.62	Northwest	\$406,047	\$954,562
37	90/118N	KACHESS R	69.49	South Central	\$294,920	\$676,882
38	90/154S	YAKIMA R	102.49	South Central	\$618,666	\$1,302,027
39	82/135N	BNI&UPRR OC	41.53	South Central	\$1,042,137	\$2,044,241
40	203/104	DRAINAGE OVERFLOW	22.05	Northwest	\$87,090	\$289,946
41	82/10S	SR 821 OC THRALL RD	3.22	South Central	\$621,954	\$1,408,614
42	203/3	SLOUGH	0.49	Northwest	\$28,567	\$48,136
43	5/537E-E	6TH-N RAMP BR	162.98	Northwest	\$104,357	\$339,932
44	90/316S	N PAHA PACKARD RD OC	215.24	Eastern	\$133,685	\$421,509
45	24/302	SAGEHILL WASTEWAY	74.15	North Central	\$84,792	\$283,162
46	97/103	SATUS CR 3RD CROSSING	37.54	South Central	\$220,573	\$646,550
47	25/130	COLUMBIA R @ NORTHPORT	113.92	Eastern	\$727,870	\$1,763,641
48	21/224	SINKING CR	85.16	Eastern	\$83,285	\$278,694
49	21/4	SAND HILLS COULEE # 3	2.72	Eastern	\$79,254	\$266,671
50	5/526W	DUWAMISH R BN & UP RR	156.35	Northwest	\$605,568	\$1,020,383
51	5/526E	DUWAMISH R BN & UP RR OC	156.34	Northwest	\$614,843	\$1,036,010
52	5/525.5E	INTERURBAN AVE OC	155.98	Northwest	\$146,584	\$246,994
53	5/417	CLOVER CR	125.64	Olympic	\$679,875	\$1,473,287
54	5/539W	SB VIADUCT STA 2075	162.98	Northwest	\$8,470,588	\$11,848,921
55	5/511W	SR 516 OC	149.17	Northwest	\$210,116	\$354,046
56	432/10S	COWLITZ R & NP RY OC	9.58	Southwest	\$958,036	\$2,199,658
57	90/43S	MERCER SL	9.24	Northwest	\$3,990,926	\$6,674,699
58	90/97.2N	DENNY CRK VIADUCT	50.44	South Central		\$12,235,600
59	18/31N	HOLDER CR HOBART RD OC	20.34	Northwest	\$329,899	\$830,030
60	153/16	METHOW R	16.85	North Central	\$119,781	\$201,830
61	153/17	METHOW R	18.91	North Central	\$82,607	\$139,193
62	153/20	METHOW R	22.31	North Central	\$90,202	\$151,990
99	5/570	LAKE WASH SHIP CANAL	169.63	Northwest		\$35,000,000
99	90/97.8N	FRANKLIN FALLS BR	51.12	South Central		\$2,366,000
99	90/562E-E	E-E RAMP OVER I-90	282.11	Eastern		\$1,670,100
99	182/16N	COL R LEE-VOLPENTEST BR	5.87	South Central		\$6,084,000
99	182/16S	COL R LEE-VOLPENTEST BR	5.87	South Central		\$6,084,000
99	290/1W-W	W-W RAMP OVER SR 290 WB	0.07	Eastern	\$201,400	\$402,800
99	303/12	PORT WASHINGTON CS1840	0.73	Olympic	\$2,358,130	\$4,029,608



## P2 Bridge Preservation - Concrete Deck Repair / Overlay Projects



### 2011-13 Bien Priority Array

(Sorted by Priority Number)



11-13 #	Bridge Number	Bridge Name	Mile post	Region	Bridge Item\$'s	Total\$'s
------------	------------------	-------------	--------------	--------	-----------------	-----------

Total Number of Bridges = 68

Totals \$ =    \$35,211,085    \$133,968,257



## P2 Bridge Preservation - Concrete Deck Repair / Overlay Projects

### 2011-13 Bien Priority Array

(Sorted by Bridge Number)



11-13 #	Bridge Number	Bridge Name	Mile post	Region	Bridge Item\$'s	Total\$'s
53	5/417	CLOVER CR	125.64	Olympic	\$679,875	\$1,473,287
55	5/511W	SR 516 OC	149.17	Northwest	\$210,116	\$354,046
52	5/525.5E	INTERURBAN AVE OC	155.98	Northwest	\$146,584	\$246,994
51	5/526E	DUWAMISH R BN & UP RR OC	156.34	Northwest	\$614,843	\$1,036,010
50	5/526W	DUWAMISH R BN & UP RR	156.35	Northwest	\$605,568	\$1,020,383
16	5/534A	N-W RAMP AIRPORT W. OC	161.27	Northwest	\$606,335	\$1,631,347
17	5/534N-W	N-W RAMP RR OC	161.27	Northwest	\$13,442	\$366,660
15	5/534S-W	S-W RAMP LUCILE ST OC	161.28	Northwest	\$378,017	\$1,017,057
18	5/536N-W	NB I5 to WB W SEA FRWY	162.98	Northwest	\$815,174	\$2,057,887
43	5/537E-E	6TH-N RAMP BR	162.98	Northwest	\$104,357	\$339,932
54	5/539W	SB VIADUCT STA 2075	162.98	Northwest	\$8,470,588	\$11,848,921
99	5/570	LAKE WASH SHIP CANAL	169.63	Northwest		\$35,000,000
14	6/123	CHEHALIS R RIVERSIDE	50.94	Southwest	\$205,992	\$347,096
33	9/315	N FK NOOKSACK R U S	78.87	Northwest	\$422,917	\$929,726
13	12/329	COWICHE CR	199.21	South Central	\$208,720	\$565,887
36	18/17S	GREEN R (NEELEY BRIDGE)	6.62	Northwest	\$406,047	\$954,562
59	18/31N	HOLDER CR HOBART RD OC	20.34	Northwest	\$329,899	\$830,030
49	21/4	SAND HILLS COULEE # 3	2.72	Eastern	\$79,254	\$266,671
48	21/224	SINKING CR	85.16	Eastern	\$83,285	\$278,694
45	24/302	SAGEHILL WASTEWAY	74.15	North Central	\$84,792	\$283,162
47	25/130	COLUMBIA R @ NORTHPORT	113.92	Eastern	\$727,870	\$1,763,641
41	82/10S	SR 821 OC THRALL RD	3.22	South Central	\$621,954	\$1,408,614
11	82/110S	EAST SELAH OC	29.02	South Central	\$220,444	\$548,041
39	82/135N	BNI&UPRR OC	41.53	South Central	\$1,042,137	\$2,044,241
10	82/213S	CHANDLER CANAL BRIDGE	81.86	South Central	\$139,798	\$438,075
35	82/217	I-82 OC, WINE COUNTRY RD	36.45	South Central	\$398,245	\$1,119,916
57	90/43S	MERCER SL	9.24	Northwest	\$3,990,926	\$6,674,699
3	90/78N	SR 18 OC	25.66	Northwest	\$133,768	\$225,400
58	90/97.2N	DENNY CRK VIADUCT	50.44	South Central		\$12,235,600
99	90/97.8N	FRANKLIN FALLS BR	51.12	South Central		\$2,366,000
37	90/118N	KACHESS R	69.49	South Central	\$294,920	\$676,882
9	90/120N	YAKIMA R	71.26	South Central	\$487,840	\$1,059,942
22	90/126N	BIG CR	75.36	South Central	\$104,217	\$312,783
5	90/126S	BIG CR	75.36	South Central	\$169,830	\$431,146



## P2 Bridge Preservation - Concrete Deck Repair / Overlay Projects

### 2011-13 Bien Priority Array

(Sorted by Bridge Number)



11-13 #	Bridge Number	Bridge Name	Mile post	Region	Bridge Item\$'s	Total\$'s
23	90/140N	YAKIMA R	86.20	South Central	\$307,153	\$782,092
24	90/150N	TANEUM CR	97.27	South Central	\$144,662	\$414,750
6	90/150S	TANEUM CR	97.27	South Central	\$144,662	\$414,750
25	90/152N	WEST SIDE CANAL	100.55	South Central	\$74,931	\$248,640
26	90/152S	WEST SIDE CANAL	100.55	South Central	\$80,910	\$264,904
38	90/154S	YAKIMA R	102.49	South Central	\$618,666	\$1,302,027
8	90/156N	DRY CR	104.71	South Central	\$307,153	\$782,092
4	90/156S	DRY CR	104.71	South Central	\$307,153	\$782,092
27	90/162N	WILSON CR	109.13	South Central	\$197,935	\$553,218
7	90/316N	N PAHA PACKARD RD OC	215.24	Eastern	\$133,685	\$421,509
44	90/316S	N PAHA PACKARD RD OC	215.24	Eastern	\$133,685	\$421,509
19	90/540N	HANGMAN CR	279.49	Eastern	\$1,176,683	\$2,364,939
20	90/540S	HANGMAN CR	279.49	Eastern	\$1,176,683	\$2,364,939
99	90/562E-E	E-E RAMP OVER I-90	282.11	Eastern		\$1,670,100
29	97/6	SWALE CR	8.08	Southwest	\$110,978	\$330,290
46	97/103	SATUS CR 3RD CROSSING	37.54	South Central	\$220,573	\$646,550
34	110/15	BOGACHIEL RIVER	8.64	Olympic	\$191,197	\$572,688
32	128/10	SNAKE R - RED WOLF BR	0.22	South Central	\$906,946	\$2,102,466
60	153/16	METHOW R	16.85	North Central	\$119,781	\$201,830
61	153/17	METHOW R	18.91	North Central	\$82,607	\$139,193
62	153/20	METHOW R	22.31	North Central	\$90,202	\$151,990
99	182/16N	COL R LEE-VOLPENTEST BR	5.87	South Central		\$6,084,000
99	182/16S	COL R LEE-VOLPENTEST BR	5.87	South Central		\$6,084,000
31	195/49	PINE CR #1	62.98	Eastern	\$324,233	\$818,149
30	195/52	MILW RR OC (CMSTP&P)	63.30	Eastern	\$187,314	\$516,517
42	203/3	SLOUGH	0.49	Northwest	\$28,567	\$48,136
40	203/104	DRAINAGE OVERFLOW	22.05	Northwest	\$87,090	\$289,946
21	203/106	SKYKOMISH R	23.20	Northwest	\$576,380	\$1,223,083
12	261/120	TUCANNON R	10.27	South Central	\$151,642	\$469,802
99	290/1W-W	W-W RAMP OVER SR 290 WB	0.07	Eastern	\$201,400	\$402,800
28	290/2W-W	2ND AVE OC	0.07	Eastern	\$314,298	\$716,661
99	303/12	PORT WASHINGTON CS1840	0.73	Olympic	\$2,358,130	\$4,029,608
2	395/545	COLUMBIA R KETTLE FALLS	241.49	Eastern	\$700,000	\$2,000,000
56	432/10S	COWLITZ R & NP RY OC	9.58	Southwest	\$958,036	\$2,199,658



## P2 Bridge Preservation - Concrete Deck Repair / Overlay Projects



### 2011-13 Bien Priority Array

(Sorted by Bridge Number)



11-13 #	Bridge Number	Bridge Name	Mile post	Region	Bridge Item\$'s	Total\$'s
---------	---------------	-------------	-----------	--------	-----------------	-----------

Total Number of Bridges = 68

Totals \$ = \$35,211,085 \$133,968,257





BRIDGE NUMBER: 5 / 417	BRIDGE NAME: CLOVER CR	REGION: Olympic	MILEPOST: 125.64
YEAR BUILT / YR WIDENED: 1957	CONTRACT NO.(S): 05523 , 09574 , 12808	SUFFICIENCY RATING: 85.00	
BRIDGE TYPE: CS DECK TYPE: Conc cast-in-place DECK THICKNESS: 13.0 in. (Main Span)	BRIDGE WIDTH (curb-curb): 194.0 ft. BRIDGE LENGTH: 69 ft. AVERAGE DAILY TRAFFIC (ADT): 125,772 NUMBER OF LANES: 10	EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: LMC Overlay Year Applied - 1985 Overlay Thickness - 1.5 inches	
<b>VERTICAL CLEARANCE</b> VC Type: NA			
<b>BRIDGE RAIL</b> BRIDGE RAIL TYPE: WSDOT CODE - 60 New Jersey Barrier RAIL MEETS CURRENT STANDARDS?: YES SIDEWALK / CURB WIDTH: 0.0 Lt 0.0 Rt			
<b>EXPANSION JOINTS</b>		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b> PROTECTIVE OVERLAY RECOMMENDED?: YES TYPE RECOMMENDED: Rapid Set LMC Overlay	
		<b>RESURFACING COMMENT</b> The existing LMC is debonding and breaking up near the ends of the bridge. The Olympic Region Maintenance Office reports that the concrete overlay has debonded in the vicinity of their deck repair areas.  We recommend removing and replacing the existing LMC Overlay with a new 1.0" Polyester or 1.5" Rapid Set Concrete overlay.	
		REVIEWED BY: <i>Bruce Thill</i>	DATE: 2/26/2010



BRIDGE NUMBER: 5 / 511W	BRIDGE NAME: SR 516 OC	REGION: Northwest	MILEPOST: 149.17
YEAR BUILT / YR WIDENED: 1962	CONTRACT NO.(S): 06820 , 15968	SUFFICIENCY RATING: 83.30	
BRIDGE TYPE: PCB DECK TYPE: Conc cast-in-place DECK THICKNESS: 7.0 in. (Main Span)	EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: ACP Overlay Year Applied - 2002		
BRIDGE WIDTH (curb-curb): 71.2 ft. BRIDGE LENGTH: 259 ft. AVERAGE DAILY TRAFFIC (ADT): 94,900 NUMBER OF LANES: 5			
<b>VERTICAL CLEARANCE</b> VC Type: NA			
<b>BRIDGE RAIL</b> BRIDGE RAIL TYPE: WSDOT CODE - 70.6 Conc Base - Type 1B w/Thrie Beam RAIL MEETS CURRENT STANDARDS?: YES SIDEWALK / CURB WIDTH: 0.0 Lt 0.0 Rt			
<b>EXPANSION JOINTS</b> Modifications may be required to accommodate a new overlay.	<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b> PROTECTIVE OVERLAY RECOMMENDED?: YES TYPE RECOMMENDED: HMA Mill Fill 0.08' <b>RESURFACING COMMENT</b> A 1.5" Modified Concrete overlay was specified as part of the widening project in 2002. The Modified Concrete overlay was deleted by change order and an ACP overlay was applied instead. Resurfacing project must remove and replace 0.08' of HMA, using 3/8" aggregate mix.		
	REVIEWED BY: <i>Bruce Thill</i>	DATE: 2/26/2010	



BRIDGE NUMBER: <b>5 / 525.5E</b>	BRIDGE NAME: <b>INTERURBAN AVE OC</b>	REGION: <b>Northwest</b>	MILEPOST: <b>155.98</b>
YEAR BUILT / YR WIDENED: <b>1966</b>	CONTRACT NO.(S): <b>07618,12291,13182,14543</b>	SUFFICIENCY RATING: <b>86.61 FO</b>	
BRIDGE TYPE: <b>PCG</b> DECK TYPE: <b>Conc cast-in-place</b> DECK THICKNESS: <b>7.0 in.</b> <small>(Main Span)</small>		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: <p style="text-align: center;"><b>ACP overlay</b></p> <p style="text-align: center;">Year Applied - 1982</p> <p style="text-align: center;">Overlay Thickness - 1.8 inches</p>	
BRIDGE WIDTH (curb-curb): <b>76.0 ft.</b>	BRIDGE LENGTH: <b>160 ft.</b>		
AVERAGE DAILY TRAFFIC (ADT): <b>84,210</b>	NUMBER OF LANES: <b>5</b>		
<b>VERTICAL CLEARANCE</b>			
VC Type: <b>NA</b>			
<b>BRIDGE RAIL</b>			
BRIDGE RAIL TYPE: <b>WSDOT CODE - 60</b> <b>New Jersey Barrier</b>			
RAIL MEETS CURRENT STANDARDS?: <b>YES</b>	SIDEWALK / CURB WIDTH: <b>0.0 Lt 0.0 Rt</b>		
<b>EXPANSION JOINTS</b>		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b>	
Coordinate with your Region's Maintenance Office to determine if any repairs are required.		PROTECTIVE OVERLAY RECOMMENDED?: <b>YES</b> TYPE RECOMMENDED: <b>HMA Mill Fill 0.08'</b>	
		<b>RESURFACING COMMENT</b>	
		If ride improvement is needed We recommend to remove and replace 0.08' of HMA, using 3/8" aggregate mix.	
		REVIEWED BY: <b><i>Bruce Thill</i></b>	DATE: <b>2/26/2010</b>





BRIDGE NUMBER: 5 / 526W	BRIDGE NAME: DUWAMISH R BN & UP RR	REGION: Northwest	MILEPOST: 156.35
YEAR BUILT / YR WIDENED: 1964 / 1996	CONTRACT NO.(S): 07171,10342,13182,14543	SUFFICIENCY RATING: 71.95 FO	
BRIDGE TYPE: SB CBOX DECK TYPE: Conc cast-in-place DECK THICKNESS: 9.0 in. (Main Span)	BRIDGE WIDTH (curb-curb): 68.0 ft. BRIDGE LENGTH: 812 ft. AVERAGE DAILY TRAFFIC (ADT): 94,276 NUMBER OF LANES: 5	EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: ACP overlay Year Applied - 1986 Overlay Thickness - 1.5 inches	
<b>VERTICAL CLEARANCE</b> VC Type: Minimum VC = 17 FT 03 in			
<b>BRIDGE RAIL</b> BRIDGE RAIL TYPE: WSDOT CODE - 60 New Jersey Barrier RAIL MEETS CURRENT STANDARDS?: YES SIDEWALK / CURB WIDTH: 0.0 Lt 0.0 Rt			
<b>EXPANSION JOINTS</b> Coordinate with your Region's Maintenance Office to determine if any repairs are required.		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b> PROTECTIVE OVERLAY RECOMMENDED?: <b>YES</b> TYPE RECOMMENDED: HMA & Memb	
		<b>RESURFACING COMMENT</b> If asphalt pavement needs replacement, we recommend Removing 1.5" HMA; placing waterproofing membrane; and placing 1.5" of new HMA.	
		REVIEWED BY: <i>Bruce Thill</i>	DATE: 2/26/2010



BRIDGE NUMBER: 5 / 534A	BRIDGE NAME: N-W RAMP AIRPORT W. OC	REGION: Northwest	MILEPOST: 161.27
YEAR BUILT / YR WIDENED: 1967	CONTRACT NO.(S): 07930 , 13737,16695	SUFFICIENCY RATING: 72.51 FO	
BRIDGE TYPE: CBox DECK TYPE: Conc cast-in-place DECK THICKNESS: 7.0 in. (Main Span)	EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: original concrete		
BRIDGE WIDTH (curb-curb): 43.0 ft. BRIDGE LENGTH: 636 ft. AVERAGE DAILY TRAFFIC (ADT): 16,113 NUMBER OF LANES: 3			
<b>VERTICAL CLEARANCE</b> VC Type: NA			
<b>BRIDGE RAIL</b> BRIDGE RAIL TYPE: WSDOT CODE - 73.2 Conc Base - Type R RAIL MEETS CURRENT STANDARDS?: YES SIDEWALK / CURB WIDTH: 1.5 Lt 1.5 Rt			
<b>EXPANSION JOINTS</b> Coordinate with your Region's Maintenance Office to determine if any repairs are required. No modifications required at this time.	<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b> PROTECTIVE OVERLAY RECOMMENDED?: <span style="background-color: green; color: white;">Yes</span> TYPE RECOMMENDED: Mod Conc <b>RESURFACING COMMENT</b> A 3/8 inch polymer overlay was applied in 1990 (Sika-epoxy) and was removed in 2004.  This bridge has nearly 0.5% of the deck with patching and delaminations. In other cases we would wait to schedule a protective overlay until the amount is over 2% but this bridge is connected to Bridge 5/534S-W and 5/534N-W so all three bridges must be included together in the same project.		
	REVIEWED BY: <i>Bruce Thill</i>	DATE: 2/26/2010	



BRIDGE NUMBER: 5 / 534N-W	BRIDGE NAME: N-W RAMP RR OC	REGION: Northwest	MILEPOST: 161.27
YEAR BUILT / YR WIDENED: 1967	CONTRACT NO.(S): 07930 , 13737,16695	SUFFICIENCY RATING: 91.66	
BRIDGE TYPE: CBox DECK TYPE: Conc cast-in-place DECK THICKNESS: 6.5 in. (Main Span)	BRIDGE WIDTH (curb-curb): 21.0 ft. BRIDGE LENGTH: 291 ft. AVERAGE DAILY TRAFFIC (ADT): 4,416 NUMBER OF LANES: 1	EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: original concrete	
<b>VERTICAL CLEARANCE</b> VC Type: NA			
<b>BRIDGE RAIL</b> BRIDGE RAIL TYPE: WSDOT CODE - 73.2 Conc Base - Type R RAIL MEETS CURRENT STANDARDS?: YES SIDEWALK / CURB WIDTH: 1.3 Lt 1.3 Rt			
<b>EXPANSION JOINTS</b> Coordinate with your Region's Maintenance Office to determine if any repairs are required. No modifications required at this time.		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b> PROTECTIVE OVERLAY RECOMMENDED?: <b>Yes</b> TYPE RECOMMENDED: Mod Concrete <b>RESURFACING COMMENT</b> A 3/8 inch polymer overlay was applied in 1990 (Sika-epoxy) and was removed in 2004.  This bridge has nearly 0.5% of the deck with patching and delaminations. In other cases we would wait to schedule a protective overlay until the amount is over 2% but this bridge is connected to Bridge 5/534S-W and 5/534N-W so all three bridges must be included together in the same project.	
REVIEWED BY: <i>Bruce Thill</i>		DATE: 2/26/2010	



BRIDGE NUMBER: 5 / 534S-W	BRIDGE NAME: S-W RAMP LUCILE ST OC	REGION: Northwest	MILEPOST: 161.28
YEAR BUILT / YR WIDENED: 1967	CONTRACT NO.(S): 07930 , 13737	SUFFICIENCY RATING: 76.33 SD	
BRIDGE TYPE: CBox DECK TYPE: Conc cast-in-place DECK THICKNESS: 6.5 in. (Main Span)	BRIDGE WIDTH (curb-curb): 31.0 ft. BRIDGE LENGTH: 550 ft. AVERAGE DAILY TRAFFIC (ADT): 12,901 NUMBER OF LANES: 2	EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: original concrete	
<b>VERTICAL CLEARANCE</b> VC Type: NA			
<b>BRIDGE RAIL</b> BRIDGE RAIL TYPE: WSDOT CODE - 73.2 Conc Base - Type R RAIL MEETS CURRENT STANDARDS?: YES SIDEWALK / CURB WIDTH: 1.5 Lt 1.5 Rt			
<b>EXPANSION JOINTS</b> Coordinate with your Region's Maintenance Office to determine if any repairs are required. No modifications required at this time.		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b> PROTECTIVE OVERLAY RECOMMENDED?: YES TYPE RECOMMENDED: MC Overlay / Hydro <b>RESURFACING COMMENT</b> Deck Rehabilitation: Place 1.5" modified concrete overlay using hydromilling. Expansion Joint modification is required.	
REVIEWED BY: <i>Bruce Thill</i>		DATE: 2/26/2010	



BRIDGE NUMBER: <b>5 / 537E-E</b>	BRIDGE NAME: <b>6TH-N RAMP BR</b>	REGION: <b>Northwest</b>	MILEPOST: <b>162.98</b>
YEAR BUILT / YR WIDENED: <b>1967</b>	CONTRACT NO.(S): <b>07741</b>	SUFFICIENCY RATING: <b>79.53 FO</b>	
BRIDGE TYPE: <b>CBOX CS</b> DECK TYPE: <b>Conc cast-in-place</b> DECK THICKNESS: <b>6.5 in.</b> <small>(Main Span)</small>		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: <b>original concrete</b>	
BRIDGE WIDTH (curb-curb): <b>16.0 ft.</b>	BRIDGE LENGTH: <b>228 ft.</b>		
AVERAGE DAILY TRAFFIC (ADT): <b>5,638</b>	NUMBER OF LANES: <b>1</b>		
<b>VERTICAL CLEARANCE</b>			
VC Type: <b>NA</b>			
<b>BRIDGE RAIL</b>			
BRIDGE RAIL TYPE: <b>WSDOT CODE - 73.2</b> <b>Conc Base - Type R</b>			
RAIL MEETS CURRENT STANDARDS?: <b>YES</b>	SIDEWALK / CURB WIDTH: <b>1.5 Lt 1.5 Rt</b>		
<b>EXPANSION JOINTS</b>		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b>	
		PROTECTIVE OVERLAY RECOMMENDED?: <b>Yes</b>	
		TYPE RECOMMENDED: <b>RSLMC</b>	
		<b>RESURFACING COMMENT</b>	
		The bridge deck has nearly 3% deterioration.	
		We recommend the bridge deck be hydromilled and a rapid set LMC be applied.	
		REVIEWED BY: <b>Bruce Thill</b>	DATE: <b>2/26/2010</b>



BRIDGE NUMBER: <b>5 / 539W</b>	BRIDGE NAME: <b>SB VIADUCT STA 2075</b>	REGION: <b>Northwest</b>	MILEPOST: <b>162.98</b>
YEAR BUILT / YR WIDENED: <b>1967</b>	CONTRACT NO.(S): <b>07741</b>	SUFFICIENCY RATING: <b>64.44</b>	
BRIDGE TYPE: <b>CS</b> DECK TYPE: <b>Conc cast-in-place</b> DECK THICKNESS: <b>18.0 in.</b> <small>(Main Span)</small>		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: <p style="text-align: center;"><b>original concrete</b></p>	
BRIDGE WIDTH (curb-to-curb): <b>68.0 ft.</b> BRIDGE LENGTH: <b>6,622 ft.</b>			
AVERAGE DAILY TRAFFIC (ADT): <b>109,480</b> NUMBER OF LANES: <b>5</b>			
<p style="text-align: center;"><b>VERTICAL CLEARANCE</b></p> VC Type: <p style="text-align: center;"><b>NA</b></p>			
<p style="text-align: center;"><b>BRIDGE RAIL</b></p>			
BRIDGE RAIL TYPE: <b>WSDOT CODE - 60</b> <p style="text-align: center;"><b>New Jersey Barrier</b></p>			
RAIL MEETS CURRENT STANDARDS?: <b>YES</b> SIDEWALK / CURB WIDTH: <b>0.0 Lt 0.0 Rt</b>			
<p style="text-align: center;"><b>EXPANSION JOINTS</b></p> <p>The steel plate expansion joints @ 41 locations need to be replaced (2,660 LF).</p>		<p style="text-align: center;"><b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b></p> PROTECTIVE OVERLAY RECOMMENDED?: <span style="background-color: green; color: white; padding: 2px;"><b>Yes</b></span> TYPE RECOMMENDED: <b>Polyester</b>	
		<p style="text-align: center;"><b>RESURFACING COMMENT</b></p> <p>A new overlay is needed to address the wheel rutting. A 3/4" Polyester overlay is the most likely solution similar to what was done on bridge 5/539E in 2008.</p>	
		REVIEWED BY: <b><i>Bruce Thill</i></b> DATE: <b>2/26/2010</b>	



BRIDGE NUMBER: <b>6 / 123</b>	BRIDGE NAME: <b>CHEHALIS R RIVERSIDE</b>	REGION: <b>Southwest</b>	MILEPOST: <b>50.94</b>
YEAR BUILT / YR WIDENED: <b>1939</b>	CONTRACT NO.(S): <b>02538</b>	SUFFICIENCY RATING: <b>65.43 FO</b>	
BRIDGE TYPE: <b>STrus TTC</b> DECK TYPE: <b>Conc cast-in-place</b> DECK THICKNESS: (Main Span) <b>6.5 in.</b>		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: <b>Original Concrete</b>	
BRIDGE WIDTH (curb-curb): <b>24.0 ft.</b> BRIDGE LENGTH: <b>1,045 ft.</b>			
AVERAGE DAILY TRAFFIC (ADT): <b>11,420</b> NUMBER OF LANES: <b>2</b>			
<b>VERTICAL CLEARANCE</b> VC Type: <b>NA</b>			
<b>BRIDGE RAIL</b> BRIDGE RAIL TYPE: <b>WSDOT CODE - 26</b> <b>Steel Post - Bull Rail</b> RAIL MEETS CURRENT STANDARDS?: <b>NO</b> SIDEWALK / CURB WIDTH: <b>0.6 Lt 3.5 Rt</b>			
<b>EXPANSION JOINTS</b> Coordinate with your Region Bridge Maintenance to determine if any repairs are needed. Std Plan A40.20, Joint Detail 8 applies at the ends and truss joints on the bridge. (Std Item Number 6517)		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b> PROTECTIVE OVERLAY RECOMMENDED?: <b>YES</b> TYPE RECOMMENDED: <b>HMA / membrane</b> <b>RESURFACING COMMENT</b> The west approach spans have an asphalt overlay. The rest of the bridge does not have an overlay.  Resurfacing project should place 0.15' of HMA with waterproofing membrane on the east approach spans and the steel truss span. Raising the steel expansion joints will be required (48 Ft @ \$600/LF). The total HMA thickness must not exceed 0.15' inches.	
REVIEWED BY: <b>Bruce Thill</b>		DATE: <b>2/26/2010</b>	



BRIDGE NUMBER: 9 / 315	BRIDGE NAME: N FK NOOKSACK R U S	REGION: Northwest	MILEPOST: 78.87	
YEAR BUILT / YR WIDENED: 1954	CONTRACT NO.(S): 04542 , 14264	SUFFICIENCY RATING: 45.66 SD		
BRIDGE TYPE: STrus CTB	EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: 3/8" Polymer Overlay Year Applied - 1993 Overlay Thickness - 0.4 inches			
DECK TYPE: Conc cast-in-place				
DECK THICKNESS: (Main Span) 6.5 in.				
BRIDGE WIDTH (curb-curb): 26.0 ft.				BRIDGE LENGTH: 410 ft.
AVERAGE DAILY TRAFFIC (ADT): 1,800				NUMBER OF LANES: 2
<b>VERTICAL CLEARANCE</b>				
VC Type: NA				
<b>BRIDGE RAIL</b>				
BRIDGE RAIL TYPE: WSDOT CODE - 25 Steel Post - Thrie Beam				
RAIL MEETS CURRENT STANDARDS?: YES		SIDEWALK / CURB WIDTH: 2.5 Lt 2.5 Rt		
<b>EXPANSION JOINTS</b>		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b>		
Coordinate with your Region's Maintenance Office to determine if any repairs are required.		PROTECTIVE OVERLAY RECOMMENDED?: <span style="background-color: green; color: white;">Yes</span>		
		TYPE RECOMMENDED: Mod Conc		
		<b>RESURFACING COMMENT</b>		
		A 3/8" Polymer overlay (Degussa-MMA) was applied to the concrete deck in 1993.		
		Bridge Inspection data indicates over 6% of the overlay has deterioration and it is estimated that over 3% of the concrete deck has deterioration.		
		We recommend hydromilling 1" of the existing concrete deck and applying a 1.5" modified concrete overlay.		
		REVIEWED BY: <i>Bruce Thill</i>	DATE: 2/26/2010	



BRIDGE NUMBER: 12 / 329	BRIDGE NAME: COWICHE CR	REGION: South Central	MILEPOST: 199.21
YEAR BUILT / YR WIDENED: 1932	CONTRACT NO.(S): 01603 , 08846 , 16318	SUFFICIENCY RATING: 81.71	
BRIDGE TYPE: CTB DECK TYPE: Conc cast-in-place DECK THICKNESS: 8.0 in. (Main Span)	BRIDGE WIDTH (curb-curb): 84.0 ft. BRIDGE LENGTH: 53 ft. AVERAGE DAILY TRAFFIC (ADT): 19,788 NUMBER OF LANES: 4	EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: Orig with ACP membrane Year Applied - 1972 Overlay Thickness - 3.0 inches	
<b>VERTICAL CLEARANCE</b> VC Type: NA			
<b>BRIDGE RAIL</b> BRIDGE RAIL TYPE: WSDOT CODE - 70.6 Conc Base - Type 1B w/Thrie Beam RAIL MEETS CURRENT STANDARDS?: YES SIDEWALK / CURB WIDTH: 0.1 Lt 0.1 Rt			
<b>EXPANSION JOINTS</b>		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b> PROTECTIVE OVERLAY RECOMMENDED?: YES TYPE RECOMMENDED: MC Overlay / Hydro	
		<b>RESURFACING COMMENT</b> The original structure requires rehabilitation. We recommend a hydromill the original deck and place a modified concrete overlay.	
		REVIEWED BY: <i>Bruce Thill</i>	DATE: 2/26/2010



BRIDGE NUMBER: 18 / 17S	BRIDGE NAME: GREEN R (NEELEY BRIDGE)	REGION: Northwest	MILEPOST: 6.62
YEAR BUILT / YR WIDENED: 1959	CONTRACT NO.(S): 06066 , 14354	SUFFICIENCY RATING: 37.45 SD	
BRIDGE TYPE: STruss CBox DECK TYPE: Conc cast-in-place DECK THICKNESS: 6.5 in. (Main Span)		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: Original Concrete	
BRIDGE WIDTH (curb-curb): 29.5 ft.	BRIDGE LENGTH: 371 ft.		
AVERAGE DAILY TRAFFIC (ADT): 23,922	NUMBER OF LANES: 2		
<p align="center"><b>VERTICAL CLEARANCE</b></p> <p>VC Type: Minimum VC = 14 FT 06 in</p>		<p align="center"><b>BRIDGE RAIL</b></p> <p>BRIDGE RAIL TYPE: WSDOT CODE - 60 New Jersey Barrier</p> <p>RAIL MEETS CURRENT STANDARDS?: YES      SIDEWALK / CURB WIDTH: 0.0 Lt 0.0 Rt</p>	
<p align="center"><b>EXPANSION JOINTS</b></p> <p>Coordinate with the Maintenance office to determine if any repairs are required.</p>			
		<p align="center"><b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b></p> <p>PROTECTIVE OVERLAY RECOMMENDED?: YES</p> <p>TYPE RECOMMENDED: Mod conc</p> <p><b>RESURFACING COMMENT</b></p> <p>A 3/8" Polymer overlay was applied and then removed.</p> <p>Bridge Inspection data indicates nearly 4% of concrete bridge deck has deterioration.</p> <p>We recommend hydromilling 1" of the existing concrete deck and applying a 1.5" modified concrete overlay.</p>	
		REVIEWED BY: <i>Bruce Thill</i>	DATE: 2/26/2010



BRIDGE NUMBER: 18 / 31N	BRIDGE NAME: HOLDER CR HOBART RD OC	REGION: Northwest	MILEPOST: 20.34
YEAR BUILT / YR WIDENED: 1961	CONTRACT NO.(S): 06541 , 13549	SUFFICIENCY RATING: 76.96	
BRIDGE TYPE: CBOX DECK TYPE: Conc cast-in-place DECK THICKNESS: 6.5 in. (Main Span)	BRIDGE WIDTH (curb-curb): 40.3 ft. BRIDGE LENGTH: 304 ft. AVERAGE DAILY TRAFFIC (ADT): 9,000 NUMBER OF LANES: 2	EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: Polyester Overlay Year Applied - 1989 Overlay Thickness - 0.8 inches	
<b>VERTICAL CLEARANCE</b> VC Type: NA			
<b>BRIDGE RAIL</b> BRIDGE RAIL TYPE: WSDOT CODE - 65 Single Slope Barrier RAIL MEETS CURRENT STANDARDS?: YES SIDEWALK / CURB WIDTH: 0.0 Lt 0.0 Rt			
<b>EXPANSION JOINTS</b> Modifications may be required to accommodate the new overlay.		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b> PROTECTIVE OVERLAY RECOMMENDED?: <b>YES</b> TYPE RECOMMENDED: Mod Concrete <b>RESURFACING COMMENT</b> The existing 3/4" Polyester is developing pot holes above the existing patch locations.  We recommend removing the existing overlay with a rotomill, hydromill for deck preparation, and replacing it with a modified concrete overlay.	
REVIEWED BY: <i>Bruce Thill</i>		DATE: 2/26/2010	



BRIDGE NUMBER: <b>21 / 4</b>	BRIDGE NAME: <b>SAND HILLS COULEE # 3</b>	REGION: <b>Eastern</b>	MILEPOST: <b>2.72</b>
YEAR BUILT / YR WIDENED: <b>1963</b>	CONTRACT NO.(S): <b>07173</b>	SUFFICIENCY RATING: <b>82.22</b>	
BRIDGE TYPE: <b>CS</b> DECK TYPE: <b>Conc cast-in-place</b> DECK THICKNESS: <b>12.3 in.</b> <small>(Main Span)</small>  BRIDGE WIDTH (curb-curb): <b>24.0 ft.</b> BRIDGE LENGTH: <b>85 ft.</b>  AVERAGE DAILY TRAFFIC (ADT): <b>224</b> NUMBER OF LANES: <b>2</b>		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: <p style="text-align: center;"><b>original concrete</b></p>	
<p style="text-align: center;"><b>VERTICAL CLEARANCE</b></p> VC Type:  <p style="text-align: center;"><b>NA</b></p>			
<p style="text-align: center;"><b>BRIDGE RAIL</b></p> BRIDGE RAIL TYPE: <b>WSDOT CODE - 25</b> <p style="text-align: center;"><b>Steel Post - Thrie Beam</b></p> RAIL MEETS CURRENT STANDARDS?: <b>YES</b> SIDEWALK / CURB WIDTH: <b>0.7 Lt 0.7 Rt</b>			
<p style="text-align: center;"><b>EXPANSION JOINTS</b></p>		<p style="text-align: center;"><b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b></p> PROTECTIVE OVERLAY RECOMMENDED?: <span style="background-color: green; color: white; padding: 2px;"><b>Yes</b></span> TYPE RECOMMENDED: <b>Mod Concrete</b>	
		<p><b>RESURFACING COMMENT</b></p> <p>The bridge deck has nearly 2% deterioration. The bridge deck needs to be repaired and then a 1.5" modified concrete overlay applied.</p>	
		REVIEWED BY: <p style="text-align: center;"><i>Bruce Thill</i></p>	DATE: <p style="text-align: center;"><b>2/26/2010</b></p>



BRIDGE NUMBER: 21 / 224	BRIDGE NAME: SINKING CR	REGION: Eastern	MILEPOST: 85.16
YEAR BUILT / YR WIDENED: 1950	CONTRACT NO.(S): 03714	SUFFICIENCY RATING: 83.08	
BRIDGE TYPE: CS DECK TYPE: Conc cast-in-place DECK THICKNESS: 12.0 in. (Main Span)		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: original concrete	
BRIDGE WIDTH (curb-curb): 26.0 ft.	BRIDGE LENGTH: 82 ft.		
AVERAGE DAILY TRAFFIC (ADT): 268	NUMBER OF LANES: 2		
<b>VERTICAL CLEARANCE</b>			
VC Type: NA			
<b>BRIDGE RAIL</b>			
BRIDGE RAIL TYPE: WSDOT CODE - 41 Balluster Rail	RAIL MEETS CURRENT STANDARDS?: NO	SIDEWALK / CURB WIDTH: 1.1 Lt 1.1 Rt	
<b>EXPANSION JOINTS</b>		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b>	
		PROTECTIVE OVERLAY RECOMMENDED?: <b>YES</b>	
		TYPE RECOMMENDED: HMA with membrane	
		<b>RESURFACING COMMENT</b>	
		Bridge Inspections indicate significant deck deterioration.	
		We recommend 0.25' of HMA w/waterproofing membrane be added to this bridge.	
		REVIEWED BY: <i>Bruce Thill</i>	DATE: 2/26/2010



BRIDGE NUMBER: <p style="text-align: center; font-size: 1.2em;">24 / 302</p>	BRIDGE NAME: <p style="text-align: center;">SAGEHILL WASTEWAY</p>	REGION: <p style="text-align: center;">North Central</p>	MILEPOST: <p style="text-align: center;">74.15</p>
YEAR BUILT / YR WIDENED: <p style="text-align: center;">1965</p>	CONTRACT NO.(S): <p style="text-align: center;">07703</p>	SUFFICIENCY RATING: <p style="text-align: center;">81.35 SD</p>	
BRIDGE TYPE: CS DECK TYPE: Conc cast-in-place DECK THICKNESS: 17.0 in. <small>(Main Span)</small>  BRIDGE WIDTH (curb-curb): 36.5 ft. BRIDGE LENGTH: 46 ft.  AVERAGE DAILY TRAFFIC (ADT): 3,892 NUMBER OF LANES: 2		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: <p style="text-align: center; font-size: 1.2em;">original concrete</p>	
<p style="text-align: center;"><b>VERTICAL CLEARANCE</b></p> VC Type: <p style="text-align: center;">NA</p>			
<p style="text-align: center;"><b>BRIDGE RAIL</b></p> BRIDGE RAIL TYPE: WSDOT CODE - 73.2 <p style="text-align: center;">Conc Base - Type R</p> RAIL MEETS CURRENT STANDARDS?: YES SIDEWALK / CURB WIDTH: 0.7 Lt 0.7 Rt			
<p style="text-align: center;"><b>EXPANSION JOINTS</b></p>		<p style="text-align: center;"><b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b></p> PROTECTIVE OVERLAY RECOMMENDED?: <span style="background-color: #90EE90;">Yes</span> TYPE RECOMMENDED: ACP w/Memb	
		<p><b>RESURFACING COMMENT</b></p> <p>The bridge deck has nearly 2% deterioration. We recommend the deck be patched and a membrane and 0.25' of HMA be applied.</p>	
		REVIEWED BY: <i>Bruce Thill</i> DATE: 2/26/2010	



BRIDGE NUMBER: 25 / 130	BRIDGE NAME: COLUMBIA R @ NORTHPORT	REGION: Eastern	MILEPOST: 113.92
YEAR BUILT / YR WIDENED: 1948	CONTRACT NO.(S): 03297	SUFFICIENCY RATING: 39.73 SD	
BRIDGE TYPE: ST CTB CG CS DECK TYPE: Conc cast-in-place DECK THICKNESS: 6.5 in. (Main Span)	EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: original concrete		
BRIDGE WIDTH (curb-curb): 24.0 ft. BRIDGE LENGTH: 1,540 ft. AVERAGE DAILY TRAFFIC (ADT): 750 NUMBER OF LANES: 2			
<b>VERTICAL CLEARANCE</b> VC Type: NA			
<b>BRIDGE RAIL</b> BRIDGE RAIL TYPE: WSDOT CODE - 25 Steel Post - Thrie Beam RAIL MEETS CURRENT STANDARDS?: YES SIDEWALK / CURB WIDTH: 3.0 Lt 3.0 Rt			
<b>EXPANSION JOINTS</b> Coordinate with you Maintenance Office to determine if any repairs are necessary.	<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b> PROTECTIVE OVERLAY RECOMMENDED?: <b>YES</b> TYPE RECOMMENDED: MC Overlay / Hydro <b>RESURFACING COMMENT</b> Bridge Inspections indicate significant deck deterioration.  A new 1.5" modified concrete overlay is required to rehabilitate the deck. A Hydromilling machine should be used to scarify the bridge deck. This bridge is on the P2 Program Deck priority array.		
	REVIEWED BY: <i>Bruce Thill</i>	DATE: 2/26/2010	



BRIDGE NUMBER: 82 / 10S	BRIDGE NAME: SR 821 OC THRALL RD	REGION: South Central	MILEPOST: 3.22
YEAR BUILT / YR WIDENED: 1970	CONTRACT NO.(S): 08672 , 12857 , 16531	SUFFICIENCY RATING: 91.18 SD	
BRIDGE TYPE: PCG DECK TYPE: Conc cast-in-place DECK THICKNESS: 9.5 in. (Main Span)	BRIDGE WIDTH (curb-curb): 53.2 ft. BRIDGE LENGTH: 357 ft. AVERAGE DAILY TRAFFIC (ADT): 8,040 NUMBER OF LANES: 3	EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: Original Concrete	
<b>VERTICAL CLEARANCE</b> VC Type: NA			
<b>BRIDGE RAIL</b> BRIDGE RAIL TYPE: WSDOT CODE - 73.2 Conc Base - Type R RAIL MEETS CURRENT STANDARDS?: YES SIDEWALK / CURB WIDTH: 0.7 Lt 0.7 Rt			
<b>EXPANSION JOINTS</b> Compression seals at the ends of the bridge may need to be replaced.		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b> PROTECTIVE OVERLAY RECOMMENDED?: YES TYPE RECOMMENDED: MC Overlay / Mill Hydro <b>RESURFACING COMMENT</b> A 3 inch reinforced concrete overlay was added to the existing 6.5 inch concrete deck during the original construction in 1970 due to problems with the original deck. The polymer overlay was added in 1985 as an experiment and removed by contract in 2003.  We recommend placing a 1.5" modified concrete overlay by rotomilling 1" and hydromilling 0.5".	
REVIEWED BY: <i>Bruce Thill</i>		DATE: 2/26/2010	



BRIDGE NUMBER: <b>82 / 110S</b>	BRIDGE NAME: <b>EAST SELAH OC</b>	REGION: <b>South Central</b>	MILEPOST: <b>29.02</b>
YEAR BUILT / YR WIDENED: <b>1967</b>	CONTRACT NO.(S): <b>08089</b>	SUFFICIENCY RATING: <b>92.06</b>	
BRIDGE TYPE: <b>CS</b> DECK TYPE: <b>Conc cast-in-place</b> DECK THICKNESS: <b>18.0 in.</b> <small>(Main Span)</small>		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: <b>original concrete</b>	
BRIDGE WIDTH (curb-curb): <b>36.5 ft.</b>	BRIDGE LENGTH: <b>104 ft.</b>		
AVERAGE DAILY TRAFFIC (ADT): <b>9,192</b>	NUMBER OF LANES: <b>2</b>		
<b>VERTICAL CLEARANCE</b>			
VC Type: <b>NA</b>			
<b>BRIDGE RAIL</b>			
BRIDGE RAIL TYPE: <b>WSDOT CODE - 73.2</b> <b>Conc Base - Type R</b>			
RAIL MEETS CURRENT STANDARDS?: <b>YES</b>		SIDEWALK / CURB WIDTH: <b>0.8 Lt 0.8 Rt</b>	
<b>EXPANSION JOINTS</b>		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b>	
Coordinate with your Region's Maintenance Office to determine if any repairs are required.		PROTECTIVE OVERLAY RECOMMENDED?: <b>Yes</b> TYPE RECOMMENDED: <b>Mod Conc</b>	
		<b>RESURFACING COMMENT</b> Bridge Inspection results indicate nearly 3.6% of the existing concrete deck is deteriorated.  We recommend hydromilling and applying a 1.5" modified concrete overlay.	
REVIEWED BY: <b><i>Bruce Thill</i></b>		DATE: <b>2/26/2010</b>	



BRIDGE NUMBER: <b>82 / 135N</b>	BRIDGE NAME: <b>BNI&amp;UPRR OC</b>	REGION: <b>South Central</b>	MILEPOST: <b>41.53</b>
YEAR BUILT / YR WIDENED: <b>1979</b>	CONTRACT NO.(S): <b>11449</b>	SUFFICIENCY RATING: <b>88.77 SD</b>	
BRIDGE TYPE: <b>PCG</b> DECK TYPE: <b>Conc cast-in-place</b> DECK THICKNESS: (Main Span) <b>7.0 in.</b> BRIDGE WIDTH (curb-curb): <b>38.0 ft.</b> BRIDGE LENGTH: <b>920 ft.</b> AVERAGE DAILY TRAFFIC (ADT): <b>11,689</b> NUMBER OF LANES: <b>2</b>		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: <b>Original Conc. &amp; ECR</b>	
<b>VERTICAL CLEARANCE</b> VC Type: <b>NA</b>			
<b>BRIDGE RAIL</b> BRIDGE RAIL TYPE: <b>WSDOT CODE - 60</b> <b>New Jersey Barrier</b> RAIL MEETS CURRENT STANDARDS?: <b>YES</b> SIDEWALK / CURB WIDTH: <b>0.0 Lt 0.0 Rt</b>			
<b>EXPANSION JOINTS</b>  Coordinate with your Region's Maintenance Office to determine if any repairs are required.		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b> PROTECTIVE OVERLAY RECOMMENDED?: <b>Yes</b> TYPE RECOMMENDED: <b>Mod Conc</b>  <b>RESURFACING COMMENT</b> Bridge Inspection results indicate nearly 2.5% of the existing concrete deck is deteriorated.  We recommend hydromilling and applying a 1.5" modified concrete overlay.	
REVIEWED BY: <b>Bruce Thill</b>		DATE: <b>2/26/2010</b>	



BRIDGE NUMBER: 82 / 213S		BRIDGE NAME: CHANDLER CANAL BRIDGE		REGION: South Central		MILEPOST: 81.86	
YEAR BUILT / YR WIDENED: 1977		CONTRACT NO.(S): 10534			SUFFICIENCY RATING: 94.23 SD		
BRIDGE TYPE: PCG DECK TYPE: Conc cast-in-place DECK THICKNESS: 0.0 in. (Main Span)				EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: original concrete			
BRIDGE WIDTH (curb-to-curb): 38.0 ft.		BRIDGE LENGTH: 113 ft.					
AVERAGE DAILY TRAFFIC (ADT): 7,714		NUMBER OF LANES: 2					
<b>VERTICAL CLEARANCE</b> VC Type: NA							
<b>BRIDGE RAIL</b> BRIDGE RAIL TYPE: WSDOT CODE - 60 New Jersey Barrier RAIL MEETS CURRENT STANDARDS?: YES SIDEWALK / CURB WIDTH: 0.0 Lt 0.0 Rt							
<b>EXPANSION JOINTS</b>				<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b> PROTECTIVE OVERLAY RECOMMENDED?: <b>YES</b> TYPE RECOMMENDED: MC Overlay / Hydro			
				<b>RESURFACING COMMENT</b> Bridge Inspection reports indicate the deck is more than 5% deteriorated.  We recommend 0.5" scarification by hydromilling and placing 1.5" modified concrete overlay.			
				REVIEWED BY: <i>Bruce Thill</i>		DATE: 2/26/2010	



BRIDGE NUMBER: <b>82 / 217</b>	BRIDGE NAME: <b>I-82 OC, WINE COUNTRY RD</b>	REGION: <b>South Central</b>	MILEPOST: <b>82.34</b>
YEAR BUILT / YR WIDENED: <b>1978</b>	CONTRACT NO.(S): <b>10534</b>	SUFFICIENCY RATING: <b>97.00 SD</b>	
BRIDGE TYPE: <b>PCG</b> DECK TYPE: <b>Conc cast-in-place</b> DECK THICKNESS: <b>7.5 in.</b> (Main Span)	EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: <b>original concrete</b>		
BRIDGE WIDTH (curb-curb): <b>47.1 ft.</b>	BRIDGE LENGTH: <b>368 ft.</b>		
AVERAGE DAILY TRAFFIC (ADT): <b>6,620</b>	NUMBER OF LANES: <b>2</b>		
<b>VERTICAL CLEARANCE</b>			
VC Type: <b>NA</b>			
<b>BRIDGE RAIL</b>			
BRIDGE RAIL TYPE: <b>WSDOT CODE - 60</b> <b>New Jersey Barrier</b>			
RAIL MEETS CURRENT STANDARDS?: <b>YES</b>	SIDEWALK / CURB WIDTH: <b>0.0 Lt 0.0 Rt</b>		
<b>EXPANSION JOINTS</b>		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b>	
		PROTECTIVE OVERLAY RECOMMENDED?: <b>YES</b> TYPE RECOMMENDED: <b>MC Overlay / Hydro</b>	
		<b>RESURFACING COMMENT</b> Bridge Inspection reports indicate the deck is more than 5% deteriorated.  We recommend 0.5" scarification by hydromilling and placing 1.5" modified concrete overlay.	
		REVIEWED BY: <b>Bruce Thill</b>	DATE: <b>2/26/2010</b>



BRIDGE NUMBER: <b>90 / 43S</b>	BRIDGE NAME: <b>MERCER SL</b>	REGION: <b>Northwest</b>	MILEPOST: <b>9.24</b>
YEAR BUILT / YR WIDENED: <b>1970</b>	CONTRACT NO.(S): <b>08610 , 13846</b>	SUFFICIENCY RATING: <b>68.64 FO</b>	
BRIDGE TYPE: <b>CBox CS</b> DECK TYPE: <b>Conc cast-in-place</b> DECK THICKNESS: <b>7.2 in.</b> (Main Span)		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: <b>original concrete</b>	
BRIDGE WIDTH (curb-curb): <b>73.5 ft.</b>	BRIDGE LENGTH: <b>2,669 ft.</b>		
AVERAGE DAILY TRAFFIC (ADT): <b>60,204</b>	NUMBER OF LANES: <b>5</b>		
<b>VERTICAL CLEARANCE</b>			
VC Type: <b>NA</b>			
<b>BRIDGE RAIL</b>			
BRIDGE RAIL TYPE: <b>WSDOT CODE - 73.2</b> <b>Conc Base - Type R</b>	RAIL MEETS CURRENT STANDARDS?: <b>YES</b>	SIDEWALK / CURB WIDTH: <b>0.8 Lt 0.8 Rt</b>	
<b>EXPANSION JOINTS</b>		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b>	
Coordinate with your Region's Maintenance Office to determine if any repairs are required.		PROTECTIVE OVERLAY RECOMMENDED?: <b>YES</b> TYPE RECOMMENDED: To Be Determined	
		<b>RESURFACING COMMENT</b> Deck protection is required due to the amount of exposed reinforcing steel in the bridge deck.  The type of overlay will be determined during the project design phase. The overlay will likely be either a 3/4" Polyester or a hydromill and 1.5" Rapid Set LMC.	
		REVIEWED BY: <b>Bruce Thill</b>	DATE: <b>2/26/2010</b>



BRIDGE NUMBER: 90 / 78N	BRIDGE NAME: I-90 OVER SR 18	REGION: Northwest	MILEPOST: 25.55
YEAR BUILT / YR WIDENED: 1963	CONTRACT NO.(S): 06966 , 13941	SUFFICIENCY RATING: 89.88 SD	
BRIDGE TYPE: PCG DECK TYPE: Conc cast-in-place DECK THICKNESS: 5.8 in. (Main Span)	BRIDGE WIDTH (curb-curb): 70.0 ft. BRIDGE LENGTH: 158 ft. AVERAGE DAILY TRAFFIC (ADT): 19,068 NUMBER OF LANES: 4	EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: MMC Overlay Year Applied - 1991 Overlay Thickness - 6.0 inches	
<b>VERTICAL CLEARANCE</b> VC Type: NA			
<b>BRIDGE RAIL</b> BRIDGE RAIL TYPE: WSDOT CODE - 60 New Jersey Barrier RAIL MEETS CURRENT STANDARDS?: YES SIDEWALK / CURB WIDTH: 0.0 Lt 0.0 Rt			
<b>EXPANSION JOINTS</b> Coordinate with your Region's Maintenance Office to determine if any repairs are required.		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b> PROTECTIVE OVERLAY RECOMMENDED?: <b>YES</b> TYPE RECOMMENDED: HMA mill only <b>RESURFACING COMMENT</b> We recommend removing the 2"-6" concrete overlay and placing HMA with membrane. The deck is in good condition.  ACP overlay was removed and replaced with 2"-6" MMC in 1991 widening project. The MMC overlay is too thick. Overlay has fractured into large pieces and has significant rutting at the joint headers.  The Load Rating includes up to 6" of additional overlay Dead Load.	
REVIEWED BY: <i>Bruce Thill</i>		DATE: 2/26/2010	



BRIDGE NUMBER: 90 / 97.2N	BRIDGE NAME: DENNY CRK VIADUCT	REGION: South Central	MILEPOST: 50.44
YEAR BUILT / YR WIDENED: 1981	CONTRACT NO.(S): 10200 , 11882	SUFFICIENCY RATING: 78.55	
BRIDGE TYPE: POBX DECK TYPE: Conc cast-in-place DECK THICKNESS: 10.0 in. <small>(Main Span)</small> BRIDGE WIDTH (curb-curb): 52.0 ft. BRIDGE LENGTH: 3,620 ft. AVERAGE DAILY TRAFFIC (ADT): 15,279 NUMBER OF LANES: 3		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: LMC Overlay Year Applied - 1980 Overlay Thickness - 1.5 inches	
<b>VERTICAL CLEARANCE</b> VC Type: NA			
<b>BRIDGE RAIL</b> BRIDGE RAIL TYPE: WSDOT CODE - 60 New Jersey Barrier RAIL MEETS CURRENT STANDARDS?: YES SIDEWALK / CURB WIDTH: 0.0 Lt 0.0 Rt			
<b>EXPANSION JOINTS</b> Coordinate with your Region's Maintenance Office to determine if any repairs are required.		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b> PROTECTIVE OVERLAY RECOMMENDED?: Yes TYPE RECOMMENDED: Mod Conc <b>RESURFACING COMMENT</b> Bridge Inspection results indicate nearly 1.0% of the existing concrete deck is deteriorated. We recommend hydromilling and applying a 1.5" modified concrete overlay.	
REVIEWED BY: <i>Bruce Thill</i>		DATE: 2/26/2010	



BRIDGE NUMBER: 90 / 118N	BRIDGE NAME: KACHESS R	REGION: South Central	MILEPOST: 69.49
YEAR BUILT / YR WIDENED: 1958	CONTRACT NO.(S): 05702 , 12857	SUFFICIENCY RATING: 92.30	
BRIDGE TYPE: CVS DECK TYPE: Conc cast-in-place DECK THICKNESS: 23.0 in. (Main Span)	BRIDGE WIDTH (curb-curb): 38.0 ft. BRIDGE LENGTH: 150 ft. AVERAGE DAILY TRAFFIC (ADT): 14,037 NUMBER OF LANES: 2	EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: LMC Overlay Year Applied - 1985 Overlay Thickness - 1.5 inches	
<b>VERTICAL CLEARANCE</b> VC Type: NA			
<b>BRIDGE RAIL</b> BRIDGE RAIL TYPE: WSDOT CODE - 60 New Jersey Barrier RAIL MEETS CURRENT STANDARDS?: YES SIDEWALK / CURB WIDTH: 0.0 Lt 0.0 Rt			
<b>EXPANSION JOINTS</b>		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b> PROTECTIVE OVERLAY RECOMMENDED?: YES TYPE RECOMMENDED: MC Overlay / Hydro <b>RESURFACING COMMENT</b> Bridge Inspection reports indicate the deck overlay is deteriorated.  A P2 project will remove the LMC overlay by 1" rotomill, 0.5" scarification by hydromilling and placing 1.5" modified concrete overlay. Rapid Set LMC may be considered to minimize traffic closure.	
REVIEWED BY: <i>Bruce Thill</i>		DATE: 2/26/2010	



BRIDGE NUMBER: <b>90 / 120N</b>	BRIDGE NAME: <b>YAKIMA R</b>	REGION: <b>South Central</b>	MILEPOST: <b>71.26</b>
YEAR BUILT / YR WIDENED: <b>1959</b>	CONTRACT NO.(S): <b>05872 , 12857 , 14902</b>	SUFFICIENCY RATING: <b>88.53 SD</b>	
BRIDGE TYPE: <b>CBox</b> DECK TYPE: <b>Conc cast-in-place</b> DECK THICKNESS: <b>6.5 in.</b> <small>(Main Span)</small>		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: <p style="text-align: center;"><b>LMC Overlay</b></p> <p style="text-align: center;">Year Applied - 1985</p> <p style="text-align: center;">Overlay Thickness - 1.5 inches</p>	
BRIDGE WIDTH (curb-curb): <b>39.3 ft.</b>	BRIDGE LENGTH: <b>317 ft.</b>		
AVERAGE DAILY TRAFFIC (ADT): <b>13,826</b>	NUMBER OF LANES: <b>2</b>		
<b>VERTICAL CLEARANCE</b>			
VC Type:  <b>NA</b>			
<b>BRIDGE RAIL</b>			
BRIDGE RAIL TYPE: <b>WSDOT CODE - 60</b> <b>New Jersey Barrier</b>			
RAIL MEETS CURRENT STANDARDS?: <b>YES</b>	SIDEWALK / CURB WIDTH: <b>0.0 Lt 0.0 Rt</b>		
<b>EXPANSION JOINTS</b>		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b>	
Coordinate with your Region's Maintenance Office to determine if any repairs are required.		PROTECTIVE OVERLAY RECOMMENDED?: <b>Yes</b> TYPE RECOMMENDED: Mod Conc	
		<b>RESURFACING COMMENT</b> Bridge Inspection results indicate nearly 8.0% of the existing concrete overlay and deck is deteriorated.  We recommend removing the existing LMC and using a hydromill and applying a 1.5" modified concrete overlay.	
		REVIEWED BY: <b>Bruce Thill</b> DATE: <b>2/26/2010</b>	



BRIDGE NUMBER: 90 / 126N	BRIDGE NAME: BIG CR	REGION: South Central	MILEPOST: 75.36
YEAR BUILT / YR WIDENED: 1962	CONTRACT NO.(S): 07016 , 12459 , 15306	SUFFICIENCY RATING: 93.62 SD	
BRIDGE TYPE: CS DECK TYPE: Conc cast-in-place DECK THICKNESS: in. (Main Span) BRIDGE WIDTH (curb-curb): 38.0 ft. BRIDGE LENGTH: 55 ft. AVERAGE DAILY TRAFFIC (ADT): 13,822 NUMBER OF LANES: 2	EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: Low Slump Mod Conc Year Applied - 1983 Overlay Thickness - 2.0 inches		
<b>VERTICAL CLEARANCE</b> VC Type: NA			
<b>BRIDGE RAIL</b> BRIDGE RAIL TYPE: WSDOT CODE - 70.6 Conc Base - Type 1B w/Thrie Beam RAIL MEETS CURRENT STANDARDS?: YES SIDEWALK / CURB WIDTH: 0.0 Lt 0.0 Rt			
<b>EXPANSION JOINTS</b>	<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b> PROTECTIVE OVERLAY RECOMMENDED?: <span style="background-color: green; color: white;">Yes</span> TYPE RECOMMENDED: Mod Conc <b>RESURFACING COMMENT</b> Bridge Inspection results indicate nearly 9.0% of the existing concrete overlay and deck is deteriorated.  We recommend removing the existing LMC and using a hydromill and applying a 1.5" modified concrete overlay.		
	REVIEWED BY: <i>Bruce Thill</i>	DATE: 2/26/2010	



BRIDGE NUMBER: <b>90 / 126S</b>	BRIDGE NAME: <b>BIG CR</b>	REGION: <b>South Central</b>	MILEPOST: <b>75.36</b>
YEAR BUILT / YR WIDENED: <b>1973</b>	CONTRACT NO.(S): <b>09428</b>	SUFFICIENCY RATING: <b>92.62 SD</b>	
BRIDGE TYPE: <b>CS</b> DECK TYPE: <b>Conc cast-in-place</b> DECK THICKNESS: <b>in.</b> <small>(Main Span)</small> BRIDGE WIDTH (curb-curb): <b>38.0 ft.</b> BRIDGE LENGTH: <b>55 ft.</b> AVERAGE DAILY TRAFFIC (ADT): <b>13,822</b> NUMBER OF LANES: <b>2</b>		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: <b>original concrete</b>	
<b>VERTICAL CLEARANCE</b> VC Type: <b>NA</b>			
<b>BRIDGE RAIL</b> BRIDGE RAIL TYPE: <b>WSDOT CODE - 63</b> <b>New Jersey - Type R</b> RAIL MEETS CURRENT STANDARDS?: <b>YES</b> SIDEWALK / CURB WIDTH: <b>0.0 Lt 0.0 Rt</b>			
<b>EXPANSION JOINTS</b>		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b> PROTECTIVE OVERLAY RECOMMENDED?: <b>YES</b> TYPE RECOMMENDED: <b>Rapid Set LMC Overlay</b> <b>RESURFACING COMMENT</b> Bridge Inspection reports indicate the deck is over 5% deteriorated.  We recommend 0.5" scarification by hydromilling and placing 1.5" modified concrete overlay.	
REVIEWED BY: <b>Bruce Thill</b>		DATE: <b>2/26/2010</b>	



BRIDGE NUMBER: <b>90 / 140N</b>	BRIDGE NAME: <b>YAKIMA R</b>	REGION: <b>South Central</b>	MILEPOST: <b>86.20</b>
YEAR BUILT / YR WIDENED: <b>1965</b>	CONTRACT NO.(S): <b>07582 , 13438 , 15306</b>	SUFFICIENCY RATING: <b>81.50</b>	
BRIDGE TYPE: <b>CBOX</b> DECK TYPE: <b>Conc cast-in-place</b> DECK THICKNESS: <b>6.5 in.</b> <small>(Main Span)</small>		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: <b>LMC Overlay</b> Year Applied - 1989 Overlay Thickness - 1.5 inches	
BRIDGE WIDTH (curb-curb): <b>30.0 ft.</b>	BRIDGE LENGTH: <b>390 ft.</b>		
AVERAGE DAILY TRAFFIC (ADT): <b>12,827</b>	NUMBER OF LANES: <b>2</b>		
<b>VERTICAL CLEARANCE</b>			
VC Type: <b>NA</b>			
<b>BRIDGE RAIL</b>			
BRIDGE RAIL TYPE: <b>WSDOT CODE - 70.6</b> <b>Conc Base - Type 1B w/Thrie Beam</b>			
RAIL MEETS CURRENT STANDARDS?: <b>YES</b>		SIDEWALK / CURB WIDTH: <b>0.0 Lt 0.0 Rt</b>	
<b>EXPANSION JOINTS</b>		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b>	
Coordinate with your Region's Maintenance Office to determine if any repairs are required.		PROTECTIVE OVERLAY RECOMMENDED?: <b>Yes</b> TYPE RECOMMENDED: Mod conc	
		<b>RESURFACING COMMENT</b> Bridge Inspection results indicate nearly 5.0% of the existing concrete overlay and deck is deteriorated.  We recommend removing the existing LMC and using a hydromill and applying a 1.5" modified concrete overlay.	
REVIEWED BY: <b><i>Bruce Thill</i></b>		DATE: <b>2/26/2010</b>	



BRIDGE NUMBER: <b>90 / 150N</b>	BRIDGE NAME: <b>TANEUM CR</b>	REGION: <b>South Central</b>	MILEPOST: <b>97.27</b>
YEAR BUILT / YR WIDENED: <b>1965</b>	CONTRACT NO.(S): <b>07724 , 14902</b>	SUFFICIENCY RATING: <b>91.74 SD</b>	
BRIDGE TYPE: <b>PCB</b> DECK TYPE: <b>Conc cast-in-place</b> DECK THICKNESS: <b>5.8 in.</b> (Main Span)		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: <b>Low Slump Mod Conc</b> <b>Year Applied - 1983</b> <b>Overlay Thickness - 2.0 inches</b>	
BRIDGE WIDTH (curb-curb): <b>36.5 ft.</b>	BRIDGE LENGTH: <b>108 ft.</b>		
AVERAGE DAILY TRAFFIC (ADT): <b>12,472</b>	NUMBER OF LANES: <b>2</b>		
<b>VERTICAL CLEARANCE</b>			
VC Type: <b>NA</b>			
<b>BRIDGE RAIL</b>			
BRIDGE RAIL TYPE: <b>WSDOT CODE - 73.2</b> <b>Conc Base - Type R</b>			
RAIL MEETS CURRENT STANDARDS?: <b>YES</b>	SIDEWALK / CURB WIDTH: <b>0.8 Lt 0.8 Rt</b>		
<b>EXPANSION JOINTS</b>		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b>	
		PROTECTIVE OVERLAY RECOMMENDED?: <b>YES</b> TYPE RECOMMENDED: <b>MC Overlay / Hydro</b>	
		<b>RESURFACING COMMENT</b> Bridge Inspection reports indicate the deck overlay is more than 10% deteriorated.  We recommend 1.0" rotomill, 0.5" scarification by hydromilling and placing 1.5" modified concrete overlay.	
		REVIEWED BY: <b><i>Bruce Thill</i></b>	DATE: <b>2/26/2010</b>



BRIDGE NUMBER: <b>90 / 150S</b>	BRIDGE NAME: <b>TANEUM CR</b>	REGION: <b>South Central</b>	MILEPOST: <b>97.27</b>
YEAR BUILT / YR WIDENED: <b>1965</b>	CONTRACT NO.(S): <b>07724 , 14902</b>	SUFFICIENCY RATING: <b>90.74 SD</b>	
BRIDGE TYPE: <b>PCG</b> DECK TYPE: <b>Conc cast-in-place</b> DECK THICKNESS: <b>5.8 in.</b> <small>(Main Span)</small> BRIDGE WIDTH (curb-curb): <b>36.5 ft.</b> BRIDGE LENGTH: <b>108 ft.</b> AVERAGE DAILY TRAFFIC (ADT): <b>12,472</b> NUMBER OF LANES: <b>2</b>		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: <p style="text-align: center;"> <b>Low Slump Mod Conc</b>            Year Applied - 1983            Overlay Thickness - 2.0 inches         </p>	
<b>VERTICAL CLEARANCE</b> VC Type: <p style="text-align: center;"><b>NA</b></p>			
<b>BRIDGE RAIL</b> BRIDGE RAIL TYPE: <b>WSDOT CODE - 73.2</b> <b>Conc Base - Type R</b> RAIL MEETS CURRENT STANDARDS?: <b>YES</b> SIDEWALK / CURB WIDTH: <b>0.8 Lt 0.8 Rt</b>			
<b>EXPANSION JOINTS</b>		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b> PROTECTIVE OVERLAY RECOMMENDED?: <b>YES</b> TYPE RECOMMENDED: <b>MC Overlay / Hydro</b> <b>RESURFACING COMMENT</b> Bridge Inspection reports indicate the deck overlay is more than 10% deteriorated.  We recommend 1.0" rotomill, 0.5" scarification by hydromilling and placing 1.5" modified concrete overlay.	
REVIEWED BY: <p style="text-align: center;"><i>Bruce Thill</i></p>		DATE: <p style="text-align: center;"><b>2/26/2010</b></p>	



BRIDGE NUMBER: <b>90 / 152N</b>	BRIDGE NAME: <b>WEST SIDE CANAL</b>	REGION: <b>South Central</b>	MILEPOST: <b>100.55</b>
YEAR BUILT / YR WIDENED: <b>1966</b>	CONTRACT NO.(S): <b>07904 , 12459</b>	SUFFICIENCY RATING: <b>88.69 SD</b>	
BRIDGE TYPE: <b>CS</b> DECK TYPE: <b>Conc cast-in-place</b> DECK THICKNESS: <b>12.0 in.</b> <small>(Main Span)</small>		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: <b>Low Slump Mod Conc</b> <b>Year Applied - 1983</b> <b>Overlay Thickness - 2.0 inches</b>	
BRIDGE WIDTH (curb-curb): <b>36.5 ft.</b>	BRIDGE LENGTH: <b>31 ft.</b>		
AVERAGE DAILY TRAFFIC (ADT): <b>12,472</b>	NUMBER OF LANES: <b>2</b>		
<b>VERTICAL CLEARANCE</b>			
VC Type: <b>NA</b>			
<b>BRIDGE RAIL</b>			
BRIDGE RAIL TYPE: <b>WSDOT CODE - 73.2</b> <b>Conc Base - Type R</b>			
RAIL MEETS CURRENT STANDARDS?: <b>YES</b>	SIDEWALK / CURB WIDTH: <b>0.7 Lt 0.7 Rt</b>		
<b>EXPANSION JOINTS</b>		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b>	
		PROTECTIVE OVERLAY RECOMMENDED?: <b>YES</b> TYPE RECOMMENDED: <b>MC Overlay / Hydro</b>	
		<b>RESURFACING COMMENT</b> Bridge Inspection reports indicate the deck overlay is more than 10% deteriorated.  We recommend 1.0" rotomill, 0.5" scarification by hydromilling and placing 1.5" modified concrete overlay.	
		REVIEWED BY: <b><i>Bruce Thill</i></b>	DATE: <b>2/26/2010</b>



BRIDGE NUMBER: <b>90 / 152S</b>	BRIDGE NAME: <b>WEST SIDE CANAL</b>	REGION: <b>South Central</b>	MILEPOST: <b>100.55</b>
YEAR BUILT / YR WIDENED: <b>1966</b>	CONTRACT NO.(S): <b>07904 , 12459</b>	SUFFICIENCY RATING: <b>86.66 SD</b>	
BRIDGE TYPE: <b>CS</b> DECK TYPE: <b>Conc cast-in-place</b> DECK THICKNESS: <b>12.0 in.</b> (Main Span)	BRIDGE WIDTH (curb-curb): <b>36.5 ft.</b> BRIDGE LENGTH: <b>38 ft.</b> AVERAGE DAILY TRAFFIC (ADT): <b>12,472</b> NUMBER OF LANES: <b>2</b>	EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: <b>Low Slump Mod Conc</b> <b>Year Applied - 1983</b> <b>Overlay Thickness - 2.0 inches</b>	
<b>VERTICAL CLEARANCE</b> VC Type: <b>NA</b>			
<b>BRIDGE RAIL</b> BRIDGE RAIL TYPE: <b>WSDOT CODE - 73.2</b> <b>Conc Base - Type R</b> RAIL MEETS CURRENT STANDARDS?: <b>YES</b> SIDEWALK / CURB WIDTH: <b>0.5 Lt 0.5 Rt</b>			
<b>EXPANSION JOINTS</b>		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b> PROTECTIVE OVERLAY RECOMMENDED?: <b>YES</b> TYPE RECOMMENDED: <b>MC Overlay / Hydro</b> <b>RESURFACING COMMENT</b> <b>Exclude this bridge from resurfacing projects.</b>	
REVIEWED BY: <b>Bruce Thill</b>		DATE: <b>2/26/2010</b>	



BRIDGE NUMBER: <b>90 / 154S</b>	BRIDGE NAME: <b>YAKIMA R</b>	REGION: <b>South Central</b>	MILEPOST: <b>102.49</b>
YEAR BUILT / YR WIDENED: <b>1967</b>	CONTRACT NO.(S): <b>08010 , 12857 , 14632</b>	SUFFICIENCY RATING: <b>79.43</b>	
BRIDGE TYPE: <b>CBOX</b> DECK TYPE: <b>Conc cast-in-place</b> DECK THICKNESS: <b>6.5 in.</b> <small>(Main Span)</small>		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: <p style="text-align: center;"><b>LMC Overlay</b>          Year Applied - 1985          Overlay Thickness - 1.5 inches</p>	
BRIDGE WIDTH (curb-curb): <b>30.0 ft.</b>	BRIDGE LENGTH: <b>595 ft.</b>		
AVERAGE DAILY TRAFFIC (ADT): <b>13,390</b>	NUMBER OF LANES: <b>2</b>		
<b>VERTICAL CLEARANCE</b>			
VC Type: <b>NA</b>			
<b>BRIDGE RAIL</b>			
BRIDGE RAIL TYPE: <b>WSDOT CODE - 73.2</b>	<b>Conc Base - Type R</b>		
RAIL MEETS CURRENT STANDARDS?: <b>YES</b>	SIDEWALK / CURB WIDTH: <b>1.5 Lt 1.5 Rt</b>		
<b>EXPANSION JOINTS</b>		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b>	
Coordinate with your Region's Maintenance Office to determine if any repairs are required.		PROTECTIVE OVERLAY RECOMMENDED?: <span style="background-color: green; color: white; padding: 2px;">Yes</span> TYPE RECOMMENDED: Mod Conc  <b>RESURFACING COMMENT</b> Bridge Inspection results indicate nearly 2.0% of the existing concrete overlay and deck is deteriorated.  We recommend removing the existing LMC and using a hydromill and applying a 1.5" modified concrete overlay.	
REVIEWED BY: <b><i>Bruce Thill</i></b>		DATE: <b>2/26/2010</b>	



BRIDGE NUMBER: 90 / 156N	BRIDGE NAME: DRY CR	REGION: South Central	MILEPOST: 104.71
YEAR BUILT / YR WIDENED: 1967	CONTRACT NO.(S): 08036 , 13131 , 15126	SUFFICIENCY RATING: 76.31 SD	
BRIDGE TYPE: CBOX DECK TYPE: Conc cast-in-place DECK THICKNESS: 6.5 in. (Main Span) BRIDGE WIDTH (curb-curb): 30.0 ft. BRIDGE LENGTH: 390 ft. AVERAGE DAILY TRAFFIC (ADT): 13,390 NUMBER OF LANES: 2		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: LMC Overlay Year Applied - 1986 Overlay Thickness - 1.5 inches	
<b>VERTICAL CLEARANCE</b> VC Type: NA			
<b>BRIDGE RAIL</b> BRIDGE RAIL TYPE: WSDOT CODE - 73.2 Conc Base - Type R RAIL MEETS CURRENT STANDARDS?: YES SIDEWALK / CURB WIDTH: 1.4 Lt 1.4 Rt			
<b>EXPANSION JOINTS</b>		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b> PROTECTIVE OVERLAY RECOMMENDED?: <b>YES</b> TYPE RECOMMENDED: MC Overlay / Hydro <b>RESURFACING COMMENT</b> Bridge Inspection reports indicate the deck overlay is more than 10% deteriorated.  We recommend 1.0" rotomill, 0.5" scarification by hydromilling and placing 1.5" modified concrete overlay.	
		REVIEWED BY: <i>Bruce Thill</i>	DATE: 2/26/2010





BRIDGE NUMBER: <b>90 / 316N</b>	BRIDGE NAME: <b>N PAHA PACKARD RD OC</b>	REGION: <b>Eastern</b>	MILEPOST: <b>215.24</b>
YEAR BUILT / YR WIDENED: <b>1972</b>	CONTRACT NO.(S): <b>09206</b>	SUFFICIENCY RATING: <b>93.53 SD</b>	
BRIDGE TYPE: <b>PCB</b> DECK TYPE: <b>Conc cast-in-place</b> DECK THICKNESS: <b>7.0 in.</b> <small>(Main Span)</small>		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: <b>original concrete</b>	
BRIDGE WIDTH (curb-curb): <b>38.0 ft.</b>	BRIDGE LENGTH: <b>105 ft.</b>		
AVERAGE DAILY TRAFFIC (ADT): <b>4,700</b>	NUMBER OF LANES: <b>2</b>		
<b>VERTICAL CLEARANCE</b>			
VC Type: <b>NA</b>			
<b>BRIDGE RAIL</b>			
BRIDGE RAIL TYPE: <b>WSDOT CODE - 73.2</b> <b>Conc Base - Type R</b>			
RAIL MEETS CURRENT STANDARDS?: <b>YES</b>		SIDEWALK / CURB WIDTH: <b>0.7 Lt 0.7 Rt</b>	
<b>EXPANSION JOINTS</b>		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b>	
		PROTECTIVE OVERLAY RECOMMENDED?: <b>YES</b> TYPE RECOMMENDED: <b>MC Overlay / Hydro</b>	
		<b>RESURFACING COMMENT</b> A chain drag survey was completed in 10/2001 and found 4.1% of the deck has delaminations. Bridge Inspections indicate significant deck deterioration.  A new 1.5" modified concrete overlay is required to rehabilitate the deck. A Hydromilling machine should be used to scarify the bridge deck. This bridge is on the P2 Program Deck priority array.	
REVIEWED BY: <b>Bruce Thill</b>		DATE: <b>2/26/2010</b>	



BRIDGE NUMBER: <b>90 / 316S</b>	BRIDGE NAME: <b>N PAHA PACKARD RD OC</b>	REGION: <b>Eastern</b>	MILEPOST: <b>215.24</b>
YEAR BUILT / YR WIDENED: <b>1972</b>	CONTRACT NO.(S): <b>09206</b>	SUFFICIENCY RATING: <b>95.51 SD</b>	
BRIDGE TYPE: <b>PCB</b> DECK TYPE: <b>Conc cast-in-place</b> DECK THICKNESS: <b>7.0 in.</b> <small>(Main Span)</small> BRIDGE WIDTH (curb-curb): <b>38.0 ft.</b> BRIDGE LENGTH: <b>105 ft.</b> AVERAGE DAILY TRAFFIC (ADT): <b>5,013</b> NUMBER OF LANES: <b>2</b>		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: <p style="text-align: center;"><b>original concrete</b></p> <p style="text-align: center;">Overlay Thickness - 1.5 inches</p>	
<p style="text-align: center;"><b>VERTICAL CLEARANCE</b></p> VC Type: <p style="text-align: center;"><b>NA</b></p>			
<p style="text-align: center;"><b>BRIDGE RAIL</b></p> BRIDGE RAIL TYPE: <b>WSDOT CODE - 73.2</b> <p style="text-align: center;"><b>Conc Base - Type R</b></p> RAIL MEETS CURRENT STANDARDS?: <b>YES</b> SIDEWALK / CURB WIDTH: <b>0.7 Lt 0.7 Rt</b>			
<p style="text-align: center;"><b>EXPANSION JOINTS</b></p>		<p style="text-align: center;"><b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b></p> PROTECTIVE OVERLAY RECOMMENDED?: <b>YES</b> TYPE RECOMMENDED: <b>MC Overlay / Hydro</b>	
		<p><b>RESURFACING COMMENT</b></p> <p>A chain drag survey was completed in 10/2001 and found 2.1% of the deck has delaminations. Bridge Inspections indicate significant deck deterioration.</p> <p>A new 1.5" modified concrete overlay is required to rehabilitate the deck. Remove and replace 1.5" LMC overlay by milling 1" and hydromill 0.5". This bridge is on the P2 Deck Program priority array.</p>	
		REVIEWED BY: <b><i>Bruce Thill</i></b>	DATE: <b>2/26/2010</b>



BRIDGE NUMBER: <b>90 / 512N</b>	BRIDGE NAME: <b>BN RR OC (NP)</b>	REGION: <b>Eastern</b>	MILEPOST: <b>270.10</b>
YEAR BUILT / YR WIDENED: <b>1966</b>	CONTRACT NO.(S): <b>07903 , 12136</b>	SUFFICIENCY RATING: <b>95.17 SD</b>	
BRIDGE TYPE: <b>PCB</b> DECK TYPE: <b>Conc cast-in-place</b> DECK THICKNESS: <b>7.0 in.</b> (Main Span)		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: <b>LMC Overlay</b> <b>Year Applied - 1981</b> <b>Overlay Thickness - 1.5 inches</b>	
BRIDGE WIDTH (curb-curb): <b>36.5 ft.</b>	BRIDGE LENGTH: <b>150 ft.</b>		
AVERAGE DAILY TRAFFIC (ADT): <b>8,400</b>	NUMBER OF LANES: <b>2</b>		
<b>VERTICAL CLEARANCE</b>			
VC Type: <b>NA</b>			
<b>BRIDGE RAIL</b>			
BRIDGE RAIL TYPE: <b>WSDOT CODE - 73.2</b> <b>Conc Base - Type R</b>	RAIL MEETS CURRENT STANDARDS?: <b>YES</b>	SIDEWALK / CURB WIDTH: <b>0.7 Lt 0.7 Rt</b>	
<b>EXPANSION JOINTS</b>		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b>	
		PROTECTIVE OVERLAY RECOMMENDED?: <b>YES</b> TYPE RECOMMENDED: <b>MC Overlay / Mill &amp; Hydro</b>	
		<b>RESURFACING COMMENT</b> Bridge Inspections indicate significant deck deterioration. There are areas in the overlay that have debonded and are now patched.  We recommend removing and replacing the 1.5" LMC overlay by milling 1" and hydromilling 0.5" of overlay. This bridge is on the P2 Deck Program priority array.	
		REVIEWED BY: <b>Bruce Thill</b>	DATE: <b>2/26/2010</b>



BRIDGE NUMBER: <b>90 / 512S</b>	BRIDGE NAME: <b>BN RR OC (NP)</b>	REGION: <b>Eastern</b>	MILEPOST: <b>270.10</b>
YEAR BUILT / YR WIDENED: <b>1966</b>	CONTRACT NO.(S): <b>07903 , 12136</b>	SUFFICIENCY RATING: <b>92.13 SD</b>	
BRIDGE TYPE: <b>PCB</b> DECK TYPE: <b>Conc cast-in-place</b> DECK THICKNESS: <b>7.0 in.</b> (Main Span)	BRIDGE WIDTH (curb-curb): <b>36.5 ft.</b> BRIDGE LENGTH: <b>150 ft.</b> AVERAGE DAILY TRAFFIC (ADT): <b>8,672</b> NUMBER OF LANES: <b>2</b>	EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: <b>LMC Overlay</b> <b>Year Applied - 1981</b> <b>Overlay Thickness - 1.5 inches</b>	
<b>VERTICAL CLEARANCE</b> VC Type: <b>NA</b>			
<b>BRIDGE RAIL</b> BRIDGE RAIL TYPE: <b>WSDOT CODE - 73.2</b> <b>Conc Base - Type R</b> RAIL MEETS CURRENT STANDARDS?: <b>YES</b> SIDEWALK / CURB WIDTH: <b>0.7 Lt 0.7 Rt</b>			
<b>EXPANSION JOINTS</b>		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b> PROTECTIVE OVERLAY RECOMMENDED?: <b>YES</b> TYPE RECOMMENDED: <b>MC Overlay / Mill &amp; Hydro</b>	
		<b>RESURFACING COMMENT</b> Bridge Inspections indicate significant deck deterioration. There are areas in the overlay that have debonded and are now patched.  We recommend removing and replacing the 1.5" LMC overlay by milling 1" and hydromilling 0.5" of overlay. This bridge is on the P2 Deck Program priority array.	
REVIEWED BY: <b>Bruce Thill</b>		DATE: <b>2/26/2010</b>	



BRIDGE NUMBER: <b>90 / 540N</b>	BRIDGE NAME: <b>HANGMAN CR</b>	REGION: <b>Eastern</b>	MILEPOST: <b>279.49</b>
YEAR BUILT / YR WIDENED: <b>1963</b>	CONTRACT NO.(S): <b>06579 , 12842</b>	SUFFICIENCY RATING: <b>65.39</b>	
BRIDGE TYPE: <b>CBox</b> DECK TYPE: <b>Conc cast-in-place</b> DECK THICKNESS: <b>8.0 in.</b> (Main Span)		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: <b>LMC Overlay</b> <b>Year Applied - 1985</b> <b>Overlay Thickness - 1.5 inches</b>	
BRIDGE WIDTH (curb-curb): <b>44.0 ft.</b>	BRIDGE LENGTH: <b>1,222 ft.</b>		
AVERAGE DAILY TRAFFIC (ADT): <b>40,141</b>	NUMBER OF LANES: <b>3</b>		
<b>VERTICAL CLEARANCE</b>			
VC Type: <b>NA</b>			
<b>BRIDGE RAIL</b>			
BRIDGE RAIL TYPE: <b>WSDOT CODE - 25</b> <b>Steel Post - Thrie Beam</b>			
RAIL MEETS CURRENT STANDARDS?: <b>YES</b>	SIDEWALK / CURB WIDTH: <b>1.5 Lt 1.5 Rt</b>		
<b>EXPANSION JOINTS</b>		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b>	
Coordinate with your Region's Maintenance Office to determine if any repairs are required.		PROTECTIVE OVERLAY RECOMMENDED?: <b>YES</b> TYPE RECOMMENDED: <b>MC Overlay / Hydro</b>	
		<b>RESURFACING COMMENT</b> The LMC Overlay is rutted to a depth of 1/2 inch or greater in the center lane.  We recommend removing and replacing the 1.5" LMC overlay by milling 1" and hydromilling 0.5" of overlay. This bridge is on the P2 Deck Program priority array.  The cost of removing and replacing the existing LMC will be affected by the type of new overlay to be used (modified Conc or Polyester).	
		REVIEWED BY: <b>Bruce Thill</b>	DATE: <b>2/26/2010</b>



BRIDGE NUMBER: <b>90 / 540S</b>	BRIDGE NAME: <b>HANGMAN CR</b>	REGION: <b>Eastern</b>	MILEPOST: <b>279.49</b>
YEAR BUILT / YR WIDENED: <b>1963</b>	CONTRACT NO.(S): <b>06579 , 12842</b>	SUFFICIENCY RATING: <b>54.04 FO</b>	
BRIDGE TYPE: <b>CBox</b> DECK TYPE: <b>Conc cast-in-place</b> DECK THICKNESS: <b>8.0 in.</b> (Main Span)		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: <b>LMC Overlay</b> <b>Year Applied - 1985</b> <b>Overlay Thickness - 1.5 inches</b>	
BRIDGE WIDTH (curb-curb): <b>44.0 ft.</b>	BRIDGE LENGTH: <b>1,222 ft.</b>		
AVERAGE DAILY TRAFFIC (ADT): <b>41,300</b>	NUMBER OF LANES: <b>4</b>		
<b>VERTICAL CLEARANCE</b> VC Type: <b>NA</b>		<p><b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b></p> <p>PROTECTIVE OVERLAY RECOMMENDED?: <b>YES</b></p> <p>TYPE RECOMMENDED: MC Overlay / Hydro</p> <p><b>RESURFACING COMMENT</b></p> <p>The LMC Overlay is rutted to a depth of 1/2 inch or greater in the center lane.</p> <p>We recommend removing and replacing the 1.5" LMC overlay by milling 1" and hydromilling 0.5" of overlay. This bridge is on the P2 Deck Program priority array.</p> <p>The cost of removing and replacing the existing LMC will be affected by the type of new overlay to be used (modified Conc or Polyester).</p>	
<b>BRIDGE RAIL</b> BRIDGE RAIL TYPE: <b>WSDOT CODE - 70.4</b> <b>Conc Base - Type 1B</b> RAIL MEETS CURRENT STANDARDS?: <b>NO</b>			
<b>EXPANSION JOINTS</b>  Coordinate with your Region's Maintenance Office to determine if any repairs are required.		<p>SIDEWALK / CURB WIDTH: <b>1.5 Lt 1.5 Rt</b></p>	
		REVIEWED BY: <b>Bruce Thill</b>	DATE: <b>2/26/2010</b>



BRIDGE NUMBER: <b>90 / 566</b>	BRIDGE NAME: <b>ALTAMONT ST OC</b>	REGION: <b>Eastern</b>	MILEPOST: <b>283.03</b>
YEAR BUILT / YR WIDENED: <b>1957</b>	CONTRACT NO.(S): <b>05453 , 12748</b>	SUFFICIENCY RATING: <b>82.00 SD</b>	
BRIDGE TYPE: <b>CS</b> DECK TYPE: <b>Conc cast-in-place</b> DECK THICKNESS: <b>18.0 in.</b> (Main Span)		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: <b>LMC Overlay</b> <b>Year Applied - 1984</b> <b>Overlay Thickness - 1.5 inches</b>	
BRIDGE WIDTH (curb-curb): <b>104.0 ft.</b>	BRIDGE LENGTH: <b>66 ft.</b>		
AVERAGE DAILY TRAFFIC (ADT): <b>107,710</b>	NUMBER OF LANES: <b>6</b>		
<b>VERTICAL CLEARANCE</b>			
VC Type: <b>NA</b>			
<b>BRIDGE RAIL</b>		<p><b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b></p> <p>PROTECTIVE OVERLAY RECOMMENDED?: <b>YES</b></p> <p>TYPE RECOMMENDED: Rapid Set LMC Overlay</p> <p><b>RESURFACING COMMENT</b></p> <p>There are areas in the LMC overlay that are debonded and are now patched. We recommend removing and replacing the LMC overlay with a 1" Polyester or Rapid Set concrete overlay. This bridge is on the P2 Program Priority Array for a Concrete Overlay.</p> <p>Region may provide a temporary 1.5" Asphalt Overlay and Standard Plan A7 details (see Expansion Joints).</p>	
BRIDGE RAIL TYPE: <b>WSDOT CODE - 60</b> <b>New Jersey Barrier</b>			
RAIL MEETS CURRENT STANDARDS?: <b>YES</b>	SIDEWALK / CURB WIDTH: <b>0.0 Lt 0.0 Rt</b>		
<b>EXPANSION JOINTS</b>			
<p>If the Region chooses to provide temporary Asphalt Overlay, Standard Plan, Detail 1 should be used at the Back of Pavement Seats.</p>			
		<p>REVIEWED BY: <i>Bruce Thill</i></p>	
		<p>DATE: <b>2/26/2010</b></p>	



BRIDGE NUMBER: <b>90 / 570</b>	BRIDGE NAME: <b>HAVANA ST OC</b>	REGION: <b>Eastern</b>	MILEPOST: <b>284.35</b>
YEAR BUILT / YR WIDENED: <b>1957</b>	CONTRACT NO.(S):	SUFFICIENCY RATING: <b>81.76 SD</b>	
BRIDGE TYPE: <b>CS</b> DECK TYPE: <b>Conc cast-in-place</b> DECK THICKNESS: <b>18.0 in.</b> (Main Span)	BRIDGE WIDTH (curb-curb): <b>98.0 ft.</b> BRIDGE LENGTH: <b>66 ft.</b> AVERAGE DAILY TRAFFIC (ADT): <b>109,988</b> NUMBER OF LANES: <b>6</b>	EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: <b>LMC Overlay</b> Year Applied - 1984 Overlay Thickness - 1.5 inches	
<b>VERTICAL CLEARANCE</b> VC Type: <b>NA</b>			
<b>BRIDGE RAIL</b> BRIDGE RAIL TYPE: <b>WSDOT CODE - 60</b> <b>New Jersey Barrier</b> RAIL MEETS CURRENT STANDARDS?: <b>YES</b> SIDEWALK / CURB WIDTH: <b>0.0 Lt 0.0 Rt</b>			
<b>EXPANSION JOINTS</b>  If the Region chooses to provide temporary Asphalt Overlay, Standard Plan, Detail 1 should be used at the Back of Pavement Seats.		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b> PROTECTIVE OVERLAY RECOMMENDED?: <b>YES</b> TYPE RECOMMENDED: Rapid Set LMC Overlay <b>RESURFACING COMMENT</b> There are areas in the LMC overlay that are debonded and are now patched. We recommend removing and replacing the LMC overlay with a 1" Polyester or Rapid Set concrete overlay. This bridge is on the P2 Program Priority Array for a Concrete Overlay.  Region may provide a temporary 1.5" Asphalt Overlay and Standard Plan A7 details (see Expansion Joints).	
REVIEWED BY: <b>Bruce Thill</b>		DATE: <b>2/26/2010</b>	



BRIDGE NUMBER: <b>97 / 6</b>	BRIDGE NAME: <b>SWALE CR</b>	REGION: <b>Southwest</b>	MILEPOST: <b>8.08</b>
YEAR BUILT / YR WIDENED: <b>1960</b>	CONTRACT NO.(S): <b>06413 , 14687</b>	SUFFICIENCY RATING: <b>70.00 SD</b>	
BRIDGE TYPE: <b>CS</b>		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE:	
DECK TYPE: <b>Conc cast-in-place</b>		<b>MMC Overlay</b>	
DECK THICKNESS: (Main Span) <b>17.0 in.</b>		Year Applied - 1989	
		Overlay Thickness - 1.5 inches	
BRIDGE WIDTH (curb-curb): <b>28.0 ft.</b>	BRIDGE LENGTH: <b>103 ft.</b>		
AVERAGE DAILY TRAFFIC (ADT): <b>5,191</b>	NUMBER OF LANES: <b>2</b>		
<b>VERTICAL CLEARANCE</b>			
VC Type: <b>NA</b>			
<b>BRIDGE RAIL</b>			
BRIDGE RAIL TYPE: <b>WSDOT CODE - 70.6</b>			
<b>Conc Base - Type 1B w/Thrie Beam</b>			
RAIL MEETS CURRENT STANDARDS?: <b>YES</b>	SIDEWALK / CURB WIDTH: <b>2.0 Lt 2.0 Rt</b>		
<b>EXPANSION JOINTS</b>		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b>	
		PROTECTIVE OVERLAY RECOMMENDED?: <b>Yes</b>	
		TYPE RECOMMENDED: <b>Mod conc</b>	
		<b>RESURFACING COMMENT</b>	
		Bridge Inspection results indicate nearly 5.0% of the existing concrete overlay and deck is deteriorated.	
		We recommend removing the existing LMC and using a hydromill and applying a 1.5" modified concrete overlay.	
		REVIEWED BY: <b>Bruce Thill</b>	DATE: <b>2/26/2010</b>



BRIDGE NUMBER: <b>97 / 103</b>	BRIDGE NAME: <b>SATUS CR 3RD CROSSING</b>	REGION: <b>South Central</b>	MILEPOST: <b>37.46</b>
YEAR BUILT / YR WIDENED: <b>1975</b>	CONTRACT NO.(S): <b>09780</b>	SUFFICIENCY RATING: <b>88.14</b>	
BRIDGE TYPE: <b>PCG</b> DECK TYPE: <b>Conc cast-in-place</b> DECK THICKNESS: <b>7.0 in.</b> <small>(Main Span)</small>		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: <b>original concrete</b>	
BRIDGE WIDTH (curb-to-curb): <b>39.6 ft.</b>	BRIDGE LENGTH: <b>210 ft.</b>		
AVERAGE DAILY TRAFFIC (ADT): <b>3,594</b>	NUMBER OF LANES: <b>2</b>		
<b>VERTICAL CLEARANCE</b>			
VC Type: <b>NA</b>			
<b>BRIDGE RAIL</b>			
BRIDGE RAIL TYPE: <b>WSDOT CODE - 60</b> <b>New Jersey Barrier</b>			
RAIL MEETS CURRENT STANDARDS?: <b>YES</b>		SIDEWALK / CURB WIDTH: <b>0.0 Lt 0.0 Rt</b>	
<b>EXPANSION JOINTS</b>		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b>	
		PROTECTIVE OVERLAY RECOMMENDED?: <b>Yes</b> TYPE RECOMMENDED: <b>Mod Conc</b>	
		<b>RESURFACING COMMENT</b> Bridge Inspection results indicate nearly 2.0% of the existing concrete overlay and deck is deteriorated.  We recommend removing the existing LMC and using a hydromill and applying a 1.5" modified concrete overlay.	
REVIEWED BY: <b><i>Bruce Thill</i></b>		DATE: <b>2/26/2010</b>	



BRIDGE NUMBER: 110 / 15	BRIDGE NAME: BOGACHIEL RIVER	REGION: Olympic	MILEPOST: 8.64
YEAR BUILT / YR WIDENED: 1967	CONTRACT NO.(S):	SUFFICIENCY RATING: 60.86 SD	
BRIDGE TYPE: SB CS DECK TYPE: Conc cast-in-place DECK THICKNESS: 7.0 in. (Main Span)	EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: orig conc with ACPmem		
BRIDGE WIDTH (curb-curb): 26.0 ft. BRIDGE LENGTH: 288 ft. AVERAGE DAILY TRAFFIC (ADT): 1,190 NUMBER OF LANES: 2			
<b>VERTICAL CLEARANCE</b> VC Type: NA			
<b>BRIDGE RAIL</b> BRIDGE RAIL TYPE: WSDOT CODE - 74 Conc Base - Type S RAIL MEETS CURRENT STANDARDS?: YES SIDEWALK / CURB WIDTH: 0.4 Lt 0.4 Rt			
<b>EXPANSION JOINTS</b> Modifications will be required to accommodate the proposed overlay.	<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b> PROTECTIVE OVERLAY RECOMMENDED?: <span style="background-color: green; color: white;">Yes</span> TYPE RECOMMENDED: Mod Conc <b>RESURFACING COMMENT</b> Bridge Inspection results indicates that nearly 13% of the concrete deck is deteriorated.  We recommend removal of the existing asphalt and membrane then hydromill the concrete deck and apply a 1.5" mod conc overlay.		
	REVIEWED BY: <i>Bruce Thill</i>	DATE: 2/26/2010	



BRIDGE NUMBER: <p style="text-align: center;">128 / 10</p>	BRIDGE NAME: <p style="text-align: center;">SNAKE R - RED WOLF BR</p>	REGION: <p style="text-align: center;">South Central</p>	MILEPOST: <p style="text-align: center;">0.22</p>
YEAR BUILT / YR WIDENED: <p style="text-align: center;">1979</p>	CONTRACT NO.(S): <p style="text-align: center;">10850</p>	SUFFICIENCY RATING: <p style="text-align: center;">87.47 SD</p>	
BRIDGE TYPE:           SBOX DECK TYPE:            Conc cast-in-place DECK THICKNESS:      7.7 in. <small>(Main Span)</small>		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: <p style="text-align: center;">original concrete</p>	
BRIDGE WIDTH (curb-curb):            32.0 ft. BRIDGE LENGTH:                        1,450 ft.			
AVERAGE DAILY TRAFFIC (ADT):      4,209 NUMBER OF LANES:                      2			
<b>VERTICAL CLEARANCE</b> VC Type: <p style="text-align: center;">NA</p>			
<b>BRIDGE RAIL</b>			
BRIDGE RAIL TYPE:    WSDOT CODE - 61 <p style="text-align: center;">New Jersey Barrier w/Type BP</p> RAIL MEETS CURRENT STANDARDS?:    YES SIDEWALK / CURB WIDTH:            0.0 Lt   4.0 Rt			
<b>EXPANSION JOINTS</b>  No Modifications Required at this time.		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b> PROTECTIVE OVERLAY RECOMMENDED?: <span style="background-color: green; color: white; padding: 2px;">YES</span> TYPE RECOMMENDED: MC Overlay / Hydro  <b>RESURFACING COMMENT</b> Bridge Inspection reports indicate the deck is more than 5% deteriorated.  We recommend placing 1.5" modified concrete overlay with 0.5" hydromill scarification.	
REVIEWED BY: <p style="text-align: center;"><i>Bruce Thill</i></p>		DATE: <p style="text-align: center;">2/26/2010</p>	



BRIDGE NUMBER: <p style="text-align: center;">153 / 16</p>	BRIDGE NAME: <p style="text-align: center;">METHOW R</p>	REGION: <p style="text-align: center;">North Central</p>	MILEPOST: <p style="text-align: center;">16.85</p>
YEAR BUILT / YR WIDENED: <p style="text-align: center;">1939</p>	CONTRACT NO.(S): <p style="text-align: center;">03507 , 10053 , 15037</p>	SUFFICIENCY RATING: <p style="text-align: center;">48.16</p>	
BRIDGE TYPE:           CTB DECK TYPE:            Conc cast-in-place DECK THICKNESS:     7.0 in. <small>(Main Span)</small>		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: <p style="text-align: center;">ACP w/membrane</p> <p style="text-align: center;">Year Applied - 1975</p> <p style="text-align: center;">Overlay Thickness - 3.0 inches</p>	
BRIDGE WIDTH (curb-curb): <p style="text-align: center;">24.0 ft.</p>	BRIDGE LENGTH: <p style="text-align: center;">454 ft.</p>		
AVERAGE DAILY TRAFFIC (ADT): <p style="text-align: center;">1,321</p>	NUMBER OF LANES: <p style="text-align: center;">2</p>		
<b>VERTICAL CLEARANCE</b> VC Type: <p style="text-align: center;">NA</p>			
<b>BRIDGE RAIL</b>			
BRIDGE RAIL TYPE:    WSDOT CODE - 41 <p style="text-align: center;">Balluster Rail</p>	RAIL MEETS CURRENT STANDARDS?:      SIDEWALK / CURB WIDTH: <p style="text-align: center;">NO    0.5 Lt   3.5 Rt</p>		
<b>EXPANSION JOINTS</b>		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b> PROTECTIVE OVERLAY RECOMMENDED?: <span style="background-color: green; color: white; padding: 2px;">YES</span> TYPE RECOMMENDED: ACP w/Memb	
		<b>RESURFACING COMMENT</b> The concrete bridge deck is showing signs of distress.  We recommend: removing the 0.25' ACP; deck prep; place 0.25' HMA with membrane.  The bridge rails are also in need of replacement.	
		REVIEWED BY: <p style="text-align: center;"><i>Bruce Thill</i></p>	DATE: <p style="text-align: center;">2/26/2010</p>



BRIDGE NUMBER: <p style="text-align: center;">153 / 17</p>	BRIDGE NAME: <p style="text-align: center;">METHOW R</p>	REGION: <p style="text-align: center;">North Central</p>	MILEPOST: <p style="text-align: center;">18.91</p>
YEAR BUILT / YR WIDENED: <p style="text-align: center;">1939</p>	CONTRACT NO.(S): 	SUFFICIENCY RATING: <p style="text-align: center;">49.32</p>	
BRIDGE TYPE:           CTB DECK TYPE:            Conc cast-in-place DECK THICKNESS:      7.0 in. <small>(Main Span)</small>		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: <p style="text-align: center;">ACP w/membrane</p> <p style="text-align: center;">Year Applied - 1975</p> <p style="text-align: center;">Overlay Thickness - 1.8 inches</p>	
BRIDGE WIDTH (curb-curb): <p style="text-align: center;">24.0 ft.</p>	BRIDGE LENGTH: <p style="text-align: center;">302 ft.</p>		
AVERAGE DAILY TRAFFIC (ADT): <p style="text-align: center;">1,321</p>	NUMBER OF LANES: <p style="text-align: center;">2</p>		
<p style="text-align: center;"><b>VERTICAL CLEARANCE</b></p> VC Type: <p style="text-align: center;">NA</p>			
<p style="text-align: center;"><b>BRIDGE RAIL</b></p> BRIDGE RAIL TYPE:    WSDOT CODE - 41 <p style="text-align: center;">Balluster Rail</p>			
RAIL MEETS CURRENT STANDARDS?: <p style="text-align: center;">NO</p>		SIDEWALK / CURB WIDTH: <p style="text-align: center;">0.4 Lt    3.5 Rt</p>	
<p style="text-align: center;"><b>EXPANSION JOINTS</b></p> <p>Coordinate with your Region's Maintenance Office to determine if any repairs are required.</p>		<p style="text-align: center;"><b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b></p> PROTECTIVE OVERLAY RECOMMENDED?: <span style="background-color: green; color: white; padding: 2px;">YES</span> TYPE RECOMMENDED: RR 0.15 HMA / mem	
		<p><b>RESURFACING COMMENT</b></p> <p>The concrete bridge deck is showing signs of distress.</p> <p>We recommend: removing the 0.15' ACP; deck prep; place 0.25' HMA with membrane. Expansion joint modification is required.</p> <p>The bridge rails are also in need of replacement.</p>	
		REVIEWED BY: <p style="text-align: center;"><i>Bruce Thill</i></p>	DATE: <p style="text-align: center;">2/26/2010</p>



BRIDGE NUMBER: 195 / 49	BRIDGE NAME: PINE CR #1	REGION: Eastern	MILEPOST: 62.98
YEAR BUILT / YR WIDENED: 1975	CONTRACT NO.(S): 09676	SUFFICIENCY RATING: 92.65	
BRIDGE TYPE: PCG DECK TYPE: Conc cast-in-place DECK THICKNESS: 7.0 in. (Main Span)		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: ACP w/membrane Year Applied - 2006 Overlay Thickness - 3.0 inches	
BRIDGE WIDTH (curb-curb): 40.0 ft.	BRIDGE LENGTH: 300 ft.		
AVERAGE DAILY TRAFFIC (ADT): 4,579	NUMBER OF LANES: 2		
<b>VERTICAL CLEARANCE</b>			
VC Type: NA			
<b>BRIDGE RAIL</b>			
BRIDGE RAIL TYPE: WSDOT CODE - 60 New Jersey Barrier			
RAIL MEETS CURRENT STANDARDS?: YES	SIDEWALK / CURB WIDTH: 0.0 Lt 0.0 Rt		
<b>EXPANSION JOINTS</b>		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b>	
Use Std. Plan A7, Transverse Joint Detail 1 at the ends of the bridge deck.		PROTECTIVE OVERLAY RECOMMENDED?: <b>Yes</b> TYPE RECOMMENDED: Mod Conc	
		<b>RESURFACING COMMENT</b> The bridge deck has nearly 6.7% patches under the HMA and membrane that was applied in 2006.  The bridge is on the P2 Deck Program list due to the amount of patching. If the deck continues to deteriorate then the existing HMA and membrane may need to be removed and replaced with a 1.5" Modified Concrete Overlay.	
		REVIEWED BY: <i>Bruce Thill</i>	DATE: 2/26/2010



BRIDGE NUMBER: 195 / 52	BRIDGE NAME: MILW RR OC (CMSTP&P)	REGION: Eastern	MILEPOST: 63.30
YEAR BUILT / YR WIDENED: 1975	CONTRACT NO.(S): 09676	SUFFICIENCY RATING: 95.83	
BRIDGE TYPE: PCG DECK TYPE: Conc cast-in-place DECK THICKNESS: 7.0 in. <small>(Main Span)</small> BRIDGE WIDTH (curb-curb): 40.0 ft. BRIDGE LENGTH: 142 ft. AVERAGE DAILY TRAFFIC (ADT): 4,579 NUMBER OF LANES: 2		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: ACP w/membrane Year Applied - 2006 Overlay Thickness - 3.0 inches	
<b>VERTICAL CLEARANCE</b> VC Type: NA			
<b>BRIDGE RAIL</b> BRIDGE RAIL TYPE: WSDOT CODE - 60 New Jersey Barrier RAIL MEETS CURRENT STANDARDS?: YES SIDEWALK / CURB WIDTH: 0.0 Lt 0.0 Rt			
<b>EXPANSION JOINTS</b> Use Std. Plan A7, Transverse Joint Detail 1 at the ends of the bridge deck.		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b> PROTECTIVE OVERLAY RECOMMENDED?: <span style="background-color: green; color: white;">Yes</span> TYPE RECOMMENDED: Mod Conc <b>RESURFACING COMMENT</b> The bridge deck has nearly 8.4% patches under the HMA and membrane that was applied in 2006.  The bridge is on the P2 Deck Program list due to the amount of patching. If the deck continues to deteriorate then the existing HMA and membrane may need to be removed and replaced with a 1.5" Modified Concrete Overlay.	
		REVIEWED BY: <i>Bruce Thill</i>	DATE: 2/26/2010



BRIDGE NUMBER: 203 / 3	BRIDGE NAME: SLOUGH	REGION: Northwest	MILEPOST: 0.49
YEAR BUILT / YR WIDENED: 1945	CONTRACT NO.(S): 02999	SUFFICIENCY RATING: 89.96 FO	
BRIDGE TYPE: <b>TTC</b> DECK TYPE: <b>Conc cast-in-place</b> DECK THICKNESS: <b>7.5 in.</b> (Main Span)		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: <b>original concrete</b>	
BRIDGE WIDTH (curb-curb): <b>36.0 ft.</b>	BRIDGE LENGTH: <b>52 ft.</b>		
AVERAGE DAILY TRAFFIC (ADT): <b>7,993</b>	NUMBER OF LANES: <b>2</b>		
<b>VERTICAL CLEARANCE</b>			
VC Type: <b>NA</b>			
<b>BRIDGE RAIL</b>			
BRIDGE RAIL TYPE: <b>WSDOT CODE - 42</b> <b>Balluster Rail w/Thrie Beam</b>			
RAIL MEETS CURRENT STANDARDS?: <b>YES</b>	SIDEWALK / CURB WIDTH: <b>0.0 Lt 0.0 Rt</b>		
<b>EXPANSION JOINTS</b>		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b>	
Std. Plan A7, Detail 1 should be used at the end of the bridge deck.		PROTECTIVE OVERLAY RECOMMENDED?: <b>YES</b> TYPE RECOMMENDED: HMA/Memb	
		<b>RESURFACING COMMENT</b> Bridge Inspection data indicates nearly 1.5% of the deck is deteriorated.  We recommend repairing the deck and applying a membrane and 0.15' of HMA.	
		REVIEWED BY: <i>Bruce Thill</i> DATE: 2/26/2010	



BRIDGE NUMBER: <p style="text-align: center;">203 / 104</p>	BRIDGE NAME: <p style="text-align: center;">DRAINAGE OVERFLOW</p>	REGION: <p style="text-align: center;">Northwest</p>	MILEPOST: <p style="text-align: center;">22.05</p>
YEAR BUILT / YR WIDENED: <p style="text-align: center;">1954</p>	CONTRACT NO.(S): <p style="text-align: center;">04825</p>	SUFFICIENCY RATING: <p style="text-align: center;">60.44 SD</p>	
BRIDGE TYPE: CS DECK TYPE: Conc cast-in-place DECK THICKNESS: 14.0 in. <small>(Main Span)</small>		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: <p style="text-align: center;">original concrete</p>	
BRIDGE WIDTH (curb-curb): <p style="text-align: center;">26.0 ft.</p>	BRIDGE LENGTH: <p style="text-align: center;">89 ft.</p>		
AVERAGE DAILY TRAFFIC (ADT): <p style="text-align: center;">11,317</p>	NUMBER OF LANES: <p style="text-align: center;">2</p>		
<b>VERTICAL CLEARANCE</b> VC Type: <p style="text-align: center;">NA</p>			
<b>BRIDGE RAIL</b>			
BRIDGE RAIL TYPE: WSDOT CODE - 42 <p style="text-align: center;">Balluster Rail w/Thrie Beam</p>			
RAIL MEETS CURRENT STANDARDS?: <p style="text-align: center;">YES</p>	SIDEWALK / CURB WIDTH: <p style="text-align: center;">2.5 Lt 2.5 Rt</p>		
<b>EXPANSION JOINTS</b>		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b>	
Std. Plan A7, Detail 1 should be used at the end of the bridge deck.		PROTECTIVE OVERLAY RECOMMENDED?: <span style="background-color: green; color: white; padding: 2px;">YES</span> TYPE RECOMMENDED: MC Overlay	
		<b>RESURFACING COMMENT</b> Bridge Inspection reports indicate the deck is more than 5% deteriorated.  We recommend placing 1.5" modified concrete overlay with 0.5" hydromill scarification.	
		REVIEWED BY: <i>Bruce Thill</i>	
		DATE: 2/26/2010	



BRIDGE NUMBER: 203 / 106		BRIDGE NAME: SKYKOMISH R		REGION: Northwest		MILEPOST: 23.20	
YEAR BUILT / YR WIDENED: 1957		CONTRACT NO.(S): 05294 , 14227			SUFFICIENCY RATING: 48.00 FO		
BRIDGE TYPE: ST CBOX DECK TYPE: Conc cast-in-place DECK THICKNESS: 6.5 in. (Main Span)				EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: 3/8in Polymer-Epoxy Year Applied - 1993 Overlay Thickness - 0.4 inches			
BRIDGE WIDTH (curb-curb): 28.0 ft.		BRIDGE LENGTH: 582 ft.					
AVERAGE DAILY TRAFFIC (ADT): 14,166		NUMBER OF LANES: 2					
<b>VERTICAL CLEARANCE</b> VC Type: NA							
<b>BRIDGE RAIL</b> BRIDGE RAIL TYPE: WSDOT CODE - 42 Balluster Rail w/Thrie Beam RAIL MEETS CURRENT STANDARDS?: YES SIDEWALK / CURB WIDTH: 2.5 Lt 2.5 Rt							
<b>EXPANSION JOINTS</b> Coordinate with your Region's Maintenance Office to determine if any repairs are required.				<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b> PROTECTIVE OVERLAY RECOMMENDED?: <b>YES</b> TYPE RECOMMENDED: Rapid Set LMC Overlay <b>RESURFACING COMMENT</b> Exclude bridge from resurfacing projects. The existing thin polymer overlay has failed. Deck protection is warranted. P2 project will remove existing polymer overlay and place new Polyester Concrete or RSLMC overlay. Joint modifications will be required to accommodate a new concrete overlay.			
				REVIEWED BY: <i>Bruce Thill</i>		DATE: 2/26/2010	



BRIDGE NUMBER: 261 / 120	BRIDGE NAME: TUCANNON R	REGION: South Central	MILEPOST: 10.27
YEAR BUILT / YR WIDENED: 1967	CONTRACT NO.(S):	SUFFICIENCY RATING: 88.24 SD	
BRIDGE TYPE: PCG DECK TYPE: Conc cast-in-place DECK THICKNESS: 5.8 in. (Main Span)	BRIDGE WIDTH (curb-curb): 26.0 ft. BRIDGE LENGTH: 211 ft. AVERAGE DAILY TRAFFIC (ADT): 495 NUMBER OF LANES: 2	EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: original concrete	
<b>VERTICAL CLEARANCE</b> VC Type: NA			
<b>BRIDGE RAIL</b> BRIDGE RAIL TYPE: WSDOT CODE - 73.2 Conc Base - Type R RAIL MEETS CURRENT STANDARDS?: YES SIDEWALK / CURB WIDTH: 1.5 Lt 1.5 Rt			
<b>EXPANSION JOINTS</b> Modifications are required to accommodate the new overlay, please coordinate with the Bridge Office.		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b> PROTECTIVE OVERLAY RECOMMENDED?: YES TYPE RECOMMENDED: MC Overlay / Hydro <b>RESURFACING COMMENT</b> Bridge Inspection reports indicate the deck is more than 18% deteriorated with exposed rebar through out. Many of the small delams are over the girder stirrups.  A new 1.5" modified concrete overlay is required using a 0.5" hydromill scarification.	
REVIEWED BY: <i>Bruce Thill</i>		DATE: 2/26/2010	



BRIDGE NUMBER: <p style="text-align: center;">290 / 4.6S</p>	BRIDGE NAME: <p style="text-align: center;">2ND AVE OC</p>	REGION: <p style="text-align: center;">Eastern</p>	MILEPOST: <p style="text-align: center;">1.18</p>
YEAR BUILT / YR WIDENED: <p style="text-align: center;">1974</p>	CONTRACT NO.(S): <p style="text-align: center;">09622 , 12748</p>	SUFFICIENCY RATING: <p style="text-align: center;">97.48</p>	
BRIDGE TYPE:           CBOX DECK TYPE:            Conc cast-in-place DECK THICKNESS:     6.5 in. <small>(Main Span)</small>		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: <p style="text-align: center;">LMC Overlay</p> <p style="text-align: center;">Year Applied - 1985</p> <p style="text-align: center;">Overlay Thickness - 1.5 inches</p>	
BRIDGE WIDTH (curb-curb): <p style="text-align: center;">38.0 ft.</p>	BRIDGE LENGTH: <p style="text-align: center;">167 ft.</p>		
AVERAGE DAILY TRAFFIC (ADT): <p style="text-align: center;">5,369</p>	NUMBER OF LANES: <p style="text-align: center;">2</p>		
<b>VERTICAL CLEARANCE</b> VC Type: <p style="text-align: center;">NA</p>			
<b>BRIDGE RAIL</b>			
BRIDGE RAIL TYPE:    WSDOT CODE - 60 <p style="text-align: center;">New Jersey Barrier</p>			
RAIL MEETS CURRENT STANDARDS?: <p style="text-align: center;">YES</p>	SIDEWALK / CURB WIDTH: <p style="text-align: center;">0.0 Lt   0.0 Rt</p>		
<b>EXPANSION JOINTS</b>		<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b> PROTECTIVE OVERLAY RECOMMENDED?: <span style="background-color: green; color: white; padding: 2px;">Yes</span> TYPE RECOMMENDED: Mod Conc	
		<b>RESURFACING COMMENT</b> The existing LMC has nearly 24% patched and deteriorated areas. The existing LMC needs to be removed, the deck repaired, then a new modified concrete overlay applied.	
		REVIEWED BY: <p style="text-align: center;"><i>Bruce Thill</i></p>	DATE: <p style="text-align: center;">2/26/2010</p>



BRIDGE NUMBER: <b>303 / 12</b>	BRIDGE NAME: <b>PORT WASHINGTON CS1840</b>	REGION: <b>Olympic</b>	MILEPOST: <b>0.73</b>
YEAR BUILT / YR WIDENED: <b>1958</b>	CONTRACT NO.(S): <b>05565 , XE2784 , 13916 , 14490</b>	SUFFICIENCY RATING: <b>48.91 SD</b>	
BRIDGE TYPE: <b>SG CBOX CTB</b> DECK TYPE: <b>Lightweight Conc</b> DECK THICKNESS: <b>6.5 in.</b> <small>(Main Span)</small> BRIDGE WIDTH (curb-curb): <b>55.0 ft.</b> BRIDGE LENGTH: <b>1,717 ft.</b> AVERAGE DAILY TRAFFIC (ADT): <b>40,253</b> NUMBER OF LANES: <b>4</b>		EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: <p style="text-align: center;"><b>Polyester Overlay</b>          Year Applied - 1991          Overlay Thickness - 0.8 inches</p>	
<p style="text-align: center;"><b>VERTICAL CLEARANCE</b></p> VC Type: <p style="text-align: center;"><b>NA</b></p>			
<p style="text-align: center;"><b>BRIDGE RAIL</b></p> BRIDGE RAIL TYPE: <b>WSDOT CODE - 71.1</b> <p style="text-align: center;"><b>Conc Base - Type 2</b></p> RAIL MEETS CURRENT STANDARDS?: <b>NO</b> SIDEWALK / CURB WIDTH: <b>4.0 Lt 4.0 Rt</b>			
<p style="text-align: center;"><b>EXPANSION JOINTS</b></p> No modifications required at this time.		<p style="text-align: center;"><b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b></p> PROTECTIVE OVERLAY RECOMMENDED?: <span style="background-color: green; color: white; padding: 2px;"><b>Yes</b></span> TYPE RECOMMENDED: <b>ACP w/Memb</b> <p style="text-align: center;"><b>RESURFACING COMMENT</b></p> Bridge Inspections indicate existing overlay is deteriorating.  We recommend removal of the existing 3/4" Polyester overlay and adding a new membrane and 0.12' HMA.	
REVIEWED BY: <b><i>Bruce Thill</i></b>		DATE: <b>2/26/2010</b>	



BRIDGE NUMBER: 432 / 10S	BRIDGE NAME: COWLITZ R & NP RY OC	REGION: Southwest	MILEPOST: 9.58
YEAR BUILT / YR WIDENED: 1961 / 1971	CONTRACT NO.(S): 06321	SUFFICIENCY RATING: 52.27	
BRIDGE TYPE: STrus CBox DECK TYPE: Conc cast-in-place DECK THICKNESS: 6.5 in. (Main Span)	EXISTING WEARING SURFACE AND DECK PROTECTION TYPE: original concrete		
BRIDGE WIDTH (curb-to-curb): 29.5 ft. BRIDGE LENGTH: 1,676 ft. AVERAGE DAILY TRAFFIC (ADT): 17,581 NUMBER OF LANES: 2			
<b>VERTICAL CLEARANCE</b> VC Type: Minimum VC = 16 FT 03 in			
<b>BRIDGE RAIL</b> BRIDGE RAIL TYPE: WSDOT CODE - 60 New Jersey Barrier RAIL MEETS CURRENT STANDARDS?: YES SIDEWALK / CURB WIDTH: 0.0 Lt 0.0 Rt			
<b>EXPANSION JOINTS</b> Coordinate with your Region Bridge Maintenance to determine if any repairs are needed.	<b>DECK PROTECTIVE SYSTEM RECOMMENDATIONS</b> PROTECTIVE OVERLAY RECOMMENDED?: <b>YES</b> TYPE RECOMMENDED: MC Overlay / Hydro <b>RESURFACING COMMENT</b> Bridge Inspection reports indicate the deck is more than 2% deteriorated with a significant amount of exposed rebar in the top of the deck near piers 9 and 12.  We recommend a 1.5" modified concrete overlay be placed with 0.5" hydromill scarification.		
	REVIEWED BY: <i>Bruce Thill</i>	DATE: 2/26/2010	

## P2 Bridge Preservation - Steel Bridge Painting Projects

### 2011-13 Bien Priority Array

(Sorted by Priority Number)





11-13 #	Bridge Number	Bridge Name	Mile Post	Region	Yr Work Planned	Total Project\$
1	101/1(B)	COL R ASTORIA (TRUSS)		Southwest	2011	\$18,599,000
1	433/1	COLUMBIA R-LEWIS&CLARK	0.00	Southwest	2010	\$22,000,000
2	5/40W	LEWIS R	19.83	Southwest	2012	\$9,984,000
3	5/40E	LEWIS R	19.87	Southwest	2012	\$7,260,500
4	5/232W	SKOOKUMCHUCK R	82.28	Southwest	2012	\$1,267,000
5	5/232E	SKOOKUMCHUCK R	82.28	Southwest	2012	\$1,267,000
6	5/828W	NOOKSACK R	263.05	Northwest	2012	\$1,407,000
7	5/828E	NOOKSACK R	263.05	Northwest	2012	\$1,554,000
8	5/345W	NISQUALLY R	114.86	Olympic	2012	\$3,303,835
9	5/345E	NISQUALLY RIVER	114.86	Olympic	2012	\$3,445,000
10	141/5	WHITE SALMON RIVER	8.70	Southwest	2012	\$700,000
11	97/1	BIGGS RAPIDS-SAM HILL BR	0.00	Southwest	2014	\$6,000,000
12	101/125W	HOQUIAM R-SIMPSON CS141	86.76	Olympic	2012	\$4,147,000
13	90/180	COLUMBIA R VANTAGE	137.19	South Central	2015	\$5,000,000
14	18/17S	GREEN R (NEELEY BRIDGE)	6.62	Northwest	2014	\$1,281,000
15	99/560	AURORA AVE-G WASH MEM	34.14	Northwest	2015	\$50,000,000
16	90/25S	LACEY V. MURROW BRIDGE	4.24	Northwest	2015	\$18,850,000
17	409/10	JULIA BUTLER HANSEN BR	2.92	Southwest	2015	\$7,761,000
18	101/125E	HOQUIAM R-RIVERSIDE 1417	87.31	Olympic	2015	\$3,939,000
19	12/309	WILDCAT CR	165.95	Southwest	2015	\$200,000
20	207/4	WENATCHEE RIVER	4.22	North Central	2015	\$1,015,000
21	101/310	SOL DUC R	194.30	Olympic	2015	\$756,000
22	101/322	SOL DUC RIVER #5	212.46	Olympic	2015	\$1,029,000
23	107/4	CHEHALIS R	6.83	Olympic	2015	\$2,233,000
24	101/256	BIG QUILCENE R	296.67	Olympic	2015	\$847,000
25	109/10	HUMPTULIPS R	10.24	Olympic	2015	\$1,582,000
26	21/334	KETTLE R	181.00	Eastern	2015	\$1,260,000
27	9/118	SNOHOMISH R	9.17	Northwest	2015	\$2,240,000
28	202/60	SNOQUALMIE R	26.00	Northwest	2015	\$1,491,000
29	9/122	SR 9 OC, BICKFORD AVE	10.87	Northwest	2015	\$196,000
30	5/670W	STILLAGUAMISH R	209.35	Northwest	2015	\$2,846,250
31	5/203W	COWLITZ R	59.06	Southwest	2017	\$2,205,000
32	5/203E	COWLITZ R	59.06	Southwest	2017	\$2,205,000



## P2 Bridge Preservation - Steel Bridge Painting Projects

### 2011-13 Bien Priority Array

(Sorted by Priority Number)



11-13 #	Bridge Number	Bridge Name	Mile Post	Region	Yr Work Planned	Total Project\$
33	5/532W	SB VIADUCT STA 1918	160.07	Northwest	2017	\$1,146,750
34	5/650W	EBEY SL BN RY SR 529 OC	198.51	Northwest	2017	\$1,223,750
35	5/105W	BN RR OC (NP)	26.01	Southwest	2017	\$1,100,000
36	5/104W	DIKE ACCESS RD & RR OC	22.72	Southwest	2017	\$2,227,500
37	82/280S	COLUMBIA R BR @ UMATILLA	132.36	South Central	2017	\$12,000,000
38	432/10S	COWLITZ R & NP RY OC	9.58	Southwest	2017	\$2,226,000
39	410/101	WHITE R	21.99	Northwest	2017	\$1,673,000
40	99/538	SPOKANE ST OC	29.15	Northwest	2017	\$863,500
41	167/127W	BN RR OC (NP)	20.96	Northwest	2017	\$412,500
42	167/127E	BN RR OC (NP)	20.96	Northwest	2017	\$412,500
43	12/328S	NACHES R NELSON	198.66	South Central	2017	\$2,100,000
44	12/328N	NACHES R NELSON	198.66	South Central	2017	\$1,185,000
45	24/105	COLUMBIA R VERNITA	43.60	South Central	2019	\$1,822,500
46	97/420	COLUMBIA R BEEBE	235.06	North Central	2019	\$4,860,000
47	285/10	SEN. GEORGE SELLAR BR.	0.25	North Central	2019	\$8,550,000
48	395/545	COLUMBIA R KETTLE FALLS	241.49	Eastern	2019	\$10,712,000
49	2/40	S FK SKYKOMISH R	35.21	Northwest	2019	\$1,652,000
50	20/204	DECEPTION PASS	41.81	Northwest	2019	\$7,592,000
51	12/241	TWIN CANYON CR	89.48	Southwest	2019	\$486,750
52	101/115	CHEHALIS R	83.12	Olympic	2019	\$9,142,500
53	305/10	AGATE PASS	6.82	Olympic	2019	\$10,289,500
54	25/130	COLUMBIA R @ NORTHPORT	113.92	Eastern	2019	\$7,585,500
55	6/118	CHEHALIS R ADNA	46.59	Southwest	2019	\$783,750
56	20/244	SCOTT PAPER RD OVR SR 20	76.94	Northwest	2019	\$200,000
57	5/526.1	ARCHIE CODIGA BRIDGE	156.48	Northwest	2019	\$682,000
58	504/15	N FK TOUTLE R KID VALLEY	17.29	Southwest	2019	\$602,250
59	4/209	HALF BR W OF BUNKER HILL	49.80	Southwest	2019	\$200,000
60	101/29	SOUTH NEMAH R NO 1	32.52	Southwest	2021	\$200,000
61	202/66	S FK SNOQUALMIE R	29.50	Northwest	2021	\$214,500
62	4/106A	GRAYS R ROSBURG	15.07	Southwest	2021	\$264,000
63	27/12	N FK PALOUSE R	15.02	Eastern	2021	\$574,000
64	507/114	DESCHUTES R	20.43	Olympic	2021	\$412,500
65	20/311	HALF BR STA 155	122.41	Northwest	2021	\$200,000



## P2 Bridge Preservation - Steel Bridge Painting Projects

### 2011-13 Bien Priority Array

(Sorted by Priority Number)



11-13 #	Bridge Number	Bridge Name	Mile Post	Region	Yr Work Planned	Total Project\$
66	542/33	GLACIER CR	33.49	Northwest	2021	\$200,000
67	7/105	MASHEL R	27.91	Olympic	2021	\$272,250
68	153/4	METHOW R	4.22	North Central	2021	\$813,750
69	153/101	COLUMBIA R GRAND COULE	28.26	North Central	2021	\$5,625,000
70	530/290	ROCKPORT BRIDGE	67.34	Northwest	2021	\$673,750
71	165/10	CARBON RIVER	11.50	Olympic	2021	\$671,250
73	101/308	CALAWAH R	192.36	Olympic	2021	\$1,113,000
74	536/15	SKAGIT R CS2907	4.72	Northwest	2021	\$3,471,000
75	4/120	SKAMOKAWA CR CS3505	28.92	Southwest	2021	\$547,500

Total Number of Bridges = 75


Total Project \$ = \$294,854,335



## P2 Bridge Preservation - Steel Bridge Painting Projects

### 2011-13 Bien Priority Array

(Sorted by Bridge Number)




11-13 #	Bridge Number	Bridge Name	Mile Post	Region	Yr Work Planned	Total Project\$
49	2/40	S FK SKYKOMISH R	35.21	Northwest	2019	\$1,652,000
62	4/106A	GRAYS R ROSBURG	15.07	Southwest	2021	\$264,000
75	4/120	SKAMOKAWA CR CS3505	28.92	Southwest	2021	\$547,500
59	4/209	HALF BR W OF BUNKER HILL	49.80	Southwest	2019	\$200,000
3	5/40E	LEWIS R	19.87	Southwest	2012	\$7,260,500
2	5/40W	LEWIS R	19.83	Southwest	2012	\$9,984,000
36	5/104W	DIKE ACCESS RD & RR OC	22.72	Southwest	2017	\$2,227,500
35	5/105W	BN RR OC (NP)	26.01	Southwest	2017	\$1,100,000
32	5/203E	COWLITZ R	59.06	Southwest	2017	\$2,205,000
31	5/203W	COWLITZ R	59.06	Southwest	2017	\$2,205,000
5	5/232E	SKOOKUMCHUCK R	82.28	Southwest	2012	\$1,267,000
4	5/232W	SKOOKUMCHUCK R	82.28	Southwest	2012	\$1,267,000
9	5/345E	NISQUALLY RIVER	114.86	Olympic	2012	\$3,445,000
8	5/345W	NISQUALLY R	114.86	Olympic	2012	\$3,303,835
57	5/526.1	ARCHIE CODIGA BRIDGE	156.48	Northwest	2019	\$682,000
33	5/532W	SB VIADUCT STA 1918	160.07	Northwest	2017	\$1,146,750
34	5/650W	EBEY SL BN RY SR 529 OC	198.51	Northwest	2017	\$1,223,750
30	5/670W	STILLAGUAMISH R	209.35	Northwest	2015	\$2,846,250
7	5/828E	NOOKSACK R	263.05	Northwest	2012	\$1,554,000
6	5/828W	NOOKSACK R	263.05	Northwest	2012	\$1,407,000
55	6/118	CHEHALIS R ADNA	46.59	Southwest	2019	\$783,750
67	7/105	MASHEL R	27.91	Olympic	2021	\$272,250
27	9/118	SNOHOMISH R	9.17	Northwest	2015	\$2,240,000
29	9/122	SR 9 OC, BICKFORD AVE	10.87	Northwest	2015	\$196,000
51	12/241	TWIN CANYON CR	89.48	Southwest	2019	\$486,750
19	12/309	WILDCAT CR	165.95	Southwest	2015	\$200,000
44	12/328N	NACHES R NELSON	198.66	South Central	2017	\$1,185,000
43	12/328S	NACHES R NELSON	198.66	South Central	2017	\$2,100,000
14	18/17S	GREEN R (NEELEY BRIDGE)	6.62	Northwest	2014	\$1,281,000
50	20/204	DECEPTION PASS	41.81	Northwest	2019	\$7,592,000
56	20/244	SCOTT PAPER RD OVR SR 20	76.94	Northwest	2019	\$200,000
65	20/311	HALF BR STA 155	122.41	Northwest	2021	\$200,000
26	21/334	KETTLE R	181.00	Eastern	2015	\$1,260,000



## P2 Bridge Preservation - Steel Bridge Painting Projects

### 2011-13 Bien Priority Array

(Sorted by Bridge Number)



11-13 #	Bridge Number	Bridge Name	Mile Post	Region	Yr Work Planned	Total Project\$
45	24/105	COLUMBIA R VERNITA	43.60	South Central	2019	\$1,822,500
54	25/130	COLUMBIA R @ NORTHPORT	113.92	Eastern	2019	\$7,585,500
63	27/12	N FK PALOUSE R	15.02	Eastern	2021	\$574,000
37	82/280S	COLUMBIA R BR @ UMATILLA	132.36	South Central	2017	\$12,000,000
16	90/25S	LACEY V. MURROW BRIDGE	4.24	Northwest	2015	\$18,850,000
13	90/180	COLUMBIA R VANTAGE	137.19	South Central	2015	\$5,000,000
11	97/1	BIGGS RAPIDS-SAM HILL BR	0.00	Southwest	2014	\$6,000,000
46	97/420	COLUMBIA R BEEBE	235.06	North Central	2019	\$4,860,000
40	99/538	SPOKANE ST OC	29.15	Northwest	2017	\$863,500
15	99/560	AURORA AVE-G WASH MEM	34.14	Northwest	2015	\$50,000,000
1	101/1(B)	COL R ASTORIA (TRUSS)		Southwest	2011	\$18,599,000
60	101/29	SOUTH NEMAH R NO 1	32.52	Southwest	2021	\$200,000
52	101/115	CHEHALIS R	83.12	Olympic	2019	\$9,142,500
18	101/125E	HOQUIAM R-RIVERSIDE 1417	87.31	Olympic	2015	\$3,939,000
12	101/125W	HOQUIAM R-SIMPSON CS141	86.76	Olympic	2012	\$4,147,000
24	101/256	BIG QUILCENE R	296.67	Olympic	2015	\$847,000
73	101/308	CALAWAH R	192.36	Olympic	2021	\$1,113,000
21	101/310	SOL DUC R	194.30	Olympic	2015	\$756,000
22	101/322	SOL DUC RIVER #5	212.46	Olympic	2015	\$1,029,000
23	107/4	CHEHALIS R	6.83	Olympic	2015	\$2,233,000
25	109/10	HUMPTULIPS R	10.24	Olympic	2015	\$1,582,000
10	141/5	WHITE SALMON RIVER	8.70	Southwest	2012	\$700,000
68	153/4	METHOW R	4.22	North Central	2021	\$813,750
69	153/101	COLUMBIA R GRAND COULE	28.26	North Central	2021	\$5,625,000
71	165/10	CARBON RIVER	11.50	Olympic	2021	\$671,250
42	167/127E	BN RR OC (NP)	20.96	Northwest	2017	\$412,500
41	167/127W	BN RR OC (NP)	20.96	Northwest	2017	\$412,500
28	202/60	SNOQUALMIE R	26.00	Northwest	2015	\$1,491,000
61	202/66	S FK SNOQUALMIE R	29.50	Northwest	2021	\$214,500
20	207/4	WENATCHEE RIVER	4.22	North Central	2015	\$1,015,000
47	285/10	SEN. GEORGE SELLAR BR.	0.25	North Central	2019	\$8,550,000
53	305/10	AGATE PASS	6.82	Olympic	2019	\$10,289,500
48	395/545	COLUMBIA R KETTLE FALLS	241.49	Eastern	2019	\$10,712,000



## P2 Bridge Preservation - Steel Bridge Painting Projects

### 2011-13 Bien Priority Array

(Sorted by Bridge Number)



11-13 #	Bridge Number	Bridge Name	Mile Post	Region	Yr Work Planned	Total Project\$
17	409/10	JULIA BUTLER HANSEN BR	2.92	Southwest	2015	\$7,761,000
39	410/101	WHITE R	21.99	Northwest	2017	\$1,673,000
38	432/10S	COWLITZ R & NP RY OC	9.58	Southwest	2017	\$2,226,000
1	433/1	COLUMBIA R-LEWIS&CLARK	0.00	Southwest	2010	\$22,000,000
58	504/15	N FK TOUTLE R KID VALLEY	17.29	Southwest	2019	\$602,250
64	507/114	DESCHUTES R	20.43	Olympic	2021	\$412,500
70	530/290	ROCKPORT BRIDGE	67.34	Northwest	2021	\$673,750
74	536/15	SKAGIT R CS2907	4.72	Northwest	2021	\$3,471,000
66	542/33	GLACIER CR	33.49	Northwest	2021	\$200,000

Total Number of Bridges = 75

Total Project \$ = \$294,854,335



# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 2 / 40		Bridge Name: S FK SKYKOMISH R		Milepost: 35.21	Region: Northwest
Year Built 1933	Bridge Type: ST CTB	Steel Span Length: 240 ft.	Width (curb-curb): 24 ft.	Steel Tonnage: 236	
Paint Age: 22	Paint Color: Evergreen	Steel Surf. Area: 35,400 sqft	BMS Cond State 2: 2,500 sqft	BMS Cond State 3: 1,000 sqft	
Next Paint Year: 2019	2011-13 Rank: 49	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$1,652,000

## Past Paint History

Years	Cycle
1988	11
1977	7
1970	10
1960	9
1951	

### Painting Cycle



= Current Paint Age



### Bridge Inspection Notes:

Painted stringers, floorbeams, and truss has some peeling and curling paint. Paint protection has failed at the floorbeam and stringer top flange to deck interface. Rust with section loss, up to 5%, in top flanges of the stringers at interface with the deck. Floorbeams top flanges show up to 10% section loss.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 4 / 106A		Bridge Name: GRAYS R ROSBURG		Milepost: 15.07	Region: Southwest
Year Built 1947	Bridge Type: SG PCTB	Steel Span Length: 192 ft.	Width (curb-curb): 28 ft.	Steel Tonnage: 96	
Paint Age: 29	Paint Color: Light Green	N/A	Steel Surf. Area: 10,560 sqft	BMS Cond State 2: 2,150 sqft	BMS Cond State 3: 75 sqft
Next Paint Year: 2021	2011-13 Rank: 62	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$264,000

## Past Paint History

Years	Cycle
1981	12
1969	10
1959	12
1947	29

### Painting Cycle



■ = Current Paint Age



This road was turned over to the county as part of the 1991 RJT transfer. WSDOT still has maintenance responsibility on the bridge. The old bridge number was 403/7.

The paint is still in good condition with a few spot rusting areas on the bottom flange of some steel beams. The next paint contract should exclude the steel members constructed as part of the seismic retrofit at the north and south ends of the steel beam spans.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 4 / 120		Bridge Name: SKAMOKAWA CR CS3505		Milepost: 28.92	Region: Southwest
Year Built 1939	Bridge Type: SG CTB TTT		Steel Span Length: 105 ft.	Width (curb-curb): 24 ft.	Steel Tonnage: 146
Paint Age: 20	Paint Color: 26307 Light Gray	Steel Surf. Area: 21,900 sqft	BMS Cond State 2: 9,000 sqft	BMS Cond State 3: 200 sqft	
Next Paint Year: 2021	2011-13 Rank: 75	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$547,500

## Past Paint History

Years	Cycle
1990	12
1978	12
1966	9
1957	6
1951	

### Painting Cycle



■ = Current Paint Age



**No Photo Available**

**No Photo Available**

This bridge was originally designed to be a movable bridge.

There is dirt and debris up to 6" deep on the bottom flanges of steel through girders at floor beam gussets and next to drain pipes. Many rust spots and blistered paint on top flange. Light rust pack on top flanges of floor beams near ends.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 4 / 209		Bridge Name: HALF BR W OF BUNKER HILL		Milepost: 49.80	Region: Southwest
Year Built 1930	Bridge Type: SB CS		Steel Span Length: 29 ft.	Width (curb-curb): 26 ft.	Steel Tonnage: 8
Paint Age: 32	Paint Color: Light Green	N/A	Steel Surf. Area: 880 sqft	BMS Cond State 2: 390 sqft	BMS Cond State 3: 50 sqft
Next Paint Year: 2019	2011-13 Rank: 59	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$200,000

## Past Paint History

Years	Cycle
1978	18
1950	

### Painting Cycle



■ = Current Paint Age



**No Photo Available**

**No Photo Available**

The bridge is located at the east approach to the half bridge. The roadway is very narrow in this location making the access and inspection difficult.

The paint is in fair condition. None of the steel beams have significant rusting but a couple of the bolts in the diaphragms are very rusty.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 5 / 40E		Bridge Name: LEWIS R		Milepost: 19.87	Region: Southwest
Year Built 1968	Bridge Type: ST CBOX	Steel Span Length: 810 ft.	Width (curb-curb): 48 ft.	Steel Tonnage: 1,117	
Paint Age: 20	Paint Color: Evergreen	34097	Steel Surf. Area: 167,550 sqft	BMS Cond State 2: 55,850 sqft	BMS Cond State 3: 50,265 sqft
Next Paint Year: 2012	2011-13 Rank: 3	Past Due / Due / OK Past Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$7,260,500

## Past Paint History

Years	Cycle
1990	12
1978	10
1968	

## Painting Cycle



■ = Current Paint Age



The top chords, bottom chords, end posts, end portals and some of the sways need to have full paint removal. The rest of the bridge could be overcoated.

Testing of the paint is needed to see if it can be overcoated.

### Bridge Inspector's Note:

Peeling and cracking paint on stringers and floor beams. Up to 30% of surface area of upper truss has surface rust. Paint is peeling on the inside of the bottom chord. Some blistering on the tops of the diagonals.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 5 / 40W		Bridge Name: LEWIS R		Milepost: 19.83	Region: Southwest
Year Built 1940	Bridge Type: ST CTB	Steel Span Length: 810 ft.	Width (curb-curb): 48 ft.	Steel Tonnage: 1,536	
Paint Age: 20	Paint Color: Evergreen	Steel Surf. Area: 230,400 sqft	BMS Cond State 2: 138,240 sqft	BMS Cond State 3: 11,520 sqft	
Next Paint Year: 2012	2011-13 Rank: 2	Past Due / Due / OK Past Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$9,984,000

## Past Paint History

Years	Cycle
1990	12
1978	9
1969	8
1961	11
1950	

## Painting Cycle



■ = Current Paint Age



The top chords, bottom chords, end posts, end portals and some of the sways need to have full paint removal.

### Bridge Inspector's notes:

Paint is peeling and cracking over large areas of the steel truss surface. Freckled rust spots throughout the truss. Primer is visible in many areas due to the loss of the top coat. Portal frame faces are rusty. Top chord, top surfaces of top chords from U1 thru U29 have bare metal visible. Sway frames and cross bracing have bare metal visible. Floorbeams and stringers have many areas of peeling paint with surface rust.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 5 / 104W		Bridge Name: DIKE ACCESS RD & RR OC		Milepost: 22.72	Region: Southwest
Year Built 1972	Bridge Type: SB		Steel Span Length: 675 ft.	Width (curb-curb): 52 ft.	Steel Tonnage: 810
Paint Age: 38	Paint Color: Steel Gray	G-148	Steel Surf. Area: 89,100 sqft	BMS Cond State 2: 1,000 sqft	BMS Cond State 3: 0 sqft
Next Paint Year: 2017	2011-13 Rank: 36	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$2,227,500

## Past Paint History

Years  
1972

### Painting Cycle



■ = Current Paint Age



**No Photo Available**

**No Photo Available**

The paint still looks to be in good condition. There are a few areas of rust staining on the bottom flange of the steel beams.

The cost to replace this bridge is approximately 52'x 675'x \$400/SF = \$14.0 million.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 5 / 105W		Bridge Name: BN RR OC (NP)		Milepost: 26.01	Region: Southwest
Year Built 1972	Bridge Type: SB		Steel Span Length: 384 ft.	Width (curb-curb): 52 ft.	Steel Tonnage: 400
Paint Age: 38	Paint Color: Steel Gray	G-148	Steel Surf. Area: 44,000 sqft	BMS Cond State 2: 0 sqft	BMS Cond State 3: 880 sqft
Next Paint Year: 2017	2011-13 Rank: 35	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$1,100,000

## Past Paint History

Years  
1972

Cycle

### Painting Cycle



■ = Current Paint Age



The paint still looks to be in good condition. There are a few areas of rust staining on the bottom flange of the steel beams.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 5 / 203E		Bridge Name: COWLITZ R		Milepost: 59.06	Region: Southwest
Year Built 1953	Bridge Type: ST CTB		Steel Span Length: 483 ft.	Width (curb-curb): 33 ft.	Steel Tonnage: 588
Paint Age: 18	Paint Color: Evergreen	34097	Steel Surf. Area: 88,200 sqft	BMS Cond State 2: 40,000 sqft	BMS Cond State 3: 1,000 sqft
Next Paint Year: 2017	2011-13 Rank: 32	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$2,205,000

## Past Paint History

Years	Cycle
1992	10
1982	11
1971	7
1964	11
1953	11

## Painting Cycle



■ = Current Paint Age



First project to use the current 3-part; Zinc prime coat , MC urethane intermediate and final coat.

### Bridge Inspection Notes:

There are rust blooms and bare spots throughout. Paint on top of the top chords is weathered with some rust blooms and peeling paint. The sides of top chords, the verticals, and the diagonals are typically moss stained.

The tops of the floorbeam bottom flanges have thick paint with some cracking and flaking over about 10 percent of the surface area.

The tops of stringer bottom flanges have scattered areas of peeling paint.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 5 / 203W		Bridge Name: COWLITZ R		Milepost: 59.06	Region: Southwest
Year Built 1953	Bridge Type: ST CTB		Steel Span Length: 483 ft.	Width (curb-curb): 31.9 ft.	Steel Tonnage: 588
Paint Age: 18	Paint Color: Evergreen	34097	Steel Surf. Area: 88,200 sqft	BMS Cond State 2: 800 sqft	BMS Cond State 3: 100 sqft
Next Paint Year: 2017	2011-13 Rank: 31	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$2,205,000

## Past Paint History

Years	Cycle
1992	10
1982	11
1971	7
1964	11
1953	

### Painting Cycle



= Current Paint Age

**No Photo Available**



First project to use the current 3-part; Zinc prime coat , MC urethane intermediate and final coat.

The cost to replace this bridge is approximately 36'x 760'x \$400/SF = \$11.0 million.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 5 / 232E		Bridge Name: SKOOKUMCHUCK R		Milepost: 82.28	Region: Southwest
Year Built 1951	Bridge Type: ST CTB		Steel Span Length: 160 ft.	Width (curb-curb): 31 ft.	Steel Tonnage: 181
Paint Age: 28	Paint Color: Evergreen	34097	Steel Surf. Area: 27,150 sqft	BMS Cond State 2: 14,297 sqft	BMS Cond State 3: 572 sqft
Next Paint Year: 2012	2011-13 Rank: 5	Past Due / Due / OK Past Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$1,267,000

## Past Paint History

Years	Cycle
1982	11
1971	7
1964	12
1952	28

### Painting Cycle



■ = Current Paint Age



This bridge was going to be replaced but due to estimated high project costs the SW Region decided to leave this bridge in service and build a parallel Collector/Distributor ramp bridge.

This paint on this bridge is the oldest of any WSDOT steel truss bridge not to be replaced.

The next painting project (around 2013) will require full removal of the existing paint using an SSPC-SP6 standard and then applying a new zinc-moisture cured urethane paint system.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 5 / 232W		Bridge Name: SKOOKUMCHUCK R		Milepost: 82.28	Region: Southwest
Year Built 1951	Bridge Type: ST CTB	Steel Span Length: 160 ft.	Width (curb-curb): 31 ft.	Steel Tonnage: 181	
Paint Age: 28	Paint Color: Evergreen	Steel Surf. Area: 27,150 sqft	BMS Cond State 2: 5,000 sqft	BMS Cond State 3: 1,500 sqft	
Next Paint Year: 2012	2011-13 Rank: 4	Past Due / Due / OK Past Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$1,267,000

## Past Paint History

Years	Cycle
1982	11
1971	7
1964	12
1952	28

### Painting Cycle



■ = Current Paint Age



This bridge was going to be replaced but due to estimated high project costs the SW Region decided to leave this bridge in service and build a parallel Collector/Distributor ramp bridge.

This paint on this bridge is the oldest of any WSDOT bridge not to be replaced.

The next painting project (around 2013) will require full removal of the existing paint using an SSPC-SP6 standard and then applying a new zinc-moisture cured urethane paint system.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 5 / 345E		Bridge Name: NISQUALLY RIVER		Milepost: 114.86	Region: Olympic
Year Built 1937	Bridge Type: ST PCB	Steel Span Length: 323 ft.	Width (curb-curb): 42.6 ft.	Steel Tonnage: 530	
Paint Age: 22	Paint Color: Evergreen	34097	Steel Surf. Area: 79,500 sqft	BMS Cond State 2: 23,850 sqft	BMS Cond State 3: 4,500 sqft
Next Paint Year: 2012	2011-13 Rank: 9	Past Due / Due / OK Past Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$3,445,000

## Past Paint History

Years	Cycle
1988	10
1978	13
1965	8
1957	10
1947	

### Painting Cycle



■ = Current Paint Age



May 2009 bridge inspection report notes:

Heavy accumulation of dirt and debris on and inside the truss bottom chords, heaviest in many panel point connections. Rust blooms and some rivet section loss inside bottom chords. Some pack rust noted. Some Laminar rust along top flange of steel floor beams. Top flange rust on steel stringers. Many of the top sway braces between the two truss over the roadway deck are heavily rusted.

Fatigue cracks in the steel stringers were repaired by contract in 2009.

Next Paint Project:

Full removal of the existing lead paint system is required. The new paint system will include a zinc primer and moisture cured urethane.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 5 / 345W		Bridge Name: NISQUALLY R		Milepost: 114.86	Region: Olympic
Year Built 1967	Bridge Type: ST PCB		Steel Span Length: 322 ft.	Width (curb-curb): 48 ft.	Steel Tonnage: 506
Paint Age: 22	Paint Color: Evergreen	34097	Steel Surf. Area: 75,900 sqft	BMS Cond State 2: 26,565 sqft	BMS Cond State 3: 3,795 sqft
Next Paint Year: 2012	2011-13 Rank: 8	Past Due / Due / OK Past Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$3,303,835

## Past Paint History

Years	Cycle
1988	10
1978	11
1967	

## Painting Cycle



= Current Paint Age



April 2009 bridge inspection report notes:

The paint is thin and chalky throughout. There is peeling paint, surface rust and rust blooms inside the steel bottom chord and other members.

### Next Paint Project:

Full removal of the existing lead paint system is required. The new paint system will include a zinc primer and moisture cured urethane.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 5 / 526.1		Bridge Name: ARCHIE CODIGA BRIDGE		Milepost: 156.48	Region: Northwest
Year Built 1966	Bridge Type: SB TTT		Steel Span Length: 645 ft.	Width (curb-curb): 26 ft.	Steel Tonnage: 248
Paint Age: 33	Paint Color: 26307 Light Gray	Steel Surf. Area: 27,280 sqft	BMS Cond State 2: 1,400 sqft	BMS Cond State 3: 1,300 sqft	
Next Paint Year: 2019	2011-13 Rank: 57	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$682,000

## Past Paint History

Years	Cycle
1977	11
1966	

## Painting Cycle



■ = Current Paint Age



### Bridge Inspector's Notes:

Top flange rust in exterior stringers at sidewalk joints. Rust blooms in both top and bottom flanges. Large piles of pigeon guano on bottom lateral gusset plates. Fire damage at east abutment burnt an area of the paint but no significant damage. Peeling paint is more prevalent in Spans 1 and 2.

### Bridge Office Recommendation:

Contain steel spans, use a SP7 Sweep blast, overcoat with a 2 coat moisture cured urethane.

Estimate Bridge Item costs using \$20/SF steel area. Total cost = Br\$ x 1.5

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 5 / 532W		Bridge Name: SB VIADUCT STA 1918		Milepost: 160.07	Region: Northwest
Year Built 1967	Bridge Type: SG		Steel Span Length: 529 ft.	Width (curb-curb): 76.9 ft.	Steel Tonnage: 417
Paint Age: 24	Paint Color: 26307 Light Gray	Steel Surf. Area: 45,870 sqft	BMS Cond State 2: 2,300 sqft	BMS Cond State 3: 800 sqft	
Next Paint Year: 2017	2011-13 Rank: 33	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$1,146,750

## Past Paint History

Years	Cycle
1986	9
1977	10
1967	

## Painting Cycle



■ = Current Paint Age



**No Photo Available**

This bridge was widened as part of contract #14543. Two new steel beams were added to the west outside of the bridge (131 tons). These new beams have a paint thickness of 7.0mils and used a "Washington Gray" color. The next paint project on this bridge should exclude the new beam since it was painted with a zinc primer and moisture cured urethane top coat.

### Bridge Inspection Notes:

The paint is chalky throughout with areas that are peeling and flaking, especially along the bottom of the girder top flanges. There are many areas of spot rusting.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 5 / 650W		Bridge Name: EBEY SL BN RY SR 529 OC		Milepost: 198.51	Region: Northwest
Year Built 1954	Bridge Type: SG CTB		Steel Span Length: 300 ft.	Width (curb-curb): 54 ft.	Steel Tonnage: 445
Paint Age: 22	Paint Color: 26307 Light Gray	Steel Surf. Area: 48,950 sqft	BMS Cond State 2: 2,500 sqft	BMS Cond State 3: 250 sqft	
Next Paint Year: 2017	2011-13 Rank: 34	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$1,223,750

## Past Paint History

Years	Cycle
1988	13
1975	10
1965	11
1954	22

### Painting Cycle



■ = Current Paint Age



The inspection report says:

"A few small areas of missing paint on the bottom flanges. Light top flange rust on beams and cross brace channels below the deck slab joint over piers 24 and 25. Pigeon nests and guano on lateral gusset plates and bottom flanges. Center wind locks over plate under south link & pins in span 24 is rusted and jammed with 5/8" of rust pack."

The cost to replace the steel spans is approximately 54'x 300'x \$400/SF = \$6.5 million.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 5 / 670W		Bridge Name: STILLAGUAMISH R		Milepost: 209.35	Region: Northwest
Year Built 1933	Bridge Type: ST CTB		Steel Span Length: 600 ft.	Width (curb-curb): 48 ft.	Steel Tonnage: 759
Paint Age: 17	Paint Color: Steel Gray	26329	Steel Surf. Area: 113,850 sqft	BMS Cond State 2: 3,500 sqft	BMS Cond State 3: 1,000 sqft
Next Paint Year: 2015	2011-13 Rank: 30	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$2,846,250

## Past Paint History

Years	Cycle
1993	9
1984	8
1976	23
1953	20
1933	

### Painting Cycle



■ = Current Paint Age



The 1993 painting contract was one of the first in the state that required the containment and disposal of the abrasives used to prepare the steel surfaces. The inspection report says that there is "small rust blooms scattered throughout. Some rust at bottom gusset connections to the bottom chord. Rust staining on top flanges of stringers and floorbeams." As part of the cost estimate for the next painting project, an assumption of 15% of the total steel area will need abrasive blasting.

The bridge deck is scheduled to be replaced in the 2013-15 biennium. The bridge painting should follow the deck replacement in a separate project.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 5 / 828E		Bridge Name: NOOKSACK R		Milepost: 263.05	Region: Northwest
Year Built 1955	Bridge Type: ST CTB		Steel Span Length: 220 ft.	Width (curb-curb): 28 ft.	Steel Tonnage: 222
Paint Age: 23	Paint Color: 26307 Light Gray	Steel Surf. Area: 33,300 sqft	BMS Cond State 2: 10,000 sqft	BMS Cond State 3: 3,330 sqft	
Next Paint Year: 2012	2011-13 Rank: 7	Past Due / Due / OK Past Due	CPMS Ad date:	Paint Pin Number: 100595E	Future Paint Cost: \$1,554,000

## Past Paint History

Years	Cycle
1987	11
1976	8
1968	13
1955	23

## Painting Cycle



= Current Paint Age



## Bridge Inspection Notes:

The paint system is chalking, peeling, and curling. Paint has peeled up to 10% of area to exposed rusty metal. Paint has peeled up to 30% of area without exposed metal.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 5 / 828W		Bridge Name: NOOKSACK R		Milepost: 263.05	Region: Northwest
Year Built 1971	Bridge Type: ST PCB		Steel Span Length: 220 ft.	Width (curb-curb): 38 ft.	Steel Tonnage: 201
Paint Age: 23	Paint Color: 26307 Light Gray	Steel Surf. Area: 30,150 sqft	BMS Cond State 2: 20,000 sqft	BMS Cond State 3: 500 sqft	
Next Paint Year: 2012	2011-13 Rank: 6	Past Due / Due / OK Past Due	CPMS Ad date:	Paint Pin Number: 100595E	Future Paint Cost: \$1,407,000

## Past Paint History

Years	Cycle
1987	10
1977	7
1970	

## Painting Cycle



■ = Current Paint Age



## Bridge Inspection Notes:

**STEEL STRINGERS** - Some of the ends near the floor beams are rusting in the top flange.

**FLOOR BEAMS** - Top flange of the floor beams are rusting with up to 5% section loss. The top flange at the ends has the most advanced rusting.

**TRUSS BOTTOM CHORD** - Pack rust between the bottom lateral gusset plates and the bottom chord with a few starting to bulge. Paint is peeling with over 40% gone exposing the previous paint. The top paint is not adhering to the bottom paint. Pigeon quano noted.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 6 / 118		Bridge Name: CHEHALIS R ADNA		Milepost: 46.59	Region: Southwest
Year Built 1971	Bridge Type: SB		Steel Span Length: 406 ft.	Width (curb-curb): 40 ft.	Steel Tonnage: 285
Paint Age: 39	Paint Color: Steel Gray	G-148	Steel Surf. Area: 31,350 sqft	BMS Cond State 2: 12,000 sqft	BMS Cond State 3: 30 sqft
Next Paint Year: 2019	2011-13 Rank: 55	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$783,750

## Past Paint History

Years  
1971

### Painting Cycle



■ = Current Paint Age



The steel beams are a combination of A588 weathering steel and A441. The areas under the expansion joints at piers 1 & 4 are A441.

### Bridge Inspection Notes:

Chalky thin paint on body of girder webs. Several 1" diameter paint chips on outside girders. Girders have newer paint on the west face compared to the rest of the girders. Girder 2B has paint blistered off the flange connection bolts.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 7 / 105		Bridge Name: MASHEL R		Milepost: 27.91	Region: Olympic
Year Built 1948	Bridge Type: SB		Steel Span Length: 195 ft.	Width (curb-curb): 24 ft.	Steel Tonnage: 99
Paint Age: 26	Paint Color: Steel Gray	26329	Steel Surf. Area: 10,890 sqft	BMS Cond State 2: 700 sqft	BMS Cond State 3: 500 sqft
Next Paint Year: 2021	2011-13 Rank: 67	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$272,250

## Past Paint History

Years	Cycle
1984	11
1973	25
1948	

## Painting Cycle



■ = Current Paint Age



### Bridge Inspection note:

Paint is peeling on the outside edges of bottom flange of rolled girders and riveted girders. Top flange surface rust on steel girders.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 9 / 118		Bridge Name: SNOHOMISH R		Milepost: 9.17	Region: Northwest
Year Built 1959	Bridge Type: ST CBOX CTB	Steel Span Length: 300 ft.	Width (curb-curb): 29.3 ft.	Steel Tonnage: 320	
Paint Age: 20	Paint Color: Evergreen	34097	Steel Surf. Area: 48,000 sqft	BMS Cond State 2: 9,435 sqft	BMS Cond State 3: 1,572 sqft
Next Paint Year: 2015	2011-13 Rank: 27	Past Due / Due / OK Past Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$2,240,000

## Past Paint History

Years	Cycle
1990	9
1981	10
1971	12
1959	

## Painting Cycle



■ = Current Paint Age



**No Photo Available**

### Bridge Inspection Notes:

Truss members are moss covered and have peeling paint. Inside faces have more peeling paint than the outside faces. There is bird guano and dirt accumulations up to 3" deep in joint areas. The gray primer is exposed and peeling paint as noted: Top Chord - 80% gone; Diagonals - 40% gone; Bottom Chord - 50% gone.

Full removal of the paint is warranted based on the condition of the existing paint.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 9 / 122		Bridge Name: SR 9 OC, BICKFORD AVE		Milepost: 10.87	Region: Northwest
Year Built 1963	Bridge Type: SB TTT		Steel Span Length: 64 ft.	Width (curb-curb): 30 ft.	Steel Tonnage: 28
Paint Age: 35	Paint Color: N/A	N/A	Steel Surf. Area: 3,080 sqft	BMS Cond State 2: 1,500 sqft	BMS Cond State 3: 600 sqft
Next Paint Year: 2015	2011-13 Rank: 29	Past Due / Due / OK Past Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$196,000

## Past Paint History

Years	Cycle
1975	12
1963	

### Painting Cycle



■ = Current Paint Age



### Bridge Inspector's Notes:

Spots of surface rust throughout. Peeled paint and sheet rust on girder end bottom flanges and on flange edges. Rust freckles on many bolts and end cross bracing elements.

### Bridge Office Recommendation:

Use a containment system, prepare steel using SP7 Sweep blast, apply a three coat rust penetrating sealer paint system.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 12 / 241		Bridge Name: TWIN CANYON CR		Milepost: 89.48	Region: Southwest
Year Built 1967	Bridge Type: SB		Steel Span Length: 410 ft.	Width (curb-curb): 28 ft.	Steel Tonnage: 177
Paint Age: 32	Paint Color: Light Brown	30277	Steel Surf. Area: 19,470 sqft	BMS Cond State 2: 402 sqft	BMS Cond State 3: 27 sqft
Next Paint Year: 2019	2011-13 Rank: 51	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$486,750

## Past Paint History

Years	Cycle
1978	11
1967	

## Painting Cycle



■ = Current Paint Age



The bridge has three steel girders with a 7'-4" height and spaced 11.5' apart.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 12 / 309		Bridge Name: WILDCAT CR		Milepost: 165.95	Region: Southwest
Year Built 1936	Bridge Type: SB TTT		Steel Span Length: 35 ft.	Width (curb-curb): 26 ft.	Steel Tonnage: 10
Paint Age: 28	Paint Color: 30318 Warm Conc Gray	Steel Surf. Area: 1,100 sqft	BMS Cond State 2: 110 sqft	BMS Cond State 3: 110 sqft	
Next Paint Year: 2015	2011-13 Rank: 19	Past Due / Due / OK Past Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$200,000

## Past Paint History

Years	Cycle
1982	16
1966	30
1936	

### Painting Cycle



■ = Current Paint Age



### Bridge Inspector's Notes:

Paint has failed in many areas but mostly at east end of girders and diaphragm over Pier 5. Rust blooms in several areas of the girder flanges.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 12 / 328N		Bridge Name: NACHES R NELSON		Milepost: 198.66	Region: South Central
Year Built 1958	Bridge Type: ST		Steel Span Length: 304 ft.	Width (curb-curb): 28 ft.	Steel Tonnage: 316
Paint Age: 22	Paint Color: 30277 Light Brown	Steel Surf. Area: 47,400 sqft	BMS Cond State 2: 15,000 sqft	BMS Cond State 3: 1,000 sqft	
Next Paint Year: 2017	2011-13 Rank: 44	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$1,185,000

## Past Paint History

Years	Cycle
1988	10
1978	7
1971	13
1958	

## Painting Cycle



= Current Paint Age



## Bridge Inspection Notes:

Paint is peeling on all members except stringers, mostly in locations where the pigeons are. The green base paint is exposed along the top of the bottom chords. Surface rust is visible on vertical faces exposed to sunlight.  
 Floorbeams - Most have rusting in the top flange. A few small areas of paint peeling scattered throughout.  
 Truss - Pack rust in bottom chord splice plate L6-L7.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 12 / 328S		Bridge Name: NACHES R NELSON		Milepost: 198.66	Region: South Central
Year Built 1966	Bridge Type: ST		Steel Span Length: 304 ft.	Width (curb-curb): 30.2 ft.	Steel Tonnage: 300
Paint Age: 22	Paint Color: Light Brown	30277	Steel Surf. Area: 45,000 sqft	BMS Cond State 2: 20,000 sqft	BMS Cond State 3: 10,000 sqft
Next Paint Year: 2017	2011-13 Rank: 43	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$2,100,000


## Past Paint History

Years	Cycle
1988	10
1978	12
1966	

## Painting Cycle



= Current Paint Age



### Bridge Inspector's notes:

Paint is peeling on all members except stringers, mostly in locations with pigeons guano. The green base paint is exposed along the top of the bottom chords. Surface rust is visible on vertical faces exposed to sunlight.

A paint inspection will be needed to determine if the existing paint can be overcoated or if it needs to be removed.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 18 / 17S		Bridge Name: GREEN R (NEELEY BRIDGE)		Milepost: 6.62	Region: Northwest
Year Built 1959	Bridge Type: ST CBOX	Steel Span Length: 200 ft.	Width (curb-curb): 29.5 ft.	Steel Tonnage: 183	
Paint Age: 22	Paint Color: Evergreen	34097	Steel Surf. Area: 27,450 sqft	BMS Cond State 2: 5,500 sqft	BMS Cond State 3: 3,700 sqft
Next Paint Year: 2014	2011-13 Rank: 14	Past Due / Due / OK Past Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$1,281,000

## Past Paint History

Years	Cycle
1988	11
1977	9
1968	9
1959	

## Painting Cycle



■ = Current Paint Age



### Bridge Inspector's notes:

Rusting in sliding joints at stringers and on top flanges of stringer near floor beams. Rusting in several exposed areas at floor beams.

TRUSS: Mossy growth on paint with a few pits and rust blooms. Rust blooms on portals and top sways throughout. Paint peeling off in sheets on W. portal frame.

FLOOR BEAMS: Mud and rust staining on the top flanges, webs and bottom flanges. Sheet rust on the bottom side of the top flange up to 1/8" deep. Top flange has 5-10% section loss, mostly near the end of the floor beams.

Full removal of the paint is warranted based on existing paint condition.

# Steel Bridge Paint Form




Bridge Number: 20 / 204		Bridge Name: DECEPTION PASS		Milepost: 41.81	Region: Northwest
Year Built 1935	Bridge Type: ST CTB	Steel Span Length: 900 ft.		Width (curb-curb): 22 ft.	Steel Tonnage: 1,168
Paint Age: 13	Paint Color: Evergreen	34097	Steel Surf. Area: 175,200 sqft	BMS Cond State 2: 87,600 sqft	BMS Cond State 3: 10,260 sqft
Next Paint Year: 2019	2011-13 Rank: 50	Past Due/Due/OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$7,592,000

## Years

Years	Cycle
1997	13
1984	7
1977	6
1971	7
1954	

## Painting Cycle



■ = Current Paint Age



Full removal of the existing paint was required to the floor beams and stringers in the last painting contract.

Up to 10% section loss was noted in the top and bottom flanges of the stringers prior to being painted in 1998. Rust at interface between top flanges and deck. Surface rust with some pitting. Pack rust in the bottom flanges and bearing seats with up to 50% section loss, especially Stringers A and E. There are many areas that are rusting through the paint. Paint preparation and thickness varied greatly throughout the bridge from several layers of paint protection to over spray with no preparation to the metal. Rust stains on several of the members. Surface rust on several of the stringers and truss members.

# Steel Bridge Paint Form

2011-13 Biennium Priorities



Bridge Number: 20 / 244		Bridge Name: SCOTT PAPER CO RD UC		Milepost: 76.94	Region: Northwest
Year Built 1967	Bridge Type: SB TTT		Steel Span Length: 41 ft.	Width (curb-curb): 14 ft.	Steel Tonnage: 7
Paint Age: 35	Paint Color: Warm Brown	30099	Steel Surf. Area: 770 sqft	BMS Cond State 2: 77 sqft	BMS Cond State 3: 0 sqft
Next Paint Year: 2019	2011-13 Rank: 56	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$200,000

## Past Paint History

### Years


1975

1967

### Cycle

8

### Painting Cycle



■ = Current Paint Age



**No Photo Available**

**No Photo Available**

The last inspection report says there are a few small paint blisters on the web of beam 3C. There is also light top flange rust on all stringers.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 20 / 311		Bridge Name: HALF BR STA 155		Milepost: 122.41	Region: Northwest
Year Built 1900	Bridge Type: SB		Steel Span Length: 62 ft.	Width (curb-curb): 28 ft.	Steel Tonnage: 38
Paint Age: 26	Paint Color: Steel Gray	26329	Steel Surf. Area: 4,180 sqft	BMS Cond State 2: 418 sqft	BMS Cond State 3: 41 sqft
Next Paint Year: 2021	2011-13 Rank: 65	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$200,000


## Past Paint History

Years	Cycle
1984	22
1962	26

### Painting Cycle



■ = Current Paint Age



This bridge has an open grid deck that has been filled with concrete.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 21 / 334		Bridge Name: KETTLE R		Milepost: 181.00	Region: Eastern
Year Built 1960	Bridge Type: ST	Steel Span Length: 205 ft.	Width (curb-curb): 26 ft.	Steel Tonnage: 180	
Paint Age: 20	Paint Color: 30099 Warm Brown	Steel Surf. Area: 27,000 sqft	BMS Cond State 2: 21,600 sqft	BMS Cond State 3: 5,400 sqft	
Next Paint Year: 2015	2011-13 Rank: 26	Past Due / Due / OK Past Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$1,260,000

## Past Paint History

Years	Cycle
1990	11
1979	10
1969	9
1960	

## Painting Cycle



■ = Current Paint Age



The top flange of the floor beams and stringers are embedded in concrete.

### Bridge Inspector's Notes:

Paint is chalky and peeling, heavy in spots, on the diagonals and portals of the truss with rust blooms, approximately 15%. The paint on the stringers and floor beams is in good condition except for scattered rock chips from kids throwing rocks at swallow nests. The sand build up on the lower chord has been flushed, revealing the failed paint system.

Full removal of the paint is warranted on the top and bottom chords and the connection areas.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 24 / 105		Bridge Name: COLUMBIA R VERNITA		Milepost: 43.60	Region: South Central
Year Built 1965	Bridge Type: ST PCB		Steel Span Length: 579 ft.	Width (curb-curb): 28 ft.	Steel Tonnage: 486
Paint Age: 17	Paint Color: Gold	30266	Steel Surf. Area: 72,900 sqft	BMS Cond State 2: 5,832 sqft	BMS Cond State 3: 1,458 sqft
Next Paint Year: 2019	2011-13 Rank: 45	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$1,822,500

## Past Paint History

Years	Cycle
1993	15
1978	13
1965	

## Painting Cycle



■ = Current Paint Age



## Bridge Inspection Notes:

Stringers - Bottom flanges have up to 12 square inch areas of peeling paint. A few small areas of peeled rusty paint. Some paint chips.

Bottom Chord -The paint is thin in places and has small areas of peeling; a few rusty. Rusty peeling paint in isolated areas of the bottom chord for total of 1% of area. Through Truss - There are scattered small areas of peeling paint on a few diagonals. There are small areas of thin paint on the top chord total area less than 3%. The top chord has peeling paint on the bottom side. Truss diagonals and verticals have scattered peeling rusty areas 2% of total area. Truss top laterals have peeling paint with some rust on 5% of the area. Floorbeams - There is peeling paint on the bottom flanges, and within the bottom chord, and on the lateral bracing.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 25 / 130		Bridge Name: COLUMBIA R @ NORTHPORT		Milepost: 113.92	Region: Eastern
Year Built 1948	Bridge Type: ST CTB CG CS		Steel Span Length: 840 ft.	Width (curb-curb): 24 ft.	Steel Tonnage: 1,167
Paint Age: 18	Paint Color: Evergreen	34097	Steel Surf. Area: 175,050 sqft	BMS Cond State 2: 10,000 sqft	BMS Cond State 3: 930 sqft
Next Paint Year: 2019	2011-13 Rank: 54	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$7,585,500

## Past Paint History

Years	Cycle
1992	13
1979	8
1971	9
1962	11
1951	

## Painting Cycle



■ = Current Paint Age



### Bridge Inspector's note:

Paint is missing from most steel members due to the impact of snow removal with gravel. Steel Floorbeams; Peeling paint throughout webs. Steel Truss Members; The primer is exposed in places with some light rust where the paint has failed completely. The top paint coat is also peeling off in places with scattered rust blooms, particularly at top sways and laterals and inside top chords. Surface rust on the truss members at the deck level to about 6 ft. off of the deck. Paint is peeling inside most of the enclosed truss members. Metal Bridge Railing; All members are rusty with paint peeling or missing on 30% of the surface.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 27 / 12		Bridge Name: N FK PALOUSE R		Milepost: 15.02	Region: Eastern
Year Built 1938	Bridge Type: SG CTB		Steel Span Length: 95 ft.	Width (curb-curb): 24 ft.	Steel Tonnage: 82
Paint Age: 28	Paint Color: 26307 Light Gray	Steel Surf. Area: 12,300 sqft	BMS Cond State 2: 4,800 sqft	BMS Cond State 3: 100 sqft	
Next Paint Year: 2021	2011-13 Rank: 63	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$574,000

## Past Paint History

Years	Cycle
1982	13
1969	16
1953	15
1938	

## Painting Cycle



■ = Current Paint Age



All the paint on the top flange of the open girder should be removed to bare metal.

Bridge Inspector's notes:

Thin and peeling paint with surface rust on most of the top flange of the girders (Photo 15). Paint is worn and peeling on lower portions of webs and bottom flanges of girders (approximately 20%). Rust blooms on lower webs and bottom flanges of girder (approximately 5%). Top coat of paint is peeling on floorbeams exposing primer (approximately 20% - Photo 22). A few areas of surface rust (less than 5%) on floorbeams.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 82 / 280S		Bridge Name: COLUMBIA R BR @ UMATILLA		Milepost: 132.36	Region: South Central
Year Built 1955	Bridge Type: ST SB		Steel Span Length: 3380 ft.	Width (curb-curb): 27.5 ft.	Steel Tonnage: 3,737
Paint Age: 19	Paint Color: Warm Conc Gray	30318	Steel Surf. Area: 560,550 sqft	BMS Cond State 2: 30,000 sqft	BMS Cond State 3: 2,000 sqft
Next Paint Year: 2017	2011-13 Rank: 37	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$12,000,000

## Past Paint History

Years	Cycle
1991	17
1974	19
1955	

## Painting Cycle



■ = Current Paint Age



## Bridge Inspection Notes:

**Truss Floor System** - The truss stringer diaphragms have flaking paint top coat in many places over approximately 10% of area. Many stringers have very thin paint. Approximately 5% of the stringer area is affected. There is extensive peeling paint on the stringers in the east bays of the east truss span. The truss floor beam bottom flanges have peeled paint in 2 sq.ft. areas ( approximately 2% peeling).

**Truss Bottom Chord** - There are areas on the bottom of the bottom chord and inside the bottom chord that have missing or peeled off top coat, amounting to approximately 5% of the total painted area. The drop in span bottom of the South bottom chord has up to 10% peeled paint. The girder cross brace chord angles have flaking top coat of paint on approximately 5% of the area.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 90 / 25S		Bridge Name: LACEY V. MURROW BRIDGE		Milepost: 4.24	Region: Northwest
Year Built 1940	Bridge Type: CFP SA ST CBOX S		Steel Span Length: 884 ft.	Width (curb-curb): 52 ft.	Steel Tonnage: 2,900
Paint Age: 17	Paint Color: Wa. Gray	N/A	Steel Surf. Area: 435,000 sqft	BMS Cond State 2: 145,000 sqft	BMS Cond State 3: 0 sqft
Next Paint Year: 2015	2011-13 Rank: 16	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$18,850,000

## Past Paint History

Years	Cycle
1993	17
1976	10
1966	7
1959	10
1949	17

## Painting Cycle



■ = Current Paint Age



The steel truss spans were spread apart and rehabilitated as part of the bridge widening project in 1993. Full containment was used during the painting work.

### Bridge Inspection Notes:

Exterior stringers in the deck truss have approximately 30% of the surface paint layer flaking off and areas of freckle rust. Stringers in the tied arch spans have approximately 50% of the top coat peeling throughout. Surface layer of paint is flaking off on approximately 5% of the truss members. Approximately 10% of the top coat of paint is peeling off of the outside flanges of the tied arch hangers, and 5% off of the arch ties. All floorbeams in deck truss have top layer of paint flaking off.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 90 / 180		Bridge Name: COLUMBIA R VANTAGE		Milepost: 137.19	Region: South Central
Year Built 1962	Bridge Type: ST SA SG		Steel Span Length: 2504 ft.	Width (curb-curb): 56 ft.	Steel Tonnage: 4,063
Paint Age: 26	Paint Color: Gold	33448	Steel Surf. Area: 446,930 sqft	BMS Cond State 2: 300 sqft	BMS Cond State 3: 80 sqft
Next Paint Year: 2015	2011-13 Rank: 13	Past Due / Due / OK Past Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$5,000,000

## Past Paint History

Years	Cycle
1984	9
1975	13
1962	

## Painting Cycle



■ = Current Paint Age



The paint on the steel girder approaches and the upper portion of the truss was last painted in 1984. These elements still should be coded with the BMS element 901.

A 2002 project (contract 16387) painted the steel elements under the deck in the truss spans and truss elements 10' above the roadway deck. The quantity was approximately 141,400 sq ft.

The steel surface above the roadway deck need to be painted.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 97 / 1		Bridge Name: BIGGS RAPIDS-SAM HILL BR		Milepost: 0.00	Region: Southwest
Year Built 1962	Bridge Type: ST SB		Steel Span Length: 2567 ft.	Width (curb-curb): 26 ft.	Steel Tonnage: 1,847
Paint Age: 23	Paint Color: Warm Brown	30099	Steel Surf. Area: 277,050 sqft	BMS Cond State 2: 133,000 sqft	BMS Cond State 3 81,200 sqft
Next Paint Year: 2014	2011-13 Rank: 11	Past Due/Due/OK Past Due	CPMS Ad date: 5/7/2014	Paint Pin Number: 409712P	Future Paint Cost: \$12,605,100


**Years**

Years	Cycle
1988	15
1973	11
1962	

**Painting Cycle**



■ = Current Paint Age



This is a border bridge that is maintained by Washington and reimbursed 50% by Oregon. There is one steel truss main span with steel girder approach spans. The bridge deck was replaced in 2009.

**Bridge Inspection notes:**

The paint is peeling and curling with exposed and rusty spots on the webs of the girders.

**Bridge Office Recommendations:**

Full removal of the existing paint and apply a new three coat moisture cured urethane paint.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 97 / 420		Bridge Name: COLUMBIA R BEEBE		Milepost: 235.06	Region: North Central
Year Built 1962	Bridge Type: SA CBOX	Steel Span Length: 1040 ft.	Width (curb-curb): 26 ft.	Steel Tonnage: 1,296	
Paint Age: 22	Paint Color: 20040 Dark Brown	Steel Surf. Area: 194,400 sqft	BMS Cond State 2: 20,000 sqft	BMS Cond State 3: 3,000 sqft	
Next Paint Year: 2019	2011-13 Rank: 46	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$4,860,000


## Past Paint History

Years	Cycle
1988	10
1978	16
1962	

## Painting Cycle



= Current Paint Age



The vertical hangers are color Fed No 30318 - Light Brown.

### Bridge Inspection Notes:

Various members of Spans 1, 2, and 3 have areas of peeled paint and primer exposing bare steel and have surface rust. Some of stringers show areas of laminar rust in the top flange at the floorbeam connections. Most of the bottom chord vertical gussets where three members in the vertical plane frame that were filled with dirt are now cleaned. Some of stringers show areas of laminar rust in the top flange at the floorbeam connections. Steel arch in Span 2. Light surface rust on many of the members.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 99 / 538		Bridge Name: SPOKANE ST OC		Milepost: 29.15	Region: Northwest
Year Built 1959	Bridge Type: SB CBOX TTT	Steel Span Length: 192 ft.	Width (curb-curb): 76 ft.	Steel Tonnage: 314	
Paint Age: 22	Paint Color: 26307 Light Gray	Steel Surf. Area: 34,540 sqft	BMS Cond State 2: 1,500 sqft	BMS Cond State 3: 1,000 sqft	
Next Paint Year: 2017	2011-13 Rank: 40	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$863,500

## Past Paint History

Years	Cycle
1988	12
1976	17
1959	

### Painting Cycle



■ = Current Paint Age

**No Photo Available**



**No Photo Available**

The paint thickness was not specified in contract 13456.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 99 / 560		Bridge Name: AURORA AVE-G WASH MEM BR		Milepost: 34.14	Region: Northwest
Year Built 1931	Bridge Type: ST CG		Steel Span Length: 1950 ft.	Width (curb-curb): 56.5 ft.	Steel Tonnage: 7,983
Paint Age: 25	Paint Color: 26307 Light Gray	Steel Surf. Area: 1,197,450 sqft	BMS Cond State 2: 957 sqft	BMS Cond State 3: 120 sqft	
Next Paint Year: 2015	2011-13 Rank: 15	Past Due / Due / OK Past Due	CPMS Ad date:	Paint Pin Number: 109947B	Future Paint Cost: \$50,000,000

## Past Paint History

Years	Cycle
1985	11
1974	12
1962	10
1952	21
1931	21

### Painting Cycle



■ = Current Paint Age



In 1995 (C#14547) 0.75' of the sidewalk and 3.75' of the roadway slab on both sides of the bridge was removed and replaced. The steel supporting this area was rehabilitated and painted with a MC Urethane.

Inspection of the paint is needed to determine if it can be overcoated or not.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 101 / 29		Bridge Name: SOUTH NEMAH R NO 1		Milepost: 32.52	Region: Southwest
Year Built 1957	Bridge Type: SB		Steel Span Length: 48 ft.	Width (curb-curb): 29 ft.	Steel Tonnage: 20
Paint Age: 32	Paint Color: N/A	N/A	Steel Surf. Area: 2,200 sqft	BMS Cond State 2: 1,750 sqft	BMS Cond State 3: 220 sqft
Next Paint Year: 2021	2011-13 Rank: 60	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$200,000

## Past Paint History

Years  
1978

Cycle

### Painting Cycle



■ = Current Paint Age



Since this bridge has a small tonnage the region's maintenance personnel may be able to paint the rusted areas with the "Devoe" rust penetrating sealer.

Bridge Inspector's note:

Paint blisters along girder flanges with rust under the blisters and rust blooms all over webs. Paint failed with heavy rust at several bottom flange splice plates.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 101 / 115		Bridge Name: CHEHALIS R		Milepost: 83.12	Region: Olympic
Year Built 1955	Bridge Type: BAS SG CBOX CTB		Steel Span Length: 606 ft.	Width (curb-curb): 28 ft.	Steel Tonnage: 2,438
Paint Age: 15	Paint Color: 26307 Light Gray	Steel Surf. Area: 365,700 sqft	BMS Cond State 2: 0 sqft	BMS Cond State 3: 0 sqft	
Next Paint Year: 2019	2011-13 Rank: 52	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$9,142,500

## Past Paint History

Years	Cycle
1995	14
1981	10
1971	16
1955	15

## Painting Cycle



■ = Current Paint Age



# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 101 / 125E		Bridge Name: HOQUIAM R-RIVERSIDE 1417		Milepost: 87.31	Region: Olympic
Year Built 1970	Bridge Type: SL SB		Steel Span Length: 465 ft.	Width (curb-curb): 28 ft.	Steel Tonnage: 606
Paint Age: 18	Paint Color: 26329 Steel Gray	Steel Surf. Area: 90,900 sqft	BMS Cond State 2: 10,000 sqft	BMS Cond State 3: 0 sqft	
Next Paint Year: 2015	2011-13 Rank: 18	Past Due / Due / OK Past Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$3,939,000

## Past Paint History

Years	Cycle
1992	12
1980	10
1970	

## Painting Cycle



= Current Paint Age



# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 101 / 125W		Bridge Name: HOQUIAM R-SIMPSON CS1412		Milepost: 86.76	Region: Olympic
Year Built 1928	Bridge Type: BAS ST CG CST		Steel Span Length: 470 ft.	Width (curb-curb): 20 ft.	Steel Tonnage: 638
Paint Age: 18	Paint Color: Steel Gray	26329	Steel Surf. Area: 95,700 sqft	BMS Cond State 2: 87,200 sqft	BMS Cond State 3: 8,500 sqft
Next Paint Year: 2012	2011-13 Rank: 12	Past Due / Due / OK Past Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$4,147,000

## Past Paint History

Years	Cycle
1992	8
1984	7
1977	15
1962	16
1946	

### Painting Cycle



■ = Current Paint Age



The bridge was rehabilitated in 2007 thru 2008.

Bridge Inspector's notes:

Primer coat on bascule span stringer and floorbeams is failed. Paint is peeled off exposing red lead primer. Paint is failed on floor system bracing. Paint is moldy on the bascule floor system beams and is peeled off in large areas exposing red lead. The paint is covered with wet dirt and moss in many parts of the floor system. Paint on the west 150 ft. steel truss bottom chord is rusted through and blistered along the 4" diameter utility.

Next Painting Project - Full removal of all the existing paint is required.

# Steel Bridge Paint Form

2011-13 Biennium Priorities



Bridge Number: 101 / 1(B)		Bridge Name: COL R ASTORIA - OR SIDE		Milepost: 0.00	Region: Southwest
Year Built	Bridge Type: ST SG		Steel Span Length: ft.	Width (curb-curb): ft.	Steel Tonnage:
Paint Age:	Paint Color:	Steel Surf. Area: sqft	BMS Cond State 2: sqft	BMS Cond State 3: sqft	
Next Paint Year: 2011	2011-13 Rank: 1	Past Due / Due / OK	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$18,599,000

## Past Paint History

Years  
Cycle

### Painting Cycle

= Current Paint Age



**No Photo Available**

**No Photo Available**

The Oregon DOT maintains the US 101 Astoria bridge. ODOT is scheduled to repaint the steel spans on the Oregon/Astoria side in 2011. WSDOT will pay 1/2 of the project costs.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 101 / 256		Bridge Name: BIG QUILCENE R		Milepost: 296.67	Region: Olympic
Year Built 1936	Bridge Type: ST CTB	Steel Span Length: 240 ft.	Width (curb-curb): 24 ft.	Steel Tonnage: 121	
Paint Age: 20	Paint Color: Evergreen	34097	Steel Surf. Area: 18,150 sqft	BMS Cond State 2: 5,000 sqft	BMS Cond State 3: 1,500 sqft
Next Paint Year: 2015	2011-13 Rank: 24	Past Due / Due / OK Past Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$847,000

## Past Paint History

Years	Cycle
1990	8
1982	14
1968	22
1946	10
1936	

### Painting Cycle



■ = Current Paint Age



The 1990 painting project specified that areas on top of the bottom chord that entrap water on the sidewalk side of the bridge were to receive 16 mils of coal tar epoxy. Bridge Inspectors Notes:  
Top coat of paint is peeling on bottom flanges of steel stringers. Paint underneath is still intact with very little rust, mostly on top flange at the deck. Paint peeling on face of top chord of thru truss approximately 30% to previous layer of paint.

Next Paint Project will require full paint removal.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 101 / 308		Bridge Name: CALAWAH R		Milepost: 192.36	Region: Olympic
Year Built 1938	Bridge Type: ST CTB	Steel Span Length: 170 ft.	Width (curb-curb): 24 ft.	Steel Tonnage: 159	
Paint Age: 20	Paint Color: Evergreen	Steel Surf. Area: 23,850 sqft	BMS Cond State 2: 23,350 sqft	BMS Cond State 3: 500 sqft	
Next Paint Year: 2021	2011-13 Rank: 73	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$1,113,000

## Past Paint History

Years	Cycle
1990	9
1981	9
1972	9
1963	12
1951	

### Painting Cycle



■ = Current Paint Age



### Bridge Inspection Notes:

The paint system has widespread flaking, especially on inside surfaces of members. The top surfaces of the top chords, top lateral and sway bracing have extensive areas of exposed rusty steel.

Next Paint Project will require full paint removal.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 101 / 310		Bridge Name: SOL DUC R		Milepost: 194.30	Region: Olympic
Year Built 1958	Bridge Type: ST CTB	Steel Span Length: 150 ft.	Width (curb-curb): 26 ft.	Steel Tonnage: 108	
Paint Age: 20	Paint Color: Evergreen	Steel Surf. Area: 16,200 sqft	BMS Cond State 2: 8,100 sqft	BMS Cond State 3: 1,620 sqft	
Next Paint Year: 2015	2011-13 Rank: 21	Past Due / Due / OK Past Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$756,000

## Past Paint History

Years	Cycle
1990	10
1980	8
1972	14
1958	

## Painting Cycle



■ = Current Paint Age



### Bridge Inspection Note:

The steel stringers have scattered areas of peeling paint. The top surfaces of the top chord members have rust blooms and peeling paint. The bottom chord interiors have paint failure causing active corrosion on the inside surfaces, at the rivet heads, and at the plate edges.

Next Paint Project will require full paint removal.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 101 / 322		Bridge Name: SOL DUC RIVER #5		Milepost: 212.46	Region: Olympic
Year Built: 1948	Bridge Type: ST CTB		Steel Span Length: 160 ft.	Width (curb-curb): 24 ft.	Steel Tonnage: 147
Paint Age: 13	Paint Color: Evergreen	34097	Steel Surf. Area: 22,050 sqft	BMS Cond State 2: 4,400 sqft	BMS Cond State 3: 1,100 sqft
Next Paint Year: 2015	2011-13 Rank: 22	Past Due / Due / OK: Past Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$1,029,000

## Past Paint History

Years	Cycle
1997	17
1980	12
1968	14
1954	6
1948	

### Painting Cycle



■ = Current Paint Age



### Bridge Inspection Notes:

Paint on the stringers is starting to peel in the webs and flanges with light rust. Some areas of the bottom chord has peeling paint. 15% of the paint is missing on the top chords of the truss.

Next Paint Project will require full paint removal.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 107 / 4		Bridge Name: CHEHALIS R		Milepost: 6.83	Region: Olympic
Year Built 1958	Bridge Type: ST CBOX TTT		Steel Span Length: 300 ft.	Width (curb-curb): 26 ft.	Steel Tonnage: 319
Paint Age: 20	Paint Color: Evergreen	34097	Steel Surf. Area: 47,850 sqft	BMS Cond State 2: 32,000 sqft	BMS Cond State 3: 3,000 sqft
Next Paint Year: 2015	2011-13 Rank: 23	Past Due / Due / OK Past Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$2,233,000


## Past Paint History

Years	Cycle
1990	10
1980	8
1972	14
1958	14

## Painting Cycle



= Current Paint Age



### Bridge Inspector's Notes:

Peeling paint is typical, especially on and in the bottom chords. The stringer and floorbeam top flanges as well as the truss portal tops and west truss above deck members all have surface rust. The truss also has a few rust blooms.

### Next Paint Project:

Pressure wash bridge with 5,000psi  
 Assume about 15% of the bridge will need rust to be spot blasted  
 Prime blasted areas then Overcoat with two new paint layers

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 109 / 10		Bridge Name: HUMPTULIPS R		Milepost: 10.24	Region: Olympic
Year Built 1956	Bridge Type: ST CTB	Steel Span Length: 234 ft.	Width (curb-curb): 26 ft.	Steel Tonnage: 226	
Paint Age: 19	Paint Color: Evergreen	34097	Steel Surf. Area: 33,900 sqft	BMS Cond State 2: 8,500 sqft	BMS Cond State 3: 7,800 sqft
Next Paint Year: 2015	2011-13 Rank: 25	Past Due / Due / OK Past Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$1,582,000

## Past Paint History

Years	Cycle
1991	10
1981	9
1972	17
1955	

## Painting Cycle



■ = Current Paint Age



### Bridge Inspector's Notes:

Paint is chalky throughout with scattered rust blooms especially on the upper areas of the truss. Many areas of peeling paint and rusty rivet heads on the bottom chord of the truss with areas of exposed metal. Top flanges of upper cross bracing have areas of peeling paint and exposed metal.

Scattered small areas of peeling paint in a few places on lower 10 feet of vertical and diagonal members.

Floorbeams have areas of paint missing on both top and bottom flanges exposing metal which is rusting.

### Next Paint Project:

Pressure wash bridge with 5,000psi

Assume about 20% of the bridge will need rust to be spot blasted

Prime blasted areas then Overcoat with two new paint layers

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 141 / 5		Bridge Name: WHITE SALMON RIVER		Milepost: 8.70	Region: Southwest
Year Built 1940	Bridge Type: ST CTB		Steel Span Length: 120 ft.	Width (curb-curb): 27 ft.	Steel Tonnage: 96
Paint Age: 23	Paint Color: Evergreen	34097	Steel Surf. Area: 21,717 sqft	BMS Cond State 2: 4,600 sqft	BMS Cond State 3 7,200 sqft
Next Paint Year: 2014	2011-13 Rank: 10	Past Due/Due/OK Past Due	CPMS Ad date: 5/7/2014	Paint Pin Number: 414110P	Future Paint Cost: \$860,524

**Years**

Years	Cycle
1988	10
1978	8
1970	7
1963	12
1951	

**Painting Cycle**



■ = Current Paint Age



STRINGERS: Rust stains and light rust on the top flanges.  
 TRUSS: The paint has failed on many members of the steel truss. The amount of paint failure (over 53%) on the trusses warrants full removal. Planned costs are estimated to be:  
 Total cost per surface Area is \$39.6/SF (21,717 / \$860,524)  
 Total cost per tonnage is \$8,963/ton (\$860,524 / 96)  
 Total cost per deck area is \$265.6/SF (\$860,524 / 3,240)  
 Bridge Replacement cost is estimated to be \$7.7 million (40'x193' x \$1,000)

**Bridge Office Recommendations:**

Full removal of the existing paint and apply a new three coat moisture cured urethane paint.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 153 / 4		Bridge Name: METHOW R		Milepost: 4.22	Region: North Central
Year Built 1950	Bridge Type: ST CTB	Steel Span Length: 220 ft.	Width (curb-curb): 24 ft.	Steel Tonnage: 217	
Paint Age: 25	Paint Color: 30318 Warm Conc Gray	Steel Surf. Area: 32,550 sqft	BMS Cond State 2: 5,000 sqft	BMS Cond State 3: 5 sqft	
Next Paint Year: 2021	2011-13 Rank: 68	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$813,750


## Past Paint History

Years	Cycle
1985	16
1969	12
1957	7
1950	25

## Painting Cycle



= Current Paint Age



### Inspector's notes:

BOTTOM CHORD - Light crevice rust with no section loss noted.  
 FLOORBEAM - Minor surface rust at interface with deck. No section loss.  
 PAINT - Very thin and peeling on inside face of top chords.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 155 / 101		Bridge Name: COLUMBIA R GRAND COULEE		Milepost: 28.26	Region: North Central
Year Built 1935	Bridge Type: ST CTB		Steel Span Length: 952 ft.	Width (curb-curb): 20.2 ft.	Steel Tonnage: 1,500
Paint Age: 24	Paint Color: 30318 Warm Conc Gray	Steel Surf. Area: 225,000 sqft	BMS Cond State 2: 25,000 sqft	BMS Cond State 3: 300 sqft	
Next Paint Year: 2021	2011-13 Rank: 69	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$5,625,000


## Past Paint History

Years	Cycle
1986	11
1975	15
1960	25
1935	

## Painting Cycle



= Current Paint Age



The bridge deck is orthotropic. The bottom side of the deck needs to be painted when the bridge is painted. The deck joints may need to be rehabilitated.

The next paint project will likely require full removal of the paint.

### Inspection Notes:

**TRUSS BOTTOM CHORD** - Very light surface rust with minor areas of peeling paint. A few scattered rust blooms. There is some pack rust at the bottom chord/gusset plate connections at a few scattered locations with some minor section loss.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 165 / 10		Bridge Name: CARBON R		Milepost: 11.50	Region: Olympic
Year Built 1921	Bridge Type: SA TTT	Steel Span Length: 240 ft.	Width (curb-curb): 17.4 ft.	Steel Tonnage: 179	
Paint Age: 22	Paint Color: Evergreen	34097	Steel Surf. Area: 26,850 sqft	BMS Cond State 2: 1,000 sqft	BMS Cond State 3: 270 sqft
Next Paint Year: 2021	2011-13 Rank: 71	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$671,250

## Past Paint History

Years	Cycle
1988	9
1979	15
1964	15
1949	28
1921	

### Painting Cycle



■ = Current Paint Age



**No Photo Available**

**No Photo Available**

The timber bridge deck was replaced in 1995 as part of contract 14575.

A fire started on the north timber approaches in March of 1998. The fire damaged the paint on a portion of the north tower and arch.

The inspection report indicates:

The steel arches and compression struts have areas of thin paint with moss growth and rust blooms on rivets and between plates. The paint on the stringers and floor beams is generally in good condition with a few rust blooms.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 167 / 127E		Bridge Name: BN RR OC (NP)		Milepost: 20.96	Region: Northwest
Year Built 1967	Bridge Type: SB	Steel Span Length: 314 ft.	Width (curb-curb): 56 ft.	Steel Tonnage: 150	
Paint Age: 18	Paint Color: 26307 Light Gray	Steel Surf. Area: 16,500 sqft	BMS Cond State 2: 2,000 sqft	BMS Cond State 3: 200 sqft	
Next Paint Year: 2017	2011-13 Rank: 42	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$412,500

## Past Paint History

Years	Cycle
1992	14
1978	11
1967	

## Painting Cycle



■ = Current Paint Age



**No Photo Available**

The thickness of the paint was not specified in contract 14057.

This bridge was widened as part of contract 14771. There are two new girders placed on the north side and one new girder placed on the south side. These girders should be excluded from the next paint contract.

### Bridge Inspection Notes:

There are several areas of thin, peeling paint and spots of surface rust.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 167 / 127W		Bridge Name: BN RR OC (NP)		Milepost: 20.96	Region: Northwest
Year Built 1967	Bridge Type: SB	Steel Span Length: 314 ft.	Width (curb-curb): 50 ft.	Steel Tonnage: 150	
Paint Age: 18	Paint Color: 26307 Light Gray	Steel Surf. Area: 16,500 sqft	BMS Cond State 2: 800 sqft	BMS Cond State 3: 500 sqft	
Next Paint Year: 2017	2011-13 Rank: 41	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$412,500

## Past Paint History

Years	Cycle
1992	14
1978	11
1967	

### Painting Cycle



■ = Current Paint Age



The thickness of the paint was not specified in contract 14057. This bridge was widened as part of contract 14771. There are two new girders placed on the south side. These girders should be excluded from the next paint contract.

There are rust blooms throughout, especially on the bottom flanges. There is peeling paint in the webs and bottom flanges. Girders E and F were installed when the bridge was widened in 1998. There are a few spots of rust on the original girders where the paint is thin.

The cost estimate is based on overcoat. The quantity of steel used in 1967 is estimated to be about 14,500 sq ft.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 202 / 60		Bridge Name: SNOQUALMIE R		Milepost: 26.00	Region: Northwest
Year Built 1931	Bridge Type: ST CTB	Steel Span Length: 220 ft.	Width (curb-curb): 24 ft.	Steel Tonnage: 213	
Paint Age: 20	Paint Color: Evergreen	Steel Surf. Area: 31,950 sqft	BMS Cond State 2: 16,000 sqft	BMS Cond State 3: 1,500 sqft	
Next Paint Year: 2015	2011-13 Rank: 28	Past Due / Due / OK Past Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$1,491,000

## Past Paint History

Years	Cycle
1990	12
1978	8
1970	15
1955	24
1931	

## Painting Cycle



■ = Current Paint Age



The last paint contract (13767) did not specify the thickness of the paint.

### Bridge Inspection Notes:

Steel truss has peeling and cracking paint throughout, and rusting in some of the members. Rust in the top and bottom flanges of stringers and floorbeams. Some rust staining along web of sidewalk stringers.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 202 / 66		Bridge Name: S FK SNOQUALMIE R		Milepost: 29.50	Region: Northwest
Year Built 1936	Bridge Type: SG CS		Steel Span Length: 95 ft.	Width (curb-curb): 24 ft.	Steel Tonnage: 78
Paint Age: 29	Paint Color: 26307 Light Gray	Steel Surf. Area: 8,580 sqft	BMS Cond State 2: 1,000 sqft	BMS Cond State 3: 100 sqft	
Next Paint Year: 2021	2011-13 Rank: 61	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$214,500

## Past Paint History

Years	Cycle
1981	10
1971	14
1957	6
1951	15
1936	

## Painting Cycle



■ = Current Paint Age



## Bridge Inspection Notes:

Paint has failed with many paint blister spots on the steel open girder top flanges over 15 percent of the area. The paint blisters range from 1" to 12" in diameter. The steel open girders have areas of surface rust with no section loss. The bottom flanges and crossbraces have built up debris. Girder 9A at Floorbeam 9-8 has minor pack rust pushing the bottom plate out 1/8". Girder 9A at Floorbeam 9-9 has a rivet with 50 percent section loss (not found in 2006). Girder 9B at Floorbeam 9-9 has a rivet with 15% section loss (not found in 2006)."

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 207 / 4		Bridge Name: WENATCHEE RIVER		Milepost: 4.22	Region: North Central
Year Built 1940	Bridge Type: ST CTB	Steel Span Length: 160 ft.	Width (curb-curb): 24 ft.	Steel Tonnage: 145	
Paint Age: 22	Paint Color: Evergreen	34097	Steel Surf. Area: 21,750 sqft	BMS Cond State 2: 5,000 sqft	BMS Cond State 3: 1,000 sqft
Next Paint Year: 2015	2011-13 Rank: 20	Past Due / Due / OK Past Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$1,015,000

## Past Paint History

Years	Cycle
1988	11
1977	6
1971	14
1957	8
1949	

### Painting Cycle



■ = Current Paint Age



### Bridge Inspection Notes:

Areas of peeling paint and blistered paint on steel stringers. Rust blooms and peeling paint scattered throughout top of truss and upper lateral brace members. STEEL TRUSS - Some rust pitting of panel point gusset plates. Heavy amounts of gravel and sand on the top of and inside of the bottom chord and lower panel point gusset plates. STEEL FLOOR BEAMS - Minor rust in top flanges at deck interface, due to leaking joints above.

### Next Paint Project:

Remove all the existing paint and add a new zinc primer and moisture cured urethane.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 225 / 1		Bridge Name: BENTON CITY KIONA BRIDGE		Milepost: 0.03	Region: South Central
Year Built 1957	Bridge Type: SB CG		Steel Span Length: ft.	Width (curb-curb): 25.7 ft.	Steel Tonnage: 168
Paint Age: 21	Paint Color: Light Green	Steel Surf. Area: 18,480 sqft	BMS Cond State 2: 2,000 sqft	BMS Cond State 3: 5 sqft	
Next Paint Year: 2019	2011-13 Rank: 72	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$462,000

## Past Paint History

Years  
1989

### Painting Cycle



■ = Current Paint Age



This bridge was transferred to the State as part of the 1991 Route Transfer. The year this bridge was last painted is unknown.

The inspection report indicates that the paint is starting to peel on the steel girders. There are some areas of rust visible on the steel box beam that spans between the pier towers. The steel bridge rail has a lot of areas with exposed bare metal.

The town of Benton City repainted the steel above the roadway deck.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 285 / 10		Bridge Name: SEN. GEORGE SELLAR BR.		Milepost: 0.25	Region: North Central
Year Built 1950	Bridge Type: SA CTB		Steel Span Length: 928 ft.	Width (curb-curb): 54 ft.	Steel Tonnage: 2,280
Paint Age: 20	Paint Color: Warm Conc Gray	30318	Steel Surf. Area: 342,000 sqft	BMS Cond State 2: 120,000 sqft	BMS Cond State 3: 300 sqft
Next Paint Year: 2019	2011-13 Rank: 47	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$8,550,000

## Past Paint History

Years	Cycle
1990	11
1979	8
1971	10
1961	12
1949	

### Painting Cycle



■ = Current Paint Age



### Inspection Notes:

There are areas of peeling paint to the primer on all the truss and arch members, especially the bottom surfaces of most diagonals and horizontal members, and the bottom flanges and webs of the stringers and floorbeams. Any paint that is not peeling is slightly chalky. There is seam rust in some areas of the truss, arch and floorbeams. The metal pedestrian railing has a moderate amount of peeling paint.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 305 / 10		Bridge Name: AGATE PASS		Milepost: 6.82	Region: Olympic
Year Built 1950	Bridge Type: ST CTB	Steel Span Length: 1020 ft.	Width (curb-curb): 26 ft.	Steel Tonnage: 1,583	
Paint Age: 19	Paint Color: Evergreen	Steel Surf. Area: 237,450 sqft	BMS Cond State 2: 71,000 sqft	BMS Cond State 3: 23,000 sqft	
Next Paint Year: 2019	2011-13 Rank: 53	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$10,289,500

## Past Paint History

Years	Cycle
1991	9
1982	10
1972	13
1959	6
1953	

## Painting Cycle



■ = Current Paint Age



### Bridge Inspector's notes:

Floorbeams in general have thin chalky paint and essentially no topcoat. Many stringers have thin and flaking paint on flanges. Welded steel girders in Span 13 have small areas of flaking and thin paint as well as holidays. Piers 16 and 17 steel columns have peeling rough paint on struts and cross bracing. Paint is generally in deteriorating condition due to age, weather and poor surface preparation.

### Next Paint Project:

Pressure wash bridge with 5,000psi  
 Assume about 10% of the bridge will need rust to be spot blasted  
 Prime blasted areas then Overcoat with two new paint layers

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 395 / 545		Bridge Name: COLUMBIA R KETTLE FALLS		Milepost: 241.49	Region: Eastern
Year Built 1941	Bridge Type: ST CTB		Steel Span Length: 1051 ft.	Width (curb-curb): 24 ft.	Steel Tonnage: 1,648
Paint Age: 22	Paint Color: Evergreen	34097	Steel Surf. Area: 247,200 sqft	BMS Cond State 2: 9,600 sqft	BMS Cond State 3: 2,400 sqft
Next Paint Year: 2019	2011-13 Rank: 48	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$10,712,000

## Past Paint History

Years	Cycle
1988	11
1977	11
1966	15
1951	10
1941	

## Painting Cycle



■ = Current Paint Age



**No Photo Available**

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 409 / 10		Bridge Name: JULIA BUTLER HANSEN BR		Milepost: 2.92	Region: Southwest
Year Built 1938	Bridge Type: ST PCB SG CTB	Steel Span Length: 1274 ft.	Width (curb-curb): 20 ft.	Steel Tonnage: 1,194	
Paint Age: 20	Paint Color: 26307 Light Gray	Steel Surf. Area: 179,100 sqft	BMS Cond State 2: 89,550 sqft	BMS Cond State 3: 17,910 sqft	
Next Paint Year: 2015	2011-13 Rank: 17	Past Due / Due / OK Past Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$7,761,000

## Past Paint History

Years	Cycle
1990	12
1978	9
1969	9
1960	10
1950	

## Painting Cycle



■ = Current Paint Age



Portions of the bridge will require full removal of the exiting paint.

Bridge Inspector's notes:

Floorbeams in general have thin chalky paint and essentially no topcoat. Many stringers have thin and flaking paint on flanges. Welded steel girders in Span 13 have small areas of flaking and thin paint as well as holidays. Piers 16 and 17 steel columns have peeling rough paint on struts and cross bracing. There are many areas of peeling paint and thin or no paint inside the bottom chord especially at the joints. Thin, missing, peeled off and rusty paint on 25% of the bottom chord and diagonals. L21-L22 west truss shows typical rust blooms and paint condition of truss members. Top sways, cross bracing and top chords have many paint holidays in the topcoat, thin paint and rusty spots on 10% of area.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 410 / 101		Bridge Name: WHITE R		Milepost: 21.99	Region: Northwest
Year Built 1949	Bridge Type: ST CTB	Steel Span Length: 200 ft.	Width (curb-curb): 32 ft.	Steel Tonnage: 239	
Paint Age: 22	Paint Color: Evergreen	Steel Surf. Area: 35,850 sqft	BMS Cond State 2: 17,000 sqft	BMS Cond State 3: 1,000 sqft	
Next Paint Year: 2017	2011-13 Rank: 39	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$1,673,000

## Past Paint History

Years	Cycle
1988	11
1977	9
1968	13
1955	6
1949	

## Painting Cycle



= Current Paint Age



## Bridge Inspection Notes:

Paint is failing in several areas. The top flange of the bottom sway braces have areas of peeling paint. The top of truss has many rust blooms and areas of peeling paint - chalky throughout. Paint is chipped and peeling on bottom of diagonals and on verticals. Paint is peeling and failing on the bottom chord, bottom lateral gussets, top chord connections, floor beam to truss connections, and bottom of stringer to floor beam connections. There are areas of blistered and peeling paint on floorbeams.

Assume full paint removal to estimate next painting project cost.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 432 / 10S		Bridge Name: COWLITZ R & NP RY OC		Milepost: 9.58	Region: Southwest
Year Built 1961	Bridge Type: ST CBOX	Steel Span Length: 300 ft.	Width (curb-curb): 29.5 ft.	Steel Tonnage: 318	
Paint Age: 20	Paint Color: Evergreen	34097	Steel Surf. Area: 47,700 sqft	BMS Cond State 2: 13,000 sqft	BMS Cond State 3: 1,000 sqft
Next Paint Year: 2017	2011-13 Rank: 38	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$2,226,000

## Past Paint History

Years	Cycle
1990	8
1982	13
1969	8
1961	8

## Painting Cycle



■ = Current Paint Age



## Bridge Inspection Notes:

Peeling paint is typical throughout the truss. There is surface rust on the stringers, floorbeams, and sway bracing. The truss shows bare metal in places, especially on the south side surfaces.

Stringers - There are five stringers per panel. There is rusting in spots, including surface pitting and minor section loss at the top flange including the copes. There are mud and rust stains at all the seats.

Floorbeams - There are eleven 2ft. 10in. deep floorbeams in Span 7 that have rusting top flanges and laminar rust forming at some locations. The floorbeams are covered with mud and rust staining.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 433 / 1		Bridge Name: COLUMBIA R-LEWIS&CLARK B		Milepost: 0.00	Region: Southwest
Year Built 1929	Bridge Type: ST SB		Steel Span Length: 5478 ft.	Width (curb-curb): 34.2 ft.	Steel Tonnage: 14,236
Paint Age: 26	Paint Color: Steel Gray	26329	Steel Surf. Area: 2,135,400 sqft	BMS Cond State 2: 438,600 sqft	BMS Cond State 3: 110,000 sqft
Next Paint Year: 2010	2011-13 Rank: 1	Past Due / Due / OK Past Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$22,000,000


## Past Paint History

Years	Cycle
1984	10
1974	3
1971	8
1963	13
1950	

## Painting Cycle



■ = Current Paint Age



A contract from 2006 thru 2008 painted the Oregon approach to the main truss span and the superstructure of the Washington approach.

The existing paint is deteriorating and in need of replacement with a new paint system. A contract in 2009 will paint the main span towers (Piers 1,2,3) and the towers under the Washington Approach span. Based on a visual inspection a decision has been made to totally removal all the existing paint and replace it with a new 3 coat system.

A Stimulus funded project in the amount of \$12.5 million is planned for 2010 to paint portions of the main truss. A future project in 2012 or 2013 will finish painting the main truss span. The painting project will be administered by WSDOT with ODOT participating in 1/2 of the total costs.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 504 / 15		Bridge Name: N FK TOUTLE R KID VALLEY		Milepost: 17.29	Region: Southwest
Year Built 1965	Bridge Type: SB PCB		Steel Span Length: 424 ft.	Width (curb-curb): 28 ft.	Steel Tonnage: 219
Paint Age: 32	Paint Color: 30277 Light Brown	Steel Surf. Area: 24,090 sqft	BMS Cond State 2: 200 sqft	BMS Cond State 3: 50 sqft	
Next Paint Year: 2019	2011-13 Rank: 58	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$602,250

## Past Paint History

Years	Cycle
1978	13
1965	32

### Painting Cycle



■ = Current Paint Age



**No Photo Available**

### Bridge Inspector's Note:

The paint has rusty scatches and occational rust blooms throughout.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 507 / 114		Bridge Name: DESCHUTES R		Milepost: 20.43	Region: Olympic
Year Built 1943	Bridge Type: SB		Steel Span Length: 202 ft.	Width (curb-curb): 26.4 ft.	Steel Tonnage: 150
Paint Age: 27	Paint Color: Evergreen	34097	Steel Surf. Area: 16,500 sqft	BMS Cond State 2: 500 sqft	BMS Cond State 3: 200 sqft
Next Paint Year: 2021	2011-13 Rank: 64	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$412,500

## Past Paint History

Years	Cycle
1983	10
1973	30
1943	

### Painting Cycle



■ = Current Paint Age



**No Photo Available**

This bridge is a riveted steel girder with a wood deck.

The inspection report notes that the top flange of steel stringers have laminar and seam rust up to 1/8". Stringers are mud stained, with rust stains and peeling paint on webs and bottom flanges.

The paint looks in relatively good condition. There is some rusting along the edges of the top and bottom flange.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 530 / 290		Bridge Name: ROCKPORT BRIDGE		Milepost: 67.34	Region: Northwest
Year Built 1961	Bridge Type: SB CTB	Steel Span Length: 456 ft.	Width (curb-curb): 24.2 ft.	Steel Tonnage: 245	
Paint Age: 24	Paint Color: Evergreen	Steel Surf. Area: 26,950 sqft	BMS Cond State 2: 1,000 sqft	BMS Cond State 3: 1,000 sqft	
Next Paint Year: 2021	2011-13 Rank: 70	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$673,750

## Past Paint History

Years	Cycle
1986	25
1961	24

### Painting Cycle



 = Current Paint Age



A LMC overlay was applied to the bridge deck in 1995 (C#14696). The bridge rails and expansion joints were also replaced.

### Bridge Inspection Notes:

Girder paint system is starting to peel and flake in some locations. The top flange of the outside girders are starting to rust in few areas.

Light rust in bottom flange and diaphragms at hinges. Areas of rust in top flanges at interface with deck.

Cost estimate based on overcoating the existing paint system.

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 536 / 15		Bridge Name: SKAGIT R		Milepost: 4.72	Region: Northwest
Year Built 1953	Bridge Type: SS ST CTB		Steel Span Length: 451 ft.	Width (curb-curb): 28 ft.	Steel Tonnage: 534
Paint Age: 20	Paint Color: 26307 Light Gray	Steel Surf. Area: 80,100 sqft	BMS Cond State 2: 20,000 sqft	BMS Cond State 3: 4,000 sqft	
Next Paint Year: 2021	2011-13 Rank: 74	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$3,471,000

## Past Paint History

Years	Cycle
1990	6
1984	10
1974	10
1964	11
1953	

## Painting Cycle



■ = Current Paint Age



### Bridge Inspection Notes:

Top layer of paint has failed on the bottom chord. Paint breaking down and steel surface is rusting in hand holds, bottom half of truss diagonals, end posts and portal frames, top chords and sway frames.

### Bridge Office Recommendation:

Containment system, Prepare bridge with 3,000psi pressure wash or SP7 Sweep Blast, spot blast rust areas.

Bridge Item cost based on \$25/SF steel surface area. Total Cost = Br\$ x 1.5

# Steel Bridge Paint Form

2011-13 Biennium Priorities




Bridge Number: 542 / 33		Bridge Name: GLACIER CR		Milepost: 33.49	Region: Northwest
Year Built 1956	Bridge Type: SB	Steel Span Length: 84 ft.	Width (curb-curb): 26 ft.	Steel Tonnage: 35	
Paint Age: 26	Paint Color: Evergreen	Steel Surf. Area: 3,850 sqft	BMS Cond State 2: 2,050 sqft	BMS Cond State 3: 200 sqft	
Next Paint Year: 2021	2011-13 Rank: 66	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$200,000

## Past Paint History

Years	Cycle
1984	28
1956	26

### Painting Cycle



■ = Current Paint Age



**No Photo Available**

**No Photo Available**

The last inspection report indicates that there are many paint chips on the bottom flange of the steel beams. The top flanges have laminar rust near abutments. The top flanges of cross brace channels are rusty.

Many of the roadway rail posts have peeling paint. The bearing plates and bolts are heavily corroded.

## P2 Bridge Preservation - Seismic Retrofit

### 2011-13 Bien Priority Array

(Sorted by Priority Number)

11-13 #	Bridge Number	Bridge Name	Mile post	Region	Bridge Item\$'s	Total\$'s
1	5/445E	SR7&CW RR OC (CMSTP&P)	133.71	Olympic		\$2,000,000
2	522/138	SNOHOMISH R	20.50	Northwest	\$1,129,000	\$2,691,000
3	8/104S	SR 101 OC MUD BAY	20.63	Olympic		\$626,500
4	8/104N	SR 101 OC MUD BAY	20.63	Olympic		\$626,500
5	20/15	SNC RR OC (CMSTPP)	9.16	Olympic	\$84,000	\$386,000
6	9/128	GETCHELL BRIDGE	21.09	Northwest	\$82,000	\$272,000
7	167/111W-N	W-N RAMP N-E RAMP OC	14.28	Northwest	\$88,000	\$295,000
8	12/114	BN RR OC (NP)	44.92	Olympic	\$102,000	\$443,000
9	107/4	CHEHALIS R	6.83	Olympic	\$134,000	\$435,000
10	410/115	SCATTER CR	31.06	Northwest	\$176,000	\$810,000
11	101/427	US 101 OC, LOST LK RD	348.08	Olympic	\$69,000	\$286,000
12	5/570	LAKE WASH SHIP CANAL	169.63	Northwest		\$5,000,000
13	5/433	S-N RAMP OC	132.26	Olympic	\$503,000	\$891,238
14	5/437	S M ST OC	132.84	Olympic	\$379,000	\$668,547
15	5/445W	SR7&CW RR OC (CMSTP&P)	133.71	Olympic	\$1,518,000	\$2,696,582
16	5/455	EAST T ST SEWER OC	135.17	Olympic	\$526,000	\$933,045
17	5/503E	SR 18 OC	142.00	Northwest	\$900,000	\$1,800,000
18	5/503W	SR 18 OC	142.00	Northwest	\$900,000	\$1,800,000
19	5/504W	S 336TH ST OC	142.79	Northwest	\$146,000	\$258,588
20	5/504E	S 336TH ST OC	142.79	Northwest	\$178,000	\$314,048
21	5/506W	MILITARY RD OC	144.65	Northwest	\$183,000	\$322,403
22	5/506E	MILITARY RD OC	144.65	Northwest	\$190,000	\$335,283
23	5/507E	S 288TH ST OC	145.79	Northwest	\$264,000	\$467,973
24	5/507W	S 288TH ST OC	145.79	Northwest	\$246,000	\$436,838
25	5/508W	MILITARY RD OC	146.43	Northwest	\$608,000	\$1,082,466
26	5/508E	MILITARY RD OC	146.44	Northwest	\$434,000	\$772,646
27	5/509W	S 272ND ST OC	146.81	Northwest	\$243,000	\$431,353
28	5/509E	S 272ND ST OC	146.81	Northwest	\$248,000	\$440,451
29	5/510E	S 260TH ST OC	147.64	Northwest	\$153,000	\$271,003
30	5/510W	S 260TH ST OC	147.64	Northwest	\$111,000	\$195,812
31	5/511E	SR 516 OC	149.17	Northwest	\$455,000	\$806,424
32	5/516W	ORILLA RD OC-SO188TH ST	152.26	Northwest	\$388,000	\$685,466
33	5/516E	ORILLA RD OC	152.26	Northwest	\$304,000	\$539,590
34	5/520W	KLICKITAT DR OC	154.13	Northwest	\$220,000	\$389,704
35	5/521W	E-N RAMP OC	154.52	Northwest	\$186,000	\$329,621
36	5/521E	E-N S-N RAMPS OC	154.52	Northwest	\$285,000	\$505,148
37	5/531W	MILITARY RD OC	159.67	Northwest	\$215,000	\$379,932
38	5/531E	MILITARY RD OC	159.67	Northwest	\$235,000	\$416,869
39	5/534W	LUCILE ST OC	161.27	Northwest	\$441,000	\$783,189



## P2 Bridge Preservation - Seismic Retrofit

### 2011-13 Bien Priority Array

(Sorted by Priority Number)

11-13 #	Bridge Number	Bridge Name	Mile post	Region	Bridge Item\$'s	Total\$'s
40	5/534E	LUCILE ST OC	161.27	Northwest	\$470,000	\$836,699
41	5/535W	SB VIADUCT STA 2032	162.24	Northwest	\$1,638,000	\$2,916,293
42	5/536E	NB VIADUCT STA 2064	162.98	Northwest	\$742,000	\$1,311,067
43	5/536W	SB VIADUCT STA 2064	162.98	Northwest	\$965,000	\$1,702,147
44	5/538E	NB VIADUCT STA 2075	162.98	Northwest	\$1,438,000	\$2,531,717
45	5/539W	SB VIADUCT STA 2075	162.98	Northwest	\$9,795,000	\$17,299,191
46	5/539E	NB VIADUCT STA 2085	163.24	Northwest	\$8,585,000	\$15,166,523
47	5/543SCD	SBCD KING JACKSON ST OC	164.41	Northwest	\$512,105	\$921,789
48	5/332	PACIFIC AVE OC	107.45	Olympic	\$233,261	\$419,869
49	5/543E	KING-JACKSON ST OC	164.41	Northwest	\$384,214	\$691,584
50	5/543W	KING-JACKSON ST OC	164.41	Northwest	\$372,961	\$671,329
51	5/542E	DEARBORN ST OC	164.41	Northwest	\$121,787	\$219,216
52	5/542W	DEARBORN ST OC	164.41	Northwest	\$108,746	\$195,743
53	5/542SCD	SBCD DEARBORN ST OC	164.41	Northwest	\$221,529	\$398,752
54	5/543NCD	NBCD KING JACKSON ST OC	164.41	Northwest	\$453,195	\$815,750
55	5/539NCD	NBCD RAMP BR	164.41	Northwest	\$70,730	\$127,314
56	5/542NCD	NBCD DEARBORN ST OC	164.41	Northwest	\$153,527	\$276,349
56	405/1	I-5 OC	0.00	Northwest	\$319,539	\$575,170
57	5/539SCD	SBCD VIADUCT STA 2133	164.41	Northwest	\$1,070,091	\$1,926,164
58	5/545W	SB VIADUCT STA 2195	165.69	Northwest	\$398,646	\$717,562
59	5/545E	NB VIADUCT STA 2195	165.69	Northwest	\$4,311,269	\$7,760,283
60	5/545SCD	SBCD VIADUCT STA 2195	165.71	Northwest	\$559,460	\$1,007,028
61	5/566W	DENNY WAY-LAKEVIEW V	166.98	Northwest	\$12,064,641	\$21,716,353
62	5/562E	NB LANES VIADUCT	166.98	Northwest	\$187,798	\$338,036
63	5/588SCD	SBCD NORTHGATE WAY OC	172.76	Northwest	\$200,767	\$361,380
64	5/588W	NORTHGATE WAY OC	172.76	Northwest	\$376,272	\$677,289
65	5/588E	NORTHGATE WAY OC	172.76	Northwest	\$421,702	\$759,063
66	5/463	I-5 OC, PORTER WAY	139.06	Olympic	\$184,000	\$329,779
67	5/501	I-5 OC, S 375TH	140.15	Northwest	\$287,271	\$517,087
68	5/505	I-5 OC, S320TH	143.83	Northwest	\$410,000	\$726,620
69	5/513	I-5 OC, S 216TH	150.33	Northwest	\$247,000	\$437,194
70	5/517A	S-W RAMP OC	152.48	Northwest	\$228,000	\$403,088
71	5/518	I-5 OC, S 178TH ST	153.15	Northwest	\$207,000	\$366,211
72	5/528	I-5 OC, S 107TH ST	158.01	Northwest	\$495,000	\$876,724
73	5/532.1	N-SWIFT RAMP	161.27	Northwest	\$299,442	\$538,996
74	5/534A	N-W RAMP AIRPORT W. OC	161.27	Northwest	\$870,843	\$1,567,517
75	5/533.5W	N-W RAMP OC	161.27	Northwest	\$1,024,111	\$1,843,400
76	5/536N-W	NB I5 to WB W SEA FRWY	162.98	Northwest	\$423,924	\$763,062
77	5/538S-E	S-E RAMP I-5 OC	162.99	Northwest		\$500,000



## P2 Bridge Preservation - Seismic Retrofit

### 2011-13 Bien Priority Array

(Sorted by Priority Number)

11-13 #	Bridge Number	Bridge Name	Mile post	Region	Bridge Item\$'s	Total\$'s
78	5/537N	S-E RAMP WB LANES	162.99	Northwest	\$1,273,000	\$2,241,707
79	5/537E-S	E-S RAMP BR	162.99	Northwest	\$213,131	\$383,635
80	5/537W-W	W-6TH RAMP BR	163.00	Northwest	\$97,895	\$176,210
81	5/537S	EB LANES I-5 OC	163.00	Northwest	\$919,000	\$1,617,323
82	5/544	I-5 OC, YESLER ST	165.69	Northwest	\$678,513	\$1,221,323
83	5/546	I-5 OC, MADISON ST	165.69	Northwest	\$485,546	\$873,982
84	5/547	I-5 OC, SPRING ST	165.69	Northwest	\$612,150	\$1,101,870
85	5/548	I-5 OC, SENECA ST	165.69	Northwest	\$616,594	\$1,109,869
86	5/549	I-5 UC, 8TH AVE	165.69	Northwest	\$218,609	\$393,495
87	5/550	I-5 OC, PIKE ST	166.06	Northwest	\$723,195	\$1,301,751
88	5/551	I-5 OC, PINE ST-BOREN	166.06	Northwest	\$1,326,650	\$2,387,969
89	5/596	I-5 OC, NE 185TH ST	176.72	Northwest	\$372,444	\$670,398
90	5/629A	BROADWAY AVE UC	192.59	Northwest	\$299,783	\$539,609
91	405/11	SR 181 OC	0.96	Northwest	\$764,044	\$1,375,278
92	405/12	BN RR OC (CMSTPP & NP)	1.14	Northwest	\$928,439	\$1,671,189
93	405/15	SR 167 OC	2.30	Northwest	\$560,313	\$1,008,563
94	405/16	SR 515 OC	2.77	Northwest	\$318,247	\$572,844
95	405/41E	SE 8TH ST OC	12.78	Northwest	\$144,216	\$259,588
96	405/41W	WILBURTON INTERCHANGE	12.79	Northwest	\$144,799	\$260,637
97	405/45E	N-W N-E RAMP OC	14.82	Northwest	\$106,788	\$192,218
98	405/45W	N-W & N-E RAMPS OC	14.82	Northwest	\$107,569	\$193,624
99	405/46E	SR 520 OC	14.83	Northwest	\$212,993	\$383,387
100	405/46W	SR 520 OC	14.83	Northwest	\$208,093	\$374,567
101	405/47E	NORTHUP WAY OC	14.83	Northwest	\$120,599	\$217,077
102	405/47W	NORTHUP WAY OC	14.83	Northwest	\$327,124	\$588,822
103	405/48E	BNRR & 115th AVE NE OC	15.00	Northwest	\$288,915	\$520,047
104	405/48W	BNRR & 115 AVE NE OC	15.00	Northwest	\$392,293	\$706,127
105	405/52E	SR 908 OC	18.11	Northwest	\$158,142	\$284,655
106	405/52NCD	NBCD, SR 908 OC	17.84	Northwest	\$158,296	\$284,932
107	405/52SCD	SBCD, SR 908 OC	18.11	Northwest	\$236,269	\$425,284
108	405/52W	SR 908 OC	18.11	Northwest	\$156,866	\$282,358
109	405/56E	BN RR OC (NP)	20.05	Northwest	\$252,604	\$454,687
110	405/56W	BN RR OC (NP)	20.05	Northwest	\$73,508	\$132,314
111	405/59E	NE 132ND ST OC	20.90	Northwest	\$163,059	\$293,505
112	405/59W	NE 132ND ST OC	20.90	Northwest	\$138,958	\$250,124
113	405/103E	228TH ST OC	26.31	Northwest	\$206,234	\$371,220
114	405/103W	228TH ST OC	26.33	Northwest	\$191,345	\$344,421
115	405/5	I-405 OC, 61ST AVE S	0.34	Northwest	\$203,880	\$366,983
116	405/44	I-405 OC, 12TH ST	14.12	Northwest	\$263,852	\$474,933



## P2 Bridge Preservation - Seismic Retrofit

### 2011-13 Bien Priority Array

(Sorted by Priority Number)

11-13 #	Bridge Number	Bridge Name	Mile post	Region	Bridge Item\$'s	Total\$'s
117	405/48S-W	S-W RAMP BNRR OC	14.83	Northwest	\$72,710	\$130,878
118	405/64	I-405 OC, NE 160TH ST	22.62	Northwest	\$188,381	\$339,085
119	405/73	I-405 OC, 195TH ST	24.48	Northwest	\$138,342	\$249,015
120	5/418	I-5 OC, BRIDGEPORT WAY	125.86	Olympic	\$728,794	\$1,311,829
121	5/411W	FT LEWIS RD OC	120.87	Olympic	\$472,098	\$849,776
122	5/411SCD	SBCD FT LEWIS RD OC	120.87	Olympic	\$311,592	\$560,865
123	5/411NCD	NBCD FT LEWIS RD OC	120.87	Olympic	\$247,440	\$445,391
124	5/411E	FT LEWIS RD OC	120.87	Olympic	\$331,881	\$597,386
125	5/406	I-5 OC, OLD NISQUALLY RD	116.70	Olympic	\$45,733	\$82,319
126	5/345W	NISQUALLY R	114.86	Olympic	\$387,998	\$698,396
127	5/342W	MCALLISTER CR	114.09	Olympic	\$231,875	\$417,374
128	5/342E	MCALLISTER CR	114.09	Olympic	\$232,304	\$418,146
129	5/341	I-5 OC, MERIDIAN RD	113.08	Olympic	\$139,953	\$251,915
130	5/339	I-5 OC, CARPENTER RD	110.40	Olympic	\$148,319	\$266,973
131	5/337W	MARTIN WAY OC	109.14	Olympic	\$364,012	\$655,222
132	5/337E	MARTIN WAY OC	109.14	Olympic	\$253,578	\$456,440
134	5/325S-W	HENDERSON BLVD,UPRR OC	105.46	Olympic	\$240,603	\$433,085
135	5/325A	N-14TH RAMP,OWR&N RR OC	105.45	Olympic	\$485,942	\$874,695
136	5/321	CAPITOL LAKE	104.52	Olympic	\$1,505,059	\$2,709,105
137	5/309	I-5 OC, 113TH AVE SW	97.22	Olympic	\$111,326	\$200,386
138	5/304	I-5 OC, 183RD AVE SW	89.84	Olympic	\$436,942	\$786,496
140	5/233	HARRISON AVE OC	82.74	Southwest	\$322,817	\$581,071
141	5/232W	SKOOKUMCHUCK R	82.28	Southwest	\$11,000	\$19,800
142	5/232E	SKOOKUMCHUCK R	82.28	Southwest	\$11,000	\$19,800
143	5/230	SR 507 MELLEN ST OC	81.67	Southwest	\$712,426	\$1,282,367
144	5/642	I-5 OC, 23RD ST	194.44	Northwest	\$53,614	\$96,505
145	5/645E	SNOHOMISH R BN RR	194.81	Northwest	\$1,317,844	\$2,372,119
146	5/645W	SNOHOMISH R BN RR	194.81	Northwest	\$1,317,844	\$2,372,119
147	5/701	I-5 OC, STARBIRD RD	218.54	Northwest	\$284,086	\$511,355
148	5/707	I-5 OC, BLACKBURN ST	225.64	Northwest	\$243,254	\$437,857
149	18/5	PEASLEY CANYON RD OC	1.86	Northwest	\$833,162	\$1,499,692
150	18/6	W VALLEY HIGHWAY OC	2.30	Northwest	\$268,191	\$482,744
151	18/9	NP RY OC	3.82	Northwest	\$2,730,904	\$4,915,627
152	526/20	CASINO RD OC	3.74	Northwest	\$203,082	\$365,548
153	526/14	HARDESON ROAD OC	2.90	Northwest	\$167,382	\$301,287
154	410/31	WHITE R (STUCK R)	8.99	Olympic	\$712,547	\$1,282,585
155	167/121E	GREEN R	19.04	Northwest	\$329,670	\$593,406
156	167/121W	GREEN R	19.04	Northwest	\$329,698	\$593,456
157	16/12E	CEDAR ST OC	0.62	Olympic		



## P2 Bridge Preservation - Seismic Retrofit

### 2011-13 Bien Priority Array

(Sorted by Priority Number)

11-13 #	Bridge Number	Bridge Name	Mile post	Region	Bridge Item\$'s	Total\$'s
158	16/12W	CEDAR ST OC	0.62	Olympic		
159	518/18N	42ND AVE S OC	2.91	Northwest	\$241,434	\$434,580
160	518/18S	42ND AVE S OC	2.91	Northwest	\$176,567	\$317,820
161	167/126E	4TH ST OC	20.70	Northwest	\$112,860	\$203,148
162	167/126W	4TH AVE OC	20.70	Northwest	\$112,596	\$202,673
163	16/20W	SNAKE LAKE BR	1.57	Olympic	\$163,000	\$292,377
164	167/124E	JAMES ST OC	20.20	Northwest	\$87,439	\$157,390
165	167/124W	JAMES ST OC	20.20	Northwest	\$94,639	\$170,349
166	167/125E	UP RR OC (CMSTPP)	20.40	Northwest	\$122,540	\$220,572
167	167/125W	UP RR OC (CMSTPP)	20.40	Northwest	\$122,540	\$220,572
168	167/127E	BN RR OC (NP)	20.96	Northwest	\$193,996	\$349,193
169	167/127W	BN RR OC (NP)	20.96	Northwest	\$193,397	\$348,114
170	16/20E	SNAKE LAKE BR	1.57	Olympic	\$243,000	\$436,550
171	7/122	SR 512 OC	52.54	Olympic	\$147,274	\$265,092
172	16/15W	UNION AVE OC	1.15	Olympic		
173	16/15E	UNION AVE OC	1.15	Olympic		
174	167/122E	SR 516 OC	19.60	Northwest	\$33,666	\$60,598
175	167/122W	SR 516 OC	19.60	Northwest	\$34,348	\$61,826
176	167/123E	MEEKER ST OC	19.83	Northwest	\$110,831	\$199,495
177	167/123W	MEEKER ST OC	19.83	Northwest	\$76,467	\$137,640
178	167/128E	84TH AVE SOUTH O'XING	21.31	Northwest	\$112,228	\$202,010
179	167/128W	84TH AVE SOUTH O'XING	21.31	Northwest	\$110,682	\$199,228
180	167/133	SR 167 OC, S 180TH ST	24.42	Northwest	\$264,523	\$476,141
181	18/8N	UP RR OC (CMSTPP)	3.49	Northwest	\$403,524	\$726,343
182	18/8S	UP RR OC (CMSTPP)	3.49	Northwest	\$299,371	\$538,867
183	167/112W	SR 18 OC	14.28	Northwest	\$308,022	\$554,440
184	512/21N	WOODLAND AVE OC	6.84	Olympic	\$216,579	\$389,842
185	512/21S	WOODLAND AVE OC	6.84	Olympic	\$216,832	\$390,298
186	512/23N	FRUITLAND AVE OC	7.22	Olympic	\$213,593	\$384,467
187	512/23S	FRUITLAND AVE OC	7.22	Olympic	\$190,108	\$342,194
188	512/15N	WALLER RD OC	4.35	Olympic	\$120,918	\$217,652
189	512/15S	WALLER RD OC	4.35	Olympic	\$120,918	\$217,652
190	512/29S	15TH AVE SW OC	9.84	Olympic	\$168,597	\$303,475
191	512/31N	MERIDIAN ST OC	10.06	Olympic	\$148,676	\$267,617
192	512/31S	MERIDIAN ST OC	10.06	Olympic	\$163,636	\$294,545
193	900/30	I-90 OC	21.58	Northwest	\$150,667	\$271,201
194	303/12	PORT WASHINGTON CS1840	0.73	Olympic	\$3,257,122	\$5,862,820
195	167/34E	WEST VALLEY HWY OC	7.56	Olympic	\$313,291	\$563,924
196	512/29N	15TH AVE SW OC	9.84	Olympic	\$245,355	\$441,639



## P2 Bridge Preservation - Seismic Retrofit

### 2011-13 Bien Priority Array

(Sorted by Priority Number)

11-13 #	Bridge Number	Bridge Name	Mile post	Region	Bridge Item\$'s	Total\$'s
197	512/19	SR 512 OC, CANYON RD	5.86	Olympic	\$288,365	\$519,057
198	16/130E	ROSEDALE RD OC	12.76	Olympic	\$407,006	\$732,610
199	16/130W	ROSEDALE RD OC	12.77	Olympic	\$216,409	\$389,535
200	167/129	SR 167OC S 212TH	22.38	Northwest	\$110,985	\$199,772
201	161/10	SR 161 OVER SR 512	25.67	Olympic	\$159,231	\$286,615
202	99/400	I-5 OC	0.00	Olympic	\$366,212	\$659,182
203	18/14N	NP RY OC - NORTH	4.95	Northwest	\$112,404	\$202,326
204	167/30E	W-S RAMP OC	7.05	Olympic	\$150,695	\$271,250
205	167/32E	VALLEY AVE & UPRR O'XING	7.22	Olympic	\$1,374,142	\$2,473,456
206	167/116	SR 167 OC, 15TH ST NW	15.77	Northwest	\$91,091	\$163,964
207	526/10	AIRPORT RD OC	1.43	Northwest	\$146,603	\$263,885
208	522/136	CATHCART RD OC	20.41	Northwest	\$163,103	\$293,585
209	522/142	W. Main Street OC	23.14	Northwest	\$137,346	\$247,223
210	3/123E	ERLAND POINT RD OC	40.44	Olympic	\$108,301	\$194,941
211	3/123W	ERLAND POINT RD OC	40.44	Olympic	\$99,292	\$178,725
212	410/39N	166TH AVE E OC	11.46	Olympic	\$97,114	\$174,804
213	3/124E	CHICO I/C OC	41.09	Olympic	\$108,603	\$195,485
214	3/124W	CHICO I/C OC	41.09	Olympic	\$121,077	\$217,939
215	101/350	MORSE CR	252.16	Olympic	\$149,127	\$268,429
216	18/17S	GREEN R (NEELEY BRIDGE)	6.62	Northwest	\$72,600	\$130,680
217	7/130	SR 7 OC, 38TH ST	57.45	Olympic	\$717,503	\$1,291,505
218	16/120	SR 16 OC, OLYMPIC I/C	10.74	Olympic	\$75,708	\$136,274
219	2/17	FRENCH CR	11.41	Northwest	\$322,179	\$579,922
220	2/18	FARM RD OC	11.68	Northwest	\$322,179	\$579,922
221	9/118	SNOHOMISH R	9.17	Northwest	\$904,607	\$1,628,293
222	18/16S	BNRR OC-SOUTH	6.41	Northwest	\$352,176	\$633,917
223	18/20N	KENT-BLACK DIAMOND RD O	10.31	Northwest	\$31,647	\$56,965
224	18/24N	SOOS CR	10.87	Northwest	\$126,187	\$227,136
225	512/40N	SR 167 OC	11.99	Olympic	\$185,620	\$334,115
226	3/130W	ANDERSON HILL RD OC	44.70	Olympic	\$118,349	\$213,028
227	305/10	AGATE PASS	6.82	Olympic	\$385,457	\$693,822
228	18/34	RAGING RIVER	26.30	Northwest	\$282,557	\$508,603
229	2/26	SULTAN R	22.04	Northwest	\$1,033,720	\$1,860,695
230	2/22	WOODS CR	15.37	Northwest	\$277,717	\$499,891
231	3/128E	NEWBERRY HILL RD OC	43.48	Olympic	\$82,819	\$149,074
232	3/128W	NEWBERRY HILL RD OC	43.48	Olympic	\$98,720	\$177,695
233	90/83N	424TH AVE SE OC	31.94	Northwest	\$140,547	\$252,985
234	90/83S	424TH AVE SE OC	31.94	Northwest	\$138,402	\$249,124
235	12/25	WYNOOCHEE R	8.33	Olympic	\$85,800	\$154,440



## P2 Bridge Preservation - Seismic Retrofit

### 2011-13 Bien Priority Array

(Sorted by Priority Number)

11-13 #	Bridge Number	Bridge Name	Mile post	Region	Bridge Item\$'s	Total\$'s
236	162/2	SR 410 OC	0.01	Olympic	\$123,761	\$222,770
237	167/110	SR 167 OC, 15TH ST SW	13.81	Northwest	\$208,632	\$375,537
238	410/32	SR 410 OC, LINDEN DR	9.32	Olympic	\$88,391	\$159,103
239	9/121	72ND STREET SE OC	10.69	Northwest	\$258,687	\$465,637
240	532/6	GN RY COUNTY RD OC	4.98	Northwest	\$568,178	\$1,022,720
241	101/428	MILL CREEK	348.44	Olympic	\$96,899	\$174,418
242	522/144	179TH AVE SE OC	24.14	Northwest	\$160,490	\$288,882
243	522/150	US 2 & BN RR OC	24.65	Northwest	\$383,521	\$690,337
245	18/26	SR 18 OC, SE 231ST ST	15.73	Northwest	\$195,085	\$351,153
246	90/85N	BN RR OC (CMSTPP) TANNER	33.39	Northwest	\$72,919	\$131,254
247	90/85S	BN RR OC (CMSTPP) TANNER	33.39	Northwest	\$73,546	\$132,383
248	529/8E	WALNUT ST OC	4.93	Northwest	\$83,782	\$150,807
249	20/209N	ABANDONED RR OC	49.86	Northwest	\$177,430	\$319,374
250	529/8W	WALNUT ST OC	4.93	Northwest	\$82,489	\$148,480
251	529/15E	UNION SL	5.12	Northwest	\$2,288,370	\$4,119,065
252	90/90N	S FK SNOQUALMIE R LOWER	36.62	South Central	\$112,552	\$202,594
253	90/90S	S FK SNOQUALMIE R LOWER	36.62	South Central	\$66,435	\$119,582
254	9/119	2ND ST OC	9.56	Northwest	\$153,901	\$277,022
255	512/13	SR 512 OC, PORTLAND AVE	3.71	Olympic	\$44,715	\$80,487
256	90/89N	EDGEWICK RD OC	34.63	South Central	\$138,039	\$248,470
257	90/89S	EDGEWICK RD OC	34.63	South Central	\$137,720	\$247,896
258	203/106	SKYKOMISH R	23.20	Northwest	\$46,200	\$83,160
259	101/425	GOLDSBOROUGH CR & RR O	346.51	Olympic	\$475,585	\$856,053
260	101/426	MATLOCK RD OC	346.79	Olympic	\$140,822	\$253,480
261	530/115	I-5 OC	16.95	Northwest	\$182,903	\$329,225
262	101/430E	SKOOKUM CR NP RY OC	353.81	Olympic	\$303,815	\$546,866
263	101/430W	SKOOKUM CR NP RY OC	353.81	Olympic	\$303,573	\$546,431
264	510/9	BN RR OC (NP)	6.48	Olympic	\$34,056	\$61,301
265	510/10	BN RR OC (NP)	6.63	Olympic	\$61,276	\$110,296
266	9/130	BN RR (NP) & SSH 1-E OC	28.88	Northwest	\$265,106	\$477,190
267	169/12	BN RR OC (NP)	10.41	Northwest	\$352,831	\$635,095
268	526/12S-E	S-E RAMP, SR 526 OC	1.98	Northwest	\$134,453	\$242,015
269	12/59N	BN RR OC (NP)	20.59	Olympic	\$167,387	\$301,297
270	12/59S	BN RR OC (NP)	20.59	Olympic	\$157,229	\$283,011
271	121/15	I-5 OC, SR 121	7.63	Olympic	\$134,431	\$241,976
272	203/33	CHERRY CR	17.22	Northwest	\$374,693	\$674,447
273	522/28N	NORTH CR	10.85	Northwest	\$89,722	\$161,499
274	522/28S	NORTH CR	10.85	Northwest	\$91,586	\$164,855
275	3/15	SHERWOOD CR	20.36	Olympic	\$269,500	\$485,100



## P2 Bridge Preservation - Seismic Retrofit

### 2011-13 Bien Priority Array

(Sorted by Priority Number)

11-13 #	Bridge Number	Bridge Name	Mile post	Region	Bridge Item\$'s	Total\$'s
276	12/31N	SYLVIA CR NP RY OC	9.65	Olympic	\$629,008	\$1,132,214
277	12/31S	SYLVIA CR NP RY OC	9.65	Olympic	\$638,066	\$1,148,519
278	525/10	BN RR OC (GN)	8.36	Northwest	\$40,700	\$73,260
279	18/4	SR 18 OC, MILITARY RD	1.75	Northwest	\$437,096	\$786,773
280	18/31N	HOLDER CR HOBART RD OC	20.34	Northwest	\$206,525	\$371,745
281	8/7N	CLOQUALLAM CR	1.10	Olympic	\$97,339	\$175,210
282	8/7S	CLOQUALLAM CR	1.10	Olympic	\$97,009	\$174,616
283	534/1	I-5 OC	0.00	Northwest	\$131,280	\$236,303
284	202/60	SNOQUALMIE R	26.00	Northwest	\$105,600	\$190,080
285	512/25	9TH ST SW OVER SR 512	8.37	Olympic	\$158,147	\$284,665
286	7/113	S. FORK MUCK CR	36.92	Olympic	\$182,441	\$328,393
287	12/60N	US 12 OC	21.34	Olympic	\$142,824	\$257,083
288	12/60S	US 12 OC	21.34	Olympic	\$142,780	\$257,004
289	12/34N	SR 107 OC CMSTPP RR	10.24	Olympic	\$1,150,853	\$2,071,535
290	12/34S	SR 107 OC CMSTPP RR	10.24	Olympic	\$1,164,515	\$2,096,127
291	105/108	JOHNS R	37.23	Olympic	\$473,209	\$851,776
292	105/104	SOUTH BAY - ELK RIVER	32.07	Olympic	\$579,744	\$1,043,539
293	167/130	SR 167 OC, S 208TH ST	22.63	Northwest	\$223,328	\$401,990
294	167/115	SR 167 OC, W MAIN ST	14.77	Northwest	\$278,647	\$501,564
295	99/507E	SR 599 OC	22.94	Northwest	\$92,000	\$163,578
296	18/3	SR 18 OC, 32ND AVE S	0.77	Northwest	\$459,289	\$826,719
297	166/24	SR 166 OC	4.04	Olympic	\$342,513	\$616,523
298	507/116	WEYERHAEUSER RR OC	21.18	Olympic	\$80,322	\$144,580
299	167/117	SR 167 OC 37TH	17.00	Northwest	\$91,223	\$164,201
300	101/310	SOL DUC R	194.30	Olympic	\$63,800	\$114,840
301	101/312	LAKE CR	198.49	Olympic	\$148,748	\$267,746
302	509/103	JOES CREEK	9.93	Northwest	\$35,200	\$63,360
303	101/314	SOL DUC RIVER #2	203.15	Olympic	\$246,554	\$443,797
304	101/316	SOL DUC RIVER	203.66	Olympic	\$63,800	\$114,840
305	512/33	SR 512 UC 7TH	10.86	Olympic	\$245,636	\$442,144
306	104/1	S-E RAMP, US 101 OC	0.02	Olympic	\$246,367	\$443,461
307	401/10	NASELLE R	11.37	Southwest	\$375,293	\$675,527
308	101/266	DUCKABUSH R	310.22	Olympic	\$63,800	\$114,840
309	7/25	NISQUALLY R	16.74	Southwest	\$22,000	\$39,600
310	16/8	SR 16 OC, S25TH ST	0.40	Olympic		
311	507/102	SKOOKUMCHUCK RIVER BR	6.10	Olympic	\$53,570	\$96,426
312	101/138	W FK HOQUIAM R	96.69	Olympic	\$144,639	\$260,350
313	101/147	BIG CREEK	102.61	Olympic	\$238,524	\$429,343
314	101/320	SOL DUC R	211.55	Olympic	\$346,935	\$624,482



## P2 Bridge Preservation - Seismic Retrofit

### 2011-13 Bien Priority Array

(Sorted by Priority Number)

11-13 #	Bridge Number	Bridge Name	Mile post	Region	Bridge Item\$'s	Total\$'s
315	101/322	SOL DUC RIVER #5	212.46	Olympic	\$263,010	\$473,418
316	101/149	HUMPTULIPS OVERFLOW	108.84	Olympic	\$435,639	\$784,149
317	101/150	HUMPTULIPS R	109.00	Olympic	\$483,681	\$870,626
318	116/5	PORTAGE CANAL	2.67	Olympic	\$770,484	\$1,386,871
319	112/20	CLALLAM R	19.00	Olympic	\$120,291	\$216,523
320	6/13	WILLAPA R	14.02	Southwest	\$170,478	\$306,860
321	117/1	US 101 OC, SR 117	0.00	Olympic	\$144,579	\$260,241
322	7/105	MASHEL R	27.91	Olympic	\$36,300	\$65,340
323	82/120N	OVERFLOW CHANNEL	31.99	South Central	\$93,126	\$167,627
323	512/38	SR 512 OC, BENSTON DR	11.59	Olympic	\$117,898	\$212,216
324	82/120S	OVERFLOW CHANNEL	31.99	South Central	\$93,126	\$167,627
325	82/121N	NP RY OC MOXEE	32.47	South Central	\$151,261	\$272,270
326	82/121S	NP RY OC MOXEE	32.47	South Central	\$151,261	\$272,270
327	90/154N	YAKIMA R	102.49	South Central	\$337,090	\$606,761
328	90/154S	YAKIMA R	102.49	South Central	\$335,258	\$603,464
329	90/156N	DRY CR	104.71	South Central	\$267,460	\$481,427
330	90/156S	DRY CR	104.71	South Central	\$266,888	\$480,398
331	90/140S	YAKIMA R	86.20	South Central	\$134,129	\$241,431
332	90/140N	YAKIMA R	86.20	South Central	\$135,262	\$243,471
333	90/136S	I-90 OVR CLE ELUM RD, BN	83.53	South Central	\$245,020	\$441,035
334	90/136N	I-90 OVR CLE ELUM RD, BN	83.53	South Central	\$238,640	\$429,551
335	82/117S	N 1ST ST N-W RAMP OC	31.36	South Central	\$59,411	\$106,940
336	2/228N	WENATCHEE R	107.03	North Central	\$218,515	\$393,327
337	2/228S	WENATCHEE R	107.03	North Central	\$235,032	\$423,057
338	28/12	DOUGLAS CR	15.78	North Central	\$157,058	\$282,704
339	12/331N	BN RY (ABAND) & RAMP OC	199.95	South Central	\$221,766	\$399,178
340	12/331S	W-W RAMP OC	199.95	South Central	\$244,470	\$440,045
341	82/122N-W	82N RAMP OVR I-82	33.24	South Central	\$335,363	\$603,653
342	82/123N-W	82N RAMP OVR TERRACE HT	33.24	South Central	\$115,874	\$208,573
343	97/508	METHOW R	253.49	North Central	\$445,330	\$801,593
344	2/233A	WENATCHEE R DIVISION ST	111.09	North Central	\$83,908	\$151,034
345	82/2S	W-E RAMP, E-E RAMP OC	0.00	South Central	\$65,412	\$117,741
346	82/1N	I-82 OVER I-90	0.00	South Central	\$265,034	\$477,061
347	82/1S	I-82 OVER I-90	0.00	South Central	\$121,006	\$217,810
348	20/259	BAKER R	89.35	Northwest	\$290,114	\$635,036
349	6/124E-S	E-S RAMP DILLENBAUGH CR	51.33	Southwest		\$3,926,000
350	5/223N-W	N-W RAMP DILLENBAUGH CR	77.96	Southwest		
351	90/135E-N	E-N RAMP I-90 OC	83.12	South Central	\$99,627	\$179,329
352	20/280	BACON CR	110.75	Northwest	\$93,005	\$167,409



## P2 Bridge Preservation - Seismic Retrofit

### 2011-13 Bien Priority Array

(Sorted by Priority Number)

11-13 #	Bridge Number	Bridge Name	Mile post	Region	Bridge Item\$'s	Total\$'s
353	90/119	WEST EASTON RD OVER I-90	70.28	South Central	\$85,344	\$153,618
354	20/609	EARLY WINTERS CR	175.98	North Central	\$110,231	\$198,416
355	90/167	I-90 OC, RD #6	111.46	South Central	\$34,408	\$61,934
356	90/172	I-90 OC, MUNDY RD	117.82	South Central	\$34,452	\$62,014
357	90/94	I-90 OC, TINKHAM RD	42.32	South Central	\$130,818	\$259,019
358	90/95.8	I-90 OC HANSEN CR RD	47.73	South Central	\$70,802	\$140,187
359	512/1	I-5 OC	0.00	Olympic	\$219,000	\$393,258
360	5/712	SKAGIT R	228.25	Northwest	\$1,348,391	\$2,427,104
361	5/708	SR 536 OC KINCAID ST	226.39	Northwest	\$331,887	\$597,396
362	5/711	SR 538 OC	227.73	Northwest	\$252,296	\$454,133
363	5/710	GN RY OC	226.99	Northwest	\$2,847,125	\$5,124,824
364	5/228	SALZER CR	80.21	Southwest	\$62,150	\$111,870
365	5/40W	LEWIS R	19.83	Southwest	\$1,400,768	\$2,521,382
366	5/222	CM&E RR OC (CW)	77.51	Southwest	\$305,415	\$549,747
367	5/221	NP RY O'XING	77.12	Southwest	\$1,886,033	\$3,394,859
368	5/812	IOWA ST OC	253.79	Northwest	\$329,890	\$593,802
369	5/813	KENTUCKY ST OC	253.88	Northwest	\$411,708	\$741,074
370	5/206	LACAMAS CR	61.31	Southwest	\$587,384	\$1,057,290
371	500/6	I-205 OC	4.77	Southwest	\$274,780	\$494,604
372	205/16W	BURTON RD OC	29.79	Southwest	\$93,396	\$168,112
373	205/16E	BURTON RD OC	29.79	Southwest	\$92,835	\$167,102
374	14/25	WEST CAMAS SL	12.62	Southwest		
375	5/714	SR 20 & BN RY OC	230.14	Northwest	\$824,527	\$1,484,149
376	500/5	SR 500 OC, 4TH PLAIN RD	4.44	Southwest	\$387,596	\$697,673
377	4/230	COWLITZ R-P CRAWFORD BR	61.08	Southwest	\$3,996,955	\$7,194,518
378	5/102E	SR 503 OC	21.08	Southwest	\$147,890	\$266,201
379	5/36W	E FK LEWIS R	18.21	Southwest	\$897,507	\$1,615,512
380	5/102W	SR 503 OC	21.08	Southwest	\$144,656	\$260,380
381	5/216W	NEWAUKUM R	72.23	Southwest	\$49,500	\$89,100
382	5/216E	NEWAUKUM R	72.23	Southwest	\$49,500	\$89,100
383	5/104W	DIKE ACCESS RD & RR OC	22.72	Southwest	\$11,000	\$19,800
384	5/107W	TODD RD OC	27.70	Southwest	\$119,812	\$215,662
385	5/105W	BN RR OC (NP)	26.01	Southwest	\$150,656	\$271,181
386	161/102	I-5 OC	34.21	Northwest	\$276,172	\$497,109
387	90/104	SR 906 OC	54.69	South Central	\$270,699	\$487,258
388	5/127W	C&C RY & COUNTY RD OC	42.02	Southwest	\$232,903	\$419,225
389	5/127E	C&C RY & COUNTY RD OC	42.02	Southwest	\$217,267	\$391,080
390	5/810W	MEADOR AVE OC	253.53	Northwest	\$134,739	\$242,530
391	5/28W	SR 502 OC	9.51	Southwest	\$131,731	\$237,115



## P2 Bridge Preservation - Seismic Retrofit

### 2011-13 Bien Priority Array

(Sorted by Priority Number)

11-13 #	Bridge Number	Bridge Name	Mile post	Region	Bridge Item\$'s	Total\$'s
392	5/28E	SR 502 OC KOZY KAMP	9.51	Southwest	\$127,958	\$230,324
393	5/806E	SR 11 (CONNELLY AVE)	250.73	Northwest	\$151,470	\$272,646
394	5/806W	SR 11 (CONNELLY AVE)	250.73	Northwest	\$152,653	\$274,775
395	5/801W	NULLE RD OC	242.86	Northwest	\$193,490	\$348,282
396	5/801E	NULLE RD OC	242.86	Northwest	\$204,100	\$367,379
397	5/724W	COLONY RD OC	240.02	Northwest	\$156,514	\$281,724
398	5/724E	COLONY RD OC	240.02	Northwest	\$155,513	\$279,923
399	5/133E	HUNTINGTON AVE OC	47.97	Southwest	\$126,456	\$227,621
400	5/133W	HUNTINGTON AVE OC	47.97	Southwest	\$136,510	\$245,718
401	5/822W	SR 539 OC MERIDIAN ST	256.21	Northwest	\$43,863	\$78,953
402	5/824E	NORTHWEST AVE OC	256.98	Northwest	\$104,638	\$188,348
403	5/824W	NORTHWEST AVE OC	256.98	Northwest	\$109,010	\$196,218
404	90/99	SR 906 W-W RAMP OC	52.24	South Central	\$273,059	\$491,505
405	90/101	ACCESS RD OC	52.95	South Central	\$406,225	\$731,204
406	205/20	I-205 OC, 4TH PLAIN BLVD	31.11	Southwest	\$460,427	\$828,769
407	536/15	SKAGIT R CS2907	4.72	Northwest	\$427,972	\$770,349
408	5/203W	COWLITZ R	59.06	Southwest	\$427,801	\$770,042
409	5/203E	COWLITZ R	59.06	Southwest	\$427,801	\$770,042
410	5/829W	N FERNDALE OC	263.46	Northwest	\$258,786	\$465,815
411	5/829E	N FERNDALE OC	263.46	Northwest	\$201,636	\$362,944
412	5/828W	NOOKSACK R	263.05	Northwest		
413	205/28	I-205 OC, NE 78TH ST	32.61	Southwest	\$384,615	\$692,307
414	432/10S	COWLITZ R & NP RY OC	9.58	Southwest	\$1,294,502	\$2,330,104
415	432/10N	HARRY MORGAN BRIDGE	9.58	Southwest	\$1,167,172	\$2,100,909
416	205/42W	SALMON CR & AVE OC	36.00	Southwest	\$99,825	\$179,685
417	205/34E	LP & N RY OC	34.00	Southwest	\$133,359	\$240,045
418	205/34W	LP & N RY	34.00	Southwest	\$134,156	\$241,481
419	205/36E	ST JOHNS RD OC	34.29	Southwest	\$94,232	\$169,617
420	205/42E	SALMON CR & AVE OC	36.00	Southwest	\$107,470	\$193,446
421	205/36W	ST JOHNS RD OC	34.29	Southwest	\$89,342	\$160,816
422	432/12	SR 432 OC I-5	10.29	Southwest	\$246,895	\$444,411
423	5/227	I-5 OC, CHAMBER WAY	79.08	Southwest	\$176,000	\$316,800
424	20/209S	ABANDONED RR OC	49.86	Northwest	\$165,275	\$297,495
425	90/133	I-90 OC, BULLFROG RD	80.31	South Central	\$180,054	\$324,096
426	529/10W	SNOHOMISH R CS3114	3.85	Northwest		\$10,000,000
427	14/30	27TH ST & BN RY OC	16.73	Southwest	\$190,267	\$342,481
428	11/1	I-5 OC	0.00	Northwest	\$214,148	\$385,466
429	90/120N	YAKIMA R	71.26	South Central	\$242,583	\$436,649
430	90/120S	YAKIMA R	71.26	South Central	\$252,126	\$453,826



## P2 Bridge Preservation - Seismic Retrofit

### 2011-13 Bien Priority Array

(Sorted by Priority Number)

11-13 #	Bridge Number	Bridge Name	Mile post	Region	Bridge Item\$'s	Total\$'s
431	90/141N	PEOH RD OC	86.63	South Central	\$241,736	\$435,125
432	90/141S	PEOH RD OC	86.63	South Central	\$247,649	\$445,767
433	90/134N	CLE ELUM R	80.79	South Central	\$63,800	\$114,840
434	90/134S	CLE ELUM R	80.79	South Central	\$63,800	\$114,840
435	90/97.8N	FRANKLIN FALLS BR	51.12	South Central	\$38,500	\$69,300
436	90/96S	S FK SNOQUALMIE R	47.95	South Central	\$184,283	\$331,709
437	90/96.5N	DENNY CRK RD O-XING	47.96	South Central	\$194,453	\$350,015
438	90/98.6N	UPPER SNOQUALMIE R BR	51.83	South Central	\$581,515	\$1,046,727
439	90/124S	LAKE VALLEY RD OC	74.05	South Central	\$198,864	\$357,954
440	90/124N	LAKE VALLEY RD OC	74.05	South Central	\$197,549	\$355,588
441	5/836W	DAKOTA CR	273.86	Northwest	\$580,261	\$1,044,470
442	5/836E	DAKOTA CR	273.86	Northwest	\$580,261	\$1,044,470
443	90/130S	NELSON RD OC	78.06	South Central	\$183,970	\$331,145
444	90/130N	NELSON RD OC	78.06	South Central	\$180,395	\$324,710
445	90/118N	KACHESS R	69.49	South Central	\$65,302	\$117,543
446	9/215	SKAGIT R	54.38	Northwest	\$147,087	\$264,756
447	14/12	SR 14 OC, LIESER RD	4.35	Southwest	\$48,296	\$86,932
448	548/1	I-5 OC	0.00	Northwest	\$284,647	\$512,365
449	5/842E	SR 548 OC	276.20	Northwest	\$76,373	\$137,471
450	5/842W	SR 548 OC	276.20	Northwest	\$95,502	\$171,904
451	504/1	I-5 OC	0.00	Southwest	\$80,498	\$144,896
452	205/32	I-205 OC, NE ANDRESEN RD	33.52	Southwest	\$153,428	\$276,170
453	205/14	I-205 OC, NE 18TH ST	29.34	Southwest	\$103,109	\$185,595
454	122/10	MOSSYROCK	6.56	Southwest	\$417,027	\$750,648
455	12/221	I-5 OC	66.54	Southwest	\$166,188	\$299,138
456	432/8S	3RD AVE OC	7.62	Southwest	\$297,314	\$535,164
457	543/1	I-5 OC, SR 543	0.00	Northwest	\$135,256	\$243,461
458	205/30S	I-205 OC, NE 83RD ST	33.04	Southwest	\$119,070	\$214,325
459	205/30N	PADDEN PKWY OVER I-205	33.04	Southwest	\$174,856	\$314,741
460	205/10	I-205 OC, NE 9TH ST	28.83	Southwest	\$190,025	\$342,045
461	5/834	I-5 OC, BIRCH BAY	270.24	Northwest	\$270,947	\$487,704
462	6/118	CHEHALIS R ADNA	46.59	Southwest	\$55,000	\$99,000
463	5/841	I-5 OC, H ST	275.81	Northwest	\$207,081	\$372,745
464	5/825.2	I-5 OC, SLATER RD	260.13	Northwest	\$194,178	\$349,520
465	970/5	NP RY OC	0.29	South Central	\$160,936	\$289,684
466	970/1	SR 970 OVER I-90	0.00	South Central	\$180,527	\$324,948
467	205/38	I-205 OC, NE 50TH AVE	34.82	Southwest	\$99,468	\$179,042
468	2/119	S FORK SKYKOMISH RIVER	51.02	Northwest	\$390,280	\$702,504
469	2/126	TYE RIVER 2ND X-ING	58.19	North Central	\$241,318	\$434,372



## P2 Bridge Preservation - Seismic Retrofit

### 2011-13 Bien Priority Array

(Sorted by Priority Number)

11-13 #	Bridge Number	Bridge Name	Mile post	Region	Bridge Item\$'s	Total\$'s
470	2/127	TYE R 1ST CROSSING	58.77	North Central	\$220,270	\$396,485
471	14/35	BN RR OC	18.77	Southwest	\$220,864	\$397,554
472	12/265	COWLITZ R CORA	122.76	Southwest	\$358,160	\$644,688
473	14/13	SR 14 OC, ELLSWORTH RD	5.57	Southwest	\$59,043	\$106,277
474	530/128	N FK STILLAGUAMISH R OSO	33.86	Northwest	\$30,250	\$54,450
475	12/245	LAKE CR	96.88	Southwest	\$118,008	\$212,414
476	205/44	I-205 OC, NE 134TH ST	36.75	Southwest	\$284,169	\$511,503
477	205/40	I-205 OC, NE 119TH ST	35.65	Southwest	\$194,970	\$350,945
478	205/46	I-205 OC, NE 20TH AVE	36.90	Southwest	\$279,158	\$502,484
479	90/137	I-90 OC, OAKES AVE	84.20	South Central	\$182,815	\$329,066
480	5/830	I-5 OC, PORTAL WAY	265.21	Northwest	\$229,389	\$412,899
481	14/115	BN OC	40.48	Southwest	\$227,172	\$408,910
482	501/24	I-5 OC	19.84	Southwest	\$163,273	\$293,891
483	7/9	CW RR OC(CMSTPP)LINDBER	2.47	Southwest	\$646,140	\$1,163,052
484	530/132	BOULDER CR	40.13	Northwest	\$55,666	\$100,198
485	5/840	I-5 OC, MITCHEL ST	275.54	Northwest	\$168,949	\$304,108
486	505/125	I-5 OC	2.94	Southwest	\$312,802	\$563,043
487	90/144	I-90 OC THORP	89.77	South Central	\$203,379	\$366,082
488	2/130N	TUNNEL CREEK	60.31	North Central	\$229,323	\$412,781
489	410/123	SLIPPERY CR	42.49	Northwest	\$77,754	\$139,956
490	5/826	I-5 OC, SMITH RD	261.51	Northwest	\$211,272	\$380,289
491	20/262	JACKMAN CR	91.03	Northwest	\$295,323	\$531,581
492	5/837N-W	N-W RAMP	274.17	Northwest	\$140,756	\$253,361
493	12/282	CLEAR FORK CR	138.06	Southwest	\$830,610	\$1,495,098
494	5/225	I-5 OC (WEST ST)	78.40	Southwest	\$209,039	\$376,269
495	122/5	TILTON	3.57	Southwest	\$814,000	\$1,465,200
496	12/304	N FK CLEAR CR	153.44	Southwest	\$202,516	\$364,528
497	20/268	SWIFT CR	99.67	Northwest	\$78,705	\$141,669
498	4/125	ELOCHOMAN RIVER	33.71	Southwest	\$11,000	\$19,800
499	12/280	PURCELL CREEK	137.19	Southwest	\$89,964	\$161,934
500	12/289	GULCH	144.89	Southwest	\$294,949	\$530,907
501	9/315	N FK NOOKSACK R U S	78.87	Northwest	\$99,000	\$178,200
502	20/338	GORGE LAKE	126.12	Northwest	\$333,179	\$599,722
503	409/5	BIRNIE SL	1.78	Southwest	\$82,500	\$148,500
504	5/110	I-5 OC, OAK STREET	30.65	Southwest	\$158,026	\$284,447
505	5/835	I-5 OC, LOOMIS	271.60	Northwest	\$278,834	\$501,900
506	4/110	GRAYS R	19.30	Southwest	\$11,000	\$19,800
507	5/833	I-5 OC, CUSTER	268.93	Northwest	\$219,472	\$395,050
508	5/838	I-5 OC, HUGHES AVE	274.52	Northwest	\$248,716	\$447,688



## P2 Bridge Preservation - Seismic Retrofit

### 2011-13 Bien Priority Array

(Sorted by Priority Number)

11-13 #	Bridge Number	Bridge Name	Mile post	Region	Bridge Item\$'s	Total\$'s
509	503/112	JIM CR	39.55	Southwest	\$186,445	\$335,600
510	6/20	BN RR OC (NP)	19.90	Southwest	\$261,800	\$471,240
511	5/725	I-5 OC, ALGER RD	240.93	Northwest	\$206,756	\$372,161
512	506/108	I-5 OC	11.50	Southwest	\$158,059	\$284,506
513	5/29	NE 199TH ST OVER I-5	10.53	Southwest	\$202,065	\$363,716
514	542/34	N FK NOOKSACK R	35.32	Northwest	\$129,872	\$233,769
515	506/102	STILLWATER CR	4.69	Southwest	\$233,382	\$420,087
516	5/803	I-5 OC, LAKE SAMISH RD	246.24	Northwest	\$286,770	\$516,186
517	5/129	I-5 OC, PLEASANT HILL RD	43.20	Southwest	\$135,515	\$243,926
518	5/827	I-5 OC, MAIN ST	262.57	Northwest	\$110,710	\$199,277
519	505/102	SALMON CR	16.40	Southwest	\$251,774	\$453,192
520	205/24	I-205 OC, NE 63RD ST	31.79	Southwest	\$137,390	\$247,302
521	5/128	I-5 OC, ROCKY PT	42.66	Southwest	\$135,212	\$243,382
522	508/32	TILTON R	32.25	Southwest	\$160,094	\$288,169
523	506/2	CAMPBELL CR	0.90	Southwest	\$72,188	\$129,938
524	5/31	I-5 OC, CARTY RD	12.56	Southwest	\$110,715	\$199,287
525	5/131	I-5 OC, HQ RD	46.13	Southwest	\$184,113	\$331,403
526	90/147	I-90 OC, ELK HT	93.62	South Central	\$128,002	\$230,403
527	90/121	EAST EASTON UC	71.56	South Central	\$275,556	\$496,000
528	5/134	I-5 OC, POWELL	49.17	Southwest	\$195,767	\$352,381
529	5/33	NW LA CENTER RD OVER I-5	16.80	Southwest	\$140,388	\$252,698
530	542/46	GALENA CR UPPER X-ING	53.65	Northwest	\$249,695	\$449,450
531	5/722	I-5 OC, BOW HILL RD	236.39	Northwest	\$164,060	\$295,307
532	14/23S-E	SR 14 OC, NE 6TH AVE	12.32	Southwest	\$128,332	\$230,997
533	5/113	I-5 OC, KALAMA R RD	32.28	Southwest	\$36,284	\$65,310
534	90/113	STAMPEDE RD OVER I-90	62.97	South Central	\$135,691	\$244,243
535	90/114	CABIN CR RD OVER I-90	63.98	South Central	\$254,914	\$458,845
Total Number of Bridges = 534				Total\$ =	\$191,699,595	\$369,362,855

## P2 Bridge Preservation - Seismic Retrofit

### 2011-13 Bien Priority Array

(Sorted by Bridge Number)

11-13 #	Bridge Number	Bridge Name	Mile post	Region	Bridge Item\$'s	Total\$'s
219	2/17	FRENCH CR	11.41	Northwest	\$322,179	\$579,922
220	2/18	FARM RD OC	11.68	Northwest	\$322,179	\$579,922
230	2/22	WOODS CR	15.37	Northwest	\$277,717	\$499,891
229	2/26	SULTAN R	22.04	Northwest	\$1,033,720	\$1,860,695
468	2/119	S FORK SKYKOMISH RIVER	51.02	Northwest	\$390,280	\$702,504
469	2/126	TYE RIVER 2ND X-ING	58.19	North Central	\$241,318	\$434,372
470	2/127	TYE R 1ST CROSSING	58.77	North Central	\$220,270	\$396,485
488	2/130N	TUNNEL CREEK	60.31	North Central	\$229,323	\$412,781
336	2/228N	WENATCHEE R	107.03	North Central	\$218,515	\$393,327
337	2/228S	WENATCHEE R	107.03	North Central	\$235,032	\$423,057
344	2/233A	WENATCHEE R DIVISION ST	111.09	North Central	\$83,908	\$151,034
275	3/15	SHERWOOD CR	20.36	Olympic	\$269,500	\$485,100
210	3/123E	ERLAND POINT RD OC	40.44	Olympic	\$108,301	\$194,941
211	3/123W	ERLAND POINT RD OC	40.44	Olympic	\$99,292	\$178,725
213	3/124E	CHICO I/C OC	41.09	Olympic	\$108,603	\$195,485
214	3/124W	CHICO I/C OC	41.09	Olympic	\$121,077	\$217,939
231	3/128E	NEWBERRY HILL RD OC	43.48	Olympic	\$82,819	\$149,074
232	3/128W	NEWBERRY HILL RD OC	43.48	Olympic	\$98,720	\$177,695
226	3/130W	ANDERSON HILL RD OC	44.70	Olympic	\$118,349	\$213,028
506	4/110	GRAYS R	19.30	Southwest	\$11,000	\$19,800
498	4/125	ELOCHOMAN RIVER	33.71	Southwest	\$11,000	\$19,800
377	4/230	COWLITZ R-P CRAWFORD BR	61.08	Southwest	\$3,996,955	\$7,194,518
392	5/28E	SR 502 OC KOZY KAMP	9.51	Southwest	\$127,958	\$230,324
391	5/28W	SR 502 OC	9.51	Southwest	\$131,731	\$237,115
513	5/29	NE 199TH ST OVER I-5	10.53	Southwest	\$202,065	\$363,716
524	5/31	I-5 OC, CARTY RD	12.56	Southwest	\$110,715	\$199,287
529	5/33	NW LA CENTER RD OVER I-5	16.80	Southwest	\$140,388	\$252,698
379	5/36W	E FK LEWIS R	18.21	Southwest	\$897,507	\$1,615,512
365	5/40W	LEWIS R	19.83	Southwest	\$1,400,768	\$2,521,382
378	5/102E	SR 503 OC	21.08	Southwest	\$147,890	\$266,201
380	5/102W	SR 503 OC	21.08	Southwest	\$144,656	\$260,380
383	5/104W	DIKE ACCESS RD & RR OC	22.72	Southwest	\$11,000	\$19,800
385	5/105W	BN RR OC (NP)	26.01	Southwest	\$150,656	\$271,181
384	5/107W	TODD RD OC	27.70	Southwest	\$119,812	\$215,662
504	5/110	I-5 OC, OAK STREET	30.65	Southwest	\$158,026	\$284,447
533	5/113	I-5 OC, KALAMA R RD	32.28	Southwest	\$36,284	\$65,310
389	5/127E	C&C RY & COUNTY RD OC	42.02	Southwest	\$217,267	\$391,080
388	5/127W	C&C RY & COUNTY RD OC	42.02	Southwest	\$232,903	\$419,225
521	5/128	I-5 OC, ROCKY PT	42.66	Southwest	\$135,212	\$243,382
517	5/129	I-5 OC, PLEASANT HILL RD	43.20	Southwest	\$135,515	\$243,926



## P2 Bridge Preservation - Seismic Retrofit

### 2011-13 Bien Priority Array

(Sorted by Bridge Number)

11-13 #	Bridge Number	Bridge Name	Mile post	Region	Bridge Item\$'s	Total\$'s
525	5/131	I-5 OC, HQ RD	46.13	Southwest	\$184,113	\$331,403
399	5/133E	HUNTINGTON AVE OC	47.97	Southwest	\$126,456	\$227,621
400	5/133W	HUNTINGTON AVE OC	47.97	Southwest	\$136,510	\$245,718
528	5/134	I-5 OC, POWELL	49.17	Southwest	\$195,767	\$352,381
409	5/203E	COWLITZ R	59.06	Southwest	\$427,801	\$770,042
408	5/203W	COWLITZ R	59.06	Southwest	\$427,801	\$770,042
370	5/206	LACAMAS CR	61.31	Southwest	\$587,384	\$1,057,290
382	5/216E	NEWAUKUM R	72.23	Southwest	\$49,500	\$89,100
381	5/216W	NEWAUKUM R	72.23	Southwest	\$49,500	\$89,100
367	5/221	NP RY O'XING	77.12	Southwest	\$1,886,033	\$3,394,859
366	5/222	CM&E RR OC (CW)	77.51	Southwest	\$305,415	\$549,747
350	5/223N-W	N-W RAMP DILLENBAUGH CR	77.96	Southwest		
494	5/225	I-5 OC (WEST ST)	78.40	Southwest	\$209,039	\$376,269
423	5/227	I-5 OC, CHAMBER WAY	79.08	Southwest	\$176,000	\$316,800
364	5/228	SALZER CR	80.21	Southwest	\$62,150	\$111,870
143	5/230	SR 507 MELLEN ST OC	81.67	Southwest	\$712,426	\$1,282,367
142	5/232E	SKOOKUMCHUCK R	82.28	Southwest	\$11,000	\$19,800
141	5/232W	SKOOKUMCHUCK R	82.28	Southwest	\$11,000	\$19,800
140	5/233	HARRISON AVE OC	82.74	Southwest	\$322,817	\$581,071
138	5/304	I-5 OC, 183RD AVE SW	89.84	Olympic	\$436,942	\$786,496
137	5/309	I-5 OC, 113TH AVE SW	97.22	Olympic	\$111,326	\$200,386
136	5/321	CAPITOL LAKE	104.52	Olympic	\$1,505,059	\$2,709,105
135	5/325A	N-14TH RAMP,OWR&N RR OC	105.45	Olympic	\$485,942	\$874,695
134	5/325S-W	HENDERSON BLVD,UPRR OC	105.46	Olympic	\$240,603	\$433,085
48	5/332	PACIFIC AVE OC	107.45	Olympic	\$233,261	\$419,869
132	5/337E	MARTIN WAY OC	109.14	Olympic	\$253,578	\$456,440
131	5/337W	MARTIN WAY OC	109.14	Olympic	\$364,012	\$655,222
130	5/339	I-5 OC, CARPENTER RD	110.40	Olympic	\$148,319	\$266,973
129	5/341	I-5 OC, MERIDIAN RD	113.08	Olympic	\$139,953	\$251,915
128	5/342E	MCALLISTER CR	114.09	Olympic	\$232,304	\$418,146
127	5/342W	MCALLISTER CR	114.09	Olympic	\$231,875	\$417,374
126	5/345W	NISQUALLY R	114.86	Olympic	\$387,998	\$698,396
125	5/406	I-5 OC, OLD NISQUALLY RD	116.70	Olympic	\$45,733	\$82,319
124	5/411E	FT LEWIS RD OC	120.87	Olympic	\$331,881	\$597,386
123	5/411NCD	NBCD FT LEWIS RD OC	120.87	Olympic	\$247,440	\$445,391
122	5/411SCD	SBCD FT LEWIS RD OC	120.87	Olympic	\$311,592	\$560,865
121	5/411W	FT LEWIS RD OC	120.87	Olympic	\$472,098	\$849,776
120	5/418	I-5 OC, BRIDGEPORT WAY	125.86	Olympic	\$728,794	\$1,311,829
13	5/433	S-N RAMP OC	132.26	Olympic	\$503,000	\$891,238
14	5/437	S M ST OC	132.84	Olympic	\$379,000	\$668,547



## P2 Bridge Preservation - Seismic Retrofit

### 2011-13 Bien Priority Array

(Sorted by Bridge Number)

11-13 #	Bridge Number	Bridge Name	Mile post	Region	Bridge Item\$'s	Total\$'s
1	5/445E	SR7&CW RR OC (CMSTP&P)	133.71	Olympic		\$2,000,000
15	5/445W	SR7&CW RR OC (CMSTP&P)	133.71	Olympic	\$1,518,000	\$2,696,582
16	5/455	EAST T ST SEWER OC	135.17	Olympic	\$526,000	\$933,045
66	5/463	I-5 OC, PORTER WAY	139.06	Olympic	\$184,000	\$329,779
67	5/501	I-5 OC, S 375TH	140.15	Northwest	\$287,271	\$517,087
17	5/503E	SR 18 OC	142.00	Northwest	\$900,000	\$1,800,000
18	5/503W	SR 18 OC	142.00	Northwest	\$900,000	\$1,800,000
20	5/504E	S 336TH ST OC	142.79	Northwest	\$178,000	\$314,048
19	5/504W	S 336TH ST OC	142.79	Northwest	\$146,000	\$258,588
68	5/505	I-5 OC, S320TH	143.83	Northwest	\$410,000	\$726,620
22	5/506E	MILITARY RD OC	144.65	Northwest	\$190,000	\$335,283
21	5/506W	MILITARY RD OC	144.65	Northwest	\$183,000	\$322,403
23	5/507E	S 288TH ST OC	145.79	Northwest	\$264,000	\$467,973
24	5/507W	S 288TH ST OC	145.79	Northwest	\$246,000	\$436,838
26	5/508E	MILITARY RD OC	146.44	Northwest	\$434,000	\$772,646
25	5/508W	MILITARY RD OC	146.43	Northwest	\$608,000	\$1,082,466
28	5/509E	S 272ND ST OC	146.81	Northwest	\$248,000	\$440,451
27	5/509W	S 272ND ST OC	146.81	Northwest	\$243,000	\$431,353
29	5/510E	S 260TH ST OC	147.64	Northwest	\$153,000	\$271,003
30	5/510W	S 260TH ST OC	147.64	Northwest	\$111,000	\$195,812
31	5/511E	SR 516 OC	149.17	Northwest	\$455,000	\$806,424
69	5/513	I-5 OC, S 216TH	150.33	Northwest	\$247,000	\$437,194
33	5/516E	ORILLA RD OC	152.26	Northwest	\$304,000	\$539,590
32	5/516W	ORILLA RD OC-SO188TH ST	152.26	Northwest	\$388,000	\$685,466
70	5/517A	S-W RAMP OC	152.48	Northwest	\$228,000	\$403,088
71	5/518	I-5 OC, S 178TH ST	153.15	Northwest	\$207,000	\$366,211
34	5/520W	KLICKITAT DR OC	154.13	Northwest	\$220,000	\$389,704
36	5/521E	E-N S-N RAMPS OC	154.52	Northwest	\$285,000	\$505,148
35	5/521W	E-N RAMP OC	154.52	Northwest	\$186,000	\$329,621
72	5/528	I-5 OC, S 107TH ST	158.01	Northwest	\$495,000	\$876,724
38	5/531E	MILITARY RD OC	159.67	Northwest	\$235,000	\$416,869
37	5/531W	MILITARY RD OC	159.67	Northwest	\$215,000	\$379,932
73	5/532.1	N-SWIFT RAMP	161.27	Northwest	\$299,442	\$538,996
75	5/533.5W	N-W RAMP OC	161.27	Northwest	\$1,024,111	\$1,843,400
74	5/534A	N-W RAMP AIRPORT W. OC	161.27	Northwest	\$870,843	\$1,567,517
40	5/534E	LUCILE ST OC	161.27	Northwest	\$470,000	\$836,699
39	5/534W	LUCILE ST OC	161.27	Northwest	\$441,000	\$783,189
41	5/535W	SB VIADUCT STA 2032	162.24	Northwest	\$1,638,000	\$2,916,293
42	5/536E	NB VIADUCT STA 2064	162.98	Northwest	\$742,000	\$1,311,067
76	5/536N-W	NB I5 to WB W SEA FRWY	162.98	Northwest	\$423,924	\$763,062



## P2 Bridge Preservation - Seismic Retrofit

### 2011-13 Bien Priority Array

(Sorted by Bridge Number)

11-13 #	Bridge Number	Bridge Name	Mile post	Region	Bridge Item\$'s	Total\$'s
43	5/536W	SB VIADUCT STA 2064	162.98	Northwest	\$965,000	\$1,702,147
79	5/537E-S	E-S RAMP BR	162.99	Northwest	\$213,131	\$383,635
78	5/537N	S-E RAMP WB LANES	162.99	Northwest	\$1,273,000	\$2,241,707
81	5/537S	EB LANES I-5 OC	163.00	Northwest	\$919,000	\$1,617,323
80	5/537W-W	W-6TH RAMP BR	163.00	Northwest	\$97,895	\$176,210
44	5/538E	NB VIADUCT STA 2075	162.98	Northwest	\$1,438,000	\$2,531,717
77	5/538S-E	S-E RAMP I-5 OC	162.99	Northwest		\$500,000
46	5/539E	NB VIADUCT STA 2085	163.24	Northwest	\$8,585,000	\$15,166,523
55	5/539NCD	NBCD RAMP BR	164.41	Northwest	\$70,730	\$127,314
57	5/539SCD	SBCD VIADUCT STA 2133	164.41	Northwest	\$1,070,091	\$1,926,164
45	5/539W	SB VIADUCT STA 2075	162.98	Northwest	\$9,795,000	\$17,299,191
51	5/542E	DEARBORN ST OC	164.41	Northwest	\$121,787	\$219,216
56	5/542NCD	NBCD DEARBORN ST OC	164.41	Northwest	\$153,527	\$276,349
53	5/542SCD	SBCD DEARBORN ST OC	164.41	Northwest	\$221,529	\$398,752
52	5/542W	DEARBORN ST OC	164.41	Northwest	\$108,746	\$195,743
49	5/543E	KING-JACKSON ST OC	164.41	Northwest	\$384,214	\$691,584
54	5/543NCD	NBCD KING JACKSON ST OC	164.41	Northwest	\$453,195	\$815,750
47	5/543SCD	SBCD KING JACKSON ST OC	164.41	Northwest	\$512,105	\$921,789
50	5/543W	KING-JACKSON ST OC	164.41	Northwest	\$372,961	\$671,329
82	5/544	I-5 OC, YESLER ST	165.69	Northwest	\$678,513	\$1,221,323
59	5/545E	NB VIADUCT STA 2195	165.69	Northwest	\$4,311,269	\$7,760,283
60	5/545SCD	SBCD VIADUCT STA 2195	165.71	Northwest	\$559,460	\$1,007,028
58	5/545W	SB VIADUCT STA 2195	165.69	Northwest	\$398,646	\$717,562
83	5/546	I-5 OC, MADISON ST	165.69	Northwest	\$485,546	\$873,982
84	5/547	I-5 OC, SPRING ST	165.69	Northwest	\$612,150	\$1,101,870
85	5/548	I-5 OC, SENECA ST	165.69	Northwest	\$616,594	\$1,109,869
86	5/549	I-5 UC, 8TH AVE	165.69	Northwest	\$218,609	\$393,495
87	5/550	I-5 OC, PIKE ST	166.06	Northwest	\$723,195	\$1,301,751
88	5/551	I-5 OC, PINE ST-BOREN	166.06	Northwest	\$1,326,650	\$2,387,969
62	5/562E	NB LANES VIADUCT	166.98	Northwest	\$187,798	\$338,036
61	5/566W	DENNY WAY-LAKEVIEW V	166.98	Northwest	\$12,064,641	\$21,716,353
12	5/570	LAKE WASH SHIP CANAL	169.63	Northwest		\$5,000,000
65	5/588E	NORTHGATE WAY OC	172.76	Northwest	\$421,702	\$759,063
63	5/588SCD	SBCD NORTHGATE WAY OC	172.76	Northwest	\$200,767	\$361,380
64	5/588W	NORTHGATE WAY OC	172.76	Northwest	\$376,272	\$677,289
89	5/596	I-5 OC, NE 185TH ST	176.72	Northwest	\$372,444	\$670,398
90	5/629A	BROADWAY AVE UC	192.59	Northwest	\$299,783	\$539,609
144	5/642	I-5 OC, 23RD ST	194.44	Northwest	\$53,614	\$96,505
145	5/645E	SNOHOMISH R BN RR	194.81	Northwest	\$1,317,844	\$2,372,119
146	5/645W	SNOHOMISH R BN RR	194.81	Northwest	\$1,317,844	\$2,372,119



## P2 Bridge Preservation - Seismic Retrofit

### 2011-13 Bien Priority Array

(Sorted by Bridge Number)

11-13 #	Bridge Number	Bridge Name	Mile post	Region	Bridge Item\$'s	Total\$'s
147	5/701	I-5 OC, STARBIRD RD	218.54	Northwest	\$284,086	\$511,355
148	5/707	I-5 OC, BLACKBURN ST	225.64	Northwest	\$243,254	\$437,857
361	5/708	SR 536 OC KINCAID ST	226.39	Northwest	\$331,887	\$597,396
363	5/710	GN RY OC	226.99	Northwest	\$2,847,125	\$5,124,824
362	5/711	SR 538 OC	227.73	Northwest	\$252,296	\$454,133
360	5/712	SKAGIT R	228.25	Northwest	\$1,348,391	\$2,427,104
375	5/714	SR 20 & BN RY OC	230.14	Northwest	\$824,527	\$1,484,149
531	5/722	I-5 OC, BOW HILL RD	236.39	Northwest	\$164,060	\$295,307
398	5/724E	COLONY RD OC	240.02	Northwest	\$155,513	\$279,923
397	5/724W	COLONY RD OC	240.02	Northwest	\$156,514	\$281,724
511	5/725	I-5 OC, ALGER RD	240.93	Northwest	\$206,756	\$372,161
396	5/801E	NULLE RD OC	242.86	Northwest	\$204,100	\$367,379
395	5/801W	NULLE RD OC	242.86	Northwest	\$193,490	\$348,282
516	5/803	I-5 OC, LAKE SAMISH RD	246.24	Northwest	\$286,770	\$516,186
393	5/806E	SR 11 (CONNELLY AVE)	250.73	Northwest	\$151,470	\$272,646
394	5/806W	SR 11 (CONNELLY AVE)	250.73	Northwest	\$152,653	\$274,775
390	5/810W	MEADOR AVE OC	253.53	Northwest	\$134,739	\$242,530
368	5/812	IOWA ST OC	253.79	Northwest	\$329,890	\$593,802
369	5/813	KENTUCKY ST OC	253.88	Northwest	\$411,708	\$741,074
401	5/822W	SR 539 OC MERIDIAN ST	256.21	Northwest	\$43,863	\$78,953
402	5/824E	NORTHWEST AVE OC	256.98	Northwest	\$104,638	\$188,348
403	5/824W	NORTHWEST AVE OC	256.98	Northwest	\$109,010	\$196,218
464	5/825.2	I-5 OC, SLATER RD	260.13	Northwest	\$194,178	\$349,520
490	5/826	I-5 OC, SMITH RD	261.51	Northwest	\$211,272	\$380,289
518	5/827	I-5 OC, MAIN ST	262.57	Northwest	\$110,710	\$199,277
412	5/828W	NOOKSACK R	263.05	Northwest		
411	5/829E	N FERNDALE OC	263.46	Northwest	\$201,636	\$362,944
410	5/829W	N FERNDALE OC	263.46	Northwest	\$258,786	\$465,815
480	5/830	I-5 OC, PORTAL WAY	265.21	Northwest	\$229,389	\$412,899
507	5/833	I-5 OC, CUSTER	268.93	Northwest	\$219,472	\$395,050
461	5/834	I-5 OC, BIRCH BAY	270.24	Northwest	\$270,947	\$487,704
505	5/835	I-5 OC, LOOMIS	271.60	Northwest	\$278,834	\$501,900
442	5/836E	DAKOTA CR	273.86	Northwest	\$580,261	\$1,044,470
441	5/836W	DAKOTA CR	273.86	Northwest	\$580,261	\$1,044,470
492	5/837N-W	N-W RAMP	274.17	Northwest	\$140,756	\$253,361
508	5/838	I-5 OC, HUGHES AVE	274.52	Northwest	\$248,716	\$447,688
485	5/840	I-5 OC, MITCHEL ST	275.54	Northwest	\$168,949	\$304,108
463	5/841	I-5 OC, H ST	275.81	Northwest	\$207,081	\$372,745
449	5/842E	SR 548 OC	276.20	Northwest	\$76,373	\$137,471
450	5/842W	SR 548 OC	276.20	Northwest	\$95,502	\$171,904



## P2 Bridge Preservation - Seismic Retrofit

### 2011-13 Bien Priority Array

(Sorted by Bridge Number)

11-13 #	Bridge Number	Bridge Name	Mile post	Region	Bridge Item\$'s	Total\$'s
320	6/13	WILLAPA R	14.02	Southwest	\$170,478	\$306,860
510	6/20	BN RR OC (NP)	19.90	Southwest	\$261,800	\$471,240
462	6/118	CHEHALIS R ADNA	46.59	Southwest	\$55,000	\$99,000
349	6/124E-S	E-S RAMP DILLENBAUGH CR	51.33	Southwest		\$3,926,000
483	7/9	CW RR OC(CMSTPP)LINDBER	2.47	Southwest	\$646,140	\$1,163,052
309	7/25	NISQUALLY R	16.74	Southwest	\$22,000	\$39,600
322	7/105	MASHEL R	27.91	Olympic	\$36,300	\$65,340
286	7/113	S. FORK MUCK CR	36.92	Olympic	\$182,441	\$328,393
171	7/122	SR 512 OC	52.54	Olympic	\$147,274	\$265,092
217	7/130	SR 7 OC, 38TH ST	57.45	Olympic	\$717,503	\$1,291,505
281	8/7N	CLOQUALLAM CR	1.10	Olympic	\$97,339	\$175,210
282	8/7S	CLOQUALLAM CR	1.10	Olympic	\$97,009	\$174,616
4	8/104N	SR 101 OC MUD BAY	20.63	Olympic		\$626,500
3	8/104S	SR 101 OC MUD BAY	20.63	Olympic		\$626,500
221	9/118	SNOHOMISH R	9.17	Northwest	\$904,607	\$1,628,293
254	9/119	2ND ST OC	9.56	Northwest	\$153,901	\$277,022
239	9/121	72ND STREET SE OC	10.69	Northwest	\$258,687	\$465,637
6	9/128	GETCHELL BRIDGE	21.09	Northwest	\$82,000	\$272,000
266	9/130	BN RR (NP) & SSH 1-E OC	28.88	Northwest	\$265,106	\$477,190
446	9/215	SKAGIT R	54.38	Northwest	\$147,087	\$264,756
501	9/315	N FK NOOKSACK R U S	78.87	Northwest	\$99,000	\$178,200
428	11/1	I-5 OC	0.00	Northwest	\$214,148	\$385,466
235	12/25	WYNOOCHEE R	8.33	Olympic	\$85,800	\$154,440
276	12/31N	SYLVIA CR NP RY OC	9.65	Olympic	\$629,008	\$1,132,214
277	12/31S	SYLVIA CR NP RY OC	9.65	Olympic	\$638,066	\$1,148,519
289	12/34N	SR 107 OC CMSTPP RR	10.24	Olympic	\$1,150,853	\$2,071,535
290	12/34S	SR 107 OC CMSTPP RR	10.24	Olympic	\$1,164,515	\$2,096,127
269	12/59N	BN RR OC (NP)	20.59	Olympic	\$167,387	\$301,297
270	12/59S	BN RR OC (NP)	20.59	Olympic	\$157,229	\$283,011
287	12/60N	US 12 OC	21.34	Olympic	\$142,824	\$257,083
288	12/60S	US 12 OC	21.34	Olympic	\$142,780	\$257,004
8	12/114	BN RR OC (NP)	44.92	Olympic	\$102,000	\$443,000
455	12/221	I-5 OC	66.54	Southwest	\$166,188	\$299,138
475	12/245	LAKE CR	96.88	Southwest	\$118,008	\$212,414
472	12/265	COWLITZ R CORA	122.76	Southwest	\$358,160	\$644,688
499	12/280	PURCELL CREEK	137.19	Southwest	\$89,964	\$161,934
493	12/282	CLEAR FORK CR	138.06	Southwest	\$830,610	\$1,495,098
500	12/289	GULCH	144.89	Southwest	\$294,949	\$530,907
496	12/304	N FK CLEAR CR	153.44	Southwest	\$202,516	\$364,528
339	12/331N	BN RY (ABAND) & RAMP OC	199.95	South Central	\$221,766	\$399,178



## P2 Bridge Preservation - Seismic Retrofit

### 2011-13 Bien Priority Array

(Sorted by Bridge Number)

11-13 #	Bridge Number	Bridge Name	Mile post	Region	Bridge Item\$'s	Total\$'s
340	12/331S	W-W RAMP OC	199.95	South Central	\$244,470	\$440,045
447	14/12	SR 14 OC, LIESER RD	4.35	Southwest	\$48,296	\$86,932
473	14/13	SR 14 OC, ELLSWORTH RD	5.57	Southwest	\$59,043	\$106,277
532	14/23S-E	SR 14 OC, NE 6TH AVE	12.32	Southwest	\$128,332	\$230,997
374	14/25	WEST CAMAS SL	12.62	Southwest		
427	14/30	27TH ST & BN RY OC	16.73	Southwest	\$190,267	\$342,481
471	14/35	BN RR OC	18.77	Southwest	\$220,864	\$397,554
481	14/115	BN OC	40.48	Southwest	\$227,172	\$408,910
310	16/8	SR 16 OC, S25TH ST	0.40	Olympic		
157	16/12E	CEDAR ST OC	0.62	Olympic		
158	16/12W	CEDAR ST OC	0.62	Olympic		
173	16/15E	UNION AVE OC	1.15	Olympic		
172	16/15W	UNION AVE OC	1.15	Olympic		
170	16/20E	SNAKE LAKE BR	1.57	Olympic	\$243,000	\$436,550
163	16/20W	SNAKE LAKE BR	1.57	Olympic	\$163,000	\$292,377
218	16/120	SR 16 OC, OLYMPIC I/C	10.74	Olympic	\$75,708	\$136,274
198	16/130E	ROSEDALE RD OC	12.76	Olympic	\$407,006	\$732,610
199	16/130W	ROSEDALE RD OC	12.77	Olympic	\$216,409	\$389,535
296	18/3	SR 18 OC, 32ND AVE S	0.77	Northwest	\$459,289	\$826,719
279	18/4	SR 18 OC, MILITARY RD	1.75	Northwest	\$437,096	\$786,773
149	18/5	PEASLEY CANYON RD OC	1.86	Northwest	\$833,162	\$1,499,692
150	18/6	W VALLEY HIGHWAY OC	2.30	Northwest	\$268,191	\$482,744
181	18/8N	UP RR OC (CMSTPP)	3.49	Northwest	\$403,524	\$726,343
182	18/8S	UP RR OC (CMSTPP)	3.49	Northwest	\$299,371	\$538,867
151	18/9	NP RY OC	3.82	Northwest	\$2,730,904	\$4,915,627
203	18/14N	NP RY OC - NORTH	4.95	Northwest	\$112,404	\$202,326
222	18/16S	BNRR OC-SOUTH	6.41	Northwest	\$352,176	\$633,917
216	18/17S	GREEN R (NEELEY BRIDGE)	6.62	Northwest	\$72,600	\$130,680
223	18/20N	KENT-BLACK DIAMOND RD O	10.31	Northwest	\$31,647	\$56,965
224	18/24N	SOOS CR	10.87	Northwest	\$126,187	\$227,136
245	18/26	SR 18 OC, SE 231ST ST	15.73	Northwest	\$195,085	\$351,153
280	18/31N	HOLDER CR HOBART RD OC	20.34	Northwest	\$206,525	\$371,745
228	18/34	RAGING RIVER	26.30	Northwest	\$282,557	\$508,603
5	20/15	SNC RR OC (CMSTPP)	9.16	Olympic	\$84,000	\$386,000
249	20/209N	ABANDONED RR OC	49.86	Northwest	\$177,430	\$319,374
424	20/209S	ABANDONED RR OC	49.86	Northwest	\$165,275	\$297,495
348	20/259	BAKER R	89.35	Northwest	\$290,114	\$635,036
491	20/262	JACKMAN CR	91.03	Northwest	\$295,323	\$531,581
497	20/268	SWIFT CR	99.67	Northwest	\$78,705	\$141,669
352	20/280	BACON CR	110.75	Northwest	\$93,005	\$167,409



## P2 Bridge Preservation - Seismic Retrofit

### 2011-13 Bien Priority Array

(Sorted by Bridge Number)

11-13 #	Bridge Number	Bridge Name	Mile post	Region	Bridge Item\$'s	Total\$'s
502	20/338	GORGE LAKE	126.12	Northwest	\$333,179	\$599,722
354	20/609	EARLY WINTERS CR	175.98	North Central	\$110,231	\$198,416
338	28/12	DOUGLAS CR	15.78	North Central	\$157,058	\$282,704
346	82/1N	I-82 OVER I-90	0.00	South Central	\$265,034	\$477,061
347	82/1S	I-82 OVER I-90	0.00	South Central	\$121,006	\$217,810
345	82/2S	W-E RAMP, E-E RAMP OC	0.00	South Central	\$65,412	\$117,741
335	82/117S	N 1ST ST N-W RAMP OC	31.36	South Central	\$59,411	\$106,940
323	82/120N	OVERFLOW CHANNEL	31.99	South Central	\$93,126	\$167,627
324	82/120S	OVERFLOW CHANNEL	31.99	South Central	\$93,126	\$167,627
325	82/121N	NP RY OC MOXEE	32.47	South Central	\$151,261	\$272,270
326	82/121S	NP RY OC MOXEE	32.47	South Central	\$151,261	\$272,270
341	82/122N-W	82N RAMP OVR I-82	33.24	South Central	\$335,363	\$603,653
342	82/123N-W	82N RAMP OVR TERRACE HT	33.24	South Central	\$115,874	\$208,573
233	90/83N	424TH AVE SE OC	31.94	Northwest	\$140,547	\$252,985
234	90/83S	424TH AVE SE OC	31.94	Northwest	\$138,402	\$249,124
246	90/85N	BN RR OC (CMSTPP) TANNER	33.39	Northwest	\$72,919	\$131,254
247	90/85S	BN RR OC (CMSTPP) TANNER	33.39	Northwest	\$73,546	\$132,383
256	90/89N	EDGEWICK RD OC	34.63	South Central	\$138,039	\$248,470
257	90/89S	EDGEWICK RD OC	34.63	South Central	\$137,720	\$247,896
252	90/90N	S FK SNOQUALMIE R LOWER	36.62	South Central	\$112,552	\$202,594
253	90/90S	S FK SNOQUALMIE R LOWER	36.62	South Central	\$66,435	\$119,582
357	90/94	I-90 OC, TINKHAM RD	42.32	South Central	\$130,818	\$259,019
358	90/95.8	I-90 OC HANSEN CR RD	47.73	South Central	\$70,802	\$140,187
437	90/96.5N	DENNY CRK RD O-XING	47.96	South Central	\$194,453	\$350,015
436	90/96S	S FK SNOQUALMIE R	47.95	South Central	\$184,283	\$331,709
435	90/97.8N	FRANKLIN FALLS BR	51.12	South Central	\$38,500	\$69,300
438	90/98.6N	UPPER SNOQUALMIE R BR	51.83	South Central	\$581,515	\$1,046,727
404	90/99	SR 906 W-W RAMP OC	52.24	South Central	\$273,059	\$491,505
405	90/101	ACCESS RD OC	52.95	South Central	\$406,225	\$731,204
387	90/104	SR 906 OC	54.69	South Central	\$270,699	\$487,258
534	90/113	STAMPEDE RD OVER I-90	62.97	South Central	\$135,691	\$244,243
535	90/114	CABIN CR RD OVER I-90	63.98	South Central	\$254,914	\$458,845
445	90/118N	KACHESS R	69.49	South Central	\$65,302	\$117,543
353	90/119	WEST EASTON RD OVER I-90	70.28	South Central	\$85,344	\$153,618
429	90/120N	YAKIMA R	71.26	South Central	\$242,583	\$436,649
430	90/120S	YAKIMA R	71.26	South Central	\$252,126	\$453,826
527	90/121	EAST EASTON UC	71.56	South Central	\$275,556	\$496,000
440	90/124N	LAKE VALLEY RD OC	74.05	South Central	\$197,549	\$355,588
439	90/124S	LAKE VALLEY RD OC	74.05	South Central	\$198,864	\$357,954
444	90/130N	NELSON RD OC	78.06	South Central	\$180,395	\$324,710



## P2 Bridge Preservation - Seismic Retrofit

### 2011-13 Bien Priority Array

(Sorted by Bridge Number)

11-13 #	Bridge Number	Bridge Name	Mile post	Region	Bridge Item\$'s	Total\$'s
443	90/130S	NELSON RD OC	78.06	South Central	\$183,970	\$331,145
425	90/133	I-90 OC, BULLFROG RD	80.31	South Central	\$180,054	\$324,096
433	90/134N	CLE ELUM R	80.79	South Central	\$63,800	\$114,840
434	90/134S	CLE ELUM R	80.79	South Central	\$63,800	\$114,840
351	90/135E-N	E-N RAMP I-90 OC	83.12	South Central	\$99,627	\$179,329
334	90/136N	I-90 OVR CLE ELUM RD, BN	83.53	South Central	\$238,640	\$429,551
333	90/136S	I-90 OVR CLE ELUM RD, BN	83.53	South Central	\$245,020	\$441,035
479	90/137	I-90 OC, OAKES AVE	84.20	South Central	\$182,815	\$329,066
332	90/140N	YAKIMA R	86.20	South Central	\$135,262	\$243,471
331	90/140S	YAKIMA R	86.20	South Central	\$134,129	\$241,431
431	90/141N	PEOH RD OC	86.63	South Central	\$241,736	\$435,125
432	90/141S	PEOH RD OC	86.63	South Central	\$247,649	\$445,767
487	90/144	I-90 OC THORP	89.77	South Central	\$203,379	\$366,082
526	90/147	I-90 OC, ELK HT	93.62	South Central	\$128,002	\$230,403
327	90/154N	YAKIMA R	102.49	South Central	\$337,090	\$606,761
328	90/154S	YAKIMA R	102.49	South Central	\$335,258	\$603,464
329	90/156N	DRY CR	104.71	South Central	\$267,460	\$481,427
330	90/156S	DRY CR	104.71	South Central	\$266,888	\$480,398
355	90/167	I-90 OC, RD #6	111.46	South Central	\$34,408	\$61,934
356	90/172	I-90 OC, MUNDY RD	117.82	South Central	\$34,452	\$62,014
343	97/508	METHOW R	253.49	North Central	\$445,330	\$801,593
202	99/400	I-5 OC	0.00	Olympic	\$366,212	\$659,182
295	99/507E	SR 599 OC	22.94	Northwest	\$92,000	\$163,578
312	101/138	W FK HOQUIAM R	96.69	Olympic	\$144,639	\$260,350
313	101/147	BIG CREEK	102.61	Olympic	\$238,524	\$429,343
316	101/149	HUMPTULIPS OVERFLOW	108.84	Olympic	\$435,639	\$784,149
317	101/150	HUMPTULIPS R	109.00	Olympic	\$483,681	\$870,626
308	101/266	DUCKABUSH R	310.22	Olympic	\$63,800	\$114,840
300	101/310	SOL DUC R	194.30	Olympic	\$63,800	\$114,840
301	101/312	LAKE CR	198.49	Olympic	\$148,748	\$267,746
303	101/314	SOL DUC RIVER #2	203.15	Olympic	\$246,554	\$443,797
304	101/316	SOL DUC RIVER	203.66	Olympic	\$63,800	\$114,840
314	101/320	SOL DUC R	211.55	Olympic	\$346,935	\$624,482
315	101/322	SOL DUC RIVER #5	212.46	Olympic	\$263,010	\$473,418
215	101/350	MORSE CR	252.16	Olympic	\$149,127	\$268,429
259	101/425	GOLDSBOROUGH CR & RR O	346.51	Olympic	\$475,585	\$856,053
260	101/426	MATLOCK RD OC	346.79	Olympic	\$140,822	\$253,480
11	101/427	US 101 OC, LOST LK RD	348.08	Olympic	\$69,000	\$286,000
241	101/428	MILL CREEK	348.44	Olympic	\$96,899	\$174,418
262	101/430E	SKOOKUM CR NP RY OC	353.81	Olympic	\$303,815	\$546,866



## P2 Bridge Preservation - Seismic Retrofit

### 2011-13 Bien Priority Array

(Sorted by Bridge Number)

11-13 #	Bridge Number	Bridge Name	Mile post	Region	Bridge Item\$'s	Total\$'s
263	101/430W	SKOOKUM CR NP RY OC	353.81	Olympic	\$303,573	\$546,431
306	104/1	S-E RAMP, US 101 OC	0.02	Olympic	\$246,367	\$443,461
292	105/104	SOUTH BAY - ELK RIVER	32.07	Olympic	\$579,744	\$1,043,539
291	105/108	JOHNS R	37.23	Olympic	\$473,209	\$851,776
9	107/4	CHEHALIS R	6.83	Olympic	\$134,000	\$435,000
319	112/20	CLALLAM R	19.00	Olympic	\$120,291	\$216,523
318	116/5	PORTAGE CANAL	2.67	Olympic	\$770,484	\$1,386,871
321	117/1	US 101 OC, SR 117	0.00	Olympic	\$144,579	\$260,241
271	121/15	I-5 OC, SR 121	7.63	Olympic	\$134,431	\$241,976
495	122/5	TILTON	3.57	Southwest	\$814,000	\$1,465,200
454	122/10	MOSSYROCK	6.56	Southwest	\$417,027	\$750,648
201	161/10	SR 161 OVER SR 512	25.67	Olympic	\$159,231	\$286,615
386	161/102	I-5 OC	34.21	Northwest	\$276,172	\$497,109
236	162/2	SR 410 OC	0.01	Olympic	\$123,761	\$222,770
297	166/24	SR 166 OC	4.04	Olympic	\$342,513	\$616,523
204	167/30E	W-S RAMP OC	7.05	Olympic	\$150,695	\$271,250
205	167/32E	VALLEY AVE & UPRR O'XING	7.22	Olympic	\$1,374,142	\$2,473,456
195	167/34E	WEST VALLEY HWY OC	7.56	Olympic	\$313,291	\$563,924
237	167/110	SR 167 OC, 15TH ST SW	13.81	Northwest	\$208,632	\$375,537
7	167/111W-N	W-N RAMP N-E RAMP OC	14.28	Northwest	\$88,000	\$295,000
183	167/112W	SR 18 OC	14.28	Northwest	\$308,022	\$554,440
294	167/115	SR 167 OC, W MAIN ST	14.77	Northwest	\$278,647	\$501,564
206	167/116	SR 167 OC, 15TH ST NW	15.77	Northwest	\$91,091	\$163,964
299	167/117	SR 167 OC 37TH	17.00	Northwest	\$91,223	\$164,201
155	167/121E	GREEN R	19.04	Northwest	\$329,670	\$593,406
156	167/121W	GREEN R	19.04	Northwest	\$329,698	\$593,456
174	167/122E	SR 516 OC	19.60	Northwest	\$33,666	\$60,598
175	167/122W	SR 516 OC	19.60	Northwest	\$34,348	\$61,826
176	167/123E	MEEKER ST OC	19.83	Northwest	\$110,831	\$199,495
177	167/123W	MEEKER ST OC	19.83	Northwest	\$76,467	\$137,640
164	167/124E	JAMES ST OC	20.20	Northwest	\$87,439	\$157,390
165	167/124W	JAMES ST OC	20.20	Northwest	\$94,639	\$170,349
166	167/125E	UP RR OC (CMSTPP)	20.40	Northwest	\$122,540	\$220,572
167	167/125W	UP RR OC (CMSTPP)	20.40	Northwest	\$122,540	\$220,572
161	167/126E	4TH ST OC	20.70	Northwest	\$112,860	\$203,148
162	167/126W	4TH AVE OC	20.70	Northwest	\$112,596	\$202,673
168	167/127E	BN RR OC (NP)	20.96	Northwest	\$193,996	\$349,193
169	167/127W	BN RR OC (NP)	20.96	Northwest	\$193,397	\$348,114
178	167/128E	84TH AVE SOUTH O'XING	21.31	Northwest	\$112,228	\$202,010
179	167/128W	84TH AVE SOUTH O'XING	21.31	Northwest	\$110,682	\$199,228



## P2 Bridge Preservation - Seismic Retrofit

### 2011-13 Bien Priority Array

(Sorted by Bridge Number)

11-13 #	Bridge Number	Bridge Name	Mile post	Region	Bridge Item\$'s	Total\$'s
200	167/129	SR 167OC S 212TH	22.38	Northwest	\$110,985	\$199,772
293	167/130	SR 167 OC, S 208TH ST	22.63	Northwest	\$223,328	\$401,990
180	167/133	SR 167 OC, S 180TH ST	24.42	Northwest	\$264,523	\$476,141
267	169/12	BN RR OC (NP)	10.41	Northwest	\$352,831	\$635,095
284	202/60	SNOQUALMIE R	26.00	Northwest	\$105,600	\$190,080
272	203/33	CHERRY CR	17.22	Northwest	\$374,693	\$674,447
258	203/106	SKYKOMISH R	23.20	Northwest	\$46,200	\$83,160
460	205/10	I-205 OC, NE 9TH ST	28.83	Southwest	\$190,025	\$342,045
453	205/14	I-205 OC, NE 18TH ST	29.34	Southwest	\$103,109	\$185,595
373	205/16E	BURTON RD OC	29.79	Southwest	\$92,835	\$167,102
372	205/16W	BURTON RD OC	29.79	Southwest	\$93,396	\$168,112
406	205/20	I-205 OC, 4TH PLAIN BLVD	31.11	Southwest	\$460,427	\$828,769
520	205/24	I-205 OC, NE 63RD ST	31.79	Southwest	\$137,390	\$247,302
413	205/28	I-205 OC, NE 78TH ST	32.61	Southwest	\$384,615	\$692,307
459	205/30N	PADDEN PKWY OVER I-205	33.04	Southwest	\$174,856	\$314,741
458	205/30S	I-205 OC, NE 83RD ST	33.04	Southwest	\$119,070	\$214,325
452	205/32	I-205 OC, NE ANDRESEN RD	33.52	Southwest	\$153,428	\$276,170
417	205/34E	LP & N RY OC	34.00	Southwest	\$133,359	\$240,045
418	205/34W	LP & N RY	34.00	Southwest	\$134,156	\$241,481
419	205/36E	ST JOHNS RD OC	34.29	Southwest	\$94,232	\$169,617
421	205/36W	ST JOHNS RD OC	34.29	Southwest	\$89,342	\$160,816
467	205/38	I-205 OC, NE 50TH AVE	34.82	Southwest	\$99,468	\$179,042
477	205/40	I-205 OC, NE 119TH ST	35.65	Southwest	\$194,970	\$350,945
420	205/42E	SALMON CR & AVE OC	36.00	Southwest	\$107,470	\$193,446
416	205/42W	SALMON CR & AVE OC	36.00	Southwest	\$99,825	\$179,685
476	205/44	I-205 OC, NE 134TH ST	36.75	Southwest	\$284,169	\$511,503
478	205/46	I-205 OC, NE 20TH AVE	36.90	Southwest	\$279,158	\$502,484
194	303/12	PORT WASHINGTON CS1840	0.73	Olympic	\$3,257,122	\$5,862,820
227	305/10	AGATE PASS	6.82	Olympic	\$385,457	\$693,822
307	401/10	NASELLE R	11.37	Southwest	\$375,293	\$675,527
56	405/1	I-5 OC	0.00	Northwest	\$319,539	\$575,170
115	405/5	I-405 OC, 61ST AVE S	0.34	Northwest	\$203,880	\$366,983
91	405/11	SR 181 OC	0.96	Northwest	\$764,044	\$1,375,278
92	405/12	BN RR OC (CMSTPP & NP)	1.14	Northwest	\$928,439	\$1,671,189
93	405/15	SR 167 OC	2.30	Northwest	\$560,313	\$1,008,563
94	405/16	SR 515 OC	2.77	Northwest	\$318,247	\$572,844
95	405/41E	SE 8TH ST OC	12.78	Northwest	\$144,216	\$259,588
96	405/41W	WILBURTON INTERCHANGE	12.79	Northwest	\$144,799	\$260,637
116	405/44	I-405 OC, 12TH ST	14.12	Northwest	\$263,852	\$474,933
97	405/45E	N-W N-E RAMP OC	14.82	Northwest	\$106,788	\$192,218



## P2 Bridge Preservation - Seismic Retrofit

### 2011-13 Bien Priority Array

(Sorted by Bridge Number)

11-13 #	Bridge Number	Bridge Name	Mile post	Region	Bridge Item\$'s	Total\$'s
98	405/45W	N-W & N-E RAMPS OC	14.82	Northwest	\$107,569	\$193,624
99	405/46E	SR 520 OC	14.83	Northwest	\$212,993	\$383,387
100	405/46W	SR 520 OC	14.83	Northwest	\$208,093	\$374,567
101	405/47E	NORTHUP WAY OC	14.83	Northwest	\$120,599	\$217,077
102	405/47W	NORTHUP WAY OC	14.83	Northwest	\$327,124	\$588,822
103	405/48E	BNRR & 115th AVE NE OC	15.00	Northwest	\$288,915	\$520,047
117	405/48S-W	S-W RAMP BNRR OC	14.83	Northwest	\$72,710	\$130,878
104	405/48W	BNRR & 115 AVE NE OC	15.00	Northwest	\$392,293	\$706,127
105	405/52E	SR 908 OC	18.11	Northwest	\$158,142	\$284,655
106	405/52NCD	NBCD, SR 908 OC	17.84	Northwest	\$158,296	\$284,932
107	405/52SCD	SBCD, SR 908 OC	18.11	Northwest	\$236,269	\$425,284
108	405/52W	SR 908 OC	18.11	Northwest	\$156,866	\$282,358
109	405/56E	BN RR OC (NP)	20.05	Northwest	\$252,604	\$454,687
110	405/56W	BN RR OC (NP)	20.05	Northwest	\$73,508	\$132,314
111	405/59E	NE 132ND ST OC	20.90	Northwest	\$163,059	\$293,505
112	405/59W	NE 132ND ST OC	20.90	Northwest	\$138,958	\$250,124
118	405/64	I-405 OC, NE 160TH ST	22.62	Northwest	\$188,381	\$339,085
119	405/73	I-405 OC, 195TH ST	24.48	Northwest	\$138,342	\$249,015
113	405/103E	228TH ST OC	26.31	Northwest	\$206,234	\$371,220
114	405/103W	228TH ST OC	26.33	Northwest	\$191,345	\$344,421
503	409/5	BIRNIE SL	1.78	Southwest	\$82,500	\$148,500
154	410/31	WHITE R (STUCK R)	8.99	Olympic	\$712,547	\$1,282,585
238	410/32	SR 410 OC, LINDEN DR	9.32	Olympic	\$88,391	\$159,103
212	410/39N	166TH AVE E OC	11.46	Olympic	\$97,114	\$174,804
10	410/115	SCATTER CR	31.06	Northwest	\$176,000	\$810,000
489	410/123	SLIPPERY CR	42.49	Northwest	\$77,754	\$139,956
456	432/8S	3RD AVE OC	7.62	Southwest	\$297,314	\$535,164
415	432/10N	HARRY MORGAN BRIDGE	9.58	Southwest	\$1,167,172	\$2,100,909
414	432/10S	COWLITZ R & NP RY OC	9.58	Southwest	\$1,294,502	\$2,330,104
422	432/12	SR 432 OC I-5	10.29	Southwest	\$246,895	\$444,411
376	500/5	SR 500 OC, 4TH PLAIN RD	4.44	Southwest	\$387,596	\$697,673
371	500/6	I-205 OC	4.77	Southwest	\$274,780	\$494,604
482	501/24	I-5 OC	19.84	Southwest	\$163,273	\$293,891
509	503/112	JIM CR	39.55	Southwest	\$186,445	\$335,600
451	504/1	I-5 OC	0.00	Southwest	\$80,498	\$144,896
519	505/102	SALMON CR	16.40	Southwest	\$251,774	\$453,192
486	505/125	I-5 OC	2.94	Southwest	\$312,802	\$563,043
523	506/2	CAMPBELL CR	0.90	Southwest	\$72,188	\$129,938
515	506/102	STILLWATER CR	4.69	Southwest	\$233,382	\$420,087
512	506/108	I-5 OC	11.50	Southwest	\$158,059	\$284,506



## P2 Bridge Preservation - Seismic Retrofit

### 2011-13 Bien Priority Array

(Sorted by Bridge Number)

11-13 #	Bridge Number	Bridge Name	Mile post	Region	Bridge Item\$'s	Total\$'s
311	507/102	SKOOKUMCHUCK RIVER BR	6.10	Olympic	\$53,570	\$96,426
298	507/116	WEYERHAEUSER RR OC	21.18	Olympic	\$80,322	\$144,580
522	508/32	TILTON R	32.25	Southwest	\$160,094	\$288,169
302	509/103	JOES CREEK	9.93	Northwest	\$35,200	\$63,360
264	510/9	BN RR OC (NP)	6.48	Olympic	\$34,056	\$61,301
265	510/10	BN RR OC (NP)	6.63	Olympic	\$61,276	\$110,296
359	512/1	I-5 OC	0.00	Olympic	\$219,000	\$393,258
255	512/13	SR 512 OC, PORTLAND AVE	3.71	Olympic	\$44,715	\$80,487
188	512/15N	WALLER RD OC	4.35	Olympic	\$120,918	\$217,652
189	512/15S	WALLER RD OC	4.35	Olympic	\$120,918	\$217,652
197	512/19	SR 512 OC, CANYON RD	5.86	Olympic	\$288,365	\$519,057
184	512/21N	WOODLAND AVE OC	6.84	Olympic	\$216,579	\$389,842
185	512/21S	WOODLAND AVE OC	6.84	Olympic	\$216,832	\$390,298
186	512/23N	FRUITLAND AVE OC	7.22	Olympic	\$213,593	\$384,467
187	512/23S	FRUITLAND AVE OC	7.22	Olympic	\$190,108	\$342,194
285	512/25	9TH ST SW OVER SR 512	8.37	Olympic	\$158,147	\$284,665
196	512/29N	15TH AVE SW OC	9.84	Olympic	\$245,355	\$441,639
190	512/29S	15TH AVE SW OC	9.84	Olympic	\$168,597	\$303,475
191	512/31N	MERIDIAN ST OC	10.06	Olympic	\$148,676	\$267,617
192	512/31S	MERIDIAN ST OC	10.06	Olympic	\$163,636	\$294,545
305	512/33	SR 512 UC 7TH	10.86	Olympic	\$245,636	\$442,144
323	512/38	SR 512 OC, BENSTON DR	11.59	Olympic	\$117,898	\$212,216
225	512/40N	SR 167 OC	11.99	Olympic	\$185,620	\$334,115
159	518/18N	42ND AVE S OC	2.91	Northwest	\$241,434	\$434,580
160	518/18S	42ND AVE S OC	2.91	Northwest	\$176,567	\$317,820
273	522/28N	NORTH CR	10.85	Northwest	\$89,722	\$161,499
274	522/28S	NORTH CR	10.85	Northwest	\$91,586	\$164,855
208	522/136	CATHCART RD OC	20.41	Northwest	\$163,103	\$293,585
2	522/138	SNOHOMISH R	20.50	Northwest	\$1,129,000	\$2,691,000
209	522/142	W. Main Street OC	23.14	Northwest	\$137,346	\$247,223
242	522/144	179TH AVE SE OC	24.14	Northwest	\$160,490	\$288,882
243	522/150	US 2 & BN RR OC	24.65	Northwest	\$383,521	\$690,337
278	525/10	BN RR OC (GN)	8.36	Northwest	\$40,700	\$73,260
207	526/10	AIRPORT RD OC	1.43	Northwest	\$146,603	\$263,885
268	526/12S-E	S-E RAMP, SR 526 OC	1.98	Northwest	\$134,453	\$242,015
153	526/14	HARDESON ROAD OC	2.90	Northwest	\$167,382	\$301,287
152	526/20	CASINO RD OC	3.74	Northwest	\$203,082	\$365,548
248	529/8E	WALNUT ST OC	4.93	Northwest	\$83,782	\$150,807
250	529/8W	WALNUT ST OC	4.93	Northwest	\$82,489	\$148,480
426	529/10W	SNOHOMISH R CS3114	3.85	Northwest		\$10,000,000



## P2 Bridge Preservation - Seismic Retrofit

### 2011-13 Bien Priority Array

(Sorted by Bridge Number)

11-13 #	Bridge Number	Bridge Name	Mile post	Region	Bridge Item\$'s	Total\$'s
251	529/15E	UNION SL	5.12	Northwest	\$2,288,370	\$4,119,065
261	530/115	I-5 OC	16.95	Northwest	\$182,903	\$329,225
474	530/128	N FK STILLAGUAMISH R OSO	33.86	Northwest	\$30,250	\$54,450
484	530/132	BOULDER CR	40.13	Northwest	\$55,666	\$100,198
240	532/6	GN RY COUNTY RD OC	4.98	Northwest	\$568,178	\$1,022,720
283	534/1	I-5 OC	0.00	Northwest	\$131,280	\$236,303
407	536/15	SKAGIT R CS2907	4.72	Northwest	\$427,972	\$770,349
514	542/34	N FK NOOKSACK R	35.32	Northwest	\$129,872	\$233,769
530	542/46	GALENA CR UPPER X-ING	53.65	Northwest	\$249,695	\$449,450
457	543/1	I-5 OC, SR 543	0.00	Northwest	\$135,256	\$243,461
448	548/1	I-5 OC	0.00	Northwest	\$284,647	\$512,365
193	900/30	I-90 OC	21.58	Northwest	\$150,667	\$271,201
466	970/1	SR 970 OVER I-90	0.00	South Central	\$180,527	\$324,948
465	970/5	NP RY OC	0.29	South Central	\$160,936	\$289,684
Total Number of Bridges = 534				Total\$ =	\$191,699,595	\$369,362,855

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0006207B		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/508E		MILITARY RD OC		5	146.44	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
4.4 N JCT SR 18	1 miles	122° 17' 43.8"	47° 21' 8.4"	243 ft.		73 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
MILITARY RD		31.76 %g	41.8% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1960	<b>ADT:</b> 80000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1994	<b>Truck Pct:</b> 15 %	26	41	Pier with more than two columns		



No Photo Available

**Bridge Notes:**

Piers 2 and 3, each has six columns. Retrofit five east 3'-0" diameter columns. #3 hoops @ 12". #10 bars with 2'-2" splices. Footing without top mat. (E-21g)

**Retrofit Program Notes:**

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (5 ea. 10 total, 3' dia.). Large skew (41 degree), deep excavation (12 ft). Install girder stops at Pier 1 thru 4.

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

Estimated Total Bridge Item Cost:  
 Estimated Total Retrofit Project Cost:

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0006313D		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/509W		S 272ND ST OC		5	146.81	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
4.8 N JCT SR 18	1 miles	122 17 48	47 21 27.6	151 ft.		91.5 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
S 272ND ST		31.83 %g	41.9% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1961	<b>ADT:</b> 80000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 2002	<b>Truck Pct:</b> 15 %	27	4	Pier with more than two columns		



**Bridge Notes:**

Piers 2 and 3, each has seven columns. Retrofit five east 3'-0" diameter columns. #3 hoops @ 12". #10 bars with 3'-8" splices. Footing without top mat. (E-23h)

**Retrofit Program Notes:**

Bridge widened (c5981). Add two 3'-0" dia. Columns West side on 4'-6" drilled shafts at Piers 2 and 3 each side of bridge.

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (5 ea. 10 total, 3' dia.)

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0006313C		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/509E		S 272ND ST OC		5	146.81	<b>County:</b> King
<b>Location:</b> 4.8 N JCT SR 18	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> 122° 17' 46"	<b>Latitude:</b> 47° 21' 27.4"	<b>Structure Length:</b> 151 ft.		<b>Out to Out Width:</b> 76.5 ft.
<b>Feature Intersected:</b> S 272ND ST		<b>PGA (500 yr):</b> 31.83 %g	<b>PGA (1000 yr):</b> 41.9% %g	<b>Span Type:</b> PCG		<b>Main Spans:</b> 3 <b>Appr. Spans:</b> 0
<b>Year Built:</b> 1961	<b>ADT:</b> 80000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1994	<b>Truck Pct:</b> 15 %	28	4	Pier with more than two columns		
				<h2 style="font-size: 2em; color: black; opacity: 0.5;">No Photo Available</h2>		
<b>Bridge Notes:</b>			<b>Retrofit Program Notes:</b>			
Piers 2 and 3, each has six columns. Retrofit five east 3'-0" diameter columns. #3 hoops @ 12". #10 bars with 3'-8" splices. Footing without top mat. (E-23h)			Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.			
<b>Completed Retrofit Notes:</b>			<b>Remaining Retrofit Notes:</b>			
			Retrofit columns at Piers 2 and 3. (5 ea. 10 total, 3' dia.)			
<b>Overall Retrofit Status:</b>		<h3 style="font-size: 1.2em;">Estimated Total Bridge Item Cost:</h3> <h3 style="font-size: 1.2em;">Estimated Total Retrofit Project Cost:</h3>				
<b>Single Column Pier Status:</b>						
<b>Multi Column Pier Status:</b>						
C=Complete P=Partially Complet R=Required N=Not Required D=Differed X=Excluded I=In Progress						
P						
N						
R						

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0006186A		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/510E		S 260TH ST OC		5	147.64	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
5.6 N JCT SR 18	1 miles	122 17 36	47 22 12	162 ft.		68 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
S 260TH ST		31.99 %g	42.2% %g	CVS	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1960	<b>ADT:</b> 80000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1991	<b>Truck Pct:</b> 15 %	29	0	Pier with more than two columns		



**Bridge Notes:**

Piers 2 and 3, each has four columns. Retrofit three east 2'-9" diameter columns. #4 hoops @ 12". #9 bars with 3'-4" splices. Footing without top mat.

**Retrofit Program Notes:**

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (3 ea. 6 total, 2'-9" dia.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0006186B		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/510W		S 260TH ST OC		5	147.64	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
5.6 N JCT SR 18	1 miles	122° 17' 36"	47° 22' 12"	162 ft.		92.2 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
S 260TH ST		31.99 %g	42.2% %g	CVS	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1960	<b>ADT:</b> 80000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 2002	<b>Truck Pct:</b> 15 %	30	0	Pier with more than two columns		



**Bridge Notes:**

Piers 2 and 3, each has five columns. Retrofit three center 2'-9" diameter columns. #4 hoops @ 12". #9 bars with 3'-4" splices. Footing without top mat.

**Retrofit Program Notes:**

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (3 ea. 6 total, 2'-9" dia.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0006820A		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/511E		SR 516 OC		5	149.17	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
7.2 N JCT SR 18	1 miles	122° 17' 24"	47° 23' 0"	269 ft.		90 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 4	
SR 516		32.15 %g	42.6% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1962	<b>ADT:</b> 85000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1991	<b>Truck Pct:</b> 15 %	31	30	Pier with more than two columns		



**Bridge Notes:**

Piers 2, 3 and 4, each has seven 3'-0" diameter columns. Retrofit six east columns only. These columns have #3 hoops @ 12". #10 bars with 3'-8" splices. Footing without top mat. (E-23h)

**Retrofit Program Notes:**

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2, 3 and 4. (6 ea. 18 total, 3' dia.)

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007090C		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/516W		ORILLA RD OC-SO188TH ST		5	152.26	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
3.1 N JCT SR 516	0 miles	122° 16' 12"	47° 25' 54"	230 ft.		93.8 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
ORILLA RD		32.62 %g	43.8% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1963	<b>ADT:</b> 89500	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1997	<b>Truck Pct:</b> 15 %	32	0	Pier with more than two columns		



**Bridge Notes:**

Piers 2 and 3, each has seven 3'-0" diameter columns. Retrofit six west columns only. These 3'-0" diameter columns have #3 hoops @ 12" and longitudinal bars with lap splices. Footing without top mat. (E-54m)

**Retrofit Program Notes:**

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (6 ea. 12 total, 3' dia.)

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007090B		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/516E		ORILLA RD OC		5	152.26	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
3.1 N JCT SR 516	0 miles	122° 16' 12"	47° 25' 54"	195 ft.		79 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
ORILLA RD		32.62 %g	43.8% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1963	<b>ADT:</b> 89500	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1994	<b>Truck Pct:</b> 15 %	33	1	Pier with more than two columns		



**Bridge Notes:**

Piers 2 and 3, each has seven 3'-0" diameter columns. Retrofit six east columns only. These 3'-0" diameter columns have #3 hoops @ 12" and longitudinal bars with lap splices. Footing without top mat. (E-54m)

**Retrofit Program Notes:**

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (6 ea. 12 total, 3' dia.)

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007401D		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/520W		KLICKITAT DR OC		5	154.13	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
5.0 N JCT SR 516	5 miles	122° 15' 52.1"	47° 27' 28.9"	163 ft.		81.7 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
KLICKITAT DR		32.83 %g	44.6% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1965	<b>ADT:</b> 102000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1997	<b>Truck Pct:</b> 15 %	34	0	Pier with more than two columns		



**Bridge Notes:**

Retrofit five 3'-0" diameter columns at Piers 2 and 3. These columns have #3 hoops @ 12". Longitudinal bars with lap splices. Footing without top mat. (E-54m)

**Retrofit Program Notes:**

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (5 ea. 10 total, 3' dia.)

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007401F		<b>Bridge Name:</b> E-N RAMP OC		<b>Route:</b> 5	<b>Milepost:</b> 154.52	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/521W						<b>County:</b> King
<b>Location:</b> 5.2 N JCT SR 516	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> 122° 15' 54"	<b>Latitude:</b> 47° 27' 42"	<b>Structure Length:</b> 146 ft.		<b>Out to Out Width:</b> 81.6 ft.
<b>Feature Intersected:</b> I-405 E-E RAMP		<b>PGA (500 yr):</b> 32.87 %g	<b>PGA (1000 yr):</b> 44.7% %g	<b>Span Type:</b> PCG	<b>Main Spans:</b> 3 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1966	<b>ADT:</b> 102000	<b>11-13 Rank:</b> 35	<b>Skew Angle:</b> 13	<b>Pier Type:</b> Pier with more than two columns	<b>Footing Type:</b> Timber pile	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 15 %					



**Bridge Notes:**

Piers 2 and 3, each has four 3'-0" diameter columns. #3 hoops @ 12". Longitudinal #9 bars with 3'-4" lap splices. Footing without top mat.

**Retrofit Program Notes:**

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (4 ea. 8 total, 3' dia.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007401E		<b>Bridge Name:</b> E-N S-N RAMPS OC		<b>Route:</b> 5	<b>Milepost:</b> 154.52	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/521E						<b>County:</b> King
<b>Location:</b> 5.2 N JCT SR 516	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> 122° 15' 48"	<b>Latitude:</b> 47° 27' 42"	<b>Structure Length:</b> 217 ft.		<b>Out to Out Width:</b> 71.6 ft.
<b>Feature Intersected:</b> I-405 E-E S-E RAMP		<b>PGA (500 yr):</b> 32.85 %g	<b>PGA (1000 yr):</b> 44.6% %g	<b>Span Type:</b> PCG	<b>Main Spans:</b> 4 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1966	<b>ADT:</b> 102000	<b>11-13 Rank:</b> 36	<b>Skew Angle:</b> 0	<b>Pier Type:</b> Pier with more than two columns	<b>Footing Type:</b> Timber pile	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 15 %					



**Bridge Notes:**

Piers 2, 3 and 4, each has four 3'-0" diameter columns. #3 hoops @ 12". longitudinal bars with lap splices. Footing without top mat. (E-54m)

**Retrofit Program Notes:**

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2, 3 and 4. (4 ea. 12 total, 3' dia.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007617D		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/531W		MILITARY RD OC		5	159.67	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
2.2 N JCT SR 900	1 miles	122° 17' 36"	47° 31' 48"	149 ft.		81 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
MILITARY RD ROSE ST		33.42 %g	46.3% %g	CS	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1966	<b>ADT:</b> 106000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1995	<b>Truck Pct:</b> 15 %	37	0	Pier with more than two columns		



**Bridge Notes:**

Piers 2 and 3, each has five 3'-0" diameter columns. Retrofit four east columns only. These columns have #4 hoops @ 12". longitudinal #9 bars with 3'-4" lap splices. Footings without top mat.

**Retrofit Program Notes:**

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (4 ea. 8 total, 3' dia.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007617C		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/531E		MILITARY RD OC		5	159.67	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
2.2 N JCT SR 900	1 miles	122° 17' 37.3"	47° 31' 49.7"	161 ft.		83 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
MILITARY RD ROSE ST		33.42 %g	46.3% %g	CS	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1966	<b>ADT:</b> 106000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1991	<b>Truck Pct:</b> 15 %	38	13	Pier with more than two columns	Steel pile	



**Bridge Notes:**

Piers 2 and 3, each has five 3'-0" diameter columns. Retrofit four west columns only. These columns have #4 hoops @ 12". longitudinal #9 bars with 3'-4" lap splices. Footings without top mat.

**Retrofit Program Notes:**

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (4 ea. 8 total, 3' dia.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007734C		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/534W		LUCILE ST OC		5	161.27	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
4.1 N JCT SR 900	1 miles	122° 19' 6.2"	47° 33' 11.5"	190 ft.		79 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
LUCILE ST		33.61 %g	46.7% %g	CS	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1966	<b>ADT:</b> 106000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1995	<b>Truck Pct:</b> 15 %	39	22	Pier with more than two columns		



**Bridge Notes:**

Piers 2 and 3, each has five 3'-0" diameter columns. Retrofit four east columns per pier only. These columns have #4 hoops @ 12". longitudinal #9 bars with 3'-4" lap splices. Footing without top mat.

**Retrofit Program Notes:**

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (4 ea. 8 total, 3' dia.). 12' excavation. Install catchers and stops at Piers 1 and 4 (22 degree skew).

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007734B		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/534E		LUCILE ST OC		5	161.27	<b>County:</b> King
<b>Location:</b> 3.9 N JCT SR 900	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> ° ' " 122 19 0	<b>Latitude:</b> ° ' " 47 33 12	<b>Structure Length:</b> 172 ft.		<b>Out to Out Width:</b> 93.6 ft.
<b>Feature Intersected:</b> LUCILE ST		<b>PGA (500 yr):</b> 33.61 %g	<b>PGA (1000 yr):</b> 46.7% %g	<b>Span Type:</b> CS	<b>Main Spans:</b> 3 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1966	<b>ADT:</b> 106000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 15 %	40	22	Pier with more than two columns		
				<h2 style="font-size: 2em; transform: rotate(-10deg);">No Photo Available</h2>		
<b>Bridge Notes:</b>			<b>Retrofit Program Notes:</b>			
Piers 2 and 3, each has five 3'-0" diameter columns. #4 hoops @ 12". Longitudinal #9 bars with 3'-4" lap splices. Footing without top mat.			Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.			
<b>Completed Retrofit Notes:</b>			<b>Remaining Retrofit Notes:</b>			
			Retrofit columns at Piers 2 and 3. (5 ea. 10 total, 3' dia.). Install catcher blocks at piers 1 and 4.			
<b>Overall Retrofit Status:</b> R		<h3>Estimated Total Bridge Item Cost:</h3> <h3>Estimated Total Retrofit Project Cost:</h3>				
<b>Single Column Pier Status:</b> N						
<b>Multi Column Pier Status:</b> R						
C=Complete P=Partially Complet R=Required N=Not Required D=Differed X=Excluded I=In Progress						

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007816B		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/535W		SB VIADUCT STA 2032		5	162.24	<b>County:</b> King
<b>Location:</b> 4.5 N JCT SR 900	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> 122 19 18.8	<b>Latitude:</b> 47 33 47	<b>Structure Length:</b> 604 ft.		<b>Out to Out Width:</b> 73 ft.
<b>Feature Intersected:</b> SB VIADUCT STA 2032		<b>PGA (500 yr):</b> 33.55 %g	<b>PGA (1000 yr):</b> 46.4% %g	<b>Span Type:</b> PCG		<b>Main Spans:</b> 6 <b>Appr. Spans:</b> 0
<b>Year Built:</b> 1966	<b>ADT:</b> 118000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1992	<b>Truck Pct:</b> 15 %	41	0	Pier with more than two columns		



**Bridge Notes:**

Piers 2 thru 5, each has six 4'-0" diameter columns. Pier 6 has six 4'-6" diameter columns. Retrofit four center columns per pier at piers 2 thru 5 only. These columns have #4 hoops @ 12". longitudinal bars with lap or/and welded splices. Footing with top mat. Pier 6 has four 4'-6" (O.D.) x 5" wall prestressed concrete piles, filled with cylinder concrete after piles are set in place. No retrofit recommended.

**Retrofit Program Notes:**

Widened in 1992. Adds one 4'-0" diameter shaft column on each side of the existing 4 columns at piers 2 thru 5 and one 4'-6" diameter shaft column on each side of the existing 4 columns at pier 6.

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2, 3, 4 and 5. (4 ea. 16 total, 4' dia.). Deep excavation (38' max.)

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007741A		<b>Bridge Name:</b> NB VIADUCT STA 2064		<b>Route:</b> 5	<b>Milepost:</b> 162.98	<b>Region:</b> Northwest	
<b>Bridge Number:</b> 5/536E						<b>County:</b> King	
<b>Location:</b> 5.2 N JCT SR 900		<b>Detour Length:</b> 1 miles		<b>Longitude:</b> 122° 19' 12.5"	<b>Latitude:</b> 47° 34' 10.5"	<b>Structure Length:</b> 746 ft.	
						<b>Out to Out Width:</b> 58.8 ft.	
<b>Feature Intersected:</b> NB VIADUCT STA 2064		<b>PGA (500 yr):</b> 33.42 %g	<b>PGA (1000 yr):</b> 46.1% %g	<b>Span Type:</b> CS		<b>Main Spans:</b> 18 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1966	<b>ADT:</b> 98500	<b>11-13 Rank:</b> 42	<b>Skew Angle:</b> 0	<b>Pier Type:</b> Pier with more than two columns		<b>Footing Type:</b> Drilled shaft	
<b>Year Rebuilt:</b> 1992	<b>Truck Pct:</b> 15 %						
<h1 style="font-size: 2em; color: black; opacity: 0.5;">No Photo Available</h1>							
<b>Bridge Notes:</b> Piers 2 thru 8, each has four 3'-0" dia. columns on 3'-6" dia. drilled shafts. Pier 9 thru 18, each has four columns. Retrofit three west columns only. These columns are 3'-0" dia. columns on 3'-6" dia. drilled shafts. Hoops are #4 @ 12". Longitudinal bars insert 5'-0" into drilled shafts. Max. span length = 42'.				<b>Retrofit Program Notes:</b> Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.			
<b>Completed Retrofit Notes:</b>				<b>Remaining Retrofit Notes:</b> Retrofit 51 columns built in 1966 (on drilled shaft, 3' dia.)			
<b>Overall Retrofit Status:</b> P		<b>Single Column Pier Status:</b> N		<b>Multi Column Pier Status:</b> R		<b>Estimated Total Bridge Item Cost:</b>  <b>Estimated Total Retrofit Project Cost:</b>	
C=Complete P=Partially Complet							
R=Required N=Not Required							
D=Differed X=Excluded I=In Progress							

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007741B		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/536W		SB VIADUCT STA 2064		5	162.98	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
5.2 N JCT SR 900	1 miles	122° 19' 6"	47° 34' 18"	746 ft.		53.7 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 18	
SB VIADUCT STA 2064		33.42 %g	46.0% %g	CS	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1967	<b>ADT:</b> 98500	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1992	<b>Truck Pct:</b> 15 %	43	0	Pier with more than two columns	Drilled shaft	

No Photo Available



**Bridge Notes:**

Piers 2 thru 5, each has four 3'-0" dia. columns on 3'-6" dia. drilled shafts. Pier 6 thru 18, each has three 3'-0" dia. columns on 3'-6" dia. drilled shafts. Hoops are #4 @ 12". Longitudinal bars insert 5'-0" into drilled shafts. Max. span length = 42'.

**Retrofit Program Notes:**

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit 55 columns built in 1967 (on drilled shaft, 3' dia.)

<b>Overall Retrofit Status:</b>	P
<b>Single Column Pier Status:</b>	N
<b>Multi Column Pier Status:</b>	R
C=Complete P=Partially Complet	
R=Required N=Not Required	
D=Differed X=Excluded I=In Progress	

Estimated Total Bridge Item Cost:  
Estimated Total Retrofit Project Cost:

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007741C		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/538E		NB VIADUCT STA 2075		5	162.98	<b>County:</b> King
<b>Location:</b> 5.6 N JCT SR 900	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> 122° 19' 6"	<b>Latitude:</b> 47° 34' 30"	<b>Structure Length:</b> 872 ft.		<b>Out to Out Width:</b> 60.7 ft.
<b>Feature Intersected:</b> NB VIADUCT STA 2075		<b>PGA (500 yr):</b> 33.39 %g	<b>PGA (1000 yr):</b> 45.9% %g	<b>Span Type:</b> CS	<b>Main Spans:</b> 21 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1966	<b>ADT:</b> 98500	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1992	<b>Truck Pct:</b> 15 %	44	0	Pier with more than two columns	Drilled shaft	



**Bridge Notes:**

Max. span length = 45'. 4 columns per pier. Retrofit columns built in 1966 only (three west columns per pier). Piers 11 thru 15, each has three 4' dia. columns on 5' dia. drilled shafts. Piers 2 thru 9 and 16 thru 21, each has three 3' dia. columns on 3'-6" dia. drilled shafts. #4 hoops @ 12". Piers 10 thru 17 have horizontal struts.

**Retrofit Program Notes:**

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 thru 21. (3 ea. 60 total, 3' dia. except P11-P15 3-4' dia. ea.)

<b>Overall Retrofit Status:</b>	P
<b>Single Column Pier Status:</b>	N
<b>Multi Column Pier Status:</b>	R
C=Complete P=Partially Complet	
R=Required N=Not Required	
D=Differed X=Excluded I=In Progress	

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007741D		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/539W		SB VIADUCT STA 2075		5	162.98	<b>County:</b> King
<b>Location:</b> 5.8 N JCT SR 900	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> 122° 19' 6"	<b>Latitude:</b> 47° 34' 30"	<b>Structure Length:</b> 6622 ft.		<b>Out to Out Width:</b> 71 ft.
<b>Feature Intersected:</b> SB VIADUCT STA 2075		<b>PGA (500 yr):</b> 33.39 %g	<b>PGA (1000 yr):</b> 45.9% %g	<b>Span Type:</b> CS		<b>Main Spans:</b> 157 <b>Appr. Spans:</b> 0
<b>Year Built:</b> 1967	<b>ADT:</b> 98500	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1992	<b>Truck Pct:</b> 15 %	45	0	Pier with more than two columns	Drilled shaft	



**Bridge Notes:**

Columns on drilled shafts. Contract 7741: Piers 2 thru 10, 16 thru 30, retrofit four columns each pier (3' dia. column on 3'-6" dia. drilled shaft), pier 11 thru 15, (four 4' dia. column on 5'-0" dia. drilled shaft). Piers 9 thru 18 have horizontal struts. Contract 7686: piers 25 thru 152, 3' dia. Columns except East columns at Piers 146 thru 152 are 4' diameter. Max. span =42'.

**Retrofit Program Notes:**

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at piers 2 thru 152 (628 total, 3' dia. except P11-P15, 2-4' dia. ea.).

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation

## Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007741E		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/539E		NB VIADUCT STA 2085		5	163.24	<b>County:</b> King
<b>Location:</b> 5.8 N JCT SR 900	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> ° ' " 122 19 10.9	<b>Latitude:</b> ° ' " 47 34 34	<b>Structure Length:</b> 5825 ft.		<b>Out to Out Width:</b> 73 ft.
<b>Feature Intersected:</b> NB VIADUCT STA 2085		<b>PGA (500 yr):</b> 33.39 %g	<b>PGA (1000 yr):</b> 45.9% %g	<b>Span Type:</b> CS	<b>Main Spans:</b> 138 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1966	<b>ADT:</b> 98500	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1992	<b>Truck Pct:</b> 15 %	46	0	Pier with more than two columns	Drilled shaft	
<div style="display: flex; justify-content: space-around; font-size: 2em; font-weight: bold; opacity: 0.5;"> <span>No Photo Available</span> <span>No Photo Available</span> </div>						
<b>Bridge Notes:</b>			<b>Retrofit Program Notes:</b>			
<p>Retrofit columns built in 1966 only. Piers 2 thru 10, each has five 3' columns on 4' shafts. Piers 11, 12, 95 thru 103 and 114 thru 127, each has five 3' columns on 3'-6" shafts. Piers 13 thru 94, each has four 3' columns on 3'-6" shafts. Piers 104 thru 114, each has six 3' columns on 3'-6" shafts. Piers 115 thru 120 and 128 thru 138, each has three 3' columns on 3'-6" shafts. #4 hoops @12". Horizontal struts at piers 15 thru 19 and 56 thru 78. Lap splices at top of drilled shafts and top of horizontal struts.</p>			<p>Columns of bridge 5/539NCD are to be included with this bridge.</p> <p>Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.</p>			
<b>Completed Retrofit Notes:</b>			<b>Remaining Retrofit Notes:</b>			
			Retrofit 577 columns. (includes bridge 5/539NCD, 3' dia.)			
<b>Overall Retrofit Status:</b>		P	<b>Estimated Total Bridge Item Cost:</b>  <b>Estimated Total Retrofit Project Cost:</b>			
<b>Single Column Pier Status:</b>		N				
<b>Multi Column Pier Status:</b>		R				
C=Complete P=Partially Complet						
R=Required N=Not Required						
D=Differed X=Excluded I=In Progress						

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007504D		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/543SCD		SBCD KING JACKSON ST OC		5	164.41	<b>County:</b> King
<b>Location:</b> 0.3 N JCT I-90	<b>Detour Length:</b> 2 miles	<b>Longitude:</b> 122° 19' 11.7"	<b>Latitude:</b> 47° 35' 53.5"	<b>Structure Length:</b> 709 ft.		<b>Out to Out Width:</b> 64.6 ft.
<b>Feature Intersected:</b> KING JACKSON ST		<b>PGA (500 yr):</b> 33.14 %g	<b>PGA (1000 yr):</b> 45.1% %g	<b>Span Type:</b> CBox		<b>Main Spans:</b> 9 <b>Appr. Spans:</b> 0
<b>Year Built:</b> 1965	<b>ADT:</b> 73582	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 10 %	47	30	Pier with more than two columns	Drilled shaft	



**Bridge Notes:**

Piers 2 thru 9, each has three 4'-0" diameter columns on 5'-0" diameter drilled shafts. End pier, pier 1, has three 24"x36" columns on 4' shafts. Columns have double hinges. End pier, pier 10, has three 4' diameter column shafts. These columns have #4 hoops @ 12". Vertical #11 bars have 6'-0" min, lap splices at top of drilled. In span hinges at span 4 near pier 4 and span 7 near pier 8.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 thru 9. (3 ea. 24 total, 4' dia.)

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0005455A		<b>Bridge Name:</b> PACIFIC AVE OC		<b>Route:</b> 5	<b>Milepost:</b> 107.45	<b>Region:</b> Olympic
<b>Bridge Number:</b> 5/332						<b>County:</b> Thurston
<b>Location:</b> 3.2 N JCT US 101	<b>Detour Length:</b> 0 miles	<b>Longitude:</b> 122° 51' 6.7"	<b>Latitude:</b> 47° 2' 28.1"	<b>Structure Length:</b> 351 ft.		<b>Out to Out Width:</b> 138 ft.
<b>Feature Intersected:</b> PACIFIC AVE		<b>PGA (500 yr):</b> 29.75 %g	<b>PGA (1000 yr):</b> 39.1% %g	<b>Span Type:</b> CBox PTCBox	<b>Main Spans:</b> 3 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1957	<b>ADT:</b> 121768	<b>11-13 Rank:</b> 48	<b>Skew Angle:</b> 0	<b>Pier Type:</b> Pier with more than two columns	<b>Footing Type:</b> Concrete Pile	
<b>Year Rebuilt:</b> 1987	<b>Truck Pct:</b> 10 %					



**Bridge Notes:**

Piers 2 and 3, each has four 6'-0" diameter columns. Retrofit two center columns per pier (built in 1957) only. These columns have #4 hoops @12", longitudinal #14 bars have splices at top of pedestal. Splice lengths are 2'-10". Footings have no top mat. Longitudinal expansion joints between bridges built in 1957 and widening portion built in 1987.

**Retrofit Program Notes:**

The 2005 Transportation Partnership Account (TPA) included funding to perform seismic retrofit work on this bridge.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

A seismic analysis will be done to determine what work is required. Typical retrofit measures and costs are: Cross-Beam Bolsters = \$1,500/LF of Cross Beam, Girder Stops = \$1,500/Each, Column Jackets (Dry) = \$50,000/Col. (Wet) = \$125,000/Col.

<b>Overall Retrofit Status:</b>	R
<b>Single Column Pier Status:</b>	N
<b>Multi Column Pier Status:</b>	R
C=Complete P=Partially Complet	
R=Required N=Not Required	
D=Differed X=Excluded I=In Progress	

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007504A		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/543E		KING-JACKSON ST OC		5	164.41	<b>County:</b> King
<b>Location:</b> 0.3 N JCT I-90	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> 122° 19' 11.7"	<b>Latitude:</b> 47° 35' 53.5"	<b>Structure Length:</b> 706 ft.		<b>Out to Out Width:</b> 62 ft.
<b>Feature Intersected:</b> KING-JACKSON ST		<b>PGA (500 yr):</b> 33.14 %g	<b>PGA (1000 yr):</b> 45.1% %g	<b>Span Type:</b> CBox		<b>Main Spans:</b> 9 <b>Appr. Spans:</b> 0
<b>Year Built:</b> 1965	<b>ADT:</b> 79500	<b>11-13 Rank:</b> 49	<b>Skew Angle:</b> 30	<b>Pier Type:</b> Double Column Pier	<b>Footing Type:</b> Drilled shaft	
<b>Year Rebuilt:</b> 1992	<b>Truck Pct:</b> 15 %					



**Bridge Notes:**

Contract 7504: Piers 2 and 3, three 4' columns on 5' shafts. Piers 4 thru 9, two 4' columns on 5' shafts. #4 hoops @ 12". Lap splices at top of shafts.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns built in 1965 at Piers 2 thru 9 (18 total, 4' dia.).

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007504B		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/543W		KING-JACKSON ST OC		5	164.41	<b>County:</b> King
<b>Location:</b> 0.3 N JCT I-90	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> 122° 19' 11.7"	<b>Latitude:</b> 47° 35' 53.5"	<b>Structure Length:</b> 712 ft.		<b>Out to Out Width:</b> 58.8 ft.
<b>Feature Intersected:</b> KING-JACKSON ST		<b>PGA (500 yr):</b> 33.14 %g	<b>PGA (1000 yr):</b> 45.1% %g	<b>Span Type:</b> CBox	<b>Main Spans:</b> 9 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1965	<b>ADT:</b> 79500	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1992	<b>Truck Pct:</b> 15 %	50	30	Double Column Pier	Drilled shaft	



**Bridge Notes:**

Piers 2 thru 9, each has three 4'-0" diameter columns on 5'-0" diameter drilled shafts. End pier, pier 1, has three 24"x36" columns on 4' shafts. Columns have double hinges. End pier, pier 10, has three 4' diameter column shafts. Retrofit two east columns at piers 2 thru 9 only. These columns have #4 hoops @ 12". Vertical #11 bars have 6'-0" min, lap splices at top of drilled. In span hinges at span 4 near pier 4 and span 7 near pier 8.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns built in 1965 at Piers 2 thru 9 (16 total, 4' dia.).

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0006207B		<b>Bridge Name:</b> MILITARY RD OC		<b>Route:</b> 5	<b>Milepost:</b> 146.44	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/508E						<b>County:</b> King
<b>Location:</b> 4.4 N JCT SR 18	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> 122° 17' 43.8"	<b>Latitude:</b> 47° 21' 8.4"	<b>Structure Length:</b> 243 ft.		<b>Out to Out Width:</b> 73 ft.
<b>Feature Intersected:</b> MILITARY RD		<b>PGA (500 yr):</b> 31.76 %g	<b>PGA (1000 yr):</b> 41.8% %g	<b>Span Type:</b> PCG		<b>Main Spans:</b> 3 <b>Appr. Spans:</b> 0
<b>Year Built:</b> 1960	<b>ADT:</b> 80000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1994	<b>Truck Pct:</b> 15 %	26	41	Pier with more than two columns		



No Photo Available

**Bridge Notes:**

Piers 2 and 3, each has six columns. Retrofit five east 3'-0" diameter columns. #3 hoops @ 12". #10 bars with 2'-2" splices. Footing without top mat. (E-21g)

**Retrofit Program Notes:**

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (5 ea. 10 total, 3' dia.). Large skew (41 degree), deep excavation (12 ft). Install girder stops at Pier 1 thru 4.

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

Estimated Total Bridge Item Cost:  
 Estimated Total Retrofit Project Cost:

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0006313D		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/509W		S 272ND ST OC		5	146.81	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
4.8 N JCT SR 18	1 miles	122 17 48	47 21 27.6	151 ft.		91.5 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
S 272ND ST		31.83 %g	41.9% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1961	<b>ADT:</b> 80000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 2002	<b>Truck Pct:</b> 15 %	27	4	Pier with more than two columns		



**Bridge Notes:**

Piers 2 and 3, each has seven columns. Retrofit five east 3'-0" diameter columns. #3 hoops @ 12". #10 bars with 3'-8" splices. Footing without top mat. (E-23h)

**Retrofit Program Notes:**

Bridge widened (c5981). Add two 3'-0" dia. Columns West side on 4'-6" drilled shafts at Piers 2 and 3 each side of bridge.

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (5 ea. 10 total, 3' dia.)

<b>Overall Retrofit Status:</b>	P
<b>Single Column Pier Status:</b>	N
<b>Multi Column Pier Status:</b>	R
C=Complete P=Partially Complet	
R=Required N=Not Required	
D=Differed X=Excluded I=In Progress	

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0006313C		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/509E		S 272ND ST OC		5	146.81	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
4.8 N JCT SR 18	1 miles	122° 17' 46"	47° 21' 27.4"	151 ft.		76.5 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
S 272ND ST		31.83 %g	41.9% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1961	<b>ADT:</b> 80000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1994	<b>Truck Pct:</b> 15 %	28	4	Pier with more than two columns		
 <div style="position: absolute; top: 50%; left: 50%; transform: translate(-50%, -50%); font-size: 48px; font-weight: bold; opacity: 0.5;">No Photo Available</div>						
<b>Bridge Notes:</b>			<b>Retrofit Program Notes:</b>			
Piers 2 and 3, each has six columns. Retrofit five east 3'-0" diameter columns. #3 hoops @ 12". #10 bars with 3'-8" splices. Footing without top mat. (E-23h)			Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.			
<b>Completed Retrofit Notes:</b>			<b>Remaining Retrofit Notes:</b>			
			Retrofit columns at Piers 2 and 3. (5 ea. 10 total, 3' dia.)			
<b>Overall Retrofit Status:</b> P		<b>Estimated Total Bridge Item Cost:</b>  <b>Estimated Total Retrofit Project Cost:</b>				
<b>Single Column Pier Status:</b> N						
<b>Multi Column Pier Status:</b> R						
C=Complete P=Partially Complet R=Required N=Not Required D=Differed X=Excluded I=In Progress						

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0006186A		<b>Bridge Name:</b> S 260TH ST OC		<b>Route:</b> 5	<b>Milepost:</b> 147.64	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/510E						<b>County:</b> King
<b>Location:</b> 5.6 N JCT SR 18	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> 122° 17' 36"	<b>Latitude:</b> 47° 22' 12"	<b>Structure Length:</b> 162 ft.		<b>Out to Out Width:</b> 68 ft.
<b>Feature Intersected:</b> S 260TH ST		<b>PGA (500 yr):</b> 31.99 %g	<b>PGA (1000 yr):</b> 42.2% %g	<b>Span Type:</b> CVS	<b>Main Spans:</b> 3 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1960	<b>ADT:</b> 80000	<b>11-13 Rank:</b> 29	<b>Skew Angle:</b> 0	<b>Pier Type:</b> Pier with more than two columns	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1991	<b>Truck Pct:</b> 15 %					



**Bridge Notes:**

Piers 2 and 3, each has four columns. Retrofit three east 2'-9" diameter columns. #4 hoops @ 12". #9 bars with 3'-4" splices. Footing without top mat.

**Retrofit Program Notes:**

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (3 ea. 6 total, 2'-9" dia.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0006186B		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/510W		S 260TH ST OC		5	147.64	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
5.6 N JCT SR 18	1 miles	122° 17' 36"	47° 22' 12"	162 ft.		92.2 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
S 260TH ST		31.99 %g	42.2% %g	CVS	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1960	<b>ADT:</b> 80000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 2002	<b>Truck Pct:</b> 15 %	30	0	Pier with more than two columns		



**Bridge Notes:**

Piers 2 and 3, each has five columns. Retrofit three center 2'-9" diameter columns. #4 hoops @ 12". #9 bars with 3'-4" splices. Footing without top mat.

**Retrofit Program Notes:**

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (3 ea. 6 total, 2'-9" dia.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0006820A		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/511E		SR 516 OC		5	149.17	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
7.2 N JCT SR 18	1 miles	122° 17' 24"	47° 23' 0"	269 ft.		90 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 4	
SR 516		32.15 %g	42.6% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1962	<b>ADT:</b> 85000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1991	<b>Truck Pct:</b> 15 %	31	30	Pier with more than two columns		



**Bridge Notes:**

Piers 2, 3 and 4, each has seven 3'-0" diameter columns. Retrofit six east columns only. These columns have #3 hoops @ 12". #10 bars with 3'-8" splices. Footing without top mat. (E-23h)

**Retrofit Program Notes:**

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2, 3 and 4. (6 ea. 18 total, 3' dia.)

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007090C		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/516W		ORILLA RD OC-SO188TH ST		5	152.26	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
3.1 N JCT SR 516	0 miles	122° 16' 12" W	47° 25' 54" N	230 ft.		93.8 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
ORILLA RD		32.62 %g	43.8% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1963	<b>ADT:</b> 89500	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1997	<b>Truck Pct:</b> 15 %	32	0	Pier with more than two columns		



**Bridge Notes:**

Piers 2 and 3, each has seven 3'-0" diameter columns. Retrofit six west columns only. These 3'-0" diameter columns have #3 hoops @ 12" and longitudinal bars with lap splices. Footing without top mat. (E-54m)

**Retrofit Program Notes:**

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (6 ea. 12 total, 3' dia.)

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007090B		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/516E		ORILLA RD OC		5	152.26	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
3.1 N JCT SR 516	0 miles	122° 16' 12" W	47° 25' 54" N	195 ft.		79 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
ORILLA RD		32.62 %g	43.8% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1963	<b>ADT:</b> 89500	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1994	<b>Truck Pct:</b> 15 %	33	1	Pier with more than two columns		



**Bridge Notes:**

Piers 2 and 3, each has seven 3'-0" diameter columns. Retrofit six east columns only. These 3'-0" diameter columns have #3 hoops @ 12" and longitudinal bars with lap splices. Footing without top mat. (E-54m)

**Retrofit Program Notes:**

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (6 ea. 12 total, 3' dia.)

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007401D		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/520W		KLICKITAT DR OC		5	154.13	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
5.0 N JCT SR 516	5 miles	122° 15' 52.1"	47° 27' 28.9"	163 ft.		81.7 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
KLICKITAT DR		32.83 %g	44.6% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1965	<b>ADT:</b> 102000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1997	<b>Truck Pct:</b> 15 %	34	0	Pier with more than two columns		



**Bridge Notes:**

Retrofit five 3'-0" diameter columns at Piers 2 and 3. These columns have #3 hoops @ 12". Longitudinal bars with lap splices. Footing without top mat. (E-54m)

**Retrofit Program Notes:**

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (5 ea. 10 total, 3' dia.)

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007401F		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/521W		E-N RAMP OC		5	154.52	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
5.2 N JCT SR 516	1 miles	122° 15' 54"	47° 27' 42"	146 ft.		81.6 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
I-405 E-E RAMP		32.87 %g	44.7% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1966	<b>ADT:</b> 102000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 15 %	35	13	Pier with more than two columns	Timber pile	



**Bridge Notes:**

Piers 2 and 3, each has four 3'-0" diameter columns. #3 hoops @ 12". Longitudinal #9 bars with 3'-4" lap splices. Footing without top mat.

**Retrofit Program Notes:**

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (4 ea. 8 total, 3' dia.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007401E		<b>Bridge Name:</b> E-N S-N RAMPS OC		<b>Route:</b> 5	<b>Milepost:</b> 154.52	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/521E						<b>County:</b> King
<b>Location:</b> 5.2 N JCT SR 516	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> 122° 15' 48"	<b>Latitude:</b> 47° 27' 42"	<b>Structure Length:</b> 217 ft.		<b>Out to Out Width:</b> 71.6 ft.
<b>Feature Intersected:</b> I-405 E-E S-E RAMP		<b>PGA (500 yr):</b> 32.85 %g	<b>PGA (1000 yr):</b> 44.6% %g	<b>Span Type:</b> PCG	<b>Main Spans:</b> 4 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1966	<b>ADT:</b> 102000	<b>11-13 Rank:</b> 36	<b>Skew Angle:</b> 0	<b>Pier Type:</b> Pier with more than two columns	<b>Footing Type:</b> Timber pile	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 15 %					



**Bridge Notes:**

Piers 2, 3 and 4, each has four 3'-0" diameter columns. #3 hoops @ 12". longitudinal bars with lap splices. Footing without top mat. (E-54m)

**Retrofit Program Notes:**

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2, 3 and 4. (4 ea. 12 total, 3' dia.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007617D		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/531W		MILITARY RD OC		5	159.67	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
2.2 N JCT SR 900	1 miles	122 17 36	47 31 48	149 ft.		81 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
MILITARY RD ROSE ST		33.42 %g	46.3% %g	CS	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1966	<b>ADT:</b> 106000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1995	<b>Truck Pct:</b> 15 %	37	0	Pier with more than two columns		



**Bridge Notes:**

Piers 2 and 3, each has five 3'-0" diameter columns. Retrofit four east columns only. These columns have #4 hoops @ 12". longitudinal #9 bars with 3'-4" lap splices. Footings without top mat.

**Retrofit Program Notes:**

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (4 ea. 8 total, 3' dia.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007617C		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/531E		MILITARY RD OC		5	159.67	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
2.2 N JCT SR 900	1 miles	122° 17' 37.3"	47° 31' 49.7"	161 ft.		83 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
MILITARY RD ROSE ST		33.42 %g	46.3% %g	CS	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1966	<b>ADT:</b> 106000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1991	<b>Truck Pct:</b> 15 %	38	13	Pier with more than two columns	Steel pile	



**Bridge Notes:**

Piers 2 and 3, each has five 3'-0" diameter columns. Retrofit four west columns only. These columns have #4 hoops @ 12". longitudinal #9 bars with 3'-4" lap splices. Footings without top mat.

**Retrofit Program Notes:**

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (4 ea. 8 total, 3' dia.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007734C		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/534W		LUCILE ST OC		5	161.27	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
4.1 N JCT SR 900	1 miles	122 19 6.2	47 33 11.5	190 ft.		79 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
LUCILE ST		33.61 %g	46.7% %g	CS	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1966	<b>ADT:</b> 106000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1995	<b>Truck Pct:</b> 15 %	39	22	Pier with more than two columns		



**Bridge Notes:**

Piers 2 and 3, each has five 3'-0" diameter columns. Retrofit four east columns per pier only. These columns have #4 hoops @ 12". longitudinal #9 bars with 3'-4" lap splices. Footing without top mat.

**Retrofit Program Notes:**

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (4 ea. 8 total, 3' dia.). 12' excavation. Install catchers and stops at Piers 1 and 4 (22 degree skew).

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

Structure ID: 0007734B		Bridge Name: LUCILE ST OC		Route: 5	Milepost: 161.27	Region: Northwest
Bridge Number: 5/534E						County: King
Location: 3.9 N JCT SR 900	Detour Length: 1 miles	Longitude: 122° 19' 0"	Latitude: 47° 33' 12"	Structure Length: 172 ft.		Out to Out Width: 93.6 ft.
Feature Intersected: LUCILE ST		PGA (500 yr): 33.61 %g	PGA (1000 yr): 46.7% %g	Span Type: CS	Main Spans: 3 Appr. Spans: 0	
Year Built: 1966	ADT: 106000	11-13 Rank: 40	Skew Angle: 22	Pier Type: Pier with more than two columns	Footing Type:	
Year Rebuilt: 0	Truck Pct: 15 %					
				<h2 style="font-size: 2em; transform: rotate(-10deg);">No Photo Available</h2>		
<b>Bridge Notes:</b> Piers 2 and 3, each has five 3'-0" diameter columns. #4 hoops @ 12". Longitudinal #9 bars with 3'-4" lap splices. Footing without top mat.			<b>Retrofit Program Notes:</b> Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.			
<b>Completed Retrofit Notes:</b>			<b>Remaining Retrofit Notes:</b> Retrofit columns at Piers 2 and 3. (5 ea. 10 total, 3' dia.). Install catcher blocks at piers 1 and 4.			
<b>Overall Retrofit Status:</b> R <b>Single Column Pier Status:</b> N <b>Multi Column Pier Status:</b> R C=Complete P=Partially Complet R=Required N=Not Required D=Differed X=Excluded I=In Progress		<b>Estimated Total Bridge Item Cost:</b> <b>Estimated Total Retrofit Project Cost:</b>				

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007816B		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/535W		SB VIADUCT STA 2032		5	162.24	<b>County:</b> King
<b>Location:</b> 4.5 N JCT SR 900	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> 122 19 18.8	<b>Latitude:</b> 47 33 47	<b>Structure Length:</b> 604 ft.		<b>Out to Out Width:</b> 73 ft.
<b>Feature Intersected:</b> SB VIADUCT STA 2032		<b>PGA (500 yr):</b> 33.55 %g	<b>PGA (1000 yr):</b> 46.4% %g	<b>Span Type:</b> PCG		<b>Main Spans:</b> 6 <b>Appr. Spans:</b> 0
<b>Year Built:</b> 1966	<b>ADT:</b> 118000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1992	<b>Truck Pct:</b> 15 %	41	0	Pier with more than two columns		



**Bridge Notes:**

Piers 2 thru 5, each has six 4'-0" diameter columns. Pier 6 has six 4'-6" diameter columns. Retrofit four center columns per pier at piers 2 thru 5 only. These columns have #4 hoops @ 12". longitudinal bars with lap or/and welded splices. Footing with top mat. Pier 6 has four 4'-6" (O.D.) x 5" wall prestressed concrete piles, filled with cylinder concrete after piles are set in place. No retrofit recommended.

**Retrofit Program Notes:**

Widened in 1992. Adds one 4'-0" diameter shaft column on each side of the existing 4 columns at piers 2 thru 5 and one 4'-6" diameter shaft column on each side of the existing 4 columns at pier 6.

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2, 3, 4 and 5. (4 ea. 16 total, 4' dia.). Deep excavation (38' max.)

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007741A		<b>Bridge Name:</b> NB VIADUCT STA 2064		<b>Route:</b> 5	<b>Milepost:</b> 162.98	<b>Region:</b> Northwest	
<b>Bridge Number:</b> 5/536E						<b>County:</b> King	
<b>Location:</b> 5.2 N JCT SR 900		<b>Detour Length:</b> 1 miles		<b>Longitude:</b> 122° 19' 12.5"	<b>Latitude:</b> 47° 34' 10.5"	<b>Structure Length:</b> 746 ft.	
						<b>Out to Out Width:</b> 58.8 ft.	
<b>Feature Intersected:</b> NB VIADUCT STA 2064		<b>PGA (500 yr):</b> 33.42 %g	<b>PGA (1000 yr):</b> 46.1% %g	<b>Span Type:</b> CS		<b>Main Spans:</b> 18 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1966	<b>ADT:</b> 98500	<b>11-13 Rank:</b> 42	<b>Skew Angle:</b> 0	<b>Pier Type:</b> Pier with more than two columns		<b>Footing Type:</b> Drilled shaft	
<b>Year Rebuilt:</b> 1992	<b>Truck Pct:</b> 15 %						
<h1 style="font-size: 2em; color: black; opacity: 0.5;">No Photo Available</h1>							
<b>Bridge Notes:</b> Piers 2 thru 8, each has four 3'-0" dia. columns on 3'-6" dia. drilled shafts. Pier 9 thru 18, each has four columns. Retrofit three west columns only. These columns are 3'-0" dia. columns on 3'-6" dia. drilled shafts. Hoops are #4 @ 12". Longitudinal bars insert 5'-0" into drilled shafts. Max. span length = 42'.				<b>Retrofit Program Notes:</b> Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.			
<b>Completed Retrofit Notes:</b>				<b>Remaining Retrofit Notes:</b> Retrofit 51 columns built in 1966 (on drilled shaft, 3' dia.)			
<b>Overall Retrofit Status:</b> P		<b>Single Column Pier Status:</b> N		<b>Multi Column Pier Status:</b> R		<b>Estimated Total Bridge Item Cost:</b>  <b>Estimated Total Retrofit Project Cost:</b>	
C=Complete P=Partially Complet							
R=Required N=Not Required							
D=Differed X=Excluded I=In Progress							

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007741B		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/536W		SB VIADUCT STA 2064		5	162.98	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
5.2 N JCT SR 900	1 miles	122° 19' 6"	47° 34' 18"	746 ft.		53.7 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 18	
SB VIADUCT STA 2064		33.42 %g	46.0% %g	CS	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1967	<b>ADT:</b> 98500	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1992	<b>Truck Pct:</b> 15 %	43	0	Pier with more than two columns	Drilled shaft	

No Photo Available



**Bridge Notes:**

Piers 2 thru 5, each has four 3'-0" dia. columns on 3'-6" dia. drilled shafts. Pier 6 thru 18, each has three 3'-0" dia. columns on 3'-6" dia. drilled shafts. Hoops are #4 @ 12". Longitudinal bars insert 5'-0" into drilled shafts. Max. span length = 42'.

**Retrofit Program Notes:**

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit 55 columns built in 1967 (on drilled shaft, 3' dia.)

<b>Overall Retrofit Status:</b>	P
<b>Single Column Pier Status:</b>	N
<b>Multi Column Pier Status:</b>	R
C=Complete P=Partially Complet	
R=Required N=Not Required	
D=Differed X=Excluded I=In Progress	

Estimated Total Bridge Item Cost:  
Estimated Total Retrofit Project Cost:

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007741C		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/538E		NB VIADUCT STA 2075		5	162.98	<b>County:</b> King
<b>Location:</b> 5.6 N JCT SR 900	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> 122° 19' 6"	<b>Latitude:</b> 47° 34' 30"	<b>Structure Length:</b> 872 ft.		<b>Out to Out Width:</b> 60.7 ft.
<b>Feature Intersected:</b> NB VIADUCT STA 2075		<b>PGA (500 yr):</b> 33.39 %g	<b>PGA (1000 yr):</b> 45.9% %g	<b>Span Type:</b> CS	<b>Main Spans:</b> 21 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1966	<b>ADT:</b> 98500	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1992	<b>Truck Pct:</b> 15 %	44	0	Pier with more than two columns	Drilled shaft	



**Bridge Notes:**

Max. span length = 45'. 4 columns per pier. Retrofit columns built in 1966 only (three west columns per pier). Piers 11 thru 15, each has three 4' dia. columns on 5' dia. drilled shafts. Piers 2 thru 9 and 16 thru 21, each has three 3' dia. columns on 3'-6" dia. drilled shafts. #4 hoops @ 12". Piers 10 thru 17 have horizontal struts.

**Retrofit Program Notes:**

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 thru 21. (3 ea. 60 total, 3' dia. except P11-P15 3-4' dia. ea.)

<b>Overall Retrofit Status:</b>	P
<b>Single Column Pier Status:</b>	N
<b>Multi Column Pier Status:</b>	R
C=Complete P=Partially Complet	
R=Required N=Not Required	
D=Differed X=Excluded I=In Progress	

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007741D		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/539W		SB VIADUCT STA 2075		5	162.98	<b>County:</b> King
<b>Location:</b> 5.8 N JCT SR 900	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> 122° 19' 6"	<b>Latitude:</b> 47° 34' 30"	<b>Structure Length:</b> 6622 ft.		<b>Out to Out Width:</b> 71 ft.
<b>Feature Intersected:</b> SB VIADUCT STA 2075		<b>PGA (500 yr):</b> 33.39 %g	<b>PGA (1000 yr):</b> 45.9% %g	<b>Span Type:</b> CS	<b>Main Spans:</b> 157 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1967	<b>ADT:</b> 98500	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1992	<b>Truck Pct:</b> 15 %	45	0	Pier with more than two columns	Drilled shaft	



**Bridge Notes:**

Columns on drilled shafts. Contract 7741: Piers 2 thru 10, 16 thru 30, retrofit four columns each pier (3' dia. column on 3'-6" dia. drilled shaft), pier 11 thru 15, (four 4' dia. column on 5'-0" dia. drilled shaft). Piers 9 thru 18 have horizontal struts. Contract 7686: piers 25 thru 152, 3' dia. Columns except East columns at Piers 146 thru 152 are 4' diameter. Max. span =42'.

**Retrofit Program Notes:**

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at piers 2 thru 152 (628 total, 3' dia. except P11-P15, 2-4' dia. ea.).

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation

## Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007741E		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/539E		NB VIADUCT STA 2085		5	163.24	<b>County:</b> King
<b>Location:</b> 5.8 N JCT SR 900	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> ° ' " 122 19 10.9	<b>Latitude:</b> ° ' " 47 34 34	<b>Structure Length:</b> 5825 ft.		<b>Out to Out Width:</b> 73 ft.
<b>Feature Intersected:</b> NB VIADUCT STA 2085		<b>PGA (500 yr):</b> 33.39 %g	<b>PGA (1000 yr):</b> 45.9% %g	<b>Span Type:</b> CS	<b>Main Spans:</b> 138 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1966	<b>ADT:</b> 98500	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1992	<b>Truck Pct:</b> 15 %	46	0	Pier with more than two columns	Drilled shaft	
<div style="display: flex; justify-content: space-around; font-size: 2em; font-weight: bold; opacity: 0.5;"> <span>No Photo Available</span> <span>No Photo Available</span> </div>						
<b>Bridge Notes:</b>			<b>Retrofit Program Notes:</b>			
<p>Retrofit columns built in 1966 only. Piers 2 thru 10, each has five 3' columns on 4' shafts. Piers 11, 12, 95 thru 103 and 114 thru 127, each has five 3' columns on 3'-6" shafts. Piers 13 thru 94, each has four 3' columns on 3'-6" shafts. Piers 104 thru 114, each has six 3' columns on 3'-6" shafts. Piers 115 thru 120 and 128 thru 138, each has three 3' columns on 3'-6" shafts. #4 hoops @12". Horizontal struts at piers 15 thru 19 and 56 thru 78. Lap splices at top of drilled shafts and top of horizontal struts.</p>			<p>Columns of bridge 5/539NCD are to be included with this bridge.</p> <p>Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.</p>			
<b>Completed Retrofit Notes:</b>			<b>Remaining Retrofit Notes:</b>			
			Retrofit 577 columns. (includes bridge 5/539NCD, 3' dia.)			
<b>Overall Retrofit Status:</b>		<div style="font-size: 1.5em; font-weight: bold;"> <b>Estimated Total Bridge Item Cost:</b>  <b>Estimated Total Retrofit Project Cost:</b> </div>				
<b>Single Column Pier Status:</b>						
<b>Multi Column Pier Status:</b>						
C=Complete P=Partially Complet R=Required N=Not Required D=Differed X=Excluded I=In Progress						
P						
N						
R						

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007504D		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/543SCD		SBCD KING JACKSON ST OC		5	164.41	<b>County:</b> King
<b>Location:</b> 0.3 N JCT I-90	<b>Detour Length:</b> 2 miles	<b>Longitude:</b> 122° 19' 11.7"	<b>Latitude:</b> 47° 35' 53.5"	<b>Structure Length:</b> 709 ft.		<b>Out to Out Width:</b> 64.6 ft.
<b>Feature Intersected:</b> KING JACKSON ST		<b>PGA (500 yr):</b> 33.14 %g	<b>PGA (1000 yr):</b> 45.1% %g	<b>Span Type:</b> CBox	<b>Main Spans:</b> 9 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1965	<b>ADT:</b> 73582	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 10 %	47	30	Pier with more than two columns	Drilled shaft	



**Bridge Notes:**

Piers 2 thru 9, each has three 4'-0" diameter columns on 5'-0" diameter drilled shafts. End pier, pier 1, has three 24"x36" columns on 4' shafts. Columns have double hinges. End pier, pier 10, has three 4' diameter column shafts. These columns have #4 hoops @ 12". Vertical #11 bars have 6'-0" min, lap splices at top of drilled. In span hinges at span 4 near pier 4 and span 7 near pier 8.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 thru 9. (3 ea. 24 total, 4' dia.)

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0005455A		<b>Bridge Name:</b> PACIFIC AVE OC		<b>Route:</b> 5	<b>Milepost:</b> 107.45	<b>Region:</b> Olympic
<b>Bridge Number:</b> 5/332						<b>County:</b> Thurston
<b>Location:</b> 3.2 N JCT US 101	<b>Detour Length:</b> 0 miles	<b>Longitude:</b> 122° 51' 6.7"	<b>Latitude:</b> 47° 2' 28.1"	<b>Structure Length:</b> 351 ft.		<b>Out to Out Width:</b> 138 ft.
<b>Feature Intersected:</b> PACIFIC AVE		<b>PGA (500 yr):</b> 29.75 %g	<b>PGA (1000 yr):</b> 39.1% %g	<b>Span Type:</b> CBox PTCBox		<b>Main Spans:</b> 3 <b>Appr. Spans:</b> 0
<b>Year Built:</b> 1957	<b>ADT:</b> 121768	<b>11-13 Rank:</b> 48	<b>Skew Angle:</b> 0	<b>Pier Type:</b> Pier with more than two columns		<b>Footing Type:</b> Concrete Pile
<b>Year Rebuilt:</b> 1987	<b>Truck Pct:</b> 10 %					



**Bridge Notes:**

Piers 2 and 3, each has four 6'-0" diameter columns. Retrofit two center columns per pier (built in 1957) only. These columns have #4 hoops @12", longitudinal #14 bars have splices at top of pedestal. Splice lengths are 2'-10". Footings have no top mat. Longitudinal expansion joints between bridges built in 1957 and widening portion built in 1987.

**Retrofit Program Notes:**

The 2005 Transportation Partnership Account (TPA) included funding to perform seismic retrofit work on this bridge.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

A seismic analysis will be done to determine what work is required. Typical retrofit measures and costs are: Cross-Beam Bolsters = \$1,500/LF of Cross Beam, Girder Stops = \$1,500/Each, Column Jackets (Dry) = \$50,000/Col. (Wet) = \$125,000/Col.

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007504A		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/543E		KING-JACKSON ST OC		5	164.41	<b>County:</b> King
<b>Location:</b> 0.3 N JCT I-90	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> 122 ° 19 ' 11.7 "	<b>Latitude:</b> 47 ° 35 ' 53.5 "	<b>Structure Length:</b> 706 ft.		<b>Out to Out Width:</b> 62 ft.
<b>Feature Intersected:</b> KING-JACKSON ST		<b>PGA (500 yr):</b> 33.14 %g	<b>PGA (1000 yr):</b> 45.1% %g	<b>Span Type:</b> CBox		<b>Main Spans:</b> 9 <b>Appr. Spans:</b> 0
<b>Year Built:</b> 1965	<b>ADT:</b> 79500	<b>11-13 Rank:</b> 49	<b>Skew Angle:</b> 30	<b>Pier Type:</b> Double Column Pier	<b>Footing Type:</b> Drilled shaft	
<b>Year Rebuilt:</b> 1992	<b>Truck Pct:</b> 15 %					



**Bridge Notes:**

Contract 7504: Piers 2 and 3, three 4' columns on 5' shafts. Piers 4 thru 9, two 4' columns on 5' shafts. #4 hoops @ 12". Lap splices at top of shafts.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns built in 1965 at Piers 2 thru 9 (18 total, 4' dia.).

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007504B		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/543W		KING-JACKSON ST OC		5	164.41	<b>County:</b> King
<b>Location:</b> 0.3 N JCT I-90	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> 122° 19' 11.7"	<b>Latitude:</b> 47° 35' 53.5"	<b>Structure Length:</b> 712 ft.		<b>Out to Out Width:</b> 58.8 ft.
<b>Feature Intersected:</b> KING-JACKSON ST		<b>PGA (500 yr):</b> 33.14 %g	<b>PGA (1000 yr):</b> 45.1% %g	<b>Span Type:</b> CBox		<b>Main Spans:</b> 9 <b>Appr. Spans:</b> 0
<b>Year Built:</b> 1965	<b>ADT:</b> 79500	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1992	<b>Truck Pct:</b> 15 %	50	30	Double Column Pier	Drilled shaft	



**Bridge Notes:**

Piers 2 thru 9, each has three 4'-0" diameter columns on 5'-0" diameter drilled shafts. End pier, pier 1, has three 24"x36" columns on 4' shafts. Columns have double hinges. End pier, pier 10, has three 4' diameter column shafts. Retrofit two east columns at piers 2 thru 9 only. These columns have #4 hoops @ 12". Vertical #11 bars have 6'-0" min, lap splices at top of drilled. In span hinges at span 4 near pier 4 and span 7 near pier 8.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns built in 1965 at Piers 2 thru 9 (16 total, 4' dia.).

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007565F		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/542E		DEARBORN ST OC		5	164.41	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
0.1 N JCT I-90	1 miles	122 19 0	47 35 42	219 ft.		64 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
DEARBORN ST		33.15 %g	45.2% %g	CBox	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1965	<b>ADT:</b> 82000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1992	<b>Truck Pct:</b> 15 %	51	0	Multiple Column Pier		



**Bridge Notes:**

Piers 2 and 3, each has three 4'-0" diameter columns. Retrofit two west columns only (built in 1965). These columns are on spread footings. Ties are #4 hoops @ 12". Vertical #11 bars have 3'-8" lap splices at top of footing. Footing without top mat. End piers, 1 and 4, are spill through abutments. Each has three columns. Columns have hinge near top of column.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3 ( 2 ea. 4 total, 4' dia.).

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007565G		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/542W		DEARBORN ST OC		5	164.41	<b>County:</b> King
<b>Location:</b> 0.1 N JCT I-90	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> ° ' "	<b>Latitude:</b> ° ' "	<b>Structure Length:</b> 219 ft.		<b>Out to Out Width:</b> 58.5 ft.
<b>Feature Intersected:</b> DEARBORN ST		<b>PGA (500 yr):</b> 33.15 %g	<b>PGA (1000 yr):</b> 45.2% %g	<b>Span Type:</b> CBox	<b>Main Spans:</b> 3 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1965	<b>ADT:</b> 82000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1992	<b>Truck Pct:</b> 15 %	52	0	Multiple Column Pier		



**Bridge Notes:**

Piers 2 and 3, each has three columns. Retrofit 2 east columns per pier only. These columns are 4' diameter columns on spread footings. #4 hoops @12". Longitudinal bars have lap splices at top of footings. Footings do not have top mat.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3 ( 2 ea. 4 total, 4' dia.).

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007565J		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/542SCD		SBCD DEARBORN ST OC		5	164.41	<b>County:</b> King
<b>Location:</b> 0.1 N JCT I-90	<b>Detour Length:</b> 2 miles	<b>Longitude:</b> 122° 19' 6"	<b>Latitude:</b> 47° 35' 42"	<b>Structure Length:</b> 216 ft.		<b>Out to Out Width:</b> 64.6 ft.
<b>Feature Intersected:</b> SBCD DEARBORN ST		<b>PGA (500 yr):</b> 33.16 %g	<b>PGA (1000 yr):</b> 45.2% %g	<b>Span Type:</b> CBox	<b>Main Spans:</b> 3 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1965	<b>ADT:</b> 73582	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 5 %	53	2	Pier with more than two columns		



**Bridge Notes:**

Piers 2 and 3, each has three 4'-0" diameter columns on spread footings. These columns have #4 hoops @ 12". Vertical #11 bars have 3'-9" min. lap splices at top of footing. Footing without top mat. End pier 1 has three 30" square columns with hinges at top of columns and top of footings. End pier 4 has three 30" square columns with hinges at top of columns.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (3 ea. 6 total, 4' dia.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007504C		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/543NCD		NBCD KING JACKSON ST OC		5	164.41	<b>County:</b> King
<b>Location:</b> 0.3 N JCT I-90	<b>Detour Length:</b> 2 miles	<b>Longitude:</b> ° ' " 122 19 11.7	<b>Latitude:</b> ° ' " 47 35 53.5	<b>Structure Length:</b> 709 ft.		<b>Out to Out Width:</b> 52.6 ft.
<b>Feature Intersected:</b> NBCD KING JACKSON ST		<b>PGA (500 yr):</b> 33.14 %g	<b>PGA (1000 yr):</b> 45.1% %g	<b>Span Type:</b> CBox	<b>Main Spans:</b> 9 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1965	<b>ADT:</b> 61357	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 10 %	54	30	Double Column Pier	Drilled shaft	



**Bridge Notes:**

Piers 2 thru 5, each has three 4'-0" diameter columns on 5'-0" diameter drilled shafts. Piers 6 thru 9, each has two 4'-0" diameter columns on 5'-0" diameter drilled shafts. These columns have #4 hoops @ 12". Vertical #11 bars have 6'-0" min, lap splices at top of drilled. In span hinges at span 4 near pier 4 and span 7 near pier 8. End pier, pier 1, has three 24"x36" columns on 4' shafts. Columns have double hinges. End pier, pier 10, has three 4' diameter column shafts.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 thru 9. ( 20 total, 4' dia.)

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007686C		<b>Bridge Name:</b> NBCD RAMP BR		<b>Route:</b> 5	<b>Milepost:</b> 164.41	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/539NCD						<b>County:</b> King
<b>Location:</b> 6.7 N JCT SR 900	<b>Detour Length:</b> 2 miles	<b>Longitude:</b> 122° 19' 12.6"	<b>Latitude:</b> 47° 35' 19.6"	<b>Structure Length:</b> 151 ft.		<b>Out to Out Width:</b> 37.6 ft.
<b>Feature Intersected:</b> NBCD RAMP BR		<b>PGA (500 yr):</b> 33.2 %g	<b>PGA (1000 yr):</b> 45.5% %g	<b>Span Type:</b> CS	<b>Main Spans:</b> 4 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1965	<b>ADT:</b> 20459	<b>11-13 Rank:</b> 55	<b>Skew Angle:</b> 0	<b>Pier Type:</b> Pier with more than two columns	<b>Footing Type:</b> Drilled shaft	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 10 %					



**Bridge Notes:**

NBCD piers 111B thru 114B. Piers 111B thru 113B, each pier has three 3'-0" diameter columns on 3'-6" diameter drilled shafts. Ties are #4 hoops @ 12".

**Retrofit Program Notes:**

Columns of bridge 5/539NCD are included in Bridge 5/539E retrofit.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Columns of bridge 5/539NCD are included in Bridge 5/539E retrofit.

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 00075651		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/542NCD		NBCD DEARBORN ST OC		5	164.41	<b>County:</b> King
<b>Location:</b> 0.1 N JCT I-90	<b>Detour Length:</b> 2 miles	<b>Longitude:</b> 122° 19' 8"	<b>Latitude:</b> 47° 35' 45.4"	<b>Structure Length:</b> 216 ft.		<b>Out to Out Width:</b> 40.8 ft.
<b>Feature Intersected:</b> DEARBORN ST		<b>PGA (500 yr):</b> 33.16 %g	<b>PGA (1000 yr):</b> 45.2% %g	<b>Span Type:</b> CBox	<b>Main Spans:</b> 3 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1965	<b>ADT:</b> 20459	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 5 %	56	0	Double Column Pier		



**Bridge Notes:**

Piers 2 and 3, each has two 4'-0" diameter columns on spread footings. These columns have #4 hoops @ 12". Vertical #11 bars have 4'-0" min. lap splices at top of footing. Footing without top mat. End piers, 1 and 4, each has two 30" square columns with hinges at top of columns.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (2 ea. 4' total, 4' dia.). 7' excavation.

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007401J		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest	
<b>Bridge Number:</b> 405/1		I-405 OVER I-5		405	0	<b>County:</b> King	
<b>Location:</b> JCT I-5	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> ° ' "	<b>Latitude:</b> ° ' "	<b>Structure Length:</b> 560 ft.		<b>Out to Out Width:</b> 52 ft.	
		122 15 58.4	47 27 45.3				
<b>Feature Intersected:</b> I-5		<b>PGA (500 yr):</b> 32.86 %g	<b>PGA (1000 yr):</b> 44.7% %g	<b>Span Type:</b> CBox	<b>Main Spans:</b> 6 <b>Appr. Spans:</b> 0		
<b>Year Built:</b> 1965	<b>ADT:</b> 31740	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>		
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 8 %	56	0	Double Column Pier	Concrete Pile		
				<h2 style="font-size: 2em; color: black; text-decoration: underline;">No Photo Available</h2>			
<b>Bridge Notes:</b>				<b>Retrofit Program Notes:</b>			
<p>Piers 2, 3, 4, 5 and 6, each has two 5'-0" diameter columns on pile footings. Columns have #4 hoops @ 12". Vertical #11 bars have 4'-2" lap splices at top of footings. Footings have no top mat. Piers 1 is a "L" abutment with six roller bearings. In span hinge at span 3 near pier 4. Pier 6 has a 23' overhang.</p>							
<b>Completed Retrofit Notes:</b>				<b>Remaining Retrofit Notes:</b>			
				<p>Retrofit columns at Piers 2, 3, 4 and 5. (2 ea. 8 total, 5' dia.) Install catcher blocks.</p>			
<b>Overall Retrofit Status:</b> P				<h3 style="font-size: 1.2em;">Estimated Total Bridge Item Cost:</h3> <h3 style="font-size: 1.2em;">Estimated Total Retrofit Project Cost:</h3>			
<b>Single Column Pier Status:</b> N							
<b>Multi Column Pier Status:</b> R							
<p>C=Complete P=Partially Complet R=Required N=Not Required D=Differed X=Excluded I=In Progress</p>							

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007686D		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/539SCD		SBCD VIADUCT STA 2133		5	164.41	<b>County:</b> King
<b>Location:</b> 6.7 N JCT SR 900	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> ° ' " 122 19 18.3	<b>Latitude:</b> ° ' " 47 35 27.7	<b>Structure Length:</b> 729 ft.		<b>Out to Out Width:</b> 52.6 ft.
<b>Feature Intersected:</b> SBCD VIADUCT STA 2133		<b>PGA (500 yr):</b> 33.2 %g	<b>PGA (1000 yr):</b> 45.4% %g	<b>Span Type:</b> CS		<b>Main Spans:</b> 17 <b>Appr. Spans:</b> 0
<b>Year Built:</b> 1967	<b>ADT:</b> 17104	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 10 %	57	0	Pier with more than two columns	Drilled shaft	

No Photo Available



**Bridge Notes:**

South end connects to Bridge 5/539W. North end connects to Bridge 90/10W-S. Piers 140 thru 145, each has three 3' columns on 3'-6" shafts. Piers 146 thru 149, each has three 3' columns on 6' shafts. Piers 150, 151 and 152, each has four 3' columns on 6' shafts. Piers 153 and 154, each has five 3' columns on 6' shafts. Pier 155 has six 3' columns on 6' shafts. Pier 156SCD has three 3' columns on 5' shafts. Pier 156W-S has three 3' columns on 6' shafts. Horizontal struts at piers 146 thru 155. #4 hoops @12". Lap splices at top of shafts.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 140 Thru 155 to top of drilled shafts. (58 total, 3' dia.). Piers 146 thru 155 are structured piers.

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007110B		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/545W		SB VIADUCT STA 2195		5	165.69	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
0.8 N JCT I-90	1 miles	122° 19' 36"	47° 36' 18"	807 ft.		42 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 11	
SB VIADUCT STA 2195		33.08 %g	44.9% %g	CBox	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1964	<b>ADT:</b> 116500	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1991	<b>Truck Pct:</b> 15 %	58	0	Double Column Pier	Concrete Pile	

No Photo Available



**Bridge Notes:**

Piers 2 thru 11, each has two 4' dia. columns. Retrofit east columns for each pier only. These columns are on pile footings. #4 hoops @12". Lap splices at top of footings. Footings have no top mat. Piers 1 and 12 (abutments), each has 5 roller bearings.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns built in 1964 at Piers 2-11 (1 ea. 10 total, 4' dia.). Install catcher blocks.

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

Estimated Total Bridge Item Cost:  
 Estimated Total Retrofit Project Cost:

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007110A		<b>Bridge Name:</b> NB VIADUCT STA 2195		<b>Route:</b> 5	<b>Milepost:</b> 165.69	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/545E						<b>County:</b> King
<b>Location:</b> 0.8 N JCT I-90	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> ° ' " 122 19 38.1	<b>Latitude:</b> ° ' " 47 36 15.1	<b>Structure Length:</b> 4714 ft.		<b>Out to Out Width:</b> 51.7 ft.
<b>Feature Intersected:</b> JAMES, CHERRY, REVERS		<b>PGA (500 yr):</b> 33.06 %g	<b>PGA (1000 yr):</b> 45.0% %g	<b>Span Type:</b> CBox		<b>Main Spans:</b> 26 <b>Appr. Spans:</b> 34
<b>Year Built:</b> 1964	<b>ADT:</b> 116500	<b>11-13 Rank:</b> 59	<b>Skew Angle:</b> 0	<b>Pier Type:</b> Double Column Pier		<b>Footing Type:</b> Concrete Pile
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 15 %					



No Photo Available

**Bridge Notes:**

Piers 2 thru 8, each has two 4' cols. on pile footings. Piers 9 and 10, each has two 4' cols. on spread footings. East columns of Piers 11 thru 57 are embedded in retaining walls. The retrofit schemes and extents should be study before programming of this bridge.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2-57. (74 total, Column size vary.)

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

Estimated Total Bridge Item Cost:  
 Estimated Total Retrofit Project Cost:

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007110G		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/545SCD		SBCD VIADUCT STA 2195		5	165.71	<b>County:</b> King
<b>Location:</b> 0.8 N JCT I-90	<b>Detour Length:</b> 2 miles	<b>Longitude:</b> ° ' " 122 19 36	<b>Latitude:</b> ° ' " 47 36 18	<b>Structure Length:</b> 806 ft.		<b>Out to Out Width:</b> 47.9 ft.
<b>Feature Intersected:</b> SBCD VIADUCT STA 2195		<b>PGA (500 yr):</b> 33.08 %g	<b>PGA (1000 yr):</b> 44.9% %g	<b>Span Type:</b> CBox	<b>Main Spans:</b> 11 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1964	<b>ADT:</b> 73582	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1991	<b>Truck Pct:</b> 10 %	60	0	Double Column Pier	Concrete Pile	



**Bridge Notes:**

Pier 1 has three 2'-6" square columns with two hinges each column (acts as roller). Piers 2 and 3, each has two columns, retrofit east column only. These columns are 4' dia. column on pile footing. Pier 4 has three columns. Retrofit two 4' dia. east columns only. Piers 5 thru 9 and 11, each has two 4' dia. columns on pile footings. Pier 10 has two 4' dia. columns on tunnel. Pier 12 has 6 roller bearings. #4 hoops @12". Longitudinal bars with lap splices. Footings w/o top mat.

**Retrofit Program Notes:**

**Remaining Retrofit Notes:**

Retrofit columns built in 1964 at Piers 2 thru 11. (18 total, 4' dia.)

**Completed Retrofit Notes:**

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0006800A <b>Bridge Number:</b> 5/566W	<b>Bridge Name:</b> DENNY WAY-LAKEVIEW V	<b>Route:</b> 5	<b>Milepost:</b> 166.98	<b>Region:</b> Northwest <b>County:</b> King	
<b>Location:</b> 2.9 N JCT I-90	<b>Detour Length:</b> 3 miles	<b>Longitude:</b> 122° 19' 36"	<b>Latitude:</b> 47° 37' 18"	<b>Structure Length:</b> 7077 ft.	<b>Out to Out Width:</b> 64.6 ft.
<b>Feature Intersected:</b> DENNY WAY-LAKEVIEW V	<b>PGA (500 yr):</b> 32.73 %g	<b>PGA (1000 yr):</b> 44.1% %g	<b>Span Type:</b> CBox PCG	<b>Main Spans:</b> 53 <b>Appr. Spans:</b> 32	
<b>Year Built:</b> 1962 <b>Year Rebuilt:</b> 0	<b>ADT:</b> 108000 <b>Truck Pct:</b> 15 %	<b>11-13 Rank:</b> 61	<b>Skew Angle:</b> 45	<b>Pier Type:</b> Double Column Pier	<b>Footing Type:</b>
<div style="display: flex; justify-content: space-around; font-size: 2em; font-weight: bold; opacity: 0.5;"> <span>No Photo Available</span> <span>No Photo Available</span> </div>					
<b>Bridge Notes:</b> Contract 6635: Piers 2, 4, has three 3'x4' columns. Pier 3, 7, 9, 10,11, has two 4'x4' columns. Pier 5 has two split columns (4'x2'-8 1/2" & 2"gap). Pier 6 has two 4'x5' columns. Pier 8 has two split columns (4'x2" & 2"gap). Pier 12 has two split columns (4'x2'6" & 2"gap). Pier 13, 14, 15, has two 4'x4'6" columns. Pier 16 has three split columns (4'x3' & 2"gap, three S 1/2, two N-1/2). Pier 17, 18, has two 4'x5'6" columns. Pier 19 has two split columns (4' x 3' & 2"gap) and a (2'-6"x 3' & 2"gap) split column.. Contract 6800: Piers 20, 21, 22, 24, 25, 26, each has two 4'x5'6" columns. Piers 23, 27, 31 each has two split columns (4' x 3' & 2"gap) . Pier 28 has a 4'x6'			<b>Retrofit Program Notes:</b> Analysis of similar hollow core piles have shown a very low capacity / Demand ratio for a 475 year design level earthquake. There is no known way to retrofit these columns. Replacement of the bridge is likely to be the only way to improve the seismic risk. This bridge has been excluded from the P2 funded Bridge Seismic Retrofit program.		
<b>Completed Retrofit Notes:</b>			<b>Remaining Retrofit Notes:</b> Double deck bridge. Retrofit columns at Piers 1-53 (118 total, column size vary) and outriggers at Piers 4,16,17,18,30, 40,41, 42, 43, 44, 45, 46, 47, 48 (14 total). Not include 180 4'-0" dia. Hollow P/S conc. Piles. Install catcher blocks.		
<b>Overall Retrofit Status:</b> H <b>Single Column Pier Status:</b> N <b>Multi Column Pier Status:</b> R C=Complete P=Partially Complet R=Required N=Not Required D=Differed X=Excluded I=In Progress			<b>Estimated Total Bridge Item Cost:</b> <b>Estimated Total Retrofit Project Cost:</b>		

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0006800B		<b>Bridge Name:</b> NB LANES VIADUCT		<b>Route:</b> 5	<b>Milepost:</b> 166.98	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/562E						<b>County:</b> King
<b>Location:</b> 2.4 N JCT I-90	<b>Detour Length:</b> 3 miles	<b>Longitude:</b> 122° 19' 36"	<b>Latitude:</b> 47° 37' 36"	<b>Structure Length:</b> 381 ft.		<b>Out to Out Width:</b> 68 ft.
<b>Feature Intersected:</b> NB LANES VIADUCT		<b>PGA (500 yr):</b> 32.63 %g	<b>PGA (1000 yr):</b> 43.9% %g	<b>Span Type:</b> CTB		<b>Main Spans:</b> 11 <b>Appr. Spans:</b> 0
<b>Year Built:</b> 1963	<b>ADT:</b> 108000	<b>11-13 Rank:</b> 62	<b>Skew Angle:</b> 0	<b>Pier Type:</b> Crossbeam on Piles	<b>Footing Type:</b> Concrete Pile	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 15 %					



**Bridge Notes:**

Piers 2 thru 11, each has a 2' diameter column on pile footing. East ends of X-beams are supported on cylinder wall. Columns have #4 hoops @ 12". #8 bars with 2'-11" splices at top of footings. Footings have no top mat.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 thru 11. (2' diameter, 10 total).

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 00071561		<b>Bridge Name:</b> SBCD NORTHGATE WAY OC		<b>Route:</b> 5	<b>Milepost:</b> 172.76	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/588SCD						<b>County:</b> King
<b>Location:</b> 2.0 N JCT SR 522	<b>Detour Length:</b> 2 miles	<b>Longitude:</b> 122° 19' 42"	<b>Latitude:</b> 47° 42' 30"	<b>Structure Length:</b> 166 ft.		<b>Out to Out Width:</b> 25.5 ft.
<b>Feature Intersected:</b> SBCD NE110TH ST		<b>PGA (500 yr):</b> 31.1 %g	<b>PGA (1000 yr):</b> 40.7% %g	<b>Span Type:</b> PCG	<b>Main Spans:</b> 3 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1964	<b>ADT:</b> 6740	<b>11-13 Rank:</b> 63	<b>Skew Angle:</b> 0	<b>Pier Type:</b> Pier with more than two columns	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 5 %					



**Bridge Notes:**

Piers 2 and 3, each has three 3' dia. columns on spread footings. These columns have #3 hoops @12", longitudinal bars have lap splices at top of footings. Footings have no top mat. End piers are "L" abutments.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (3 ea. 6 total, 3' dia.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0012197B		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/588W		NORTHGATE WAY OC		5	172.76	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
2.0 N JCT SR 522	1 miles	122° 19' 42"	47° 42' 30"	166 ft.		75 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
NE NORTHGATE WAY		31.1 %g	40.7% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1964	<b>ADT:</b> 97000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1983	<b>Truck Pct:</b> 15 %	64	0	Pier with more than two columns		



No Photo Available

**Bridge Notes:**

Piers 2 and 3, each has seven 3' dia. columns on spread footings. Retrofit six W. columns built in 1964 per pier only. These columns have #3 hoops @12", longitudinal bars have lap splices at top of footings. Footings have no top mat. End piers are "L" abutments. Bridge 5/588W is parallel to bridge 5/588SCD. Profile Photo shown is bridge 5/588SCD.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (6 ea. 12 total, 3' dia.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

Estimated Total Bridge Item Cost:  
 Estimated Total Retrofit Project Cost:

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0012197A		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/588E		NORTHGATE WAY OC		5	172.76	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
2.0 N JCT SR 522	1 miles	122 19 42	47 42 30	166 ft.		75 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
NE NORTHGATE WAY		31.1 %g	40.7% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1964	<b>ADT:</b> 97000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1983	<b>Truck Pct:</b> 15 %	65	0	Pier with more than two columns		



**Bridge Notes:**

Piers 2 and 3, each has seven 3' dia. columns on spread footings. Retrofit six E. columns built in 1964 per pier only. These columns have #3 hoops @12", longitudinal bars have lap splices at top of footings. Footings have no top mat. End piers are "L" abutments.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (6 ea. 12 total, 3' dia.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0006443A		<b>Bridge Name:</b> I-5 OC, PORTER WAY		<b>Route:</b> 5	<b>Milepost:</b> 139.06	<b>Region:</b> Olympic
<b>Bridge Number:</b> 5/463						<b>County:</b> Pierce
<b>Location:</b> 1.6 N JCT SR 99	<b>Detour Length:</b> 2 miles	<b>Longitude:</b> 122° 20' 0"	<b>Latitude:</b> 47° 15' 4.4"	<b>Structure Length:</b> 615 ft.		<b>Out to Out Width:</b> 34 ft.
<b>Feature Intersected:</b> I-5 - HYLEBOS CR		<b>PGA (500 yr):</b> 30.73 %g	<b>PGA (1000 yr):</b> 40.2% %g	<b>Span Type:</b> PCG	<b>Main Spans:</b> 13 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1960	<b>ADT:</b> 890	<b>11-13 Rank:</b> 66	<b>Skew Angle:</b> 12	<b>Pier Type:</b> Pier with more than two columns	<b>Footing Type:</b> Concrete Pile	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 1 %					



**Bridge Notes:**

Piers 2, 3 and 4, each has three 3'-0" diameter columns. #3 hoops @ 12". #10 bars with 3'-8" splices. Footing without top mat. Piers 5 thru 13 are 13" diameter concrete pile bents (5 spaces @ 5'-6 1/4" normal). Max. span length= 39'-9". No retrofit recommended for pile bents. Pier 9 has double bents. Expansion joints at piers 4 and 9.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2, 3 and 4. (3 ea. 9 total, 3' dia.)

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0006094A		<b>Bridge Name:</b> I-5 OC, S 375TH		<b>Route:</b> 5	<b>Milepost:</b> 140.15	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/501						<b>County:</b> King
<b>Location:</b> 0.7 N PIERCE CO	<b>Detour Length:</b> 5 miles	<b>Longitude:</b> 122° 19' 21.7"	<b>Latitude:</b> 47° 15' 55.4"	<b>Structure Length:</b> 301 ft.		<b>Out to Out Width:</b> 34 ft.
<b>Feature Intersected:</b> I-5		<b>PGA (500 yr):</b> 30.83 %g	<b>PGA (1000 yr):</b> 40.4% %g	<b>Span Type:</b> PCG		<b>Main Spans:</b> 5 <b>Appr. Spans:</b> 0
<b>Year Built:</b> 1959	<b>ADT:</b> 400	<b>11-13 Rank:</b> 67	<b>Skew Angle:</b> 0	<b>Pier Type:</b> Pier with more than two columns		<b>Footing Type:</b>
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 1 %					



**Bridge Notes:**

Piers 2, 3, 4 and 5, each has three 3'-0" diameter columns. #3 hoops @ 12". #10 bars with 2'-2" splices. Footing without top mat. (E-21g)

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2, 3, 4 and 5. (3 ea. 12 total, 3' dia.)

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0006262A		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/505		I-5 OC, S320TH		5	143.83	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
1.8 N JCT SR 18	4 miles	122° 17' 48"	47° 18' 54"	332 ft.		76 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 4	
I-5		31.29 %g	41.0% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1960	<b>ADT:</b> 55100	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 1 %	68	15	Pier with more than two columns		

No Photo Available



**Bridge Notes:**

Piers 2, 3 and 4, each has six 3'-0" diameter columns. #3 hoops @ 12". #10 bars with 3'-8" splices. Footing without top mat. (E-23h)

**Retrofit Program Notes:**

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2, 3 and 4. (6 ea. 18 total)

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

Estimated Total Bridge Item Cost:  
 Estimated Total Retrofit Project Cost:

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007090A		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/513		I-5 OC, S 216TH		5	150.33	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
1.1 N JCT SR 516	4 miles	122° 17' 30"	47° 24' 30"	290 ft.		36 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 4	
I-5		32.51 %g	43.3% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1963	<b>ADT:</b> 12540	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 1 %	69	8	Pier with more than two columns		



**Bridge Notes:**

Piers 2, 3 and 4, each has three 3'-0" diameter columns. #3 hoops @ 12". Longitudinal bars with lap splices. Footing without top mat. (E-54m)

**Retrofit Program Notes:**

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2, 3 and 4. (3 ea. 9 total, 3' dia.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007459A		<b>Bridge Name:</b> S-W RAMP OC		<b>Route:</b> 5	<b>Milepost:</b> 152.48	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/517A						<b>County:</b> King
<b>Location:</b> 3.3 N JCT SR 516	<b>Detour Length:</b> 4 miles	<b>Longitude:</b> 122° 16' 12"	<b>Latitude:</b> 47° 26' 6"	<b>Structure Length:</b> 227 ft.		<b>Out to Out Width:</b> 37 ft.
<b>Feature Intersected:</b> S-W RAMP TO S 188TH ST		<b>PGA (500 yr):</b> 32.66 %g	<b>PGA (1000 yr):</b> 43.9% %g	<b>Span Type:</b> PCG		<b>Main Spans:</b> 4 <b>Appr. Spans:</b> 0
<b>Year Built:</b> 1964	<b>ADT:</b> 26700	<b>11-13 Rank:</b> 70	<b>Skew Angle:</b> 30	<b>Pier Type:</b> Pier with more than two columns		<b>Footing Type:</b>
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 14 %					



**Bridge Notes:**

Piers 2, 3 and 4, each has three 3'-0" diameter columns. #3 hoops @ 12". longitudinal bars with lap splices. Footing without top mat. (E-54m)

**Retrofit Program Notes:**

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2, 3 and 4. (3 ea. 9 total, 3' dia.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007401A		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/518		I-5 OC, S 178TH ST		5	153.15	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
4.0 N JCT SR 516	4 miles	122° 16' 0"	47° 26' 36"	322 ft.		33.6 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 4	
I-5		32.73 %g	44.2% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1964	<b>ADT:</b> 15000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 1 %	71	99	Pier with three columns	Spread	



**Bridge Notes:**

Piers 2, 3 and 4, each has three 3'-0" diameter columns. #3 hoops @ 12". longitudinal bars with lap splices. Footing without top mat. (E-54m).

**Retrofit Program Notes:**

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2, 3 and 4. (3 ea. 9 total, 3' dia.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007618E		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/528		I-5 OC, S 107TH ST		5	158.01	<b>County:</b> King
<b>Location:</b> 0.5 N JCT SR 900	<b>Detour Length:</b> 4 miles	<b>Longitude:</b> 122° 17' 12"	<b>Latitude:</b> 47° 30' 27"	<b>Structure Length:</b> 337 ft.		<b>Out to Out Width:</b> 89.8 ft.
<b>Feature Intersected:</b> I-5		<b>PGA (500 yr):</b> 33.27 %g	<b>PGA (1000 yr):</b> 46.0% %g	<b>Span Type:</b> PCG		<b>Main Spans:</b> 5 <b>Appr. Spans:</b> 0
<b>Year Built:</b> 1966	<b>ADT:</b> 31000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 1 %	72	22	Pier with more than two columns		



**Bridge Notes:**

Piers 2, 3, 4 and 5, each has five 3'-0" diameter columns. #3 hoops @ 12". longitudinal #8 bars spliced at top of footing. Footing without top mat.

**Retrofit Program Notes:**

Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2, 3, 4 and 5. (5 ea. 20 total, 3' dia.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0008568A		<b>Bridge Name:</b> N-SWIFT RAMP		<b>Route:</b> 5	<b>Milepost:</b> 161.27	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/532.1						<b>County:</b> King
<b>Location:</b> 3.2 N JCT SR 900	<b>Detour Length:</b> 5 miles	<b>Longitude:</b> 122° 18' 18"	<b>Latitude:</b> 47° 32' 42"	<b>Structure Length:</b> 391 ft.		<b>Out to Out Width:</b> 35 ft.
<b>Feature Intersected:</b> N-SWIFT RAMP		<b>PGA (500 yr):</b> 33.54 %g	<b>PGA (1000 yr):</b> 46.6% %g	<b>Span Type:</b> CBox		<b>Main Spans:</b> 8 <b>Appr. Spans:</b> 0
<b>Year Built:</b> 1969	<b>ADT:</b> 3121	<b>11-13 Rank:</b> 73	<b>Skew Angle:</b> 0	<b>Pier Type:</b> Double Column Pier		<b>Footing Type:</b>
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 5 %					
				<h2 style="font-size: 2em; color: black; text-decoration: underline;">No Photo Available</h2>		
<b>Bridge Notes:</b> Piers 2 thru 8, each has four 3'-0" diameter columns. #4 hoops @ 12". Longitudinal #9 bars with 3'-4" lap splices. Footings have top mats.			<b>Retrofit Program Notes:</b>			
<b>Completed Retrofit Notes:</b>			<b>Remaining Retrofit Notes:</b> Retrofit columns at Piers 2 thru 8. (2 ea. 14 total, 3' dia.)			
<b>Overall Retrofit Status:</b> P		<h3 style="font-size: 1.2em;">Estimated Total Bridge Item Cost:</h3> <h3 style="font-size: 1.2em;">Estimated Total Retrofit Project Cost:</h3>				
<b>Single Column Pier Status:</b> N						
<b>Multi Column Pier Status:</b> R						
C=Complete P=Partially Complet R=Required N=Not Required D=Differed X=Excluded I=In Progress						

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007930B		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/534A		N-W RAMP AIRPORT W. OC		5	161.27	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
4.1 N JCT SR 900	4 miles	122° 19' 13.5"	47° 33' 3.6"	636 ft.		47.6 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 8	
AIRPORT WAY		33.61 %g	46.8% %g	CBox	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1967	<b>ADT:</b> 20202	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 5 %	74	0	Double Column Pier	Steel pile	



**Bridge Notes:**

Piers 2, 4, 6, 7, 8, each has two 4'-0" diameter columns. Piers 3, each has a 4'-6"x9'-0" elliptical column. Pier 5 has two 4'-0"x 5'-3" elliptical split columns. Pier 9 has two 5'-0"x 6'-3" elliptical split columns. #4 ties @12", longitudinal bars have lap splices. Footings have top mats. (See Bridges 5/534S-W and 5/534N-W)

**Retrofit Program Notes:**

Superstructure retrofit by contract no.17367

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2, 4, 5, 6, 7, 8 and 9. (2 ea. 14 total)

<b>Overall Retrofit Status:</b>	P
<b>Single Column Pier Status:</b>	N
<b>Multi Column Pier Status:</b>	R
C=Complete P=Partially Complet	
R=Required N=Not Required	
D=Differed X=Excluded I=In Progress	

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007734A		<b>Bridge Name:</b> N-W RAMP OC		<b>Route:</b> 5	<b>Milepost:</b> 161.27	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/533.5W						<b>County:</b> King
<b>Location:</b> 4.0 N JCT SR 900	<b>Detour Length:</b> 4 miles	<b>Longitude:</b> 122° 19' 0"	<b>Latitude:</b> 47° 33' 6"	<b>Structure Length:</b> 469 ft.		<b>Out to Out Width:</b> 84.8 ft.
<b>Feature Intersected:</b> N-W RAMP		<b>PGA (500 yr):</b> 33.63 %g	<b>PGA (1000 yr):</b> 46.7% %g	<b>Span Type:</b> CBox	<b>Main Spans:</b> 6 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1966	<b>ADT:</b> 212000	<b>11-13 Rank:</b> 75	<b>Skew Angle:</b> 35	<b>Pier Type:</b> Multiple Column Pier	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1995	<b>Truck Pct:</b> 15 %					
				<h2 style="font-size: 2em; color: black; opacity: 0.5;">No Photo Available</h2>		
<b>Bridge Notes:</b>		<b>Retrofit Program Notes:</b>				
<p>Piers 2 thru 6, each has three columns. Retrofit two east columns per pier. 5'-0" diameter columns at piers 2, 3, 5 and 5. Pier 4 has 5'-0"x 6'-3" elliptical split columns. #4 ties @12". Lap splices at top of footings. Footings have top mats.</p>						
<b>Completed Retrofit Notes:</b>		<b>Remaining Retrofit Notes:</b>				
		<p>Retrofit columns at Piers 2 thru 6. (2 ea. 10 total, 3' dia.). Max. 40 feet deep excavation.</p>				
<p><b>Overall Retrofit Status:</b> R</p> <p><b>Single Column Pier Status:</b> N</p> <p><b>Multi Column Pier Status:</b> R</p> <p>C=Complete P=Partially Complet R=Required N=Not Required D=Differed X=Excluded I=In Progress</p>		<p><b>Estimated Total Bridge Item Cost:</b></p> <p><b>Estimated Total Retrofit Project Cost:</b></p>				

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007741G		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/536N-W		NB I5 to WB W SEA FRWY		5	162.98	<b>County:</b> King
<b>Location:</b> 5.4 N JCT SR 900	<b>Detour Length:</b> 4 miles	<b>Longitude:</b> 122° 19' 12"	<b>Latitude:</b> 47° 34' 30"	<b>Structure Length:</b> 1722 ft.		<b>Out to Out Width:</b> 25.6 ft.
<b>Feature Intersected:</b> W-S, I5, EB W SEA FRWY		<b>PGA (500 yr):</b> 33.4 %g	<b>PGA (1000 yr):</b> 46.0% %g	<b>Span Type:</b> CBox	<b>Main Spans:</b> 17 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1967	<b>ADT:</b> 16485	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 5 %	76	0	Single Column Pier	Drilled shaft	



**Bridge Notes:**

Pier 2 has a 5'-0" dia. column on 6'-0" dia. drilled shaft. Piers 3, 4, 5 each has a 5'-0"x 8'-0" elliptical column on 8' dia. Drilled shaft. Pier 6 and 7, each has two 5' dia. columns on 6' dia. drilled shafts. Pier 8 has a 5'-0" dia. column on 7'-0" dia. drilled shaft. Piers 9 and 10, each has a 5' dia. column on pile supported footing. Pier 11 and 17, each has a 4' dia. column. Pier 12 thru 16, each has a 4'x5'-6" elliptical column.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns built in 1967 at Piers 6 and 7 on drilled shaft. (2 ea. 4 total, 5'dia., 68-72 ft. tall columns )

**Overall Retrofit Status:** P  
**Single Column Pier Status:** C  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007741P		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/538S-E		S-E RAMP I-5 OC		5	162.99	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
5.6 N JCT SR 900	4 miles	122° 19' 6"	47° 34' 24"	1422 ft.		25.6 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 7	
S-E RAMP I-5		33.41 %g	46.0% %g	CBox CS	<b>Appr. Spans:</b> 18	
<b>Year Built:</b> 1967	<b>ADT:</b> 23672	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 5 %	77	0	Single Column Pier	Drilled shaft	
No Photo Available						
<b>Bridge Notes:</b>				<b>Retrofit Program Notes:</b>		
<p>Piers 2 and 3, each has a 5' diameter column on 6' diameter drilled shaft. Pier 4 has a 5' column on 7' shaft. Piers 5 thru 8, each has a 6' column on 7' shaft. Piers 9 thru 13, each has two 5' column on 6' shaft with two horizontal struts. Pier 14 has two 4' columns on 5' shafts with two horizontal struts. Piers 15 thru 26, each has two 3' columns on 3'-6" shafts. #4 Hoops @ 12".</p>				<p>Pier 4 retrofitted under WIN A00518K/PIN 100518K. Piers 2, 3, 5, 6, 7, and 8 retrofitted by PIN 100518L.</p>		
<b>Completed Retrofit Notes:</b>				<b>Remaining Retrofit Notes:</b>		
				Multi column retrofit of piers 9 to 26 still remain.		
<b>Overall Retrofit Status:</b> P		<b>Estimated Total Bridge Item Cost:</b> <b>Estimated Total Retrofit Project Cost:</b>				
<b>Single Column Pier Status:</b> C						
<b>Multi Column Pier Status:</b> R						
C=Complete P=Partially Complet R=Required N=Not Required D=Differed X=Excluded I=In Progress						

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007741R		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/537N		S-E RAMP WB LANES		5	162.99	<b>County:</b> King
<b>Location:</b> 5.5 N JCT SR 900	<b>Detour Length:</b> 99 miles	<b>Longitude:</b> ° ' " 122 19 6	<b>Latitude:</b> ° ' " 47 34 24	<b>Structure Length:</b> 2885 ft.		<b>Out to Out Width:</b> 32.6 ft.
<b>Feature Intersected:</b> I-5		<b>PGA (500 yr):</b> 33.41 %g	<b>PGA (1000 yr):</b> 46.0% %g	<b>Span Type:</b> CBox	<b>Main Spans:</b> 34 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1967	<b>ADT:</b> 43328	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 5 %	78	0	Single Column Pier	Concrete Pile	
No Photo Available						
<b>Bridge Notes:</b> Piers 2 thru 9, each has a 5' diameter column on 6' diameter drilled shaft. Piers 10 and 11, each has two 4' diameter column on 5' diameter drilled shaft. Piers 12 thru 17, each has a 5' diameter column on 6' diameter drilled shaft. Pier 18 has two 5'-0" dia. columns on pile foundation. Pier 19 has three 5' dia. columns on pile foundations. Piers 20 and 21, each has three 4' dia. columns on pile foundations. Piers 22, 23,24, 25, each has two 4' dia. columns on pile foundations. Piers 24 and 26 has a 4' dia. columns on pile foundations. #4 Hoops @12". Splices at top of shafts or footings.			<b>Retrofit Program Notes:</b> Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.			
<b>Completed Retrofit Notes:</b>			<b>Remaining Retrofit Notes:</b> Retrofit columns built in 1967 at Piers 10, 11, 18-25, and 27-34. (42 total, 4' dia. except 2-5' dia. columns at Pier 18.)			
<b>Overall Retrofit Status:</b> P		<b>Estimated Total Bridge Item Cost:</b>  <b>Estimated Total Retrofit Project Cost:</b>				
<b>Single Column Pier Status:</b> C						
<b>Multi Column Pier Status:</b> R						
C=Complete P=Partially Complet R=Required N=Not Required D=Differed X=Excluded I=In Progress						

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007741N		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/537E-S		E-S RAMP BR		5	162.99	<b>County:</b> King
<b>Location:</b> 5.5 N JCT SR 900	<b>Detour Length:</b> 4 miles	<b>Longitude:</b> 122° 19' 6"	<b>Latitude:</b> 47° 34' 18"	<b>Structure Length:</b> 1206 ft.		<b>Out to Out Width:</b> 25.6 ft.
<b>Feature Intersected:</b> E-S RAMP BR		<b>PGA (500 yr):</b> 33.42 %g	<b>PGA (1000 yr):</b> 46.0% %g	<b>Span Type:</b> CBox	<b>Main Spans:</b> 15 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1967	<b>ADT:</b> 7505	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 5 %	79	0	Single Column Pier	Concrete Pile	



**Bridge Notes:**

Pier 1 has a 5' column on 6' shaft. Piers 2 thru 4, each has a 6' column on 7' shaft. Piers 5 and 6, each has two 4' column on 5' shafts. Piers 7 and 8, each has two 4' column on pile foundations. Piers 9 thru 14, each has a 4' column on pile foundation. #4 hoops @ 12". Lap splices at piers 1, 2, and 5 thru 13. Pile foundations have no top mat.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 5, 6, 7 and 8. (2 ea. 8 total, 4' dia.)

**Overall Retrofit Status:** P  
**Single Column Pier Status:** C  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007741S		<b>Bridge Name:</b> W-6TH RAMP BR		<b>Route:</b> 5	<b>Milepost:</b> 163	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/537W-W						<b>County:</b> King
<b>Location:</b> 5.5 N JCT SR 900	<b>Detour Length:</b> 4 miles	<b>Longitude:</b> 122° 19' 28"	<b>Latitude:</b> 47° 34' 16"	<b>Structure Length:</b> 398 ft.		<b>Out to Out Width:</b> 25.7 ft.
<b>Feature Intersected:</b> PARKING LOT		<b>PGA (500 yr):</b> 33.46 %g	<b>PGA (1000 yr):</b> 46.2% %g	<b>Span Type:</b> CBox CS	<b>Main Spans:</b> 2 <b>Appr. Spans:</b> 10	
<b>Year Built:</b> 1967	<b>ADT:</b> 18723	<b>11-13 Rank:</b> 80	<b>Skew Angle:</b> 0	<b>Pier Type:</b> Double Column Pier	<b>Footing Type:</b> Concrete Pile	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 5 %					



**Bridge Notes:**

Cellular abutment. Expansion joints at Bents 3 (West-6th ramp), 4(north-6th ramp), 7. Seat width = 6". Unit 1 is supported by eight 2' diameter columns. Unit 3 is supported by four 2' diameter columns. Units 2, 4 and 5 are supported by 13" diameter concrete pile bents. 2' diameter columns have #4 hoops @12" and lap splices at top of pile footings. No top mat.

**Retrofit Program Notes:**

**Remaining Retrofit Notes:**

Cellular Abutment. Retrofit columns at Bents 1- 4 (12 total, 2' dia.).

**Completed Retrofit Notes:**

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**


# Washington State Department of Transportation

## Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007741T		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/537S		EB LANES I-5 OC		5	163	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
5.5 N JCT SR 900	4 miles	122° 19' 6"	47° 34' 18"	1793 ft.		32.6 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 20	
I-5		33.42 %g	46.0% %g	CBox	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1966	<b>ADT:</b> 31525	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 5 %	81	0	Single Column Pier	Concrete Pile	
<div style="display: flex; justify-content: space-around; font-size: 2em; font-weight: bold; opacity: 0.5;"> <span>No Photo Available</span> <span>No Photo Available</span> </div>						
<b>Bridge Notes:</b>			<b>Retrofit Program Notes:</b>			
<p>Piers 2 thru 4, each has a 5' column on 6' shaft. Pier 5 has three 4' columns on 5' shafts. Piers 6 thru 9, each has two 4' columns on 5' shafts. Piers 10 thru 13, 17, 19 and 20, each has two 4' columns on pile footings. Piers 14 and 18, each has three 4' columns on pile footings. Piers 15, 16 and 21, each has a 5' column on pile footing. #4 hoops @ 12". Lap splices on either top of shafts or pile footings. No top mat.</p>			<p>Engineering analysis is needed to determine which elements of the bridge require retrofit. Cost estimate is based on retrofitting the existing columns with steel jackets.</p>			
<b>Completed Retrofit Notes:</b>			<b>Remaining Retrofit Notes:</b>			
			Retrofit columns at Piers 5-14 and 17-20. (31 total, 4' dia.)			
<b>Overall Retrofit Status:</b>		<div style="font-size: 1.5em; font-weight: bold;"> <b>Estimated Total Bridge Item Cost:</b>  <b>Estimated Total Retrofit Project Cost:</b> </div>				
<b>Single Column Pier Status:</b>						
<b>Multi Column Pier Status:</b>						
C=Complete P=Partially Complet R=Required N=Not Required D=Differed X=Excluded I=In Progress						

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007504E		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/544		I-5 OC, YESLER ST		5	165.69	<b>County:</b> King
<b>Location:</b> 0.6 N JCT I-90	<b>Detour Length:</b> 2 miles	<b>Longitude:</b> 122° 19' 24"	<b>Latitude:</b> 47° 36' 6"	<b>Structure Length:</b> 391 ft.		<b>Out to Out Width:</b> 63.6 ft.
<b>Feature Intersected:</b> I-5		<b>PGA (500 yr):</b> 33.12 %g	<b>PGA (1000 yr):</b> 45.0% %g	<b>Span Type:</b> CBox	<b>Main Spans:</b> 5 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1965	<b>ADT:</b> 8100	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 5 %	82	41	Pier with more than two columns	Spread footing	



**Bridge Notes:**

Piers 2 thru 5, each has three 2'-6"x8'-0" columns on spread footings. hoops and ties @ 12". Footings have no top mat. Longitudinal bars have lap splices at top of footings. Pier 1 has three 2'-6" square columns with hinges at top and bottom of columns. Pier 6 has 8 roller bearings.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2, 3, 4 and 5. (3 ea. 12 total, 8'x2'-6")

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007110C		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/546		I-5 OC, MADISON ST		5	165.69	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
1.1 N JCT I-90	2 miles	122° 19' 48"	47° 36' 30"	280 ft.		75.7 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
I-5		33.04 %g	44.8% %g	CBox	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1964	<b>ADT:</b> 16000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 5 %	83	99	Single Column Pier	Spread footing	



**Bridge Notes:**

Piers 2 and 3, each has three 2'-6"x8'-0" columns on spread footings. hoops and ties @ 12". Footings have no top mat. Longitudinal bars have lap splices at top of footings. Piers 1 and 4 are rigid frame abutments. (may not need retrofit).

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit 3 columns at pier 2 to top of retaining wall and 3 columns at pier 3 to top of footing.(6 total, 8'-0" x 2'-6")

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information


<b>Structure ID:</b> 0007110D		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/547		I-5 OC, SPRING ST		5	165.69	<b>County:</b> King
<b>Location:</b> 1.1 N JCT I-90	<b>Detour Length:</b> 2 miles	<b>Longitude:</b> 122° 19' 48"	<b>Latitude:</b> 47° 36' 30"	<b>Structure Length:</b> 279 ft.		<b>Out to Out Width:</b> 57.6 ft.
<b>Feature Intersected:</b> I-5		<b>PGA (500 yr):</b> 33.04 %g	<b>PGA (1000 yr):</b> 44.8% %g	<b>Span Type:</b> CBox	<b>Main Spans:</b> 3 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1964	<b>ADT:</b> 3000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 5 %	84	99	Pier with more than two columns	Spread footing	
				<h2 style="font-size: 2em; color: black; text-decoration: underline;">No Photo Available</h2>		
<b>Bridge Notes:</b>			<b>Retrofit Program Notes:</b>			
<p>Piers 2 and 3, each has three 2'-6"x8'-0" columns on spread footings. hoops and ties @ 12". Footings have no top mat. Longitudinal bars have lap splices at top of footings. Piers 1 and 4 are rigid frame abutments. (may not need retrofit).</p>						
<b>Completed Retrofit Notes:</b>			<b>Remaining Retrofit Notes:</b>			
			<p>Retrofit columns at Piers 2 and 3. (3 ea. 6 total, 8'x2'-6") May not require retrofit.</p>			
<b>Overall Retrofit Status:</b>		R	<h3 style="margin: 0;">Estimated Total Bridge Item Cost:</h3> <h3 style="margin: 0;">Estimated Total Retrofit Project Cost:</h3>			
<b>Single Column Pier Status:</b>		N				
<b>Multi Column Pier Status:</b>		R				
<p>C=Complete P=Partially Complet R=Required N=Not Required D=Differed X=Excluded I=In Progress</p>						

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007110E		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/548		I-5 OC, SENECA ST		5	165.69	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
1.2 N JCT I-90	2 miles	122° 19' 48"	47° 36' 36"	250 ft.		61.6 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
I-5		33.01 %g	44.7% %g	CBox	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1964	<b>ADT:</b> 6350	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 5 %	85	99	Pier with more than two columns	Spread footing	
<div style="display: flex; justify-content: space-around; font-size: 2em; font-weight: bold; opacity: 0.5;"> <span>No Photo Available</span> <span>No Photo Available</span> </div>						
<b>Bridge Notes:</b>			<b>Retrofit Program Notes:</b>			
<p>Piers 2 and 3, each has three 2'-6"x8'-0" columns on spread footings. hoops and ties @ 12". Footings have no top mat. Longitudinal bars have lap splices at top of footings. Piers 1 and 4 are rigid frame abutments. (may not need retrofit).</p>						
<b>Completed Retrofit Notes:</b>			<b>Remaining Retrofit Notes:</b>			
			Retrofit columns at Piers 2 and 3. (3 ea. 6 total, 8'x2'-6")			
<b>Overall Retrofit Status:</b>		R	<b>Estimated Total Bridge Item Cost:</b>  <b>Estimated Total Retrofit Project Cost:</b>			
<b>Single Column Pier Status:</b>		N				
<b>Multi Column Pier Status:</b>		R				
C=Complete P=Partially Complet						
R=Required N=Not Required						
D=Differed X=Excluded I=In Progress						

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007409A		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/549		I-5 UC, 8TH AVE		5	165.69	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
1.3 N JCT I-90	2 miles	122° 19' 48"	47° 36' 42"	859 ft.		39 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 8	
I-5 OVER, CITY ST UNDER		32.97 %g	44.7% %g	CBox CS	<b>Appr. Spans:</b> 3	
<b>Year Built:</b> 1964	<b>ADT:</b> 5000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1987	<b>Truck Pct:</b> 5 %	86	0	Single Column Pier	Concrete Pile	



No Photo Available

**Bridge Notes:**

Piers 2 and 3, each has two 3' dia. columns. Piers 4 and 5, each has a 4'-6" dia. Columns. Pier 7 has two columns. West column and upper portion of east column are 4'-6" dia. columns and lower portion of east column is a 5'-0"x8'-0" column. Pier 9 has a 4' dia. Columns. All columns are on pile footings. #4 hoops @12". Longitudinal rebars have field weld splices. Pile footings have no top mat. Piers 1 and 10 have roller bearings.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2, 3 and 7. (2 ea. 6 total, 3' dia. except P7 2-4'-6" Dia.)

**Overall Retrofit Status:** P  
**Single Column Pier Status:** C  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

Estimated Total Bridge Item Cost:  
 Estimated Total Retrofit Project Cost:

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007409C		<b>Bridge Name:</b> I-5 OC, PIKE ST		<b>Route:</b> 5	<b>Milepost:</b> 166.06	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/550						<b>County:</b> King
<b>Location:</b> 1.5 N JCT I-90	<b>Detour Length:</b> 2 miles	<b>Longitude:</b> 122° 19' 48"	<b>Latitude:</b> 47° 36' 48"	<b>Structure Length:</b> 282 ft.		<b>Out to Out Width:</b> 75.6 ft.
<b>Feature Intersected:</b> I-5		<b>PGA (500 yr):</b> 32.94 %g	<b>PGA (1000 yr):</b> 44.6% %g	<b>Span Type:</b> CBox	<b>Main Spans:</b> 2 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1964	<b>ADT:</b> 13000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 5 %	87	48	Pier with more than two columns	Spread footing	
				<h2 style="font-size: 2em; color: black; text-decoration: underline;">No Photo Available</h2>		
<b>Bridge Notes:</b>			<b>Retrofit Program Notes:</b>			
<p>Pier 2 has four 3'-1"x14'-4" columns on combined spread footing. #4 hoops and ties @ 12". Footing has top mat. #11 Longitudinal bars have 4'-2" lap splices at top of footings. Piers 1 and 3 are rigid frame abutments. No retrofit recommended.</p>						
<b>Completed Retrofit Notes:</b>			<b>Remaining Retrofit Notes:</b>			
			Retrofit 4 columns at Pier 2. (14'-4"x3'-1"). May not require retrofit.			
<b>Overall Retrofit Status:</b>		R	<b>Estimated Total Bridge Item Cost:</b>  <b>Estimated Total Retrofit Project Cost:</b>			
<b>Single Column Pier Status:</b>		N				
<b>Multi Column Pier Status:</b>		R				
C=Complete P=Partially Complet						
R=Required N=Not Required						
D=Differed X=Excluded I=In Progress						

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007409D		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/551		I-5 OC, PINE ST-BOREN		5	166.06	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
1.6 N JCT I-90	2 miles	122° 19' 42"	47° 36' 54"	825 ft.		61 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 8	
I-5		32.89 %g	44.5% %g	CBox	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1965	<b>ADT:</b> 25000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 5 %	88	99	Pier with more than two columns	Concrete Pile	



**Bridge Notes:**

This bridges carries Pine st. and Boren st. Traffics over I-5. Piers 2 and 4 Pine st. and Piers 2 and 4 Boren st., each has three 3'-0"x8'-0" columns on combined pile footing. Retaining walls between columns. Pier 3 has four 3'-0"x8'-0" columns on pile footings. #4 ties @12". Footings w/o top mat except combined footings.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit 6 columns at pier 2 (Pine and Borren St.) , 3 columns at pier 4 Pine st. to top of retaining wall, and 4 columns at pier 3 and 3 columns at pier 4 Borren st. to top of footing. (8'x3' columns.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

Structure ID: 0007299C		Bridge Name: I-5 OC, NE 185TH ST		Route: 5	Milepost: 176.72	Region: Northwest
Bridge Number: 5/596						County: King
Location: 2.1 N JCT SR 523	Detour Length: 2 miles	Longitude: 122° 19' 25"	Latitude: 47° 45' 47.2"	Structure Length: 249 ft.		Out to Out Width: 60 ft.
Feature Intersected: I-5		PGA (500 yr): 30.49 %g	PGA (1000 yr): 39.8% %g	Span Type: CBox	Main Spans: 4 Appr. Spans: 0	
Year Built: 1964	ADT: 8286	11-13 Rank: 89	Skew Angle: 16	Pier Type: Pier with more than two columns	Footing Type:	
Year Rebuilt: 0	Truck Pct: 2 %					
				<h2 style="font-size: 2em; color: black; text-decoration: underline;">No Photo Available</h2>		
<b>Bridge Notes:</b> Piers 2, 3 and 4, each has four 2'-6" square columns on spread footings. Retrofit four W. columns only. #3 hoops @ 12". Longitudinal #10 bars have lap splices at top of footing. Footings have no top mat. Piers 1 and 4 (end piers), each has four 2'-6"x1'-6" columns. Each column has a hinge at top of column. Pier 1 (abutment) has four 2'-6"x1'-6" columns with hinges at top and bottom. Pier 5 (abutment) has four 2'-6"x1'-6" columns with hinge at top.			<b>Retrofit Program Notes:</b>			
<b>Completed Retrofit Notes:</b>			<b>Remaining Retrofit Notes:</b> Retrofit columns at Piers 2, 3 and 4. (4 ea. 12 total, 30"x30" at P2&P4, 30"x24" at P3)			
<b>Overall Retrofit Status:</b> R <b>Single Column Pier Status:</b> N <b>Multi Column Pier Status:</b> R C=Complete P=Partially Complet R=Required N=Not Required D=Differed X=Excluded I=In Progress		<b>Estimated Total Bridge Item Cost:</b> <b>Estimated Total Retrofit Project Cost:</b>				

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0003842B		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/629A		BROADWAY AVE UC		5	192.59	<b>County:</b> Snohomish
<b>Location:</b> 0.1 N JCT I-5	<b>Detour Length:</b> 2 miles	<b>Longitude:</b> ° ' " 122 12 3	<b>Latitude:</b> ° ' " 47 57 40	<b>Structure Length:</b> 161 ft.		<b>Out to Out Width:</b> 23.6 ft.
<b>Feature Intersected:</b> I-5 RAMP		<b>PGA (500 yr):</b> 28.66 %g	<b>PGA (1000 yr):</b> 38.0% %g	<b>Span Type:</b> CTB	<b>Main Spans:</b> 4 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1950	<b>ADT:</b> 25028	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 5 %	90	30			



**Bridge Notes:**

Piers 2 thru 4, each has three 20"x30" columns on combined spread footing. #3 hoops @ 12", Longitudinal bars are 1 1/4 sq. bars with 4'-2" splices at top of footing. Pier 1 has five rocker bearings. Pier 5 has three rocker bearings.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**


Retrofit columns at Piers 2, 3, and 4 (3 ea. 9 total, 20"x30"). Install catchers and restrainers at Piers 1 and 5.

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007249D		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 405/11		SR 181 OC		405	0.96	<b>County:</b> King
<b>Location:</b> 1.0 N JCT I-5	<b>Detour Length:</b> 5 miles	<b>Longitude:</b> ° ' " 122 14 42	<b>Latitude:</b> ° ' " 47 27 54	<b>Structure Length:</b> 173 ft.		<b>Out to Out Width:</b> 169.4 ft.
<b>Feature Intersected:</b> SR 181		<b>PGA (500 yr):</b> 32.68 %g	<b>PGA (1000 yr):</b> 44.4% %g	<b>Span Type:</b> PCG	<b>Main Spans:</b> 4 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1964	<b>ADT:</b> 114823	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1987	<b>Truck Pct:</b> 8 %	91	3	Pier with more than two columns	Concrete Pile	



No Photo Available

**Bridge Notes:**

Piers 2 and 3, each has 17- 3'-0" diameter columns. Pier 4 has 16- 3'-0" diameter columns. Retrofit columns built in 1964 only. (total 32 columns). These columns have #3 hoops @ 12". Vertical #9 bars have 3'-4" lap splices at top of footing. Footing without top mat. (E-54m). End piers, 1 and 5, are "L" abutments.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2, 3 and 4. (32 total, 3' dia.)

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

Estimated Total Bridge Item Cost:  
 Estimated Total Retrofit Project Cost:

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007606A		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 405/12		BN RR OC (CMSTPP & NP)		405	1.14	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>	<b>Out to Out Width:</b>	
0.4 N JCT SR 181	1 miles	122° 14' 24"	47° 27' 54"	765 ft.	117.2 ft.	
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 8	
CMSTPP RR NP RY		32.63 %g	44.3% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1965	<b>ADT:</b> 114823	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1989	<b>Truck Pct:</b> 8 %	92	0	Pier with more than two columns	Concrete Pile	
<div style="display: flex; justify-content: space-around; font-size: 2em; font-weight: bold; opacity: 0.5;"> <span>No Photo Available</span> <span>No Photo Available</span> </div>						
<b>Bridge Notes:</b>			<b>Retrofit Program Notes:</b>			
<p>Piers 2 thru 8, each has six columns. Retrofit four 3'-0" diameter columns built in 1965 only. Four columns per X-beam with gap near centerline of bridge. #3 hoops @ 12". Vertical #11 bars at piers 2, 3 and 8 have 4'-2" lap splices at top of footing. Vertical #14 bars at piers 4 thru 7 have staggered field weld splices. Footing without top mat. (E-54m) End piers, 1 and 9 are stub "L" abutments. Pier 9 is a cantilever "L" abutment. Girders are on bearing pads.</p>						
<b>Completed Retrofit Notes:</b>			<b>Remaining Retrofit Notes:</b>			
			Retrofit columns built in 1965 at piers 2 thru 8. (28 Total, 3' dia.)			
<b>Overall Retrofit Status:</b>		<div style="font-size: 1.5em; font-weight: bold;"> <b>Estimated Total Bridge Item Cost:</b>  <b>Estimated Total Retrofit Project Cost:</b> </div>				
<b>Single Column Pier Status:</b>						
<b>Multi Column Pier Status:</b>						
C=Complete P=Partially Complet R=Required N=Not Required D=Differed X=Excluded I=In Progress						

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007376A		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 405/15		SR 167 OC		405	2.3	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
1.3 N JCT SR 181	1 miles	122° 13' 0"	47° 28' 6"	188 ft.		189 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 4	
SR 167		32.42 %g	44.0% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1964	<b>ADT:</b> 107403	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1989	<b>Truck Pct:</b> 8 %	93	5	Pier with more than two columns	Timber pile	
				<h2 style="font-size: 2em; color: black; text-decoration: underline;">No Photo Available</h2>		
<b>Bridge Notes:</b>				<b>Retrofit Program Notes:</b>		
<p>Piers 2, 3 and 4, each has twelve 3'-0" diameter columns. Retrofit eight center columns per pier only. These columns have #3 hoops @ 12". Vertical bars have lap splices at top of footing. Footing without top mat. (E-54m)</p>						
<b>Completed Retrofit Notes:</b>				<b>Remaining Retrofit Notes:</b>		
				Retrofit columns at Piers 2, 3 and 4. (8 ea. 24 total, 3' dia.)		
<b>Overall Retrofit Status:</b>		P		<b>Estimated Total Bridge Item Cost:</b>  <b>Estimated Total Retrofit Project Cost:</b>		
<b>Single Column Pier Status:</b>		N				
<b>Multi Column Pier Status:</b>		R				
C=Complete P=Partially Complet						
R=Required N=Not Required						
D=Differed X=Excluded I=In Progress						

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007376C		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 405/16		SR 515 OC		405	2.77	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
0.5 N JCT SR 167	1 miles	122° 12' 29"	47° 28' 8"	215 ft.		109.5 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
BURNETT ST TALBOT RD		32.33 %g	44.0% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1964	<b>ADT:</b> 104327	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1988	<b>Truck Pct:</b> 8 %	94	15	Pier with more than two columns	Steel pile	



**Bridge Notes:**

Piers 2 and 3, each has nine 3'-0" diameter columns. Retrofit six columns built in 1964 only ( columns 2 thru 7 from north). These columns have #3 hoops @ 12". Vertical bars have lap splices at top of footing. Footing without top mat. (E-54m). End piers, 1 and 4, are "L" abutments.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (6 ea. 12 total, 3' dia.)

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0008812B		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 405/41E		SE 8TH ST OC		405	12.78	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
1.7 N JCT I-90	1 miles	122 11 0 "	47 36 12 "	189 ft.		67 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
SE 8TH ST		31.74 %g	43.0% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1971	<b>ADT:</b> 67559	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1995	<b>Truck Pct:</b> 6 %	95	0	Pier with more than two columns		



**Bridge Notes:**

Piers 2 and 3, each has four 3'-0" diameter columns. Retrofit three west columns, built in 1971, only. These columns have #4 hoops @ 12". Vertical #11 bars have 4'-2" lap splices at top of footing. Footing without top mat. Piers 1 and 4 are stub abutments.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (3 ea. 6 total, 3' dia.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0009267A		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 405/41W		WILBURTON INTERCHANGE OC		405	12.79	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>	<b>Out to Out Width:</b>	
1.7 N JCT I-90	1 miles	122 11 3.31 "	47 36 10.51 "	183 ft.	64 ft.	
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
SE 8TH ST OC		31.76 %g	43.1% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1972	<b>ADT:</b> 67559	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1995	<b>Truck Pct:</b> 6 %	96	3	Pier with more than two columns		



**Bridge Notes:**

Piers 2 and 3, each has four 3'-0" diameter columns. Retrofit three east columns, built in 1972, only. These columns have #4 hoops @ 12". Vertical #11 bars have 4'-2" lap splices at top of footing. Footing without top mat. Piers 1 and 4 are stub abutments.

**Retrofit Program Notes:**

Bridge is being widened and retrofitted with column jackets under UCO design build project - PIN 840509A - Contract No. 17283. A future analysis will be needed to determine if the pier cap should be retrofitted in a future project.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Jacket all columns

<b>Overall Retrofit Status:</b>	C
<b>Single Column Pier Status:</b>	N
<b>Multi Column Pier Status:</b>	I
C=Complete P=Partially Complet	
R=Required N=Not Required	
D=Differed X=Excluded I=In Progress	

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007596A		<b>Bridge Name:</b> N-W N-E RAMP OC		<b>Route:</b> 405	<b>Milepost:</b> 14.82	<b>Region:</b> Northwest
<b>Bridge Number:</b> 405/45E						<b>County:</b> King
<b>Location:</b> 3.6 N JCT I-90	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> 122° 11' 17.9"	<b>Latitude:</b> 47° 37' 47.9"	<b>Structure Length:</b> 245 ft.		<b>Out to Out Width:</b> 71 ft.
<b>Feature Intersected:</b> N-W N-E RAMP		<b>PGA (500 yr):</b> 31.31 %g	<b>PGA (1000 yr):</b> 41.9% %g	<b>Span Type:</b> PCG	<b>Main Spans:</b> 3 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1965	<b>ADT:</b> 79098	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1993	<b>Truck Pct:</b> 5 %	97	41	Pier with more than two columns	Spread footing	



**Bridge Notes:**

Piers 2 and 3, each has four 3'-0" diameter columns on spread footings. Retrofit three East columns built in 1965 only. These columns have #3 hoops @ 12". Vertical #9 bars have 3'-4" lap splices at top of footing. Footing without top mat. (E-54m). End piers, 1 and 4, are stub abutments.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (3 ea. 6 total, 3' dia.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007596B		<b>Bridge Name:</b> N-W & N-E RAMPS OC		<b>Route:</b> 405	<b>Milepost:</b> 14.82	<b>Region:</b> Northwest
<b>Bridge Number:</b> 405/45W						<b>County:</b> King
<b>Location:</b> 3.6 N JCT I-90	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> 122° 11' 19.3"	<b>Latitude:</b> 47° 37' 49.1"	<b>Structure Length:</b> 207 ft.		<b>Out to Out Width:</b> 71 ft.
<b>Feature Intersected:</b> N-W & N-E RAMPS		<b>PGA (500 yr):</b> 31.3 %g	<b>PGA (1000 yr):</b> 41.9% %g	<b>Span Type:</b> PCG	<b>Main Spans:</b> 3 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1966	<b>ADT:</b> 79098	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1993	<b>Truck Pct:</b> 5 %	98	34	Pier with more than two columns	Spread footing	



**Bridge Notes:**

Piers 2 and 3, each has four 3'-0" diameter columns on spread footings. Retrofit three West columns built in 1966 only. These columns have #3 hoops @ 12". Vertical #9 bars have 3'-4" lap splices at top of footing. Footing without top mat. (E-54m). End piers, 1 and 4, are stub abutments.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (3 ea. 6 total, 3' dia.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007596C		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 405/46E		SR 520 OC		405	14.83	<b>County:</b> King
<b>Location:</b> 3.7 N JCT I-90	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> 122° 11' 17.04"	<b>Latitude:</b> 47° 37' 55.44"	<b>Structure Length:</b> 247 ft.		<b>Out to Out Width:</b> 78 ft.
<b>Feature Intersected:</b> SR 520		<b>PGA (500 yr):</b> 31.28 %g	<b>PGA (1000 yr):</b> 41.8% %g	<b>Span Type:</b> PCG		<b>Main Spans:</b> 4 <b>Appr. Spans:</b> 0
<b>Year Built:</b> 1966	<b>ADT:</b> 79098	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1993	<b>Truck Pct:</b> 5 %	99	10	Pier with more than two columns	Spread footing	



No Photo Available

**Bridge Notes:**

Piers 2, 3 and 4, each has four 3'-0" diameter columns on spread footings. Retrofit three East columns per pier only. These columns have #3 hoops @ 12". Vertical #9 bars have 3'-4" lap splices at top of footing. Footing without top mat. (E-54m). End piers, 1 and 5, are stub "L" abutments.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2, 3 and 4. (3 ea. 9 total, 3' dia.)

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007596D		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 405/46W		SR 520 OC		405	14.83	<b>County:</b> King
<b>Location:</b> 3.7 N JCT I-90	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> ° ' " 122 11 18.3	<b>Latitude:</b> ° ' " 47 37 55.9	<b>Structure Length:</b> 241 ft.		<b>Out to Out Width:</b> 89 ft.
<b>Feature Intersected:</b> SR 520		<b>PGA (500 yr):</b> 31.28 %g	<b>PGA (1000 yr):</b> 41.8% %g	<b>Span Type:</b> PCG	<b>Main Spans:</b> 4 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1966	<b>ADT:</b> 79098	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1993	<b>Truck Pct:</b> 5 %	100	16	Pier with more than two columns	Spread footing	



**Bridge Notes:**

Piers 2, 3 and 4, each has four 3'-0" diameter columns on spread footings. Retrofit three West columns per pier only. These columns have #3 hoops @ 12". Vertical #9 bars have 3'-4" lap splices at top of footing. Footing without top mat. (E-54m). End piers, 1 and 5, are stub "L" abutments.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2, 3 and 4. (3 ea. 9 total, 3' dia.)

<b>Overall Retrofit Status:</b>	P
<b>Single Column Pier Status:</b>	N
<b>Multi Column Pier Status:</b>	R
C=Complete P=Partially Complet	
R=Required N=Not Required	
D=Differed X=Excluded I=In Progress	

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007596E		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 405/47E		NORTHUP WAY OC		405	14.83	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>	<b>Out to Out Width:</b>	
0.1 N JCT SR 520	1 miles	122° 11' 13.1"	47° 38' 2.1"	160 ft.	78 ft.	
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
NORTHUP WAY		31.25 %g	41.7% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1965	<b>ADT:</b> 79098	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1993	<b>Truck Pct:</b> 5 %	101	12	Pier with more than two columns	Spread footing	



**Bridge Notes:**

Piers 2 and 3, each has four 3'-0" diameter columns on spread footings. Retrofit three West columns per pier only. These columns have #3 hoops @ 12". Vertical #11 bars have 4'-2" lap splices at top of footing. Footing without top mat. (E-54m). End piers, 1 and 4, are stub "L" abutments.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (3 ea. 6 total, 2' dia.). 7' excavation.

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0004609A		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 405/47W		NORTHUP WAY OC		405	14.83	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
0.1 N JCT SR 520	1 miles	122° 11' 12"	47° 38' 0"	149 ft.		71 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
NORTHUP WAY		31.25 %g	41.8% %g	CTB	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1954	<b>ADT:</b> 79098	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1993	<b>Truck Pct:</b> 5 %	102	15	Pier with more than two columns	Concrete Pile	



**Bridge Notes:**

Piers 2 and 3, each has four 38" square columns. Columns 2 and 3 are on spread footings. Columns 1 are on piles. Columns 4 are on 6' dia. drilled shafts. Retrofit three West columns only. These columns have #3 hoops @ 12". Vertical #11 bars have lap splices at top of footing. Footing without top mat. End piers, 1 and 4, are concrete pile bents.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (3 ea. 6 total, 38"x 38")

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007742A		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 405/48E		BNRR & 115th AVE NE OC		405	15	<b>County:</b> King
<b>Location:</b> 0.2 N JCT SR 520	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> 122° 11' 12.8"	<b>Latitude:</b> 47° 38' 6"	<b>Structure Length:</b> 296 ft.		<b>Out to Out Width:</b> 78 ft.
<b>Feature Intersected:</b> BNRR & 115th AVE NE		<b>PGA (500 yr):</b> 31.23 %g	<b>PGA (1000 yr):</b> 41.7% %g	<b>Span Type:</b> PCG		<b>Main Spans:</b> 4 <b>Appr. Spans:</b> 0
<b>Year Built:</b> 1965	<b>ADT:</b> 79098	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1993	<b>Truck Pct:</b> 5 %	103	39	Pier with more than two columns		



No Photo Available

**Bridge Notes:**

Piers 2, 3 and 4, each has five 3'-0" diameter columns. Four east column are on spread footings. West column is on 6' diameter drilled shaft. Retrofit four east columns only. These columns have #3 hoops @ 12". Vertical #9 bars have 3'-4" lap splices at top of footing. Footing without top mat. End piers, 1 and 5, are stub abutments. Piers 2 and 3 have collision walls.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2, 3 and 4. (4 ea. 12 total, 3' dia.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

Estimated Total Bridge Item Cost:  
 Estimated Total Retrofit Project Cost:

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0004609B		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 405/48W		BNRR & 115 AVE NE OC		405	15	<b>County:</b> King
<b>Location:</b> 0.2 N JCT SR 520	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> 122° 11' 14.41" W	<b>Latitude:</b> 47° 38' 6.36" N	<b>Structure Length:</b> 204 ft.		<b>Out to Out Width:</b> 71 ft.
<b>Feature Intersected:</b> BNRR & 115 AVE NE		<b>PGA (500 yr):</b> 31.23 %g	<b>PGA (1000 yr):</b> 41.7% %g	<b>Span Type:</b> CTB		<b>Main Spans:</b> 3 <b>Appr. Spans:</b> 0
<b>Year Built:</b> 1954	<b>ADT:</b> 79098	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1993	<b>Truck Pct:</b> 5 %	104	42	Pier with more than two columns		



No Photo Available

**Bridge Notes:**

Piers 2 and 3, each has four 42" square columns. Columns 2 and 3 from West are on spread footings. Pier 2 column 1 from west is on piles. Pier 3 on spread footing. Columns 4 are on 6' dia. drilled shafts. Retrofit three West columns only. These columns have #3 hoops @ 12". Vertical #11 bars have lap splices at top of footing. Footing without top mat. End piers, 1 and 4, are spill through abutments.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (3 ea. 6 total, 42"x42"). 10' excavation.

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0008674E		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 405/52E		SR 908 OC		405	18.11	<b>County:</b> King
<b>Location:</b> 3.3 N JCT SR 520	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> ° ' " 122 11 3.9	<b>Latitude:</b> ° ' " 47 40 45	<b>Structure Length:</b> 223 ft.		<b>Out to Out Width:</b> 66.5 ft.
<b>Feature Intersected:</b> SR 908		<b>PGA (500 yr):</b> 30.49 %g	<b>PGA (1000 yr):</b> 40.3% %g	<b>Span Type:</b> PCG	<b>Main Spans:</b> 3 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1971	<b>ADT:</b> 58995	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1994	<b>Truck Pct:</b> 5 %	105	0	Pier with more than two columns		
				<h2 style="color: black; font-weight: bold; text-decoration: none;">No Photo Available</h2>		
<b>Bridge Notes:</b>			<b>Retrofit Program Notes:</b>			
<p>Piers 2 and 3, each has four 3'-0" diameter columns on spread footings. Retrofit three east columns only. These columns have #4 hoops @ 12". Vertical #10 bars have 2'-10" min. lap splices at top of footing. Footing without top mat. End piers, 1 and 4, are stub abutments.</p>						
<b>Completed Retrofit Notes:</b>			<b>Remaining Retrofit Notes:</b>			
			Retrofit columns at Piers 2 and 3. (3 ea. 6 total, 3' dia.). 7' excavation.			
<b>Overall Retrofit Status:</b>		R	<b>Estimated Total Bridge Item Cost:</b>  <b>Estimated Total Retrofit Project Cost:</b>			
<b>Single Column Pier Status:</b>		N				
<b>Multi Column Pier Status:</b>		R				
C=Complete P=Partially Complet						
R=Required N=Not Required						
D=Differed X=Excluded I=In Progress						

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0008674D		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 405/52NCD		NBCD, SR 908 OC		405	17.84	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
3.3 N JCT SR 520	0 miles	122° 11' 0"	47° 40' 48"	211 ft.		38.5 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
SR 908		30.49 %g	40.2% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1970	<b>ADT:</b> 9986	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 5 %	106	0	Pier with more than two columns		



**Bridge Notes:**

Piers 2 and 3, each has three 3'-0" diameter columns on spread footings. #4 hoops @ 12". Vertical #9 bars have lap splices at top of footing. Footing without top mat. End piers, 1 and 4, are stub abutments.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (3 ea. 6 total, 3' dia.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0008674G		<b>Bridge Name:</b> SBCD, SR 908 OC		<b>Route:</b> 405	<b>Milepost:</b> 18.11	<b>Region:</b> Northwest	
<b>Bridge Number:</b> 405/52SCD						<b>County:</b> King	
<b>Location:</b> 3.3 N JCT SR 520	<b>Detour Length:</b> 0 miles	<b>Longitude:</b> 122° 11' 0"	<b>Latitude:</b> 47° 40' 48"	<b>Structure Length:</b> 223 ft.		<b>Out to Out Width:</b> 39 ft.	
<b>Feature Intersected:</b> SBCD, SR 908		<b>PGA (500 yr):</b> 30.49 %g	<b>PGA (1000 yr):</b> 40.2% %g	<b>Span Type:</b> PCG		<b>Main Spans:</b> 3 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1971	<b>ADT:</b> 12046	<b>11-13 Rank:</b> 107	<b>Skew Angle:</b> 0	<b>Pier Type:</b> Pier with more than two columns		<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 5 %						



**Bridge Notes:**

Piers 2 and 3, each has three 3'-0" diameter columns on spread footings. #4 hoops @ 12". Vertical #9 bars have lap splices at top of footing. Footing without top mat. End piers, 1 and 4, are stub abutments.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (3 ea. 6 total, 3' dia.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0008674F		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 405/52W		SR 908 OC		405	18.11	<b>County:</b> King
<b>Location:</b> 3.3 N JCT SR 520	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> ° ' "	<b>Latitude:</b> ° ' "	<b>Structure Length:</b> 219 ft.		<b>Out to Out Width:</b> 66 ft.
<b>Feature Intersected:</b> SR 908		<b>PGA (500 yr):</b> 30.49 %g	<b>PGA (1000 yr):</b> 40.2% %g	<b>Span Type:</b> PCG	<b>Main Spans:</b> 3 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1971	<b>ADT:</b> 58995	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1994	<b>Truck Pct:</b> 5 %	108	0	Pier with more than two columns		



**Bridge Notes:**

Piers 2 and 3, each has four 3'-0" diameter columns on spread footings. Retrofit three west columns only. These columns have #4 hoops @ 12". Vertical #10 bars have 3'-3" min. lap splices at top of footing. Footing without top mat. End piers, 1 and 4, are stub abutments.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (3 ea. 6 total, 3' dia.). 7' excavation.

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0004978A		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 405/56E		BN RR OC (NP)		405	20	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
1.9 N JCT SR 908	1 miles	122 10 48.2	47 42 22.1	199 ft.		107 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
NP RY		30.07 %g	39.5% %g	CTB	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1956	<b>ADT:</b> 57543	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1994	<b>Truck Pct:</b> 5 %	109	99	Pier with more than two columns		



**Bridge Notes:**

Piers 2 and 3, each has six 39" square columns and one 18" square column on spread footings. Retrofit five west columns only. These columns have #3 or #4 hoops @ 12". Vertical #11 bars have 2'-4" min. lap splices at top of footing. Footing without top mat. End piers, 1 and 4, are spill through abutments.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (5 ea. 10 total, 8-39"x39", 2-18"x18"). Retrofit Columns to Top of Collision Wall.

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0008615C		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 405/56W		BN RR OC (NP)		405	19.98	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
1.9 N JCT SR 908	1 miles	122° 10' 42"	47° 42' 24"	243 ft.		81 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
NP RY		30.07 %g	39.5% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1970	<b>ADT:</b> 57543	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1994	<b>Truck Pct:</b> 5 %	110	33	Pier with more than two columns		



**Bridge Notes:**

Piers 2 and 3, each has five 3'-0" diameter columns on spread footings. Retrofit four west columns only. These columns have #4 hoops @ 12". Vertical #8 bars have 5'-0" min. lap splices at top of footing. Footing without top mat. End piers, 1 and 4, are cantilever abutments.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (4 ea. 8 total, 3' dia.). Retrofit Columns to Top of Collision Wall.

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0008615E		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 405/59E		NE 132ND ST OC		405	20.9	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
2.8 N JCT SR 908	1 miles	122° 11' 14.7"	47° 43' 5.9"	180 ft.		71 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
NE 132ND ST		30 %g	39.4% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1970	<b>ADT:</b> 53951	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1994	<b>Truck Pct:</b> 5 %	111	21	Pier with more than two columns		



**Bridge Notes:**

Piers 2 and 3, each has four 3'-0" diameter columns. Retrofit three east columns only. These columns are on spread footings and have #3 hoops @ 12". Vertical #9 bars have 3'-4" lap splices at top of footing. Footing without top mat. End piers, 1 and 4, are stub "L" abutments.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (3 ea. 6 total, 3' dia.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0008615F		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 405/59W		NE 132ND ST OC		405	20.9	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
2.8 N JCT SR 908	1 miles	122 11 12	47 43 5.9	168 ft.		68 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
NE 132ND ST		30 %g	39.3% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1970	<b>ADT:</b> 53951	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1994	<b>Truck Pct:</b> 5 %	112	21	Pier with more than two columns		



**Bridge Notes:**

Piers 2 and 3, each has four 3'-0" diameter columns on spread footings. Retrofit three west columns only. These columns have #3 hoops @ 12". Vertical #9 bars have 3'-4" lap splices at top of footing. Footing without top mat. End piers, 1 and 4, are stub "L" abutments.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (3 ea. 6 total, 3' dia.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0008375C		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 405/103E		228TH ST OC		405	26.31	<b>County:</b> Snohomish
<b>Location:</b> 1.3 N KING CO	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> 122° 12' 28.5"	<b>Latitude:</b> 47° 47' 28"	<b>Structure Length:</b> 287 ft.		<b>Out to Out Width:</b> 57.6 ft.
<b>Feature Intersected:</b> 228TH ST		<b>PGA (500 yr):</b> 29.56 %g	<b>PGA (1000 yr):</b> 38.6% %g	<b>Span Type:</b> PCG		<b>Main Spans:</b> 3 <b>Appr. Spans:</b> 0
<b>Year Built:</b> 1968	<b>ADT:</b> 48000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1998	<b>Truck Pct:</b> 5 %	113	54	Pier with more than two columns		



**Bridge Notes:**

Intermediate Piers, Piers 2 and 3, each has four 3'-0" diameter columns. Retrofit three east columns only. These columns have #3 hoops @ 12". Vertical #9 bars have 3'-4" lap splices at top of footings. Footings have no top mat. End Piers 1 and 4 are "L" abutments.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (3 ea. 6 total, 3' dia.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0008375D		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 405/103W		228TH ST OC		405	26.33	<b>County:</b> Snohomish
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
1.3 N KING CO	1 miles	122° 12' 24"	47° 47' 30"	273 ft.		67.5 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
228TH ST		29.56 %g	38.6% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1968	<b>ADT:</b> 48000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1998	<b>Truck Pct:</b> 5 %	114	53	Pier with more than two columns		



**Bridge Notes:**

Intermediate Piers, Piers 2 and 3, each has four 3'-0" diameter columns. Retrofit three west columns only. These columns have #3 hoops @ 12". Vertical #9 bars have 3'-4" lap splices at top of footings. Footings have no top mat. End Piers 1 and 4 are "L" abutments.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (3 ea. 6 total, 3' dia.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0006968A		<b>Bridge Name:</b> I-405 OC, 61ST AVE S		<b>Route:</b> 405	<b>Milepost:</b> 0.34	<b>Region:</b> Northwest
<b>Bridge Number:</b> 405/5						<b>County:</b> King
<b>Location:</b> 0.3 N JCT I-5	<b>Detour Length:</b> 0 miles	<b>Longitude:</b> 122° 15' 24"	<b>Latitude:</b> 47° 27' 48"	<b>Structure Length:</b> 205 ft.	<b>Out to Out Width:</b> 65.5 ft.	
<b>Feature Intersected:</b> I-405		<b>PGA (500 yr):</b> 32.79 %g	<b>PGA (1000 yr):</b> 44.5% %g	<b>Span Type:</b> PCG	<b>Main Spans:</b> 2 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1962	<b>ADT:</b> 10550	<b>11-13 Rank:</b> 115	<b>Skew Angle:</b> 10	<b>Pier Type:</b> Pier with more than two columns	<b>Footing Type:</b> Spread footing	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 3 %					



**Bridge Notes:**

Pier 2 has six 3'-0" diameter columns on pile footings. Three columns per x-beam with 1" gap. Three columns built in 1962 are on combined spread footing. Columns have #3 hoops @ 12". Vertical #11 bars have 4'-2" lap splices at top of footings. Three columns in widened portion are on combined spread footing. 2'-0" gap between footings. Columns have #4 hoops @ 12". Vertical # 9 bars have 3'-4" lap splices at top of footings. Both footings have top mats. End piers 1 and 3 are "L" abutments. Girders are on bearing pads.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit 6 columns at Pier 2. (3' dia.)

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 000000OU		<b>Bridge Name:</b> 12TH ST NE OVER I-405		<b>Route:</b> 405	<b>Milepost:</b> 14.12	<b>Region:</b> Northwest
<b>Bridge Number:</b> 405/44						<b>County:</b> King
<b>Location:</b> 3.0 N JCT I-90	<b>Detour Length:</b> 0 miles	<b>Longitude:</b> 122° 11' 18"	<b>Latitude:</b> 47° 37' 18"	<b>Structure Length:</b> 298 ft.		<b>Out to Out Width:</b> 59 ft.
<b>Feature Intersected:</b> I-405		<b>PGA (500 yr):</b> 31.47 %g	<b>PGA (1000 yr):</b> 42.3% %g	<b>Span Type:</b> PTCBox	<b>Main Spans:</b> 2 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1970	<b>ADT:</b> 21900	<b>11-13 Rank:</b> 116	<b>Skew Angle:</b> 37	<b>Pier Type:</b> Pier with more than two columns	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 6 %					



**Bridge Notes:**

Pier 2 has three columns on spread footings. Column section various, 5'-6" x 4'-6" at top of pedestal. #4 ties @ 9" at hinge zone top of pedestal. Others #4 ties @ 12". Vertical #11 bars have 4'-0" lap splices at top of pedestal. Footings have no top mat. End piers, 1 and 3, are cantilever abutments.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit 3 columns at pier 2. (Section vary, 66"x44" at bottom)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0007839A		<b>Bridge Name:</b> S-W RAMP BNRR OC		<b>Route:</b> 405	<b>Milepost:</b> 14.83	<b>Region:</b> Northwest
<b>Bridge Number:</b> 405/48S-W						<b>County:</b> King
<b>Location:</b> 0.2 N JCT SR 520	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> 122° 10' 54" W	<b>Latitude:</b> 47° 38' 06" N	<b>Structure Length:</b> 232 ft.		<b>Out to Out Width:</b> 44 ft.
<b>Feature Intersected:</b> S-W RAMP NP RY		<b>PGA (500 yr):</b> 31.17 %g	<b>PGA (1000 yr):</b> 41.6% %g	<b>Span Type:</b> PCG	<b>Main Spans:</b> 3 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1966	<b>ADT:</b> 11657	<b>11-13 Rank:</b> 117	<b>Skew Angle:</b> 41	<b>Pier Type:</b> Multiple Column Pier	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1994	<b>Truck Pct:</b> 5 %					



**Bridge Notes:**

Piers 2 and 3, each has four 3'-0" diameter columns. Retrofit two east columns only. These columns are on spread footings and have #3 hoops @ 12". Vertical #9 bars have 3'-4" lap splices at top of footing. Footing without top mat. End piers, 1 and 4, are stub abutments. Piers 2 and 3 have collision walls.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (2 ea. 4 total, 3' dia.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0008569A		<b>Bridge Name:</b> I-405 OC, NE 160TH ST		<b>Route:</b> 405	<b>Milepost:</b> 22.62	<b>Region:</b> Northwest
<b>Bridge Number:</b> 405/64						<b>County:</b> King
<b>Location:</b> 4.5 N JCT SR 908	<b>Detour Length:</b> 4 miles	<b>Longitude:</b> 122° 11' 12"	<b>Latitude:</b> 47° 44' 36"	<b>Structure Length:</b> 292 ft.		<b>Out to Out Width:</b> 78.5 ft.
<b>Feature Intersected:</b> I-405		<b>PGA (500 yr):</b> 29.71 %g	<b>PGA (1000 yr):</b> 38.8% %g	<b>Span Type:</b> PTCBox	<b>Main Spans:</b> 2 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1969	<b>ADT:</b> 12586	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1996	<b>Truck Pct:</b> 5 %	118	45	Multiple Column Pier		



No Photo Available

**Bridge Notes:**

Pier 2 has four 6'-0" wide columns. Retrofit two south columns only. Column section various. 6'-0"x 3'-4" at top of pedestal. 12:5/8 tapers. Vertical #11 bars have 4'-2" lap splices at top of footing. #4 hoops & ties @ 12". Footing has no top mat. End piers, 1 and 3, are cantilever abutments.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit two columns at Pier 2. Column section vary, 6'x3'-4" at bottom.

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

Estimated Total Bridge Item Cost:  
 Estimated Total Retrofit Project Cost:

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0008286A		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 405/73		I-405 OC, 195TH ST		405	24.48	<b>County:</b> King
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
0.8 N JCT SR 522	1 miles	122° 11' 18"	47° 46' 6"	252 ft.		77.7 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 4	
I-405		29.54 %g	38.5% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1968	<b>ADT:</b> 4592	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1998	<b>Truck Pct:</b> 6 %	119	7	Multiple Column Pier	Concrete Pile	



No Photo Available

**Bridge Notes:**

Intermediate Piers, Piers 2, 3 and 4, each has six 3'-0" diameter columns. Retrofit two center columns only. These columns have #3 hoops @ 12". Vertical #9 bars have 3'-4" lap splices at top of footings. Footings have no top mat. End Piers 1 and 5 are "L" abutments.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2, 3 and 4. (2 ea. 6 total, 3' dia.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

Estimated Total Bridge Item Cost:  
 Estimated Total Retrofit Project Cost:

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0005582A		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Olympic
<b>Bridge Number:</b> 5/418		I-5 OC, BRIDGEPORT WAY		5	125.86	<b>County:</b> Pierce
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
11.1 N THURSTON	2 miles	122° 30' 12"	47° 8' 48"	294 ft.		63 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 4	
I-5		30.51 %g	40.0% %g	CBox	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1958	<b>ADT:</b> 26890	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 2 %	120	39	Pier with more than two columns	Spread footing	



**Bridge Notes:**

Piers 2, 3 and 4, each has four 3'-0" diameter columns. #4 hoops @ 12". #11 bars with 2'-4" splices. Footing without top mat.

**Retrofit Program Notes:**

The 2005 Transportation Partnership Account (TPA) included funding to perform seismic retrofit work on this bridge.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

A seismic analysis will be done to determine what work is required. Typical retrofit measures and costs are: Cross-Beam Bolsters = \$1,500/LF of Cross Beam, Girder Stops = \$1,500/Each, Column Jackets (Dry) = \$50,000/Col. (Wet) = \$125,000/Col.

<b>Overall Retrofit Status:</b>	R
<b>Single Column Pier Status:</b>	N
<b>Multi Column Pier Status:</b>	R
C=Complete P=Partially Complet	
R=Required N=Not Required	
D=Differed X=Excluded I=In Progress	

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0004495A		<b>Bridge Name:</b> FT LEWIS RD OC		<b>Route:</b> 5	<b>Milepost:</b> 120.87	<b>Region:</b> Olympic
<b>Bridge Number:</b> 5/411W						<b>County:</b> Pierce
<b>Location:</b> 6.1 N THURSTON	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> 122° 35' 19.5"	<b>Latitude:</b> 47° 6' 15.7"	<b>Structure Length:</b> 157 ft.		<b>Out to Out Width:</b> 54 ft.
<b>Feature Intersected:</b> FT LEWIS RD		<b>PGA (500 yr):</b> 30.27 %g	<b>PGA (1000 yr):</b> 39.8% %g	<b>Span Type:</b> CTB		<b>Main Spans:</b> 3 <b>Appr. Spans:</b> 0
<b>Year Built:</b> 1954	<b>ADT:</b> 45830	<b>11-13 Rank:</b> 121	<b>Skew Angle:</b> 0	<b>Pier Type:</b> Pier with more than two columns		<b>Footing Type:</b>
<b>Year Rebuilt:</b> 1969	<b>Truck Pct:</b> 15 %					



**Bridge Notes:**

Piers 2 and 3, each has six 25"x30" columns. 4 columns each pier near centerline of roadway (built in 1954) have #3 hoops @ 12", #9 bars with 2'-0" splices. Footings have #6 top mat. 2 columns built in 1969 have #4 ties @ 12", #9 bars with 3'-4" splices.

**Retrofit Program Notes:**

The 2005 Transportation Partnership Account (TPA) included funding to perform seismic retrofit work on this bridge.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

A seismic analysis will be done to determine what work is required. Typical retrofit measures and costs are: Cross-Beam Bolsters = \$1,500/LF of Cross Beam, Girder Stops = \$1,500/Each, Column Jackets (Dry) = \$50,000/Col. (Wet) = \$125,000/Col.

<b>Overall Retrofit Status:</b>	R
<b>Single Column Pier Status:</b>	N
<b>Multi Column Pier Status:</b>	R
C=Complete P=Partially Complet	
R=Required N=Not Required	
D=Differed X=Excluded I=In Progress	

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0004495B		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Olympic
<b>Bridge Number:</b> 5/411SCD		SBCD FT LEWIS RD OC		5	120.87	<b>County:</b> Pierce
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
6.1 N THURSTON	0 miles	122° 35' 19.6"	47° 6' 15.6"	157 ft.		36.6 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
SBCD FT LEWIS RD		30.27 %g	39.8% %g	CTB	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1954	<b>ADT:</b> 12417	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 2 %	122	0	Pier with more than two columns		



**Bridge Notes:**

Piers 2 and 3, each has four 25"x30" columns. #3 hoops @ 12", #9 bars with 2'-0" splices. Footings have #6 top mat.

**Retrofit Program Notes:**

The 2005 Transportation Partnership Account (TPA) included funding to perform seismic retrofit work on this bridge.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

A seismic analysis will be done to determine what work is required. Typical retrofit measures and costs are: Cross-Beam Bolsters = \$1,500/LF of Cross Beam, Girder Stops = \$1,500/Each, Column Jackets (Dry) = \$50,000/Col. (Wet) = \$125,000/Col.

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0008580B		<b>Bridge Name:</b> NBCD FT LEWIS RD OC		<b>Route:</b> 5	<b>Milepost:</b> 120.87	<b>Region:</b> Olympic
<b>Bridge Number:</b> 5/411NCD						<b>County:</b> Pierce
<b>Location:</b> 6.1 N THURSTON	<b>Detour Length:</b> 0 miles	<b>Longitude:</b> 122° 35' 18"	<b>Latitude:</b> 47° 6' 16"	<b>Structure Length:</b> 172 ft.		<b>Out to Out Width:</b> 40.6 ft.
<b>Feature Intersected:</b> NBCD FT LEWIS RD		<b>PGA (500 yr):</b> 30.26 %g	<b>PGA (1000 yr):</b> 39.8% %g	<b>Span Type:</b> PCG	<b>Main Spans:</b> 3 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1969	<b>ADT:</b> 12417	<b>11-13 Rank:</b> 123	<b>Skew Angle:</b> 0	<b>Pier Type:</b> Pier with more than two columns	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 2 %					



**Bridge Notes:**

Piers 2 and 3, each has three 30"x30" square columns, #4 hoops @ 12", #9 bars with 3'-4" splices. Footings have no top mat.

**Retrofit Program Notes:**

The 2005 Transportation Partnership Account (TPA) included funding to perform seismic retrofit work on this bridge.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

A seismic analysis will be done to determine what work is required. Typical retrofit measures and costs are: Cross-Beam Bolsters = \$1,500/LF of Cross Beam, Girder Stops = \$1,500/Each, Column Jackets (Dry) = \$50,000/Col. (Wet) = \$125,000/Col.

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0008580A		<b>Bridge Name:</b> FT LEWIS RD OC		<b>Route:</b> 5	<b>Milepost:</b> 120.87	<b>Region:</b> Olympic
<b>Bridge Number:</b> 5/411E						<b>County:</b> Pierce
<b>Location:</b> 6.1 N THURSTON	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> 122° 35' 18"	<b>Latitude:</b> 47° 6' 17"	<b>Structure Length:</b> 165 ft.		<b>Out to Out Width:</b> 54.6 ft.
<b>Feature Intersected:</b> FT LEWIS RD		<b>PGA (500 yr):</b> 30.27 %g	<b>PGA (1000 yr):</b> 39.8% %g	<b>Span Type:</b> PCG	<b>Main Spans:</b> 3 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1969	<b>ADT:</b> 45830	<b>11-13 Rank:</b> 124	<b>Skew Angle:</b> 0	<b>Pier Type:</b> Pier with more than two columns	<b>Footing Type:</b> Spread footing	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 15 %					



**Bridge Notes:**

Piers 2 and 3, each has four 30"x30" square columns. #4 hoops @ 12", #9 bars with 3'-4" splices. Footings have no top mat.

**Retrofit Program Notes:**

The 2005 Transportation Partnership Account (TPA) included funding to perform seismic retrofit work on this bridge.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

A seismic analysis will be done to determine what work is required. Typical retrofit measures and costs are: Cross-Beam Bolsters = \$1,500/LF of Cross Beam, Girder Stops = \$1,500/Each, Column Jackets (Dry) = \$50,000/Col. (Wet) = \$125,000/Col.

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0008134D		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Olympic
<b>Bridge Number:</b> 5/406		I-5 OC, OLD NISQUALLY RD		5	116.7	<b>County:</b> Pierce
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
2.0 N THURSTON	6 miles	122 40 12.5 "	47 4 58.1 "	138 ft.		40 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 2	
I-5		30.17 %g	39.6% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1967	<b>ADT:</b> 1870	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 2 %	125	0	Double Column Pier	Timber pile	



**Bridge Notes:**

Pier 2 has two 3'-0" diameter columns. #3 hoops @ 12". #9 bars with 3'-4" splices. Footing without top mat.

**Retrofit Program Notes:**

The 2005 Transportation Partnership Account (TPA) included funding to perform seismic retrofit work on this bridge.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

A seismic analysis will be done to determine what work is required. Typical retrofit measures and costs are: Cross-Beam Bolsters = \$1,500/LF of Cross Beam, Girder Stops = \$1,500/Each, Column Jackets (Dry) = \$50,000/Col. (Wet) = \$125,000/Col.

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0008116A		<b>Bridge Name:</b> NISQUALLY R		<b>Route:</b> 5	<b>Milepost:</b> 114.86	<b>Region:</b> Olympic
<b>Bridge Number:</b> 5/345W						<b>County:</b> Thurston
<b>Location:</b> 0.1 N THURSTON	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> 122° 42' 12"	<b>Latitude:</b> 47° 4' 18"	<b>Structure Length:</b> 430 ft.		<b>Out to Out Width:</b> 51.4 ft.
<b>Feature Intersected:</b> NISQUALLY R		<b>PGA (500 yr):</b> 30.1 %g	<b>PGA (1000 yr):</b> 39.5% %g	<b>Span Type:</b> STrus PCG	<b>Main Spans:</b> 1 <b>Appr. Spans:</b> 2	
<b>Year Built:</b> 1967	<b>ADT:</b> 45830	<b>11-13 Rank:</b> 126	<b>Skew Angle:</b> 0	<b>Pier Type:</b> Double Column Pier	<b>Footing Type:</b> Timber pile	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 15 %					



**Bridge Notes:**

Piers 2, and 3, each has two 6'-0" diameter columns. #4 hoops @ 12". Weld splices for longitudinal bars (#11 at pier 2, #14 at pier 3). Footing without top mat.

**Retrofit Program Notes:**

The 2005 Transportation Partnership Account (TPA) included funding to perform seismic retrofit work on this bridge.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

A seismic analysis will be done to determine what work is required. Typical retrofit measures and costs are: Cross-Beam Bolsters = \$1,500/LF of Cross Beam, Girder Stops = \$1,500/Each, Column Jackets (Dry) = \$50,000/Col. (Wet) = \$125,000/Col.

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0008100F		<b>Bridge Name:</b> MCALLISTER CR		<b>Route:</b> 5	<b>Milepost:</b> 114.09	<b>Region:</b> Olympic
<b>Bridge Number:</b> 5/342W						<b>County:</b> Thurston
<b>Location:</b> 2.2 N JCT SR 510	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> 122° 43' 12"	<b>Latitude:</b> 47° 4' 6.4"	<b>Structure Length:</b> 272 ft.		<b>Out to Out Width:</b> 51.4 ft.
<b>Feature Intersected:</b> MCALLISTER CR		<b>PGA (500 yr):</b> 28.89 %g	<b>PGA (1000 yr):</b> 39.5% %g	<b>Span Type:</b> PCG	<b>Main Spans:</b> 3 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1968	<b>ADT:</b> 60884	<b>11-13 Rank:</b> 127	<b>Skew Angle:</b> 12	<b>Pier Type:</b> Pier with more than two columns	<b>Footing Type:</b> Timber pile	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 10 %					



**Bridge Notes:**

Piers 2 and 3, each has three 3'-0" diameter columns. #3 hoops @ 12". #9 bars with 3'-4" splices. Footing without top mat.

**Retrofit Program Notes:**

The 2005 Transportation Partnership Account (TPA) included funding to perform seismic retrofit work on this bridge.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

A seismic analysis will be done to determine what work is required. Typical retrofit measures and costs are: Cross-Beam Bolsters = \$1,500/LF of Cross Beam, Girder Stops = \$1,500/Each, Column Jackets (Dry) = \$50,000/Col. (Wet) = \$125,000/Col.

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0008100E		<b>Bridge Name:</b> MCALLISTER CR		<b>Route:</b> 5	<b>Milepost:</b> 114.09	<b>Region:</b> Olympic
<b>Bridge Number:</b> 5/342E						<b>County:</b> Thurston
<b>Location:</b> 2.2 N JCT SR 510	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> 122° 43' 12.3"	<b>Latitude:</b> 47° 4' 4.5"	<b>Structure Length:</b> 272 ft.		<b>Out to Out Width:</b> 51.4 ft.
<b>Feature Intersected:</b> MCALLISTER CR		<b>PGA (500 yr):</b> 30.06 %g	<b>PGA (1000 yr):</b> 39.5% %g	<b>Span Type:</b> PCG		<b>Main Spans:</b> 3 <b>Appr. Spans:</b> 0
<b>Year Built:</b> 1968	<b>ADT:</b> 60884	<b>11-13 Rank:</b> 128	<b>Skew Angle:</b> 12	<b>Pier Type:</b> Pier with more than two columns		<b>Footing Type:</b> Timber pile
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 10 %					



**Bridge Notes:**

Piers 2 and 3, each has three 3'-0" diameter columns. #3 hoops @ 12". #9 bars with 3'-4" splices. Footing without top mat.

**Retrofit Program Notes:**

The 2005 Transportation Partnership Account (TPA) included funding to perform seismic retrofit work on this bridge.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

A seismic analysis will be done to determine what work is required. Typical retrofit measures and costs are: Cross-Beam Bolsters = \$1,500/LF of Cross Beam, Girder Stops = \$1,500/Each, Column Jackets (Dry) = \$50,000/Col. (Wet) = \$125,000/Col.

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0008100D		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Olympic
<b>Bridge Number:</b> 5/341		I-5 OC, MERIDIAN RD		5	113.08	<b>County:</b> Thurston
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
1.2 N JCT SR 510	5 miles	122° 44' 24"	47° 4' 0"	280 ft.		30.6 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 4	
I-5		30.05 %g	39.5% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1968	<b>ADT:</b> 2714	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 1 %	129	12	Double Column Pier		



**Bridge Notes:**

Piers 2, 3 and 4, each has two 3'-0" diameter columns. #3 hoops @ 12". #9 bars with 3'-4" splices. Footing without top mat.

**Retrofit Program Notes:**

The 2005 Transportation Partnership Account (TPA) included funding to perform seismic retrofit work on this bridge.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

A seismic analysis will be done to determine what work is required. Typical retrofit measures and costs are: Cross-Beam Bolsters = \$1,500/LF of Cross Beam, Girder Stops = \$1,500/Each, Column Jackets (Dry) = \$50,000/Col. (Wet) = \$125,000/Col.

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0008100C		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Olympic
<b>Bridge Number:</b> 5/339		I-5 OC, CARPENTER RD		5	110.4	<b>County:</b> Thurston
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
6.2 N JCT US 101	3 miles	122° 47' 48"	47° 3' 30"	356 ft.		34 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 4	
I-5		29.97 %g	39.4% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1967	<b>ADT:</b> 6450	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 2 %	130	4	Double Column Pier		
				<h2 style="font-size: 2em; color: black; text-decoration: underline;">No Photo Available</h2>		
<b>Bridge Notes:</b>			<b>Retrofit Program Notes:</b>			
Piers 2, 3 and 4, each has two 3'-0" diameter columns. #3 hoops @ 12". #9 bars with 3'-4" splices. Footing without top mat.			The 2005 Transportation Partnership Account (TPA) included funding to perform seismic retrofit work on this bridge.			
<b>Completed Retrofit Notes:</b>			<b>Remaining Retrofit Notes:</b>			
			A seismic analysis will be done to determine what work is required. Typical retrofit measures and costs are: Cross-Beam Bolsters = \$1,500/LF of Cross Beam, Girder Stops = \$1,500/Each, Column Jackets (Dry) = \$50,000/Col. (Wet) = \$125,000/Col.			
<b>Overall Retrofit Status:</b> P		<h3 style="font-size: 1.2em;">Estimated Total Bridge Item Cost:</h3> <h3 style="font-size: 1.2em;">Estimated Total Retrofit Project Cost:</h3>				
<b>Single Column Pier Status:</b> N						
<b>Multi Column Pier Status:</b> R						
C=Complete P=Partially Complet R=Required N=Not Required D=Differed X=Excluded I=In Progress						

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0008100A		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Olympic
<b>Bridge Number:</b> 5/337W		MARTIN WAY OC		5	109.14	<b>County:</b> Thurston
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
5.0 N JCT US 101	0 miles	122° 49' 6"	47° 3' 0"	276 ft.		55 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
MARTIN WAY		29.88 %g	39.2% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1967	<b>ADT:</b> 60884	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1988	<b>Truck Pct:</b> 10 %	131	50	Pier with more than two columns		



**Bridge Notes:**

Piers 2 and 3, each has five 3'-0" diameter columns. Retrofit four south columns per pier (built in 1967) only. These columns have #4 hoops @12", longitudinal #11 bars have splices at top of footings. Splice lengths are 4'-2". Footings have no top mat.

**Retrofit Program Notes:**

The 2005 Transportation Partnership Account (TPA) included funding to perform seismic retrofit work on this bridge.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

A seismic analysis will be done to determine what work is required. Typical retrofit measures and costs are: Cross-Beam Bolsters = \$1,500/LF of Cross Beam, Girder Stops = \$1,500/Each, Column Jackets (Dry) = \$50,000/Col. (Wet) = \$125,000/Col.

<b>Overall Retrofit Status:</b>	P
<b>Single Column Pier Status:</b>	N
<b>Multi Column Pier Status:</b>	R
C=Complete P=Partially Complet	
R=Required N=Not Required	
D=Differed X=Excluded I=In Progress	

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0008100B		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Olympic
<b>Bridge Number:</b> 5/337E		MARTIN WAY OC		5	109.14	<b>County:</b> Thurston
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
5.0 N JCT US 101	0 miles	122° 49' 6"	47° 3' 0"	282 ft.		55 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
MARTIN WAY		29.88 %g	39.2% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1967	<b>ADT:</b> 60884	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1988	<b>Truck Pct:</b> 10 %	132	50	Pier with more than two columns		



**Bridge Notes:**

Piers 2 and 3, each has five 3'-0" diameter columns. Retrofit three center columns per pier (built in 1967) only. These columns have #4 hoops @12", longitudinal #11 bars have splices at top of footings. Splice lengths are 4'-2". Footings have no top mat.

**Retrofit Program Notes:**

The 2005 Transportation Partnership Account (TPA) included funding to perform seismic retrofit work on this bridge.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

A seismic analysis will be done to determine what work is required. Typical retrofit measures and costs are: Cross-Beam Bolsters = \$1,500/LF of Cross Beam, Girder Stops = \$1,500/Each, Column Jackets (Dry) = \$50,000/Col. (Wet) = \$125,000/Col.

<b>Overall Retrofit Status:</b>	P
<b>Single Column Pier Status:</b>	N
<b>Multi Column Pier Status:</b>	R
C=Complete P=Partially Complet	
R=Required N=Not Required	
D=Differed X=Excluded I=In Progress	

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0005295D		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Olympic
<b>Bridge Number:</b> 5/325S-W		HENDERSON BLVD,UPRR OC		5	105.46	<b>County:</b> Thurston
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
1.4 N JCT US 101	2 miles	122° 53' 30"	47° 2' 6"	228 ft.		43 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 4	
HENDERSON BLVD,UPRR OC		29.65 %g	38.9% %g	CTB	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1957	<b>ADT:</b> 3234	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1990	<b>Truck Pct:</b> 5 %	134	0	Double Column Pier	Concrete Pile	



**Bridge Notes:**

Piers 2, 3 and 4, each has two 5'-0" diameter columns. Retrofit south columns (built in 1957) only. These columns have #3 hoops @12", longitudinal #10 bars have splices at top of footing and mid-height. Splice lengths are 2'-2". Footings have no top mat.

**Retrofit Program Notes:**

The 2005 Transportation Partnership Account (TPA) included funding to perform seismic retrofit work on this bridge.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

A seismic analysis will be done to determine what work is required. Typical retrofit measures and costs are: Cross-Beam Bolsters = \$1,500/LF of Cross Beam, Girder Stops = \$1,500/Each, Column Jackets (Dry) = \$50,000/Col. (Wet) = \$125,000/Col.

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0005295C		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Olympic
<b>Bridge Number:</b> 5/325A		N-14TH RAMP, OWR&N RR OC		5	105.45	<b>County:</b> Thurston
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
1.4 N JCT US 101	2 miles	122° 53' 30"	47° 2' 6"	275 ft.		49.2 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 4	
PLUM ST, UPRR		29.65 %g	38.9% %g	CBox	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1957	<b>ADT:</b> 8590	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1986	<b>Truck Pct:</b> 2 %	135	24	Pier with more than two columns	Concrete Pile	



**Bridge Notes:**

Piers 2, 3 and 4, each has four 24"x24" square columns, #3 hoops @ 12", #11 longitudinal bars spliced at top of footing and mid-height with 2'-4" splices. Footings have no top mat.

**Retrofit Program Notes:**

The 2005 Transportation Partnership Account (TPA) included funding to perform seismic retrofit work on this bridge.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

A seismic analysis will be done to determine what work is required. Typical retrofit measures and costs are: Cross-Beam Bolsters = \$1,500/LF of Cross Beam, Girder Stops = \$1,500/Each, Column Jackets (Dry) = \$50,000/Col. (Wet) = \$125,000/Col.

<b>Overall Retrofit Status:</b>	R
<b>Single Column Pier Status:</b>	N
<b>Multi Column Pier Status:</b>	R
C=Complete P=Partially Complet	
R=Required N=Not Required	
D=Differed X=Excluded I=In Progress	

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0005090A		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Olympic
<b>Bridge Number:</b> 5/321		CAPITOL LAKE		5	104.52	<b>County:</b> Thurston
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
0.5 N JCT US 101	8 miles	122° 54' 6"	47° 1' 24"	392 ft.		210 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 4	
CAPITOL LAKE		29.51 %g	38.7% %g	CBox	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1956	<b>ADT:</b> 45733	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1986	<b>Truck Pct:</b> 12 %	136	0	Pier with more than two columns	Concrete Pile	



**Bridge Notes:**

Retrofit 4 center columns at piers 2, 3 and 4 (built in 1956). These columns are 4'-0"x4'-0" square columns with #3 hoops @12". Longitudinal bars are #11 bars spliced at more than 2 locations, splice length is 2'-4". Footings are combined footings with top mat.

**Retrofit Program Notes:**

The 2005 Transportation Partnership Account (TPA) included funding to perform seismic retrofit work on this bridge.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

A seismic analysis will be done to determine what work is required. Typical retrofit measures and costs are: Cross-Beam Bolsters = \$1,500/LF of Cross Beam, Girder Stops = \$1,500/Each, Column Jackets (Dry) = \$50,000/Col. (Wet) = \$125,000/Col.

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0008271C		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Olympic
<b>Bridge Number:</b> 5/309		I-5 OC, 113TH AVE SW		5	97.22	<b>County:</b> Thurston
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
2.0 N JCT SR 121	9 miles	122° 56' 42"	46° 55' 24"	204 ft.		31.9 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 4	
I-5		28.26 %g	37.0% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1968	<b>ADT:</b> 673	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 1 %	137	11	Double Column Pier	Spread footing	



**Bridge Notes:**

Piers 2, 3 and 4, each has two 3'-0" diameter columns. #3 hoops @ 12". #9 bars with 3'-4" splices. Footing without top mat.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2, 3 and 4. (2 ea. 6 total, 3' dia.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0008271B		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Olympic
<b>Bridge Number:</b> 5/304		I-5 OC, 183RD AVE SW		5	89.84	<b>County:</b> Thurston
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
1.5 N JCT US 12	5 miles	122° 59' 36"	46° 49' 24"	402 ft.		31.9 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 7	
I-5		26.71 %g	35.1% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1968	<b>ADT:</b> 1786	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 1 %	138	21	Double Column Pier	Spread footing	



**Bridge Notes:**

Piers 2, 3, 4, 5, 6 and 7, each has two 3'-0" diameter columns. #3 hoops @ 12". #9 bars with 3'-4" splices. Footing without top mat. Railroad track between piers 2 and 3.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2, 3, 4, 5, 6 and 7. (2 ea. 12 total, 3' dia.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0004693A		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Southwest
<b>Bridge Number:</b> 5/234		BLAKESLEE JCT RR OC		5	83.28	<b>County:</b> Lewis
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
1.8 N JCT SR 507	1 miles	122 58 24	46 44 6	363 ft.		78.3 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 4	
BLAKESLEE JCT RR		25.41 %g	33.6% %g	CBox CTB	<b>Appr. Spans:</b> 1	
<b>Year Built:</b> 1954	<b>ADT:</b> 54298	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1975	<b>Truck Pct:</b> 20 %	139	99	Single Column Pier		



**Bridge Notes:**

N.B. and S.B. bridges, each has a 9'-0"x4'-0" rectangular column at piers 3, 4 and 5. #3 hoops and ties @ 12", #11 bars with 2'-4" splices. No top mat. 4 roller bearings at expansion joint at pier 2 of both N.B. and S.B. bridges.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Includes both East and West bridges. Retrofit single columns at piers 3, 4, and 5 and two columns at pier 2. (total 10, P2 2-3'x3', P3, P4 & P5 1-9'x4' ea. bridge) Install catcher blocks for rocker bearings at pier 2 and restrainers.

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0009251A		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Southwest
<b>Bridge Number:</b> 5/233		HARRISON AVE OC		5	82.74	<b>County:</b> Lewis
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
1.7 N JCT SR 507	0 miles	122° 58' 36"	46° 43' 42"	208 ft.		86.5 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
HARRISON AVE		25.3 %g	33.5% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1972	<b>ADT:</b> 54298	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 20 %	140	28	Pier with more than two columns	Spread footing	



**Bridge Notes:**

Piers 2 and 3, each has four 3'-0" diameter columns. #4 hoops @ 12". #9 bars with 3'-6" splices. Footing without top mat.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (4 ea. 8 total, 3' dia.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0011757B		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Southwest
<b>Bridge Number:</b> 5/232W		SKOOKUMCHUCK R		5	82.28	<b>County:</b> Lewis
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
0.7 N JCT SR 507	1 miles	122° 58' 30"	46° 43' 18"	252 ft.		34 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 1	
SKOOKUMCHUCK R		25.2 %g	33.4% %g	STrus CTB	<b>Appr. Spans:</b> 2	
<b>Year Built:</b> 1951	<b>ADT:</b> 27895	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 20 %	141	0	Pier Wall		



**Bridge Notes:**

Steel trusses supported on pier walls at piers 2 and 3. Two expansion rocker bearings at pier 3 and two fixed bearings at pier 2. Approach span has four rocker bearings, each at piers 2 and 3.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Install catcher blocks for steel trusse rocker bearings at piers 2 and 3.

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0011757A		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Southwest
<b>Bridge Number:</b> 5/232E		SKOOKUMCHUCK R		5	82.28	<b>County:</b> Lewis
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
0.7 N JCT SR 507	1 miles	122° 58' 30"	46° 43' 18"	252 ft.		34 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 1	
SKOOKUMCHUCK R		25.2 %g	33.4% %g	STrus CTB	<b>Appr. Spans:</b> 2	
<b>Year Built:</b> 1951	<b>ADT:</b> 27895	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 20 %	142	0	Pier Wall		



**Bridge Notes:**

Steel trusses supported on pier walls at piers 2 and 3. Two expansion rocker bearings at pier 3 and two fixed bearings at pier 2. Approach span has four rocker bearings, each at piers 2 and 3.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Install catcher blocks for steel trusse rocker bearings at piers 2 and 3.

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0003922A		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Southwest
<b>Bridge Number:</b> 5/230		SR 507 MELLEEN ST OC		5	81.67	<b>County:</b> Lewis
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
3.7 N JCT SR 6	0 miles	122° 58' 30"	46° 42' 42"	94 ft.		83.5 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 3	
SR 507 MELLEEN ST		25.05 %g	33.2% %g	CTB	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1951	<b>ADT:</b> 55791	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 1972	<b>Truck Pct:</b> 25 %	143	0	Pier with more than two columns	Spread footing	



**Bridge Notes:**

Piers 2, and 3, each has 16-15"x15" square columns @ 5'-0", #3 hoops @ 12", #7 bars with 4'-2" splices. Footings have #6 @11" longitudinal and #6 @ 3'-0" transverse top mat. Each pier has a 15"x24" rectangular column at centerline of roadway with #4 @12" hoop and ties.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (17 ea. 34 total, 15-15"x15" & 1-24"x15" ea.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0008085F		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/642		I-5 OC, 23RD ST		5	194.44	<b>County:</b> Snohomish
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
0.6 N JCT US 2	2 miles	122° 10' 57"	47° 59' 12"	170 ft.		51.9 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 2	
I-5		28.39 %g	37.0% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1967	<b>ADT:</b> 4716	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 5 %	144	0	Pier with more than two columns		



**Bridge Notes:**

Pier 2 has three 3'-0" diameter columns. #3 hoops @ 12". #9 vertical bars have 3'-4" lap splices at top of footings. Footing without top mat.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit 3 columns at pier 2. (3' dia.)

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0008256A		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/645E		SNOHOMISH R BN RR		5	194.81	<b>County:</b> Snohomish
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
1.0 N JCT US 2	1 miles	122° 10' 55.08" W	47° 59' 22.26" N	1622 ft.		51.4 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 8	
SNOHOMISH R GN RY		28.11 %g	37.0% %g	SG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1968	<b>ADT:</b> 63000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 15 %	145	30	Double Column Pier	Timber pile	



**Bridge Notes:**

Piers 2 thru 8, each has two 6'-0" diameter columns. #4 hoops @ 12". #11 vertical bars have 4'-2" lap splices at top of pedestals or walls. Piers 3 and 4 have 3'-0" infill walls. Footing without top mat.

**Retrofit Program Notes:**

Good candidate to use isolation bearings.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2-8 (2 ea. 14 total, 6' dia.).

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0008256B		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/645W		SNOHOMISH R BN RR		5	194.81	<b>County:</b> Snohomish
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
1.0 N JCT US 2	1 miles	122 10 55.08	47 59 22.26	1588 ft.		51.4 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 8	
SNOHOMISH R GN RY		28.11 %g	37.0% %g	SG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1968	<b>ADT:</b> 63000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 15 %	146	30	Double Column Pier	Timber pile	



**Bridge Notes:**

Piers 2 thru 8, each has two 6'-0" diameter columns. #4 hoops @ 12". #11 vertical bars have 4'-2" lap splices at top of pedestals or walls. Piers 3 and 4 have 3'-0" infill walls. Footing without top mat.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2-8 (2 ea. 14 total, 6' dia.).

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0009260A		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/701		STARBIRD RD OVER I-5		5	218.54	<b>County:</b> Skagit
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
0.8 N SNOHOMIS	6 miles	122° 18' 54"	48° 18' 30"	363 ft.		41 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 4	
I-5		26.12 %g	34.7% %g	PCG	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1972	<b>ADT:</b> 1270	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 1 %	147	20	Pier with more than two columns	Concrete Pile	



**Bridge Notes:**

Piers 2, 3 and 4, each has three 3'-0" x 4'-0" columns, #4 hoops @ 12", Vertical #11 bars with 4'-2" lap splices at top of footings. Footings have no top mat.

**Retrofit Program Notes:**

The 2005 Transportation Partnership Account (TPA) included funding to perform seismic retrofit work on this bridge. A project that includes this bridge is likely to be scheduled in the 2011-13 biennium.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

A seismic analysis will be done to determine what work is required. Typical retrofit measures and costs are: Cross-Beam Bolsters = \$1,500/LF of Cross Beam, Girder Stops = \$1,500/Each, Column Jackets (Dry) = \$50,000/Col. (Wet) = \$125,000/Col.

**Overall Retrofit Status:** P  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0004535A		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 5/707		I-5 OC, BLACKBURN ST		5	225.64	<b>County:</b> Skagit
<b>Location:</b>	<b>Detour Length:</b>	<b>Longitude:</b>	<b>Latitude:</b>	<b>Structure Length:</b>		<b>Out to Out Width:</b>
4.7 N JCT SR 534	6 miles	22° 19' 51.1"	48° 24' 23.6"	194 ft.		33.8 ft.
<b>Feature Intersected:</b>		<b>PGA (500 yr):</b>	<b>PGA (1000 yr):</b>	<b>Span Type:</b>	<b>Main Spans:</b> 5	
I-5		25.17 %g	33.7% %g	CTB	<b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1954	<b>ADT:</b> 1150	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 1 %	148	0	Double Column Pier	Concrete Pile	



**Bridge Notes:**

Piers 2 thru 5, each has two 32"x32" square columns. #3 hoops @ 12", vertical #11 bars with 2'-4" splices. Footings have no top mat.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2, 3, 4 and 5. (2 ea. 8 total, 32"x32")

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0005433A		<b>Bridge Name:</b>		<b>Route:</b>	<b>Milepost:</b>	<b>Region:</b> Northwest
<b>Bridge Number:</b> 18/5		SR 18 OVR PEASLEY CANYON		18	1.86	<b>County:</b> King
<b>Location:</b> 1.9 E JCT I-5	<b>Detour Length:</b> 4 miles	<b>Longitude:</b> 122° 16' 25.9"	<b>Latitude:</b> 47° 18' 12.9"	<b>Structure Length:</b> 360 ft.		<b>Out to Out Width:</b> 81.5 ft.
<b>Feature Intersected:</b> PEASLEY CANYON RD		<b>PGA (500 yr):</b> 31 %g	<b>PGA (1000 yr):</b> 40.6% %g	<b>Span Type:</b> CBox		<b>Main Spans:</b> 3 <b>Appr. Spans:</b> 0
<b>Year Built:</b> 1958	<b>ADT:</b> 44000	<b>11-13 Rank:</b>	<b>Skew Angle:</b>	<b>Pier Type:</b>	<b>Footing Type:</b>	
<b>Year Rebuilt:</b> 2004	<b>Truck Pct:</b> 15 %	149	0	Pier with more than two columns		



**Bridge Notes:**

Intermediate Piers, Piers 2 and 3, each has three 5'-0" diameter columns on combined spread footings. #3 hoops spaced at 12" spacing. Vertical #11 bars have 2'-4" lap splices at top of pedestal. End Piers 1 and 4 are cantilever "L" abutments. Pier 4 has seven tall rocker bearings.

**Retrofit Program Notes:**

Retrofit columns at Piers 2 and 3. (3 ea. 6 total, 5' dia.) 85 ft. tall. Catcher blocks for rocker bearings at pier 4 (seven bearings). Install transverse restrainers.

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

# Washington State Department of Transportation Bridge Seismic Retrofit Information

<b>Structure ID:</b> 0005433B		<b>Bridge Name:</b> W VALLEY HIGHWAY OC		<b>Route:</b> 18	<b>Milepost:</b> 2.3	<b>Region:</b> Northwest
<b>Bridge Number:</b> 18/6						<b>County:</b> King
<b>Location:</b> 2.7 E JCT I-5	<b>Detour Length:</b> 1 miles	<b>Longitude:</b> 122° 15' 24"	<b>Latitude:</b> 47° 18' 6"	<b>Structure Length:</b> 114 ft.		<b>Out to Out Width:</b> 73 ft.
<b>Feature Intersected:</b> W VALLEY HWY(OLD SR 181)		<b>PGA (500 yr):</b> 30.87 %g	<b>PGA (1000 yr):</b> 40.5% %g	<b>Span Type:</b> CVS	<b>Main Spans:</b> 3 <b>Appr. Spans:</b> 0	
<b>Year Built:</b> 1957	<b>ADT:</b> 44000	<b>11-13 Rank:</b> 150	<b>Skew Angle:</b> 3	<b>Pier Type:</b> Pier with more than two columns	<b>Footing Type:</b> Concrete Pile	
<b>Year Rebuilt:</b> 0	<b>Truck Pct:</b> 15 %					



**Bridge Notes:**

Intermediate piers, piers 2 and 3, each has six 21" square columns on pile footing. Ties are #3 bars @ 12". Vertical #9 bars have 2'-0" lap splices at top of footings. End piers, piers 1 and 4, are 30 ton concrete pile bents.

**Retrofit Program Notes:**

**Completed Retrofit Notes:**

**Remaining Retrofit Notes:**

Retrofit columns at Piers 2 and 3. (6 ea. 12 total, 21"x21")

**Overall Retrofit Status:** R  
**Single Column Pier Status:** N  
**Multi Column Pier Status:** R  
 C=Complete P=Partially Complet  
 R=Required N=Not Required  
 D=Differed X=Excluded I=In Progress

**Estimated Total Bridge Item Cost:**  
**Estimated Total Retrofit Project Cost:**

## WSDOT Scour Projects - 2011-13 Bien

(Sorted by Bridge Number)



Bridge Number	Bridge Name	Length	Mile post	Region	PIN #	Year Planned	11-13 #	Project Total\$'s
003/015	SHERWOOD CR	147	20.36	Olympic	300379A	2012	5	\$996,488
097/120	CANAL DRAIN DITCH	121	60.82	South Central	509703E	2011	2	\$448,000
101/251	SNOW CREEK	71	282.62	Olympic	310170S	2012	9	\$824,000
101/302	RUSSELL H. BARKER M	370	185.6	Olympic	310186F	2012	7	\$846,000
108/004	WILDCAT CR	26	0.5	Olympic	310808A	2012	6	\$627,000
142/013.25	SPRING CR	22	29.92	Southwest	414205R	2011	1	\$956,000
224/010	YAKIMA OVERFLOW BRI	80	9.43	South Central	522401C	2012	3	\$636,000
410/101	WHITE R	292	21.99	Northwest	141001C	2011	1	\$956,000
823/003E	YAKIMA RIVER	335	0.09	South Central	582301M	2011	4	\$624,000
906/105	COAL CREEK	54	2.99	South Central	590601H	2012	8	\$391,000

Total Number of Bridges = 10

Total Bien\$'s = \$7,304,488

# WSDOT Scour Projects - 2011-13 Bien

(Sorted by Priority Number)



Bridge Number	Bridge Name	Length	Mile post	Region	PIN #	Year Planned	11-13 #	Project Total\$'s
410/101	WHITE R	292	21.99	Northwest	141001C	2011	1	\$956,000
142/013.25	SPRING CR	22	29.92	Southwest	414205R	2011	1	\$956,000
097/120	CANAL DRAIN DITCH	121	60.82	South Central	509703E	2011	2	\$448,000
224/010	YAKIMA OVERFLOW BRI	80	9.43	South Central	522401C	2012	3	\$636,000
823/003E	YAKIMA RIVER	335	0.09	South Central	582301M	2011	4	\$624,000
003/015	SHERWOOD CR	147	20.36	Olympic	300379A	2012	5	\$996,488
108/004	WILDCAT CR	26	0.5	Olympic	310808A	2012	6	\$627,000
101/302	RUSSELL H. BARKER M	370	185.6	Olympic	310186F	2012	7	\$846,000
906/105	COAL CREEK	54	2.99	South Central	590601H	2012	8	\$391,000
101/251	SNOW CREEK	71	282.62	Olympic	310170S	2012	9	\$824,000


Total Number of Bridges = 10

Total Bien\$'s = \$7,304,488

# WSDOT Bridge over Water

# Scour Form

Bridge ID: <b>0004133A</b>	Bridge Number: <b>3/15</b>	Bridge Name: <b>SHERWOOD CR</b>	State Route: <b>3</b> Mile Post: <b>20.36</b>	Olympic Cnty: Mason	
Year Built: <b>1952</b> Rebuilt:	Span Type: <b>CTB</b>	ADT: <b>8920</b> ADT Truck Pct: <b>5 %</b>	Structure Length: <b>147 ft.</b> Width: <b>26 ft.</b>	main span <b>3</b> aprch: <b>0</b>	Detour Length: <b>22 miles</b>
Substructure Stability: Code: <b>2</b> Spread footing, continuous spans.		Streambed Material: <b>3</b> Gravel	Scour History: Code: <b>C</b> Current scour problems.	Last Scour repair Project Yr: C#:	
Scour Code: <b>3</b>	Scour Rating Description: Bridge is scour critical; bridge foundations determined unstable for calculated scour depths: 1) Within limits of footings or piles (Figure WB 76-80B) 2) Below footing base or pile tips (Figure WB 76-80C).		Substr Code: <b>5</b>	sufficiency_rating: <b>52.21 FO</b>	



Deficiencies:  Bridge has spread footings. Riprap near piers 2 and 3 is no longer in place. Riprap placed just upstream that protect NW embankment is now in the middle of stream. The embankment is being undermined. P2 and P3 have 2ft footings on 6ft seals. P2 seal bottom is 12ft below channel, P3 is 8ft.	First Noted: <b>11/20/2000</b>
	BPO Repair List Priority: <b>1</b>
Recommended Action:  BPO - The rip rap has settled into the stream and the bank is beginning to erode. Place riprap against the eroded upstream banks at both abutments. Bridge Management Unit - The scour repair is scheduled to be completed in 2012.	Funding - P2 or M: <b>P2</b>
	BPO Repair Num: <b>10000</b>
	11-13 Priority Rank: <b>5</b>
	WIN: PIN: <b>300379A</b>
	Total Cost Estimate: <b>\$996,488</b>

# WSDOT Bridge over Water

# Scour Form

Bridge ID: 0001516B	Bridge Number: 97/120	Bridge Name: CANAL DRAIN DITCH	State Route: 97 Mile Post: 60.82	South Central Cnty: Yakima
Year Built: 1931 Rebuilt: 1975	Span Type: CS	ADT: 3802 ADT Truck Pct: 26 %	Structure Length: 121 ft. Width: 40 ft.	main span 6 aprch: 0 Detour Length: 22 miles
Substructure Stability: Code: 4 Pile foundation, continuous spans.	Streambed Material: 3 Gravel	Scour History: Code: C Current scour problems.	Last Scour repair Project Yr: C#:	
Scour Code: 3	Scour Rating Description: Bridge is scour critical; bridge foundations determined unstable for calculated scour depths: 1) Within limits of footings or piles (Figure WB 76-80B) 2) Below footing base or pile tips (Figure WB 76-80C).	Substr Code: 5	sufficiency_rating: 64.53	



Deficiencies:  Scour hole behind Piles 2D, 2E, 2F in Pier 1 embankment. Debris hung up on Piles 3A, 3E and 3F. Calculated scour falls below pile tips at Pier 2. Monitor for channel migration. Current bottom of south channel is 4' above pile tips at Pier 2.	First Noted: 5/16/2003
	BPO Repair List Priority: 1
Recommended Action: BPO - Fill scour area in Span 1 with quarry spalls back to original ground line. Bridge Management Unit - The Scour Repair is scheduled to be done by contract in 2011.	Funding - P2 or M: P2
	BPO Repair Num: 10000
	11-13 Priority Rank: 2
	WIN: PIN: 509703E
	Total Cost Estimate: \$448,000

# WSDOT Bridge over Water

# Scour Form

Bridge ID: 0013073B	Bridge Number: 101/251	Bridge Name: SNOW CREEK	State Route: 101 Mile Post: 282.62	Olympic Cnty: Jefferson
Year Built: 1986 Rebuilt:	Span Type: PCS	ADT: 6839 ADT Truck Pct: 10 %	Structure Length: 71 ft. Width: 56.9 ft.	main span 1 aprch: 0 Detour Length: 3 miles
Substructure Stability: Code: 3 Pile foundation, simple spans.	Streambed Material: 3 Gravel	Scour History: Code: C Current scour problems.	Last Scour repair Project Yr: C#:	
Scour Code: 8	Scour Rating Description: Bridge foundations determined stable for calculated/evaluated scour conditions. Calculated/evaluated scour is above top of footing. (Figure WB76-80, A).	Substr Code: 7	sufficiency_rating: 95.3	




Deficiencies:  Pier 1 is south (west geographically) towards Port Angeles. Bridge Foundations are on steel piles that have approx 50 ft embedment. Creek bears on north abutment. North abutment pile cap is exposed full width up to 36" deep at the west end. South abutment pile cap has been exposed and undermined near centerline.	First Noted: 12/12/2006
	BPO Repair List Priority: 1
	Funding - P2 or M: P2
	BPO Repair Num: 10000
	11-13 Priority Rank: 9
Recommended Action:  BPO - Place riprap, armor the piers and protect the approach fills. Bridge Management Unit - Scour repair is scheduled to be completed by contract in 2012 or 2013.	WIN: PIN: 310170S
	Total Cost Estimate: \$824,000

# WSDOT Bridge over Water

# Scour Form

Bridge ID: 0012600A	Bridge Number: 101/302	Bridge Name: RUSSELL H. BARKER MEM.	State Route: 101 Mile Post: 185.60	Olympic Cnty: Clallam
Year Built: 1985 Rebuilt:	Span Type: PCG	ADT: 1694 ADT Truck Pct: 20 %	Structure Length: 370 ft. Width: 36 ft.	main span 3 aprch: 0 Detour Length: 99 miles
Substructure Stability: shafts	Code: 9	Streambed Material: 3 Gravel	Scour History: Code: C Current scour problems:	Last Scour repair Project Yr: C#:
Scour Code: 4	Scour Rating Description:	Bridge foundations determined stable for calculated scour condition: field review indicates action is required to protect exposed foundations from effects of additional erosion.		Substr Code: 5 sufficiency_rating: 61.48



Deficiencies:  Local scour problem at pier 3, where shaft cap is exposed. Debris piled up behind pier 3. Majority of river water bears against pier 3. High water erosion has caused undermining of heavy riprap bank protection on north bank. Drilled shaft foundations for piers 2 and 3. BPO Priority changed from "4" to "1" in 2005.	First Noted: 6/22/2005
	BPO Repair List Priority: 1
Recommended Action:  BPO - Cover the Pier 3 Cap with special heavy loose riprap at a 2:1 slope and blend into existing groundline and bank. Bridge Management Unit - Scour Repair is scheduled to be completed in 2012 or 2013.	Funding - P2 or M: P2
	BPO Repair Num: 14934
	11-13 Priority Rank: 7
	WIN: PIN: 310186F
	Total Cost Estimate: \$846,000

# WSDOT Bridge over Water

# Scour Form

Bridge ID: 0002214A	Bridge Number: 108/4	Bridge Name: WILDCAT CR	State Route: 108 Mile Post: 0.50	Olympic Cnty: Grays Harbor
Year Built: 1936 Rebuilt:	Span Type: CEFA	ADT: 4765 ADT Truck Pct: 15 %	Structure Length: 26 ft. Width: 29.5 ft.	main span 1 aprch: 0 Detour Length: 3 miles
Substructure Stability: Code: 1 Spread footing, simple spans.	Streambed Material: 3 Gravel	Scour History: Code: C Current scour problems.	Last Scour repair Project Yr: C#:	
Scour Code: 3	Scour Rating Description: Bridge is scour critical; bridge foundations determined unstable for calculated scour depths: 1) Within limits of footings or piles (Figure WB 76-80B) 2) Below footing base or pile tips (Figure WB 76-80C).	Substr Code: 5	sufficiency_rating: 67.15 FO	



Deficiencies:  P1 apron is undermined approx. 2' at the NW corner. P2 is undermined up to 4' at the NE corner and it has many holes scattered throughout. The stream appears to have shifted to the East but bends back to the bridge opening. 10" dia. riprap scattered in waterway under and downstream of bridge.	First Noted: 7/22/2001
	BPO Repair List Priority: 1
	Funding - P2 or M: P2
	BPO Repair Num: 10000
	11-13 Priority Rank: 6
Recommended Action:  BPO - Repair undermining of apron at NE corner of Pier 2 and all of Pier 1. Bridge Management Unit - Scour repair is scheduled to be completed in 2012.	WIN: PIN: 310808A
	Total Cost Estimate: \$627,000

# WSDOT Bridge over Water

# Scour Form

Bridge ID: 00000BE	Bridge Number: 142/13	Bridge Name: SPRING CR	State Route: 142 Mile Post: 29.92	Southwest Cnty: Klickitat
Year Built: 1950 Rebuilt:	Span Type: SB	ADT: 1125 ADT Truck Pct: 15 %	Structure Length: 22 ft. Width: 23.5 ft.	main span 1 aprch: 0 Detour Length: 6 miles
Substructure Stability: Code: 1 Spread footing, simple spans.	Streambed Material: 2 Sediment	Scour History: Code: N No history of scour.	Last Scour repair Project Yr: C#:	
Scour Code: 3	Scour Rating Description: Bridge is scour critical; bridge foundations determined unstable for calculated scour depths: 1) Within limits of footings or piles (Figure WB 76-80B) 2) Below footing base or pile tips (Figure WB 76-80C).	Substr Code: 4	sufficiency_rating: 48.77	



Deficiencies:  Stream flows against both abutments. Heavy silt deposition 2' thick at west abutment. Abutments are Stone & mortar wall. Unknown foundation depth. Mortar has been eroded by the stream action. Bridge has contraction scour problem and needs as much hydraulic opening as possible.	First Noted: 6/6/2006
	BPO Repair List Priority: 1
Recommended Action:  BPO - Place well graded light loose riprap, two to three layers deep (1' thick min.) along both stone & mortar abutment walls, tapering out at a 2:1 slope, blending into the existing groundline and banks. Repair modified 6/6/06 to priority 1 due to undermining of the east abutment per JHL/DCC. Bridge Management Unit - Scour repair is scheduled to be done by SW Region Maintenance in 2011.	Funding - P2 or M: P2
	BPO Repair Num: 10000
	11-13 Priority Rank: 1
	WIN: PIN: 414205R
	Total Cost Estimate: \$280,000

# WSDOT Bridge over Water

# Scour Form

Bridge ID: 0014085C	Bridge Number: 224/10	Bridge Name: YAKIMA OVERFLOW BRIDGE	State Route: 224 Mile Post: 9.43	South Central Cnty: Benton	
Year Built: 1993 Rebuilt:	Span Type: CS	ADT: 17125 ADT Truck Pct: 10 %	Structure Length: 80 ft. Width: 72 ft.	main span 2 aprch: 0	Detour Length: 1 miles
Substructure Stability: Code: 2 Spread footing, continuous spans.		Streambed Material: 2 Sediment	Scour History: Code: C Current scour problems.	Last Scour repair Project Yr: C#:	
Scour Code: 3	Scour Rating Description: Bridge is scour critical; bridge foundations determined unstable for calculated scour depths: 1) Within limits of footings or piles (Figure WB 76-80B) 2) Below footing base or pile tips (Figure WB 76-80C).		Substr Code: 5	sufficiency_rating: 86.23	



Deficiencies:  High water, high flow event has caused severe erosion. Abutments are exposed, see photos 3, 6, and 7. Scour hole around Column 3B. Riprap has been washed from Pier 3 abument at the north. Riprap in place at remaining corners of bridge.	First Noted: 5/3/2005
	BPO Repair List Priority: 1
	Funding - P2 or M: P2
	BPO Repair Num: 10001
Recommended Action:  BPO - Mitigate scour at abuments and Pier 2. Repair design in progress; construction not likely before 2009; review/update status each inspection; monitor until construction. Bridge Management Unit - Prioritize with other statewide scour needs in the 2011-13 biennium.	11-13 Priority Rank: 1
	WIN:
	PIN:
Total Cost Estimate:	

# WSDOT Bridge over Water

# Scour Form

Bridge ID: 0003523A	Bridge Number: 410/101	Bridge Name: WHITE R	State Route: 410 Mile Post: 21.99	Northwest Cnty: Pierce	
Year Built: 1949 Rebuilt:	Span Type: STrus CTB	ADT: 16066 ADT Truck Pct: 8 %	Structure Length: 292 ft. Width: 32 ft.	main span 1 aprch: 3	Detour Length: 38 miles
Substructure Stability: Code: 1 Spread footing, simple spans.		Streambed Material: 3 Gravel	Scour History: Code: C Current scour problems.		Last Scour repair Project Yr: C#:
Scour Code: 3	Scour Rating Description: Bridge is scour critical; bridge foundations determined unstable for calculated scour depths: 1) Within limits of footings or piles (Figure WB 76-80B) 2) Below footing base or pile tips (Figure WB 76-80C).		Substr Code: 5	sufficiency_rating: 52.1	



Deficiencies:  Pier 2 consists of spread footings 14' x 16' and 2.25' on 4' seals. The as-built plans say the foundation is on cemented sands. The footing at North end of Pier is exposed 1.3ft on the upstream side and 2.4ft on the down stream side. Hydraulics Office 5/28/96 - This bridge is scour critical if the thalweg migrates to Pier 2 or Pier 3. Riprap must be maintained at pier 2. Calc scour depth is 10ft below bottom of footings.	First Noted: 7/18/2005
	BPO Repair List Priority: 1
	Funding - P2 or M: P2
	BPO Repair Num: 12611
	11-13 Priority Rank: 1
Recommended Action:  BPO - Place heavy loose riprap, 2 layers thick over footing, at a minimum of 2:1 slope. Bridge Management Unit - The Cn phase for this P2 funded project is scheduled to be constructed in 2011.	WIN: PIN: 141001C
	Total Cost Estimate: \$956,000

# WSDOT Bridge over Water

# Scour Form

Bridge ID: 0003209A	Bridge Number: 823/3E	Bridge Name: YAKIMA RIVER	State Route: 823 Mile Post: 0.09	South Central Cnty: Yakima	
Year Built: 1947 Rebuilt:	Span Type: CTB	ADT: 13500 ADT Truck Pct: 5 %	Structure Length: 335 ft. Width: 28 ft.	main span 5 aprch: 0	Detour Length: 3 miles
Substructure Stability: Code: 2 Spread footing, continuous spans.		Streambed Material: 3 Gravel	Scour History: Code: N No history of scour.		Last Scour repair Project Yr: C#:
Scour Code: 3	Scour Rating Description: Bridge is scour critical; bridge foundations determined unstable for calculated scour depths: 1) Within limits of footings or piles (Figure WB 76-80B) 2) Below footing base or pile tips (Figure WB 76-80C).		Substr Code: 5	sufficiency_rating: 63.86	



**No Photo Available**

Deficiencies:  Previous inspections: Footing of P3 exposed up to 12" along the middle 12 feet of the so side. Rip-rap at nose and tail of Pier 3. The footing face of P4 exposed 5" along the north half, east end and exposed 2" along the south half, east end. The top of the east half of the Pier 4 footing is fully exposed. The top of the nw footing is exposed for 5 ft.	First Noted: 10/31/2001
	BPO Repair List Priority: 1
	Funding - P2 or M: P2
	BPO Repair Num: 13055
Recommended Action: BPO - Replace missing riprap at piers 3 & 4. Bridge Management Unit - The scour repair is scheduled to be completed in 2011.	11-13 Priority Rank: 4
	WIN: PIN: 582301M
	Total Cost Estimate: \$624,000

# WSDOT Bridge over Water

# Scour Form

Bridge ID: 0008863A	Bridge Number: 906/105	Bridge Name: COAL CREEK	State Route: 906 Mile Post: 2.98	South Central Cnty: Kittitas
Year Built: 1970 Rebuilt:	Span Type: TTLB	ADT: 260 ADT Truck Pct: 5 %	Structure Length: 54 ft. Width: 28.5 ft.	main span 1 aprch:
Substructure Stability: Code: 1 Spread footing, simple spans.		Streambed Material:	Scour History: Code: C Current scour problems.	Last Scour repair Project Yr: C#:
Scour Code: 3	Scour Rating Description: Bridge is scour critical; bridge foundations determined unstable for calculated scour depths: 1) Within limits of footings or piles (Figure WB 76-80B) 2) Below footing base or pile tips (Figure WB 76-80C).	Substr Code: 4	sufficiency_rating: 54.88 SD	



Deficiencies:  The concrete abutment is a 2 ft. x 2 ft. concrete beam which appears to be acting as a spread footing. The west abutment is undermined on the south end below the Girder E bearing, 4.5 ft. wide x 2 ft. high x 2 ft. deep. The east abutment has a 13 ft. long crack on the vertical face at 1" below the top.	First Noted: 2/16/2006
	BPO Repair List Priority: 1
Recommended Action: BPO - Fill void and place riprap on bank per repair drawings. Bridge Management Unit - Scour Repair Scheduled to be completed by contract in 2012 or 2013.	Funding - P2 or M: P2
	BPO Repair Num: 10000
	11-13 Priority Rank: 8
	WIN: PIN: 590601H
	Total Cost Estimate: \$391,000