

P2 Bridge Preservation - Replacement/Rehab Projects

2013-15 Bien Priority Array

(Sorted by Priority Number)

13-15 #	Bridge Number	Bridge Name	Mile post	Region	Length	Future work Description
5	90/322N	SR 261 OC	221.95	Eastern	169	Rehabilitate Bridge
6	90/322S	SR 261 OC	221.95	Eastern	169	Rehabilitate Bridge
18	20/924	DAVIS CR	423.75	Eastern	77	Replace Bridge
20	261/320	DRY RUN	57.72	Eastern	32	Replace Bridge

Total Number of Bridges = 4



P2 Bridge Preservation - Replacement/Rehab Projects

2013-15 Bien Priority Array

(Sorted by Bridge Number)

13-15 #	Bridge Number	Bridge Name	Mile post	Region	Length	Future work Description
18	20/924	DAVIS CR	423.75	Eastern	77	Replace Bridge
5	90/322N	SR 261 OC	221.95	Eastern	169	Rehabilitate Bridge
6	90/322S	SR 261 OC	221.95	Eastern	169	Rehabilitate Bridge
20	261/320	DRY RUN	57.72	Eastern	32	Replace Bridge

Total Number of Bridges = 4



Bridge Preservation Program

Bridge Replacement Form

Bridge Number: 20 / 924	Structure ID 0002102C	Bridge Name: DAVIS CR	Milepost: 423.75	Region: Eastern
Year Built / YR Widened: 1936	Bridge Type: Treated Timber Trestle	Number of Main/Appr span 5 / 0	Sufficiency Rating: 46.86 SD	
Bridge Width (curb-curb): 27.5 ft	Bridge Length: 77 ft	Max Span: 15 ft		
Average Daily Traffic: 1,738	Truck% 16%	Number of Lanes: 2		
Vertical Clearance: NA	Detour Length (miles): 13	Appr Rdway Width: 30.0 ft		
Design Load: H 15	HS: 0.92	Load Restricted Bridge? <input checked="" type="checkbox"/>		
Op Rating: 33.00	A1: 1.05	BL Load: 18,000		
Inv Rating: 23.00	A2: 1.14	CL-8 Load: 18,000		
	A3: 1.28	SA Load: 36,000		
Bridge Inspection Information				
Date Inspected: 4/20/2011	Structr Adequacy: 4			
Superstr Code: 6	Safe Load: 5			
Substr Code: 4	Deck Geometry: 4			
Deck Code: 6	Underclearance: 9			
Scour: 8	Waterway: 8			
Proposed Bridge Replacement / Rehab Information				
New Bridge Width: 36 ft	Bridge \$'s:			
New Bridge Length: 82 ft.	Total \$'s: \$3,957,000			
Priority Array #: 18				
PIN Number: 602042E	Repl/Rehab Year:			
WIN Number:	Ad Date:			
Contract Number:	Funding Cat: P2			
<p>THE BRIDGE IS CLASSIFIED "SD" DUE TO THE SUBSTRUCTURE CODE.</p> <p>The timber pier caps have checks up to 1/2" wide with the largest on the south half of Pier 5. The south end of Pier Cap 5 is RED TAGGED under the exterior girder. The pier cap is crushing and has a 7" rot pocket with a 2" shell. Pier cap 6 is tipped eastward and does not have full bearing on the piles.</p> <p>Many of the piles have splits and checks up to 1/2" wide with the largest at Piles 3C and 4C. Piles 3C, 3D and 4A through 4E have been repaired or replaced with new timber piles from the bottom of the pile cap down to a steel collar at the mud line (5 total).</p>				



Bridge Preservation Program

Bridge Replacement Form

Bridge Number: 90 / 322N	Structure ID 0005761B	Bridge Name: I-90 OVER SR 261	Milepost: 221.95	Region: Eastern
Year Built / YR Widened: 1952	Bridge Type: Concrete Slab (Hollow)	Number of Main/Appr span 3 / 0	Sufficiency Rating: 45.28 SD	
Bridge Width (curb-curb): 31.7 ft	Bridge Length: 169 ft	Max Span: 66 ft	<p align="center">Bridge Deck View</p> 	
Average Daily Traffic: 8,026	Truck% 28%	Number of Lanes: 2		
Vertical Clearance: NA	Detour Length (miles): 2	Appr Rdway Width: 40.0 ft		
Design Load: HS 15	HS: 1.25	Load Restricted Bridge? <input type="checkbox"/>		
Op Rating: 36.00	A1: 1.75	BL Load:		
Inv Rating: 22.00	A2: 1.59	CL-8 Load:		
	A3: 1.63	SA Load:		
Bridge Inspection Information			<p align="center">Bridge Profile View</p> 	
Date Inspected: 7/11/2012	Structr Adequacy: 4			
Superstr Code: 4	Safe Load: 5			
Substr Code: 6	Deck Geometry: 2			
Deck Code: 7	Underclearance: 8			
Scour: N	Waterway: 9			
Proposed Bridge Replacement / Rehab Information				
New Bridge Width: ft	Bridge \$'s:			
New Bridge Length: ft	Total \$'s: \$3,000,000			
Priority Array #: 5				
PIN Number: 609022B	Repl/Rehab Year: 2018			
WIN Number:	Ad Date: 4/3/2017			
Contract Number:	Funding Cat: P2			
<p>THIS BRIDGE IS CLASSIFIED "SD" BASED ON THE SUPERSTRUCTURE CONDITION. Superstructure is coded as a "4" due to the longitudinal rusty cracks in the soffit of the hollow slab. note Top of slab covered with ACP. Edge of slab Leaching at slab to barrier interface. Vertical and diagonal hairline cracks on both edges of slab. Longitudinal crack in edge of slab at the NW corner approximately 15 ft. long. Soffit. Longitudinal cracks in soffit. Leaching along longitudinal joint at bottom centerline of slab in all spans. Longitudinal rust stained and leaching cracks, almost the full lengths of Span 1 and Span 2. The northeast corner of Span 3 has a spall 4" x 4" x 1/2" deep. The ACP and membrane was removed and replaced in 2011 as part of an I-90 paving project (contract 8046).</p> <p>Rehabilitation of this bridge will include: Steel Column Jackets, removal of the exterior portion of the slab and traffic barrier, widening the bridge to full standards (40 ft?).</p>				



Bridge Preservation Program

Bridge Replacement Form

Bridge Number: 90 / 322S	Structure ID 0005761A	Bridge Name: I-90 OVER SR 261	Milepost: 221.95	Region: Eastern
Year Built / YR Widened: 1958	Bridge Type: Concrete Slab (Hollow)	Number of Main/Apr span 3 / 0	Sufficiency Rating: 40.06 SD	
Bridge Width (curb-curb): 31.7 ft	Bridge Length: 169 ft	Max Span: 66 ft	<p align="center">Bridge Deck View</p>	
Average Daily Traffic: 8,026	Truck% 28%	Number of Lanes: 2		
Vertical Clearance: NA	Detour Length (miles): 2	Apr Rdway Width: 40.0 ft		
Design Load: HS 20	HS: 0.79	Load Restricted Bridge? <input type="checkbox"/>		
Op Rating: 32.00	A1: 1.07	BL Load:	<p align="center">Bridge Profile View</p>	
Inv Rating: 19.00	A2: 1.10	CL-8 Load:		
	A3: 1.10	SA Load:		
Bridge Inspection Information				
Date Inspected: 7/11/2012	Structr Adequacy: 4			
Superstr Code: 4	Safe Load: 5			
Substr Code: 6	Deck Geometry: 2			
Deck Code: 7	Underclearance: 8			
Scour: N	Waterway: 9			
Proposed Bridge Replacement / Rehab Information				
New Bridge Width: 40 ft	Bridge \$'s:			
New Bridge Length: ft.	Total \$'s: \$3,000,000			
Priority Array #: 6				
PIN Number: 609022B	Repl/Rehab Year: 2018			
WIN Number:	Ad Date: 4/3/2017			
Contract Number:	Funding Cat: P2			
<p>THIS BRIDGE IS CLASSIFIED "SD" BASED ON THE SUPERSTRUCTURE CONDITION. Superstructure is coded as a "4" due to the longitudinal rusty cracks in the soffit of the hollow slab. Edge of slab longitudinal crack, approximately 20 ft. long in north edge of Span 1; crack starts near west abutment. Another rust stained crack that is approximately 8 ft. long along north edge of the slab in Span 1. Vertical cracks in edges of the deck. There is a 25ft. long delamination with a rusty area on the north face of Span 3.</p> <p>The ACP and membrane in the right lane was removed and replaced in 2011 as part of an I-90 paving project (contract 8046).</p> <p>Rehabilitation of this bridge will include: Fiberglass Column Jackets, removal of the exterior portion of the slab and traffic barrier, widening the bridge to full standards (40 ft).</p>				



Bridge Preservation Program

Bridge Replacement Form

Bridge Number: 261 / 320	Structure ID 000000EP	Bridge Name: DRY RUN	Milepost: 57.72	Region: Eastern
Year Built / YR Widened: 1900	Bridge Type: Encased Steel Beam	Number of Main/Appr span 2 / 0	Sufficiency Rating: 29.51 SD	
Bridge Width (curb-curb): 24.0 ft	Bridge Length: 32 ft	Max Span: 14 ft		
Average Daily Traffic: 292	Truck% 21%	Number of Lanes: 2		
Vertical Clearance: NA	Detour Length (miles): 8	Appr Rdway Width: 28.0 ft		
Design Load: Unknown	HS: 2.96	Load Restricted Bridge? <input checked="" type="checkbox"/>		
Op Rating: 25.00	A1: 3.52	BL Load: 19,000		
Inv Rating: 15.00	A2: 3.86	CL-8 Load: 21,000		
	A3: 4.28	SA Load: 32,000		
Bridge Inspection Information				
Date Inspected: 6/13/2011	Structr Adequacy: 4			
Superstr Code: 5	Safe Load: 5			
Substr Code: 4	Deck Geometry: 5			
Deck Code: 6	Underclearance: 9			
Scour: 3	Waterway: 6			
Proposed Bridge Replacement / Rehab Information				
New Bridge Width: 36 ft	Bridge \$'s:			
New Bridge Length: 40 ft.	Total \$'s: \$1,440,000			
Priority Array #: 20				
PIN Number:	Repl/Rehab Year:			
WIN Number:	Ad Date:			
Contract Number:	Funding Cat: P2			
<p>THE BRIDGE IS CLASSIFIED "SD" DUE TO A SUBSTRUCTURE CONDITION. The NBI Substructure is a '4' due to the poor condition of the Pier 2 submerged pier wall and the abutments.</p> <p>History of scour at Pier 2. Two span structure with unknown foundations. The concrete slab is 12" thick and is located on the west side of the bridge. The slab soffit is leaching with stalactites up to 2" long. The Midspan 1 edge has hairline leaching longitudinal cracks. The west slab edge near the north abutment has leaching hairline map cacks, some with rust stains.</p> <p>Bridge replacement is needed.</p>				



Special Bridge Repairs - 2013-15 Biennium - Eastern

(Sorted by Priority#)

2013-15 Priority#:	Bridge Number	Bridge Name	Milepost	Region	Repair Description	Total\$'s
45	026/002SP	N FK PALOUSE-WEST WYE	133.47	Eastern	Replace Conc Bridge Rail	\$100,000
56	090/545E-E	FOURTH-E RAMP	280.54	Eastern	Repair deteriorated conc in CBOX	\$300,000
57	290/001W-W	W-W RAMP OVER SR 290 W	0.07	Eastern	Repair deteriorated Conc Box	\$400,000
62	090/540S	HANGMAN CR	279.49	Eastern	Repair deteriorated conc in CBOX	\$300,000
78	002/601	STEVENS CR UPPER X-ING	267.23	Eastern	Replace Conc Bridge Rail	\$50,000
80	195/027	N FK PALOUSE R	38.50	Eastern	Replace Conc Bridge Rail	\$200,000
81	195/024	S FK PALOUSE R CT HOUSE	38.09	Eastern	Repair deteriorated Conc	\$200,000
82	021/321	W FK SAN POIL	145.62	Eastern	Replace Conc Bridge Rail	\$100,000
83	021/323	SAN POIL R	148.45	Eastern	Replace Conc Bridge Rail	\$100,000
9 Repairs					Sum of Bridge \$'s =	\$1,750,000


Special Bridge Repairs - 2013-15 Biennium - Eastern

(Sorted by Bridge#)

2013-15 Priority#:	Bridge Number	Bridge Name	Milepost	Region	Repair Description	Total\$'s
78	002/601	STEVENS CR UPPER X-ING	267.23	Eastern	Replace Conc Bridge Rail	\$50,000
82	021/321	W FK SAN POIL	145.62	Eastern	Replace Conc Bridge Rail	\$100,000
83	021/323	SAN POIL R	148.45	Eastern	Replace Conc Bridge Rail	\$100,000
45	026/002SP	N FK PALOUSE-WEST WYE	133.47	Eastern	Replace Conc Bridge Rail	\$100,000
62	090/540S	HANGMAN CR	279.49	Eastern	Repair deteriorated conc in CBOX	\$300,000
56	090/545E-E	FOURTH-E RAMP	280.54	Eastern	Repair deteriorated conc in CBOX	\$300,000
81	195/024	S FK PALOUSE R CT HOUSE	38.09	Eastern	Repair deteriorated Conc	\$200,000
80	195/027	N FK PALOUSE R	38.50	Eastern	Replace Conc Bridge Rail	\$200,000
57	290/001W-W	W-W RAMP OVER SR 290 W	0.07	Eastern	Repair deteriorated Conc Box	\$400,000
9 Repairs					Sum of Bridge \$'s =	\$1,750,000

Bridge Preservation Program (P2)

Bridge Repair Form

Bridge Number: 26 / 2SP		Structure ID 0002385B		Bridge Name: N FK PALOUSE-WEST WYE		Milepost: 38.50		Region: Eastern	
Year Built / YR Widened: 1938		Bridge Type: CTB		Bridge Length: 114 ft		Bridge Width (curb-curb): 26.0 ft		Sufficiency Rating: 60.45 FO	
Average Daily Traffic 9,105		Truck% 9%		Freight Route		Num of Lanes 2			
Date Inspected: 7/27/2010		Structr Adequacy: 5		Superstr Code: 6		Safe Load: 5			
Substr Code: 6		Scour: 8		BMS Element Num: 331		BMS Element Descr: Concrete Bridge Rail			
BMS Element Quantity: 228 Feet		Project Number:		2013-15 Priority#: 35		2011-13 Priority#: 84			
Repair Year: 2016		CPMS Ad Date:		Bridge \$'s: \$100,000		Repair Total\$'s: \$300,000			
									
<p>Repair Description: Replace the deteriorated concrete bridge rails and Sidewalk</p>									
<p>COMMENTS</p> <p>The concrete bridge rail and sidewalk is deteriorated and in need of replacement.</p>									

Bridge Preservation Program (P2)

Bridge Repair Form

Bridge Number: 90 / 540N		Structure ID 0006579B		Bridge Name: HANGMAN CR		Milepost: 279.49		Region: Eastern	
Year Built / YR Widened: 1963		Bridge Type: CBOX			Bridge Length: 1,222 ft		Bridge Width (curb-curb): 44.0 ft		Sufficiency Rating: 44.58 SD
Average Daily Traffic 24,152	Truck% 13%	Freight Route T-1		Num of Lanes 3					
Date Inspected: 10/6/2009		Structr Adequacy: 4							
Superstr Code: 5		Safe Load: 5							
Substr Code: 4		Scour: 7							
BMS Element Num: 105		BMS Element Descr: Concrete Box Girder							
BMS Element Quantity: 2									
Project Number:		2013-15 Priority#: 25		2011-13 Priority#: 33		Bridge \$'s: \$150,000		Repair Total\$'s: \$200,000	
Repair Year: 2016									
CPMS Ad Date:									
									
Repair Description:									
Remove loose concrete, clean rusty steel and apply a patching material and sealer.									
COMMENTS									
The strip seal expansion joints over the interior hinges were replaced in 1999. Shortly after the expansion joints were replaced the gap in the hinged area closed.									
Use assumed costs of \$150,000 and \$300,000 until better estimates are developed.									

Bridge Preservation Program (P2)

Bridge Repair Form

Bridge Number: 90 / 540S		Structure ID 0006579B		Bridge Name: HANGMAN CR		Milepost: 279.49		Region: Eastern	
Year Built / YR Widened: 1963		Bridge Type: CBOX		Bridge Length: 1,222 ft		Bridge Width (curb-curb): 44.0 ft		Sufficiency Rating: 44.58 SD	
Average Daily Traffic 24,152		Truck% 13%		Freight Route T-1		Num of Lanes 3			
Date Inspected: 10/6/2009		Structr Adequacy: 4		Superstr Code: 5		Safe Load: 5			
Substr Code: 4		Scour: 7		BMS Element Num: 105		BMS Element Descr: Concrete Box Girder			
BMS Element Quantity: 2		Project Number:		2013-15 Priority#: 26		2011-13 Priority#: 34			
Repair Year: 2016		CPMS Ad Date:		Bridge \$'s: \$150,000		Repair Total\$'s: \$200,000			
									
<p>Repair Description: Remove loose concrete, clean rusty steel and apply a patching material and sealer.</p>									
<p>COMMENTS</p>									
<p>The strip seal expansion joints over the interior hinges were replaced in 1999. Shortly after the expansion joints were replaced the gap in the hinged area closed.</p> <p>Use assumed costs of \$150,000 and \$300,000 until better estimates are developed.</p>									

P2 Bridge Preservation - Concrete Deck Repair / Overlay Projects

2013-15 Bien Priority Array

(Sorted by Priority Number)



13-15 #	Bridge Number	Bridge Name	Mile post	Region	Width	Length	Total\$'s
1	90/316N	N PAHA PACKARD RD OC	215.24	Eastern	38.0	105	\$334,500
1	90/316S	N PAHA PACKARD RD OC	215.24	Eastern	38.0	105	\$334,500
1	90/512N	BN RR OC (NP)	270.10	Eastern	36.5	150	\$473,000
1	90/512S	BN RR OC (NP)	270.10	Eastern	36.5	150	\$473,000
1	395/545	COLUMBIA R KETTLE FALLS	241.49	Eastern	24.0	1267	\$2,586,000
8	290/2W-W	2ND AVE OC	0.07	Eastern	38.0	167	\$716,661
9	290/1W-W	W-W RAMP OVER SR 290 WB	0.07	Eastern	38.0	518	\$402,800
14	90/314S	I-90 OVER N WAHL RD	210.03	Eastern	38.0	127	\$500,000
31	90/336N	BN RR OC (NP)	237.24	Eastern	33.0	320	\$1,019,700
39	395/212N-W	US 395 RAMP OVER I-90	95.00	Eastern	32.7	308	\$1,007,200
41	21/4	SAND HILLS COULEE # 3	2.72	Eastern	24.0	85	\$266,671
43	90/336S	BN RR OC (NP)	237.24	Eastern	33.0	320	\$844,800
45	21/224	SINKING CR	85.16	Eastern	26.0	82	\$278,694
Total Number of Bridges = 13						Totals \$ =	\$9,237,526

P2 Bridge Preservation - Concrete Deck Repair / Overlay Projects

2013-15 Bien Priority Array

(Sorted by Bridge Number)



13-15 #	Bridge Number	Bridge Name	Mile post	Region	Width	Length	Total\$'s
41	21/4	SAND HILLS COULEE # 3	2.72	Eastern	24.0	85	\$266,671
45	21/224	SINKING CR	85.16	Eastern	26.0	82	\$278,694
14	90/314S	I-90 OVER N WAHL RD	210.03	Eastern	38.0	127	\$500,000
1	90/316N	N PAHA PACKARD RD OC	215.24	Eastern	38.0	105	\$334,500
1	90/316S	N PAHA PACKARD RD OC	215.24	Eastern	38.0	105	\$334,500
31	90/336N	BN RR OC (NP)	237.24	Eastern	33.0	320	\$1,019,700
43	90/336S	BN RR OC (NP)	237.24	Eastern	33.0	320	\$844,800
1	90/512N	BN RR OC (NP)	270.10	Eastern	36.5	150	\$473,000
1	90/512S	BN RR OC (NP)	270.10	Eastern	36.5	150	\$473,000
9	290/1W-W	W-W RAMP OVER SR 290 WB	0.07	Eastern	38.0	518	\$402,800
8	290/2W-W	2ND AVE OC	0.07	Eastern	38.0	167	\$716,661
39	395/212N-W	US 395 RAMP OVER I-90	95.00	Eastern	32.7	308	\$1,007,200
1	395/545	COLUMBIA R KETTLE FALLS	241.49	Eastern	24.0	1267	\$2,586,000
Total Number of Bridges = 13					Totals \$ =		\$9,237,526



<p style="text-align: center;">BRIDGE DATA</p> <p>BRIDGE NUMBER: 90/336S MP: 237.40 BRIDGE NAME: BN RR OC (NP) REGION: Eastern YEAR BUILT / YR WIDENED: 1968 SUFFICIENCY RATING: 70.32 SD BRIDGE TYPE: PCG BRIDGE WIDTH: 33.0 ft. BRIDGE LENGTH: 320 ft. AVERAGE DAILY TRAFFIC: 8,210 NUMBER OF LANES: 2 SIDEWALK / CURB WIDTH: 0.7 Lt 0.7 Rt CURB HEIGHT: in</p>	<p style="text-align: center;">BRIDGE PHOTO</p> 														
<p style="text-align: center;">PAVING VERTICAL CLEARANCE</p> <p>VC to pavement under bridge: Not Available VC over bridge deck: Not Available</p>	<p style="text-align: center;">WEARING SURFACE or DECK PROTECTION</p> <p>SURFACE TYPE: MMC Overlay 1ST YEAR BRIDGE OVERLAY 1993 OVERLAY CONTRACT HISTORY</p> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:25%;">10/1/1992</td> <td style="width:25%;">014157</td> <td style="width:50%;">LMC OR MMC OLAY</td> </tr> <tr> <td>1/1/1978</td> <td>011147</td> <td>ACP/MEMBRANE</td> </tr> </table>	10/1/1992	014157	LMC OR MMC OLAY	1/1/1978	011147	ACP/MEMBRANE								
10/1/1992	014157	LMC OR MMC OLAY													
1/1/1978	011147	ACP/MEMBRANE													
<p style="text-align: center;">BRIDGE RAIL</p> <p>BRIDGE RAIL TYPE: Conc Base - Type R RAIL MEETS CURRENT STANDARDS? YES RAIL CONTRACT HISTORY</p>	<p style="text-align: center;">BRIDGE RESURFACING / DECK COMMENTS</p>														
<p style="text-align: center;">EXPANSION JOINTS</p> <p>Coordinate with your Region's Maintenance Office to determine if any repairs are required.</p> <p>EXPANSION JOINT CONTRACT HISTORY</p> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:25%;">10/1/1992</td> <td style="width:25%;">014157</td> <td style="width:50%;">EXP JOINTS-COMP SEAL</td> </tr> </table>		10/1/1992	014157	EXP JOINTS-COMP SEAL											
10/1/1992	014157	EXP JOINTS-COMP SEAL													
<p>BRG NUMBER: 90 / 336S BRIDGE DECK HMA PAVING DESIGN OPTIONS Max. Bridge HMA Depth:</p> <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th rowspan="2">DESCRIPTION</th> <th rowspan="2">PAVING CLASSIFICATION</th> <th rowspan="2">EXISTING HMA DEPTH</th> <th colspan="2">MAX. PLANE DEPTH</th> <th rowspan="2">PAVING HMA DEPTH</th> </tr> <tr> <th>PART./FULL</th> <th>DEPTH</th> </tr> </thead> <tbody> <tr> <td></td> <td></td> <td style="text-align: center;">0.13</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>		DESCRIPTION	PAVING CLASSIFICATION	EXISTING HMA DEPTH	MAX. PLANE DEPTH		PAVING HMA DEPTH	PART./FULL	DEPTH			0.13			
DESCRIPTION	PAVING CLASSIFICATION				EXISTING HMA DEPTH	MAX. PLANE DEPTH		PAVING HMA DEPTH							
		PART./FULL	DEPTH												
		0.13													
<p style="text-align: center;">BRIDGE CONTACTS</p> <p>Bridge Projects and Design Ron Lewis 360.705.7396 Bridge Rail/Barrier and Retrofit David Sawahata 360.705.6941 Vertical Clearance George Comstock 360.570.2540 BCRs - Brg HMA - P2 Bruce Thill 360.705.7393 Bridge Website: http://wwwi.wsdot.wa.gov/eesc/bridge/</p>	<p>See Bridge website for information on Bridge HMA Overlay Policies/Specs, Scoping, Region Design, and Construction Inspection: http://wwwi.wsdot.wa.gov/eesc/bridge/bridgeoverlays/</p> <p>REVIEWED BY: <i>Bruce Thill</i> DATE: 6/21/2011</p>														



<p style="text-align: center;">BRIDGE DATA</p> <p>BRIDGE NUMBER: 395/212N-W MP: 95.00 BRIDGE NAME: US 395 RAMP OVER I-90 REGION: Eastern YEAR BUILT / YR WIDENED: 1958 SUFFICIENCY RATING: 89.44 SD BRIDGE TYPE: CBOX BRIDGE WIDTH: 32.7 ft. BRIDGE LENGTH: 308 ft. AVERAGE DAILY TRAFFIC: 751 NUMBER OF LANES: 2 SIDEWALK / CURB WIDTH: 0.0 Lt 0.0 Rt CURB HEIGHT: in</p>	<p style="text-align: center;">BRIDGE PHOTO</p> 														
<p style="text-align: center;">PAVING VERTICAL CLEARANCE</p> <p>VC to pavement under bridge: Not Available VC over bridge deck: Not Available</p>	<p style="text-align: center;">WEARING SURFACE or DECK PROTECTION</p> <p>SURFACE TYPE: LMC Overlay 1ST YEAR BRIDGE OVERLAY 1984 OVERLAY CONTRACT HISTORY</p>														
<p style="text-align: center;">BRIDGE RAIL</p> <p>BRIDGE RAIL TYPE: New Jersey Barrier RAIL MEETS CURRENT STANDARDS? YES RAIL CONTRACT HISTORY</p>	<p style="text-align: center;">BRIDGE RESURFACING / DECK COMMENTS</p> <p>Exclude bridge from resurfacing projects.</p>														
<p style="text-align: center;">EXPANSION JOINTS</p> <p>EXPANSION JOINT CONTRACT HISTORY</p>															
<p>BRG NUMBER: 395 / 212N-W BRIDGE DECK HMA PAVING DESIGN OPTIONS Max. Bridge HMA Depth:</p>															
<table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th rowspan="2">DESCRIPTION</th> <th rowspan="2">PAVING CLASSIFICATION</th> <th rowspan="2">EXISTING HMA DEPTH</th> <th colspan="2">MAX. PLANE DEPTH</th> <th rowspan="2">PAVING HMA DEPTH</th> </tr> <tr> <th>PART./FULL</th> <th>DEPTH</th> </tr> </thead> <tbody> <tr> <td></td> <td></td> <td style="text-align: center;">0.13</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>		DESCRIPTION	PAVING CLASSIFICATION	EXISTING HMA DEPTH	MAX. PLANE DEPTH		PAVING HMA DEPTH	PART./FULL	DEPTH			0.13			
DESCRIPTION	PAVING CLASSIFICATION				EXISTING HMA DEPTH	MAX. PLANE DEPTH		PAVING HMA DEPTH							
		PART./FULL	DEPTH												
		0.13													
<p style="text-align: center;">BRIDGE CONTACTS</p> <p>Bridge Projects and Design Ron Lewis 360.705.7396 Bridge Rail/Barrier and Retrofit David Sawahata 360.705.6941 Vertical Clearance George Comstock 360.570.2540 BCRs - Brg HMA - P2 Bruce Thill 360.705.7393 Bridge Website: http://wwwi.wsdot.wa.gov/eesc/bridge/</p>	<p>See Bridge website for information on Bridge HMA Overlay Policies/Specs, Scoping, Region Design, and Construction Inspection: http://wwwi.wsdot.wa.gov/eesc/bridge/bridgeoverlays/</p> <p>REVIEWED BY: <i>Bruce Thill</i> DATE: 6/21/2011</p>														

P2 Bridge Preservation - Steel Bridge Painting Projects

2013-15 Bien Priority Array

(Sorted by Priority Number)




13-15 #	Bridge Number	Bridge Name	Mile Post	Region	Yr Work Planned	Total Project\$
25	21/334	KETTLE R	181.00	Eastern	2018	\$1,260,000
47	395/545	COLUMBIA R KETTLE FALLS	241.49	Eastern	2022	\$10,712,000
53	25/130	COLUMBIA R @ NORTHPORT	113.92	Eastern	2024	\$7,585,500
Total Number of Bridges = 3					Total Project \$ =	\$19,557,500

P2 Bridge Preservation - Steel Bridge Painting Projects

2013-15 Bien Priority Array

(Sorted by Bridge Number)



13-15 #	Bridge Number	Bridge Name	Mile Post	Region	Yr Work Planned	Total Project\$
25	21/334	KETTLE R	181.00	Eastern	2018	\$1,260,000
53	25/130	COLUMBIA R @ NORTHPORT	113.92	Eastern	2024	\$7,585,500
47	395/545	COLUMBIA R KETTLE FALLS	241.49	Eastern	2022	\$10,712,000
Total Number of Bridges = 3					Total Project \$ =	\$19,557,500



Steel Bridge Paint Form

2013-15 Biennium Priorities




Bridge Number: 21 / 334		Bridge Name: KETTLE R		Milepost: 181.00	Region: Eastern
Year Built 1960	Bridge Type: ST	Steel Span Length: 205 ft.	Width (curb-curb): 26 ft.	Steel Tonnage: 180	
Paint Age: 21	Paint Color: 30099 Warm Brown	Steel Surf. Area: 27,000 sqft	BMS Cond State 2: 21,600 sqft	BMS Cond State 3: 5,400 sqft	
Next Paint Year: 2018	2013-15 Rank: 25	Past Due / Due / OK Past Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$1,260,000

Past Paint History

Years	Cycle
1990	11
1979	10
1969	9
1960	

Painting Cycle



■ = Current Paint Age



The top flange of the floor beams and stringers are embedded in concrete.

Bridge Inspector's Notes:

Paint is chalky and peeling, heavy in spots, on the diagonals and portals of the truss with rust blooms, approximately 15%. The paint on the stringers and floor beams is in good condition except for scattered rock chips from kids throwing rocks at swallow nests. The sand build up on the lower chord has been flushed, revealing the failed paint system.

Full removal of the paint is warranted on the top and bottom chords and the connection areas.

Steel Bridge Paint Form

2013-15 Biennium Priorities




Bridge Number: 25 / 130		Bridge Name: COLUMBIA R @ NORTHPORT		Milepost: 113.92	Region: Eastern
Year Built 1948	Bridge Type: ST CTB CG CS		Steel Span Length: 840 ft.	Width (curb-curb): 24 ft.	Steel Tonnage: 1,167
Paint Age: 19	Paint Color: Evergreen	34097	Steel Surf. Area: 175,050 sqft	BMS Cond State 2: 10,000 sqft	BMS Cond State 3: 930 sqft
Next Paint Year: 2024	2013-15 Rank: 53	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$7,585,500

Past Paint History

Years	Cycle
1992	13
1979	8
1971	9
1962	11
1951	

Painting Cycle



■ = Current Paint Age



Bridge Inspector's note:

Paint is missing from most steel members due to the impact of snow removal with gravel. Steel Floorbeams; Peeling paint throughout webs. Steel Truss Members; The primer is exposed in places with some light rust where the paint has failed completely. The top paint coat is also peeling off in places with scattered rust blooms, particularly at top sways and laterals and inside top chords. Surface rust on the truss members at the deck level to about 6 ft. off of the deck. Paint is peeling inside most of the enclosed truss members. Metal Bridge Railing; All members are rusty with paint peeling or missing on 30% of the surface.

Steel Bridge Paint Form

2013-15 Biennium Priorities




Bridge Number: 395 / 545		Bridge Name: COLUMBIA R KETTLE FALLS		Milepost: 241.49	Region: Eastern
Year Built 1941	Bridge Type: ST CTB		Steel Span Length: 1051 ft.	Width (curb-curb): 24 ft.	Steel Tonnage: 1,648
Paint Age: 23	Paint Color: Evergreen	34097	Steel Surf. Area: 247,200 sqft	BMS Cond State 2: 9,600 sqft	BMS Cond State 3: 2,400 sqft
Next Paint Year: 2022	2013-15 Rank: 47	Past Due / Due / OK Due	CPMS Ad date:	Paint Pin Number:	Future Paint Cost: \$10,712,000

Past Paint History

Years	Cycle
1988	11
1977	11
1966	15
1951	10
1941	

Painting Cycle



■ = Current Paint Age



No Photo Available

P2 Bridge Preservation - Seismic Retrofit

2013-15 Bien Priority Array (priority 1-100)

(Sorted by Bridge Number)

13-15 #	Bridge Number	Bridge Name	Mile post	Region	Bridge Item\$'s	Total\$'s
------------	------------------	-------------	--------------	--------	-----------------	-----------

Total Number of Bridges = 0

Total\$ =

\$0

\$0



WSDOT Scour Projects - 2013-15 Bien

(Sorted by Priority Number)



13-15 #	Bridge Number	Bridge Name	Length	Mile post	Region	PIN #	Year Planned	Project Total\$'s
------------	------------------	-------------	--------	--------------	--------	-------	-----------------	-------------------

Total Number of Bridges = 0

Total Bien\$'s = \$0

P2 Bridge Preservation - Misc Structures Projects

2013-15 Bien Priority Array - Eastern Region

(Sorted by Priority Number)

13-15 #	Bridge Number	Bridge Name	Mile post	Region	Length	Total \$
1	21/332.75	CURLEW CREEK	172.85	Eastern	70	\$712,050

Total Number of Bridges = 1



Bridge Number: 21 / 332.75		Structure ID 00200373		Bridge Name: CURLW CREEK		Milepost: 172.85		Region: Eastern	
Year Built / YR Widened: 1950		Bridge Type: SCulv CCulv		Bridge Length: 17 ft		Bridge Width (curb-curb): 22.0 ft		Sufficiency Rating: 65.22	
Average Daily Traffic: 580		Detour (miles) 93		Num of Lanes: 2					
Date Inspected:		Structr Adequacy:		3					
Superstr Code: 9		Safe Load:		5					
Substr Code: 9		Scour:		2					
Project Number: 602117C		2013-15 Priority#:		1					
Repair Year: 2012		2011-13 Priority#:		1					
CPMS Ad Date: 5/21/2012		Bridge \$'s:							
		Repair Total\$'s:		\$712,050					
									
<p>Repair Description: Replace the 4 existing Culverts with a new three-sided box.</p>									
<p>COMMENTS</p>									
<p>Replace the 4 existing culverts and install a new three-sided box culvert. The channel will be realigned to prevent bank erosion and scour potential. Reconstruct lanes and shoulders of SR 21. Build a detour around the construction area.</p> <p>Scheduled to be replaced in 2012.</p>									

