

Views From the Proposed Alignment Structure**Interstate-90 Mainline**

A - Liberty Park Rock Cliffs and Historic Powerstation Building. High Vividness, Medium Intactness and Unity for Foreground, Middleground, and Background. Noise barriers may detract from the Travelers access to the views.

Alternative 7 Havana Route

B - Industrial/Railroad area spanned by proposed Viaduct roadway structure. Lane barriers may block visual access to eyesores in Foreground and Middleground. Background view of Beacon Hill High for Intactness and Unity, Medium for Vividness.

C - View of Spokane River Eastward borders on Industrial area. High Intactness and Unity in Foreground, Low Vividness, Intactness, and Unity in Middleground due to Industrial views. Far distant Background views High in Intactness and Unity.

D - View of Spokane River Westward. College Campus and Residential areas separated by Spokane River. High Intactness and Unity in Foreground, Low Intactness and Unity in Middleground.

E - Minnehaha Park area with high quality Historic structure in Day-Use area, and Undeveloped area. High Vividness, Intactness and Unity. Proposed Roadway Alignment willtraverse park with a depressed structure, lowering Visual attributes and values.

F - Rural Residential bordering "Esmeralda" Golf Course, Industrial and "Little Baldy" Undeveloped areas. Undeveloped area High for Intactness and Unity.

G - Petroleum Storage tanks in Rural setting bordering Industrial area. Low Vividness, Intactness, and Unity.

Views from the Project

Interstate 90 Mainline



Photograph A

Liberty Park viewpoint, from I-90 looking southward.