AN ILLUSTRATION OF SUFFICIENCY RATING (SR) FACTORS



SR must be ≥ 0 and ≤ 100
If $S1 + S2 + S3 \geq 50$, then subtract S4
Otherwise $SR = S1 + S2 + S3$