

Figure 3.3-3 Earthquake Resisting Elements that are not Recommended for New Bridges