
SR 706
MP 14.70
Mineral
MP 12.80
MP 11.60
Coal Creek
MP 11.40
MP 11.20
MP 10.80
WRIA 11
MP 10.25
WRIA 26
MP 9.85
MP 9.70
Tilton River
MP 8.89
MP 7.36
MP 6.91
MP 5.50
MP 5.64
MP 3.36
SR 508
Morton
US 12
FISH PASSAGE BARRIER CULVERTS
Repair required - threshold habitat gain met
Limited gain - below threshold habitat gain
Undetermined repair status -
threshold habitat gain not determined