STATE OF WASHINGTON - DEPARTMENT OF TRANSPORTATION
T R I P S S Y S T E M
STANDARD ACCIDENT HISTORY DETAIL REPORT
CURRENT ACCIDENT LOCATION
SORTED BY SR/RRT/RRQ/SRMP/DATE
JAN 01, 2002 THRU JUN 30, 2002

PROJECT #:
PROJECT DESC:
CRITERIA: STATE ROUTE 005 MAINLINE AND ALL RAMPS,CD,SP,CO
/SRMP 000.00 TO 000.50

*UNDER 23 UNITED STATES CODE - SECTION 409, THIS
*DATA CANNOT BE USED IN DISCOVERY OR AS EVIDENCE
*AT TRIAL IN ANY ACTION FOR DAMAGES AGAINST THE
*WSDOT OR THE STATE OF WASHINGTON.

CURRENT STATE ROUTE	SEQ	CURR SRMP	A/B	PRE1	U/R	ACCDNT REPORT NUMBER	DATE MM/DD/YY	TIME	DIAGRAM ANALYSIS DATA	RAMP	MSEV	#INJ	#FAT	#VEH	VEH TYPE #1	VEH TYPE #2	JUNCT RELAT	RDWY SURF	LIGHT COND	PRTL	ACCIDENT DESCRIPTION
005	00	0.01			U	011114	04/01/02	13:27	5BA065BQD1		7	7	0	4	02	02	NON INT	DRY	DAYLT		SM DIR-B STR-1 MOV-REND
005	00	0.05			U	003013	02/05/02	08:14	5BA065BQD2		1	0	0	3	02	01	NON INT	DRY	DAYLT		SM DIR-B STR-1 MOV-REND
005	00	0.10			U	014843	04/04/02	09:39	5BA065BND3		1	0	0	2	01	14	NON INT	DRY	DAYLT		SM DIR-B STR-1 MOV-REND
005	00	0.10			U	014850	04/04/02	09:38	5BA065BAD3		7	1	0	3	14	01	NON INT	DRY	DAYLT		SM DIR-B STR-B MOV-REND
005	00	0.10			U	011663	04/25/02	01:30	1AZ061AQA3		1	0	0	2	01	03	NON INT	DRY	ST.LT		SM DIR-B STR-1 MOV-REND
005	00	0.10			U	019106	06/17/02	14:04	5BA065BAD1		1	0	0	2	02	06	NON INT	WET	DAYLT		SM DIR-B STR-B MOV-REND
005	00	0.12			U	019632	06/07/02	13:34	5BA065BAD3		1	0	0	3	02	01	NON INT	DRY	DAYLT		SM DIR-B STR-B MOV-REND
005	00	0.13			U	C01049	03/23/02	16:15	5BQ165BAD2		7	1	0	2	01	01	NON INT	DRY	DAYLT		SM DIR-B STR-1 MOV-REND
005	00	0.14			U	C00537	02/15/02	17:00	1AQ161AAA1		7	1	0	3	02	02	NON INT	DRY	DAYLT		SM DIR-B STR-1 MOV-REND
005	00	0.15			U	006430	01/16/02	06:07	5BA065BAD1		7	2	0	3	06	02	NON INT	DRY	DAWN		SM DIR-B STR-B MOV-REND
005	00	0.17			U	005651	01/26/02	12:49	5BA065BQD1		1	0	0	2	01	02	NON INT	WET	DAYLT		SM DIR-B STR-1 MOV-REND
005	00	0.19			U	007814	05/04/02	22:05	1AA061AAA3		7	1	0	2	01	01	NON INT	DRY	ST.LT		SM DIR-B STR-B MOV-REND
005	00	0.22			U	014950	05/17/02	11:12	5BA065BQD1		7	1	0	5	03	02	NON INT	DRY	DAYLT		SM DIR-B STR-1 MOV-REND
005	00	0.24			U	018642	06/02/02	12:17	5BA065BAD1		1	0	0	2	01	02	NON INT	DRY	DAYLT		SM DIR-B STR-B MOV-REND
005	00	0.25			U	005034	01/26/02	13:59	5BA33000D7		1	0	0	2	01	02	NON INT	WET	DAYLT		BRIDGE RAIL, SURFACE
005	00	0.25			U	011038	03/02/02	13:20	5BA065BQD1		7	5	0	3	02	01	NON INT	DRY	DAYLT		SM DIR-B STR-1 MOV-REND
005	00	0.25			U	012669	04/24/02	14:05	1AA061AAA1		1	0	0	2	02	02	NON INT	DRY	DAYLT		SM DIR-B STR-B MOV-REND
005	00	0.25			U	018639	06/02/02	12:17	5BA065BND1		1	0	0	2	02	01	NON INT	DRY	DAYLT		SM DIR-B STR-1 MOV-REND
005	00	0.26			U	005722	01/26/02	12:49	5BA065BQD1		1	0	0	2	01	02	NON INT	WET	DAYLT		SM DIR-B STR-1 MOV-REND
005	00	0.27			U	010744	03/02/02	13:20	5BA065BAD2		6	3	0	3	02	02	NON INT	DRY	DAYLT		SM DIR-B STR-B MOV-REND
005	00	0.27			U	018099	06/21/02	14:45	5BA065BAD1		7	1	0	3	03	02	NON INT	DRY	DAYLT		SM DIR-B STR-B MOV-REND
005	00	0.28			U	009826	03/16/02	16:37	1AA061AQA3		1	0	0	2	01	02	NON INT	WET	DAYLT		SM DIR-B STR-1 MOV-REND
005P100028	00	0.09			U	018947	06/28/02	19:57	2AZ33000P9		1	0	0	1	01		NON INT	WET	DUSK		CONCRETE BARRIER, THRU
005	00	0.29			U	C01583	04/25/02	10:35	5BQ165BAD3		7	1	0	2	01	02	NON INT	DRY	DAYLT		SM DIR-B STR-1 MOV-REND
005S500029	00	0.04			U	000607	01/15/02	22:10	8AA33000S8		1	0	0	1	02		NON INT	DRY	ST.LT		CONCRETE BARRIER,SURFACE
005S500029	00	0.04			U	C01854	05/02/02	01:00	8AQ168AAS1		1	0	0	3	01	00	NON INT	DRY	DAYLT		SM DIR-B STR-1 MOV-REND
005S500029	00	0.05			U	011338	04/06/02	02:32	1AZ33000S8		1	0	0	1	01		NON INT	DRY	ST.LT		CONCRETE BARRIER,SURFACE
005S500029	00	0.17			U	018938	06/30/02	00:52	4AZ33000S8		1	0	0	1	01		NON INT	DRY	ST.LT		CONCRETE BARRIER,SURFACE
005S500029	00	0.20			U	C02032	06/19/02	06:20	6AS046AAS1	E	1	0	0	2	01	02	INT NR	DRY	DAWN		SM DIR-B STR-B MOV-SDSWP
005	00	0.30			U	000989	01/05/02	11:30	5BX33000D8		1	0	0	1	01		NON INT	WET	DAYLT		CONCRETE BARRIER,SURFACE
005	00	0.35			U	004880	01/26/02	12:34	6BA066BAD1		1	0	0	2	01	02	INT NR	WET	DAYLT		SM DIR-B STR-B MOV-REND
005	00	0.35			U	004911	02/20/02	08:30	5BZ065BAD1		1	0	0	2	01	04	AT INT	DRY	DAYLT		SM DIR-ALL OTHERS
005	00	0.36			U	016957	05/19/02	14:25	5BA065BAD1		1	0	0	2	01	03	NON INT	WET	DAYLT		SM DIR-B STR-B MOV-REND
005	00	0.37			U	C00620	02/07/02	09:15	5BK146BAD1		0	0	0	2	02	06	AT INT	WET	DAYLT		SM DIR-B STR-B MOV-SDSWP
005	00	0.37			U	C01577	04/25/02	16:55	5BK145BAD1		1	0	0	2	00	00	AT INT	DRY	DAYLT		SM DIR-B STR-B MOV-SDSWP
005	00	0.39			U	009937	03/12/02	20:18	1AA061AAA2		7	3	0	2	01	02	NON INT	WET	ST.LT		SM DIR-B STR-B MOV-REND
005	00	0.39			U	010772	03/27/02	10:10	5BA065BAD1		7	1	0	2	02	01	AT INT	DRY	DAYLT		SM DIR-B STR-B MOV-REND
005P500039	00	0.30			U	007819	05/05/02	02:10	8AZ33000P8	Y	6	1	0	1	02		AT INT	WET	ST.LT		CONCRETE BARRIER,SURFACE
005	00	0.43			U	010718	03/02/02	00:10	2AZ34000P0		1	0	0	1	01		NON INT	DRY	ST.LT		EARTH BANK OR LEDGE
005	00	0.45			U	011104	04/01/02	11:46	5BA065BQD3		7	1	0	2	01	02	NON INT	DRY	DAYLT		SM DIR-B STR-1 MOV-REND
005	00	0.50			U	000681	01/02/02	15:21	1AA061AQA3		1	0	0	2	02	02	NON INT	DRY	DAYLT		SM DIR-B STR-1 MOV-REND

Sample