

1 (November 17, 1997)
2 Welded wire fabric for the slope facing, including all facing anchor pins and tie-bars,
3 shall conform to the requirements of AASHTO M55. Welded wire fabric, anchor
4 pins, and tie-bars shall be galvanized after fabrication in accordance with ASTM A
5 641 (2 oz./ft² minimum). All damage to galvanizing shall be repaired with formula
6 A-9-73 Galvanizing Repair Paint in accordance with Section 9-08.2.