

1  
2  
3

(April 3, 2017)

- Any HMA for which the specified course thickness is greater than 0.10 feet and the HMA is placed in the shoulder.