

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17

(April 6, 2015)

Column Jacket Shop Drawings

The Contractor shall submit column jacket shop drawings as Type 2 Working Drawings. The shop drawings shall include, at a minimum, the following:

1. Plan, elevation, and sections of the jacket system and all components, with all dimensions and tolerances.
2. Field measurements of the existing column(s).
3. All material designations.
4. Location of horizontal and vertical splices.
5. Location of spacers and method of attachment.
6. Welds and welding procedures.