

1  
2  
3  
4  
5  
6  
7

(September 8, 2020)

These tolerance and specification limits constitute the allowable limits as described in Section 1-06.2. The tolerance limit for aggregate shall not exceed the limits of the control points, except the No. 8 tolerance is  $\pm 4\%$  from the JMF, the No. 200 tolerance is  $\pm 2.0\%$  from the JMF with a minimum of 2% and a maximum of 8.0% passing the No. 200 sieve, other tolerance limits for sieves designated as 100 percent passing will be 99-100.