WSDOT Errata to WAQTC TM 15

Laboratory Theoretical Maximum Dry Density of Granular Soil and Soil/Aggregate

WAQTC TM 15 has been adopted by WSDOT with the following changes:

Apparatus

Replace with below:

- Small Mold Assembly: includes mold, mold base, and mold follower.
 - Mold Follower: Steel plate, with a 12 ±1 mm (0.460 ±0.03 in.) edge thickness fitting inside the mold with 1.5 mm (0.063 in.) maximum space between mold follower and mold wall.
 For new followers, the diameter tolerance is 1 mm to 2 mm (- 0.031 in. to 0.063 in.) of the inside diameter of the matching mold.

In-service followers shall have a minimum edge thickness of 10.7 mm (0.420 in.).

- Large Mold Assembly: includes mold, mold base, and mold follower.
 - Mold Follower: Steel plate, with 14 ± 1 mm (0.550 ± 0.030 in.) edge thickness fitting inside the mold with 1.5 mm (0.063 in.) max. space between mold follower and mold wall. For new followers, the diameter tolerance is 1 mm to 2 mm (– 0.031 in. to 0.063 in.) of the inside diameter of the matching mold.

In-service followers shall have a minimum edge thickness of 12.6 mm (0.496 in.).

Sample Preparation

Replace step one with below:

Obtain a representative sample according to Table 3 below.

Table 3 TM15 Sample Size			
Minimum Mass Ib (kg			
If no more than 15 percent by weight	210	95	
of aggregate exceeds 19 mm (¾ in.)	210	73	
If 15 percent or more by weight of	330	150	
aggregate exceeds 19 mm (¾ in.)	330	130	

Theoretical Maximum Density Curve Development

Replace with below:

WSDOT Employees – Enter laboratory data into MATS to develop the maximum density chart and maximum density curve.

Non-WSDOT Employees – Enter laboratory data into WAQTC spreadsheet to develop the maximum density chart and maximum density curve. Spreadsheet available at http://waqtc.org/library/library.cfm

LABORATORY THEORETICAL MAXIMUM DRY DENSITY OF GRANULAR SOIL AND SOIL/ AGGREGATE WAQTC TM 15

Scope

This method is used to establish the theoretical maximum dry density of granular and non-granular soil-aggregate. Use Procedure 1 for material with more than 30 percent retained on the 4.75 mm (No. 4) sieve or Procedure 2 for material with more than 30 percent retained on the 19.0 mm (3/4 in.) sieve.

Terminology

- Fine aggregate portion material passing the 4.75 mm (No. 4) Sieve.
- Coarse aggregate portion material retained on the 4.75 mm (No. 4) sieve.

Significance

A theoretical maximum dry density chart and curve are developed by determining a laboratory maximum dry density of a representative sample of material passing the 4.75 mm (No. 4) and the material retained on the 4.75 mm (No. 4), and their respective apparent specific gravities (G_{sa}). The theoretical maximum dry density chart and curve address the range of theoretical maximum dry densities due to fluctuations in coarse and fine aggregate of a given material.

To determine the laboratory maximum dry density of the fine aggregate portion, this method allows for use of the FOP for AASHTO T 99/T 180 or by vibratory compactor covered in the method.

This method is for use on granular materials having 30 to 70 percent passing the 4.75 mm (No. 4) or 19.0 mm (3/4 in.) sieve.

Apparatus

- A vibratory spring-loaded compactor D G Parrott & Son Humphres Maximum Density machine, or equivalent.
- Small Mold Assembly: includes mold, mold base, and mold follower.
 - Mold: approximately 0.003 m^3 (0.1 ft.^3) volume. Made of steel tubing meeting ASTM A513 with a 165 mm (6.500 in.) nominal outside diameter, 6 mm (0.250 in.) wall thickness, $152 \pm 1 \text{ mm}$ ($6 \pm 0.03 \text{ in.}$) inside diameter, and a height of 203 $\pm 1 \text{ mm}$ ($8 \pm 0.032 \text{ in.}$). For in-service molds, do not to exceed 15 mm (6.060 in.) inside diameter.
 - Mold Base: 16 mm (0.625 in.) steel plate separate from the mold. Grind both surfaces to 15 ± 1 mm (0.600 ± 0.030 in.) thickness.

— Mold Follower: Steel plate, with a 12 ± 1 mm $(0.460 \pm 0.03 \text{ in.})$ edge thickness fitting inside the mold with 1.5 mm (0.063 in.) maximum space between mold follower and mold wall. For new followers, the diameter tolerance is -1 mm to -2 mm (-0.031 in.) to -0.063 in.) of the inside diameter of the matching mold.

- Large Mold Assembly: includes mold, mold base, and mold follower
 - Mold: approximately $0.014~\text{m}^3$ ($0.5~\text{ft.}^3$) volume. Made of steel tubing meeting ASTM A513 with a 267 mm (10.500~in.) nominal outside diameter, 6 mm (0.250~in.) wall thickness, $254~\pm1~\text{mm}$ ($10~\pm0.032~\text{in.}$) inside diameter, and a height of $254~\pm1~\text{mm}$ ($10~\pm0.032~\text{in.}$). For in-service molds, do not to exceed 256 mm (10.060~in.) inside diameter.
 - Mold Base: 6 to 8 mm (0.250 to 0.312 in.) steel plate skip welded or fully welded to the mold.
 - Mold Follower: Steel plate, with 14 ± 1 mm (0.550 \pm 0.030 in.) edge thickness fitting inside the mold with 1.5 mm (0.063 in.) max. space between mold follower and mold wall. For new followers, the diameter tolerance is -1 mm to -2 mm (-0.031 in. to -0.063 in.) of the inside diameter of the matching mold.
- Manually operated rammer: 2.5 kg (5.5 lb.) rammer meeting the requirements of the FOP for AASHTO T 99/T 180.
- Measuring device: minimum length 150 mm (6 in.), accurate and readable to 0.25 mm (0.01 in.)
- Sieves: 75 mm (3 in.), 19 mm (¾ in.), and a 4.75 mm (No. 4) conforming to the FOP for AASHTO T 27/T 11
- Balance or Scale: Capacity sufficient for the principal sample mass, readable to 0.1 percent or 0.1 g, and meeting the requirements of AASHTO M 231
- Tamping rod: straight steel, 16 mm (5/8 in.) in diameter and approximately 400 mm (24 in.) long having at least one end rounded to a hemispherical tip
- Straight edge: at least 25 mm (1 in.) longer than the diameter of the mold
- A stopwatch or timer readable to 1 second
- Miscellaneous tools including pans, spoon, trowel, mechanical mixer (optional), etc.

FOP LIBRARY WAQTC

WAQTC TM 15(22)

Laboratory Maximum Dry Density

Select the proper method for determining the laboratory maximum dry density of the fine aggregate portion of the sample, refer to Table 1, or as directed by the agency.

Select the proper method for determining the laboratory maximum dry density of the coarse aggregate portion of the sample, refer to Table 2.

Table 1
Fine Aggregate Portion Laboratory Maximum Dry Density Method

Estimated Soil Type	Recommended Test Method
Sandy, non-plastic, permeable soil or non-cohesive soil.	WAQTC TM 15 Vibratory Compactor
Silt, some plasticity, low permeability.	FOP for AASTHO T 99/T 180, T 99 Method A
Sandy/silt, some plasticity, permeable.	WAQTC TM 15 and FOP for AASHTO T 99/T 180, T 99 Method A (use highest results)

Table 2
Coarse Aggregate Portion Laboratory Maximum Dry Density Method

Coarse Aggregate Amount	Test Method
No more than 15 percent by weight of the original aggregate specimen exceeds 19 mm (¾ in.)	WAQTC TM 15 Vibratory Compactor Procedure 1
15 percent or more by weight of the original aggregate specimen is greater than 19 mm (¾ in) but does not exceed 75 mm (3 in.)	WAQTC TM 15 Vibratory Compactor Procedure 2

Sample Preparation

- 1. Obtain a representative sample according to the FOP for AASHTO R 90, minimum 180 kg. (400 lbs.).
- 2. Reduce according to the FOP for AASHTO R 76 to a sufficient size to yield amounts required in steps 7 and 8.
- 3. If the sample is damp, dry until it becomes friable under a trowel. Drying may be in air or by use of a drying apparatus maintained at a temperature not exceeding 60°C (140°F).
- 4. Thoroughly break up aggregations in a manner that avoids reducing the natural size of individual particles.

- 5. Remove the material retained on the 75 mm (3 in.) sieve.
- 6. Separate into coarse and fine aggregate portions by passing the remainder of the sample through the 4.75 mm (No. 4) sieve.

7. Fine aggregate:

a. Obtain a representative sample as described in the FOP for AASHTO T 99/T 180, T 99 Method A.

Or

- b. Obtain at least three representative test samples of approximately 6 kg (13 lb.) each for the fine aggregate vibratory compactor method.
- c. Obtain a representative sample of the remaining material and determine the apparent specific gravity (G_{sa}) according to AASHTO T 84 or Annex B.

8. Coarse aggregate:

a. Obtain a representative sample of 19 mm (¾ in) to 4.75 mm (No. 4) of approximately 5 kg (11 lb.) for coarse aggregate vibratory compactor Procedure 1.

Or

- b. Obtain a representative sample of 75 mm (3 in) to 4.75 mm (No. 4) of approximately 20 kg (45 lb.) for coarse aggregate vibratory compactor Procedure 2.
- c. Obtain a representative sample of the remaining material and determine the apparent specific gravity (G_{sa}) according to FOP for AASHTO T 85 or Annex B.

Laboratory Maximum Dry Density of Fine Aggregate Portion

Determine laboratory maximum dry density of the fine aggregate portion according to the FOP for AASHTO T 180/T 99, T 99 Method A, or the following vibratory compactor method. Refer to Table 1.

Vibratory Compactor Method

- 1. Determine and record the mass of the clean dry small mold assembly to the nearest 5 g (0.01 lb.). Designate this mass as the M_m .
- 2. Add enough water to one of the fine aggregate portions to saturate the sample, approximately optimum moisture. Do not over saturate (Note 1).

Note 1: The sample is considered saturated when one to two drops of free water are visible at the base of the mold assembly at the end of the first 2-minute load cycle, Table 3. Refer to Step 11.

3. Mix until homogenous.

FOP LIBRARY WAQTC WAQTC TM 15(22)


- 4. Place approximately one third of the sample in the mold with mold base attached.
- 5. Consolidate with 25 strokes of the tamping rod, distribute evenly over the surface, and 25 blows of the manually operated rammer.
- 6. Repeat Steps 4 and 5 for two subsequent lifts. The surface of the top lift should be finished as level as possible.
- 7. Place the follower on top of the molded specimen and mount the mold assembly on the jack platform in the compactor. Use spacers between the load spring assembly and follower to adjust the elevation of the mold assembly so the hammers strike near the center of the mass of material in the mold assembly.
- 8. Elevate the mold assembly with the jack until the load spring assembly seats on top of the follower and apply an initial seating load of approximately 100 lb_f. on the sample.
- 9. Start the compactor hammers. Continue to elevate the mold assembly, applying the load gradually over the time stated in the Table 3.


Table 3
Load Application Rate


Load lbf	Time
0 to 500	1 min.
500 to 1,000	30 sec.
1,000 to 2,000	30 sec.

- 10. Upon reaching 2,000 lb_f at the end of the 2-minute cycle, stop the hammer, release the load on the jack, and return to zero pressure.
- 11. Determine apparent moisture.
 - a. If the material is pumping around the mold follower or excessive amounts of water are seeping from between the mold and mold base, prepare a new sample and begin the test again at Step 1.
 - b. If the base of the mold is dry or there is a small amount of water, repeat Steps 7 through 10, four additional times.
- 12. Remove the mold assembly from the compactor.
- 13. Measure the height of the compacted specimen.
 - a. Lay the straight edge across the top of the mold assembly.

- b. Using the measuring device, measure from the bottom of the straight edge to the top of the follower and spacers to the nearest 0.1 mm (0.01 in.). Designate as D.
- c. Calculate and record the height of the compacted specimen, h_s, by subtracting D and T (thickness of the follower) from the height of the mold h_m. See Annex A..
- 14. Determine and record the mass of the mold assembly and specimen, M_{ms} , to the nearest 5 g (0.01 lb.).
- 15. Determine and record the mass of the specimen, M_s , by subtracting M_m from M_{ms} .
- 16. Remove the specimen from the mold assembly.
- 17. Use the entire specimen for a moisture content sample or obtain a representative sample by slicing vertically through the center of the specimen. Obtain at least 500 g. (1.1 lb.) from one of the cut faces, ensuring that all the layers are represented. If a vertical face does not exist, take a representative sample.







Representative moisture content sample

- 18. Determine and record the moisture content, w, according to the FOP for AASHTO T 255/T 265.
- 19. Calculate and record the wet density, ρ_w , of the fine aggregate portion.
- 20. Calculate and record the laboratory dry density, ρ_d , of the fine aggregate portion.

Laboratory Maximum Dry Density of the Coarse Portion

Vibratory Compactor Method

Note 2: Procedure 1 uses the small mold assembly, this procedure is not recommended for material with aggregate larger than 9.3 mm (3/4 in.).

Procedure 1

1. Determine and record the mass of the small mold assembly to the nearest 5 g (0.01 lb.). Designate this mass as the $M_{\rm m}$.

TM15 short 22 FOP Library -6 Pub. October 2022

2. Determine and record the mass of the coarse aggregate portion to the nearest 5 g (0.01 lb.). Designate this mass as the M_s. See Note 3.

Note 3: If all the coarse aggregate portion does not fit in the mold assembly or there is some indication that material may have been lost, perform alternate Step 16 to determine M_s.

- 3. Determine amount of water to add to the coarse aggregate portion by multiplying the mass determined in Step 2 by 0.025 (2.5 percent).
- 4. Add water to coarse aggregate portion, mix thoroughly.
- 5. Place approximately one third of the sample in the mold with mold base attached.
- 6. Tamp the surface lightly with the manually operated rammer to consolidate material and achieve a level surface.
- 7. Repeat Steps 5 and 6 for two subsequent lifts. Ensure all the coarse aggregate portion is placed in the mold.
- 8. Place the follower on top of the molded specimen and mount the mold assembly on the jack platform in the compactor. Use spacers between the load spring assembly and follower to adjust the elevation of the mold assembly so the hammers strike near the center of the mass of material in the mold assembly.
- 9. Elevate the mold assembly with the jack until the loading spring assembly seats on top of the follower and spacers.
- 10. Apply an initial seating load of approximately 100 lb_f on the sample.
- 11. Start the compactor hammers. Continue to elevate the mold, applying the load gradually over the time stated in the Table 3.
- 12. Upon reaching the 2,000 lb_f load at the end of the 2-minute cycle, stop the hammer, release the load on the jack, and return to zero pressure.
- 13. Repeat Steps 10 through 12 four additional times.
- 14. Remove the mold assembly from the compactor.
- 15. Measure the height of the compacted specimen.
 - a. Lay the straight edge across the top of the mold assembly.
 - b. Using the measuring device, measure from the bottom of the straight edge to the top of the follower and spacers to the nearest 0.1 mm (0.01 in.). Designate as D.
 - c. Calculate and record the height of the compacted specimen, h_s, by subtracting D and T (thickness of the follower) from the height of the mold h_m. See Annex A.

- 16. Alternate method of determining M_s
 - a. Remove the specimen from the mold assembly.
 - b. Determine the dry mass according to the FOP for AASHTO T 255. Designate as M_s.
- 17. Calculate and record the laboratory dry density, ρ_d , of the coarse aggregate portion.

Procedure 2

- 1. Determine and record the mass of the large mold assembly to the nearest 5 g (0.01 lb.). Designate this mass as the M_m .
- 2. Determine and record the mass of the coarse aggregate portion to the nearest 5 g (0.01 lb.). Designate this mass as the M_s .

Note 4: If all the coarse aggregate portion does not fit in the mold or there is some indication that material may have been lost, perform alternate Step 13 to determine M_s .

- 3. Place approximately one fifth of the sample in the large mold with mold base.
- 4. Tamp the surface lightly with the manually operated rammer to consolidate material and achieve a level surface.
- 5. Place the follower on top of the molded specimen and mount the mold assembly on the jack platform in the compactor. Use spacers between the load spring assembly and follower to adjust the elevation of the mold assembly so the hammers strike near the center of the mass of material in the mold assembly.
- 6. Elevate the mold assembly with the jack until the loading spring assembly seats on top of the follower.
- 7. Apply an initial seating load of approximately 100 lb_f on the sample.
- 8. Start the compactor hammers. Continue to elevate the mold assembly, applying the load gradually over the time stated in the Table 3.
- 9. Upon reaching the 2,000 lb_f load at the end of the 2-minute cycle, stop the hammer, release the load on the jack, and return to zero pressure.
- 10. Repeat Steps 3 through 9 four additional times. Ensure all the coarse aggregate portion is placed in the mold on the final lift.
- 11. Remove the mold assembly from the compactor.
- 12. Measure the height of the compacted specimen.
 - a. Lay the straight edge across the top of the mold assembly.

WAQTC WAQTC TM 15(22)

- b. Using the measuring device, measure from the bottom of the straight edge to the top of the follower and spacers to the nearest 0.1 mm (0.01 in.). Designate as D.
- c. Calculate and record the height of the compacted specimen, h_s, by subtracting D and T (thickness of follower) from the height of the mold, h_s. See Annex A.
- 13. Alternate method of determining M_s
 - a. Remove the specimen from the mold assembly.
 - b. Determine the dry mass of the specimen according to the FOP for AASHTO T 255. Designate as M_s.
- 14. Calculate and record the laboratory dry density, ρ_d, of the coarse aggregate portion.

Calculations

Height of specimen in mold (fine or coarse aggregate portion)

$$h_s = h_m - D - T$$

where:

hs = height of specimen in mold, 0.1 mm (0.01 in.)

height of mold, 0.1 mm (0.01 in.), Annex A $h_{\rm m}$

D measured distance from the mold top to the follower, 0.1

mm (0.01 in.)

Т = thickness of the follower, 0.1 mm (0.01 in.), Annex A

Volume of the specimen in the mold (fine or coarse aggregate portion)

$$V_{s} = \frac{h_{s} \times \pi \times \left(\frac{d}{2}\right)^{2}}{1e^{9 \, mm^{3}}/_{m^{3}} \, or \, 1728 \, in^{3}/_{ft^{3}}}$$

where:

= volume of specimen in mold m³ (ft³) $V_{\rm s}$

d inside diameter of the mold, 0.1 mm (0.01 in.), Annex A TM 15

FOP LIBRARY WAQTC

Mass of fine aggregate portion in the mold assembly

$$M_S = M_{mS} - M_m$$

where:

 M_s = mass of specimen in mold assembly, 0.005 kg (0.01 lb.)

WAQTC TM 15(22)

 M_{ms} = mass of mold assembly and specimen, 0.005 kg (0.01 lb.)

 M_m = mass of mold assembly, 0.005 kg (0.01 lb.)

Wet Density of fine aggregate portion

$$\rho_w = \frac{M_s}{V_s}$$

Where:

 $\rho_{\rm w}$ = wet density, kg/m³ (lb/ft³)

 M_s = mass of specimen in the mold assembly, 0.005 kg (0.01 lb.)

 V_s = volume of specimen in mold m^3 (ft³)

Laboratory maximum dry density fine aggregate portion

$$\rho_d = \left(\frac{\rho_w}{w + 100}\right) \times 100 \quad or \quad \rho_d = \frac{\rho_w}{\left(\frac{w}{100}\right) + 1}$$

Where:

 ρ_d = dry density, kg/m³ (lb/ft³)

w = moisture content, as a percentage (FOP for AASHTO T 255)

FOP LIBRARY WAQTC WAQTC TM 15(22)

Laboratory maximum dry density of coarse aggregate portion

$$\rho_d = \left(\frac{M_s}{V_s}\right) \times 100$$

Where:

 ρ_d = dry density, kg/m³ (lb/ft³)

 M_s = mass of specimen in the mold assembly, 0.005 kg (0.01 lb.)

 V_s = volume of specimen in mold m^3 (ft³)

Example

Example for small mold fine aggregate portion

Wet mass, $M_w = 6.470 \text{ kg} (14.26 \text{ lb})$

Moisture content, w = 11.3%

Height of mold, $h_m = 203.7 \text{ mm} (8.02 \text{ in.})$

Inside diameter of mold, d = 153.4 mm (6.04 in.)

Measurement from top of mold to follower, D = 44.5 mm (1.75 in.)

Thickness of the follower, T = 3.6 mm (0.14 in.)

Mass of specimen and mold assembly, $M_{ms} = 6.400 \text{ kg} (14.11 \text{ lb})$

Mass of mold assembly, $M_m = 0.280 \text{ kg} (0.62 \text{ lb})$

Height of fine aggregate portion in mold

$$h_s = h_m - D - T$$

$$h_s = 203.7 \ mm - 44.5 \ mm - 3.6 \ mm = 155.6 \ mm$$

$$h_s = 8.02 \ in. -1.75 \ in. -0.14 \ in. = 6.13 \ in.$$

FOP LIBRARY WAQTC WAQTC TM 15(22)

Volume of the fine aggregate in the mold

$$V_{s} = \frac{h_{s} \times \pi \times \left(\frac{d}{2}\right)^{2}}{1e^{9} mm^{3}/_{m^{3}} or \frac{1728 in^{3}}{ft^{3}}}$$

$$V_s = \frac{155.6 \, mm \times \pi \times \left(\frac{153.4 \, mm}{2}\right)^2}{1,000,000,0000 \, mm^3/_{m^3}} = 0.002876 \, m^3$$

Or

$$V_s = \frac{6.13 \text{ in. } \times \pi \times \left(\frac{6.04 \text{ in.}}{2}\right)^2}{1728 \text{ in}^3/_{ft^3}} = 0.1016 \text{ ft}^3$$

Mass of fine aggregate portion in the mold

$$M_S = M_{ms} - M_m$$

 $M_S = 6.400 \ kg - 0.280 \ kg = 6.119 \ kg$
 $M_S = 14.11 \ lb - 0.62 \ lb = 13.49 \ lb$

Wet density of fine aggregate portion

$$\rho_w = \frac{M_s}{V_s}$$

$$\rho_w = \frac{6.119 \, kg}{0.002876 \, m^3} = 2128 \, {^{kg}}/{_{m^3}}$$

$$\rho_w = \frac{13.49 \, lb}{0.1016 \, ft^3} = 132.8 \, \frac{lb}{ft^3}$$

Laboratory maximum dry density of the fine aggregate portion

$$\rho_d = \left(\frac{\rho_w}{w + 100}\right) \times 100 \quad or \quad \rho_d = \frac{\rho_w}{\left(\frac{w}{100}\right) + 1}$$

$$\rho_d = \left(\frac{2128\,kg/m^3}{11.3\% + 100}\right) \times \, 100 = 1912\,\,kg/m^3 \ \ \, \rho_d = \left(\frac{132.8\,\,lb/ft^3}{11.3\% + 100}\right) \times \, 100 = 119.3\,lb/ft^3$$

Or

$$\rho_d = \left(\frac{2128 \, kg/m^3}{\frac{11.3\%}{100} + 1}\right) = 1912 \, kg/m^3 \quad \rho_d = \left(\frac{132.8 \, lb/ft^3}{\frac{11.3\%}{100} + 1}\right) = 119.3 \, lb/ft^3$$

TM 15

Example for small mold coarse aggregate portion (Procedure 1)

Calculations will be the same for Procedure 2

Height of mold assembly, $h_m = 203.7 \text{ mm} (8.02 \text{ in.})$

Inside diameter of mold, d = 153.4 mm (6.04 in.)

Measurement from top of mold assembly

to follower, D = 42.4 mm (1.67 in.)

Thickness of the follower, T = 3.6 mm (0.14 in.)

Mass of coarse aggregate in the mold assembly, $M_s = 4.985 \text{ kg} (10.99 \text{ lb})$

Height of coarse aggregate portion in mold

$$h_{\scriptscriptstyle S} = h_m - D - T$$

$$h_s = 203.7 \ mm - 42.4 \ mm - 3.6 \ mm = 157.7 \ mm$$

$$h_s = 8.02 \text{ in.} -1.67 \text{ in.} -0.14 \text{ in.} = 6.21 \text{ in.}$$

Volume of the coarse aggregate portion in the mold

$$V_{s} = \frac{h_{s} \times \pi \times \left(\frac{d}{2}\right)^{2}}{1e^{9} mm^{3}/_{m^{3}} or \frac{1728 in^{3}}{ft^{3}}}$$

$$V_s = \frac{157.7 \ mm \times \pi \times \left(\frac{153.4 \ mm}{2}\right)^2}{1,000,000,0000 \ mm^3/_{m^3}} = 0.002915 \ m^3$$

$$V_s = \frac{6.21 \text{ in.} \times \pi \times \left(\frac{6.04 \text{ in.}}{2}\right)^2}{1728 \text{ in}^3/f_{t^3}} = 0.1030 \text{ ft}^3$$

TM 15

FOP LIBRARY WAQTC WAQTC TM 15(22)

Laboratory maximum dry density of coarse aggregate portion

$$\rho_d = \left(\frac{M_s}{V_s}\right) \times 100$$

$$\rho_d = \left(\frac{4.985 \, kg}{0.002915 \, m^3}\right) \times 100 = 1710^{-kg} / m^3$$

$$\rho_d = \left(\frac{10.99 \ lb}{0.1030 \ ft^3}\right) \times 100 = 106.7 \ lb/ft^3$$

Theoretical Maximum Density Curve Development

Enter the following data into an approved spreadsheet to develop the maximum density chart and maximum density curve.

- Laboratory maximum dry density, ρ_d , of the coarse aggregate portion to the nearest $1 \text{ kg/m}^3 (0.1 \text{ lb/ft}^3)$
- Laboratory maximum dry density, ρ_d, of the fine aggregate portion to the nearest 1 kg/m³ (0.1 lb/ft³)
- Optimum moisture content to the nearest 0.1 percent if the FOP for AASTHO T 99/T 180, T 99 Method A was used for the fine portion.
- Coarse aggregate apparent specific gravity, G_{sa} , to the nearest 0.001
- Fine aggregate portion apparent specific gravity, G_{sa}, to the nearest 0.001

Example


Theoretical Maximum Dry Density Chart

Density Curves			
Pass #4	Maximum	Pass #4	Maximum
0.0	104.8	31.0	133.7
1.0	105.6	32.0	134.5
2.0	106.4	33.0	135.2
3.0	107.1	34.0	135.8
4.0	107.9	35.0	136.4
5.0	108.7	36.0	137.0
6.0	109.5	37.0	137.5
7.0	110.3	38.0	137.9
8.0	111.1	39.0	138.3
9.0	112.0	40.0	138.6
10.0	112.8	41.0	138.9
11.0	113.7	42.0	139.0
12.0	114.5	43.0	139.2
13.0	115.4	44.0	139.2
14.0	116.4	45.0	139.2
15.0	117.3	46.0	139.2
16.0	118.2	47.0	139.1
17.0	119.2	48.0	139.0
18.0	120.2	49.0	138.8
19.0	121.3	50.0	138.6
20.0	122.3	51.0	138.3
21.0	123.4	52.0	138.1
22.0	124.5	53.0	137.8
23.0	125.6	54.0	137.5
24.0	126.8	55.0	137.1
25.0	127.9	56.0	136.8
26.0	129.0	57.0	136.4
27.0	130.0	58.0	136.0
28.0	131.0	59.0	135.7
29.0	132.0	60.0	135.3
30.0	132.8	61.0	135.0

Density Curves			
Pass #4	Maximum	Pass #4	Maximum
62.0	134.6	82.0	129.6
63.0	134.3	83.0	129.4
64.0	134.0	84.0	129.3
65.0	133.6	85.0	129.1
66.0	133.3	86.0	128.9
67.0	133.1	87.0	128.8
68.0	132.8	88.0	128.6
69.0	132.5	89.0	128.4
70.0	132.2	90.0	128.3
71.0	132.0	91.0	128.1
72.0	131.7	92.0	128.0
73.0	131.5	93.0	127.9
74.0	131.2	94.0	127.7
75.0	131.0	95.0	127.6
76.0	130.8	96.0	127.4
77.0	130.6	97.0	127.3
78.0	130.4	98.0	127.2
79.0	130.2	99.0	127.0
80.0	130.0	100.0	126.9
81.0	129.8		

Control Points for Density Curves		
Pass #4	Maximum	Loose
0.0	104.8	87.6
20.5	122.8	99.6
27.4	130.4	103.8
42.5	139.1	105.4
61.1	134.9	96.7
100.0	126.9	81.9

Theoretical Maximum Dry Density Curve



Report

- Results on standard agency forms
- Sample ID
- Laboratory maximum dry density of the coarse aggregate portion to the nearest 1 kg/m³ (0.1 lb/ft³)
- Laboratory maximum dry density of the fine aggregate portion to the nearest 1 kg/m³ (0.1 lb/ft³)
- Optimum moisture content to the nearest 0.1 percent (when using the FOP for AASTHO T 99/T 180, T 99 Method A for the fine aggregate portion)
- Coarse aggregate apparent specific gravity (G_{sa}) to the nearest 0.001
- Fine aggregate apparent specific gravity (G_{sa}) to the nearest 0.001
- Theoretical maximum dry density chart
- Theoretical maximum dry density curve

ANNEX A STANDARDIZATION OF THE MOLD ASSEMBLY

(Mandatory Information)

Apparatus

- Calipers having a range sufficient to measure the diameter of the measure being checked and readable to at least 0.1 mm (0.01 in.)
- Inside diameter caliper, 300 mm (12 in.) range
- Straight edge at least 25 mm (1 in.) larger than the mold
- Ruler readable to 0.1 mm (0.01 in.)

Procedure

Determine the height of the mold (h_m)

- 1. Place the straight edge across the top of the mold with mold base.
- 2. Using the caliper measure from the bottom of the straight edge to the center mold with base to the nearest 0.1 mm (0.01 in.)
- 3. Turn the straight edge 90 degrees.
- 4. Repeat Step 2.
- 5. Average the two measurements.
- 6. Designate as h_m

Determine the thickness of the mold follower and spacers (T)

- 1. Place follower and spacers inside the mold with mold base.
- 2. Place the straight edge across the top of the mold.
- 3. Using the caliper measure from the bottom of the straight edge to the center of the top of the follower to the nearest 0.1 mm (0.01 in.).
- 4. Turn the straight edge 90 degrees.
- 5. Repeat Step 3.
- 6. Average the two measurements.
- 7. Subtract the average measurement from h_m
- 8. Designate as T.

Determine the inside diameter of the mold (d)

- 1. Using the caliper measure the inside diameter of the mold to the nearest 0.1 mm (0.01 in.).
- 2. Turn the mold 90 degrees.
- 3. Repeat Step 1.
- 4. Average the two measurements.
- 5. Designate as d.

TM15 short 22 FOP Library -18 Pub. October 2022

ANNEX B APPARENT SPECIFIC GRAVITY (Gsb) DETERMINATION

(Mandatory Information)

This procedure covers the determination of apparent specific of coarse and fine aggregate by means of a pycnometer. When the soil is composed of material both larger and smaller than the 4.75 mm (No. 4) sieve, the sample is separated on the 4.75 mm (No. 4) sieve.

Apparatus

- Pycnometer: A flask or other suitable container in which the volume can be reproduced within ± 0.1 ml. The volume of the flask shall be at least 50 percent greater than required for the test sample.
- Pycnometer / volumetric flask cover: A glass plate or a metal or plastic cover with a vented opening
- Balance: A balance of sufficient capacity, readable to 0.1 g. Meeting AASHTO M 231, Class G2.
- Oven: Capable of maintaining a temperature of $110 \pm 5^{\circ}$ C ($230 \pm 9^{\circ}$ F) for drying the specimens to a constant mass.
- Vacuum lid: A transparent lid with a suitable vacuum connection, with a vacuum opening to be covered with a fine wire mesh
- Vacuum: Capable of evacuating air from the container to a partial vacuum of 13.33 kPa (100 mmHg) or less absolute pressure
- Manometer or vacuum gauge: Capable of measuring the vacuum being applied at the source of the vacuum
- Water bath: A constant-temperature water bath (optional)
- Thermometers: Thermometric devices accurate to 0.5°C (1°F)
- Bleeder valve to adjust vacuum
- Timer

Sample Preparation

- 1. Sample and reduce the aggregate in accordance with the FOPs for AASHTO R 90 and R 76.
- 2. Dry the sample sufficiently to obtain a clean separation of fine and coarse material in the sieving operation.
- 3. Sieve the sample in accordance with the FOP for AASHTO T 27/ T 11 over the 4.75 mm (No. 4) sieve.

Coarse test sample

- a. Split or quarter approximately 1000 g of material from the portion retained on the 4.75 mm (No. 4) sieve.
- b. Dry to constant mass according to the FOP for AASHTO T 255 at 110 ± 5 °C (230 ± 9 °F).
- c. Cool to room temperature.

Fine test sample

- a. Split or quarter approximately 500 g of material from the portion passing the 4.75 mm (No. 4) sieve.
- b. Dry to constant mass according to the FOP for AASHTO T 255/T 265 at 110 \pm 5°C (230 \pm 9°F).
- c. Cool to room temperature.

Procedure

The procedure is performed on fine and coarse aggregate separately.

- 1. Determine and record the mass of the dry test sample. Designate as A.
- 2. Place the test sample in the pycnometer.
- 3. Add water at approximately 20°C (68°F) until the pycnometer is about ¾ full.
- 4. Connect the pycnometer to the vacuum system.
- 5. Apply partial vacuum, 30 mmHg or less absolute pressure, for 20 ± 1 min.
- 6. Agitate the pycnometer and contents, either continuously by mechanical device or manually by vigorous shaking, at 2-minute intervals. This agitation facilitates the removal of entrapped air.
- 7. Release vacuum and disconnect the hoses.
- 8. Fill the pycnometer with water without reintroducing air. Water temperature should be maintained as close to 20 ± 0.5 °C (68 ± 1 °F) as possible throughout the procedure.

Note 1: It may be necessary to place the pycnometer in a water bath for 10 minutes after the release of vacuum to stabilize at 20 ± 0.5 °C (68 ± 1 °F).

- a. Metal pycnometer (coarse test sample only) Fill the pycnometer with 20 ± 0.5 °C (68 ± 1 °F) water according to manufacturer's instructions and dry the outside.
- b. Glass pycnometer (fine or coarse test samples) Completely fill the pycnometer with 20 ± 0.5 °C (68 ± 1 °F) water, slide the calibrated glass plate over the mouth of the pycnometer making sure there are no air bubbles trapped under the plate. Dry the outside.
- 9. Determine and record the mass of the pycnometer, sample, and water. Designate as C.

TM15 short 22 FOP Library -20 Pub. October 2022

WAQTC WAQTC TM 15(22)

Calculation

Calculate the G_{sa} to three decimal places as follows:

$$G_{sa} = \frac{A}{A + B - C}$$

Where:

A = Mass of dry sample in air, g

B = Mass of pycnometer filled with water at 20°C (68°F), g, determined during the Standardization of Pycnometer procedure

C = Mass of pycnometer, water, and the test sample at to 20 ± 0.5 °C (68 ± 1 °F), g

Coarse example:

$$G_{sa} = \frac{2200.3 \ g}{2200.3 \ g + 7502.5 \ g - 8812.0 \ g} = 2.470$$

Given:

$$A = 2200.3 g$$
 $B = 7502.5 g$
 $C = 8812.0 g$

Report

- Report on standard agency forms.
- Report apparent specific gravities, Gsa, to the nearest 0.001

TM 15

Standardization of Pycnometer

The pycnometer shall be standardized periodically in conformance with procedures established by the agency.

- 1. Fill the pycnometer with water at approximately 20°C (68°F).
- 2. Place the metal or plastic cover, or a glass plate on the pycnometer and eliminate all air.

Note B1: When using a metal pycnometer and cover, place the cover on the pycnometer and push down slowly, forcing excess water out of the hole in the center of the cover. Use care when filling the pycnometer to avoid reintroducing air into the water.

- 3. Stabilize the pycnometer at 20 ± 0.5 °C (68 ± 1 °F) for 10 ± 1 min.
- 4. Towel dry the outside of the pycnometer and cover.
- 5. Determine and record the mass of the pycnometer, water, and lid.
- 6. Repeat Steps 2 through 5 two more times for a total of three determinations.
- 7. If the variation of the three masses is within 0.3 g, average the three masses. Designate as "B."
- 8. If the variation of the masses is greater than 0.3 g, take corrective action and perform the "Standardization of Pycnometer" again.

Performance Exam Checklist

WAQTC TM 15

Laboratory Theoretical Maximum Dry Density of Granular Soil and Soil/Aggregate

Parti	cipant Name: Exam Date:	Exam Date:	
Reco	ord the symbols "P" for passing or "F" for failing on each step of the checklist.		
Proc	edure Element	Trial 1	Trial 2
1.	The tester has a copy of the current procedure on hand?		
2.	All equipment is functioning according to the test procedure, and if required has the current calibration/standardization/check and maintenance tags present?		
San	nple Preparation Element		
3.	A minimum of 180 kg. (400 lbs.) representative sample material obtained according to FOP for AASHTO R 90 ?		
4.	Representative sample reduced according to FOP for AASHTO R 76 to yield the sample sizes for testing?		
5.	If damp, sample dried at a temperature not exceeding 60°C (140°F)?		
6.	Material retained on the 75 mm (3 in.) sieve removed?		
7.	Coarse and fine aggregate portions separated through the 4.75 mm (No. 4) sieve?		
Fine	e Aggregate Portion Element		
8.	Proper test method selected based on Table 1?		
9.	Mass of clean dry small mold determined to the nearest 5 g (0.01 lb.)?		
10.	Enough water added to saturate sample and mixed until homogenous?		
11.	Each lift consolidated with 25 strokes of tamping rod and 25 blows of manually operated rammer?		
12.	Top lift finished as level as possible?		
13.	Mold cap placed and spacers utilized so the hammers strike near the center of mass in the mold?		
14.	Initial seating load of approximately 100 lbf applied?		
15.	Compaction begun and load application rate per Table 3 followed?		
16.	Based on the determination of apparent moisture, compaction cycle repeated four additional times or a new sample is prepared and test restarted from Step 1.?		
17.	Height of compacted specimen determined and recorded?		
18.	Mass of specimen determined and recorded?		
19.	Moisture content determined and recorded?		
20.	Dry density determined?		

rse Aggregate Portion Element		
Dranger test method selected based on Table 22		
Proper test method selected based on Table 2:		
edure 1 Element		
Mass of clean dry small mold determined to the nearest 5 g (0.01 lb.)?		
Mass of coarse aggregate portion determined to the nearest 5 g (0.01 lb.)?		
Coarse aggregate mass multiplied by 0.025 to determine mass of water to be added?		
Water and coarse aggregate mixed thoroughly?		
Each lift tamped lightly with manually operated rammer?		
Mold cap placed and spacers utilized so the hammers strike near the center of mass in the mold?		
Initial seating load of approximately 100 lbf applied?		
Compaction begun and load application rate per Table 3 followed?		
Compaction cycle repeated four additional times?		
Height of compacted specimen determined and recorded?		
Dry density determined?		
edure 2 Element		
Mass of clean dry small mold determined to the nearest 5 g (0.01 lb.)?		
Mass of coarse aggregate portion determined to the nearest 5 g (0.01 lb.)?		
Approximately one fifth of the sample place in mold?		
Lift tamped lightly with manually operated rammer to consolidate and level?		
Mold cap placed and spacers utilized so the hammers strike near the center of mass in the mold?		
Initial seating load of approximately 100 lbf applied?		
Compaction begun and load application rate per Table 3 followed?		
Aggregate placement and compaction cycle repeated four additional times?		
Height of compacted specimen determined and recorded?		
Dry density determined?		
	Mass of clean dry small mold determined to the nearest 5 g (0.01 lb.)? Mass of coarse aggregate portion determined to the nearest 5 g (0.01 lb.)? Coarse aggregate mass multiplied by 0.025 to determine mass of water to be added? Water and coarse aggregate mixed thoroughly? Each lift tamped lightly with manually operated rammer? Mold cap placed and spacers utilized so the hammers strike near the center of mass in the mold? Initial seating load of approximately 100 lbf applied? Compaction begun and load application rate per Table 3 followed? Compaction cycle repeated four additional times? Height of compacted specimen determined and recorded? Dry density determined? edure 2 Element Mass of clean dry small mold determined to the nearest 5 g (0.01 lb.)? Approximately one fifth of the sample place in mold? Lift tamped lightly with manually operated rammer to consolidate and level? Mold cap placed and spacers utilized so the hammers strike near the center of mass in the mold? Initial seating load of approximately 100 lbf applied? Compaction begun and load application rate per Table 3 followed? Aggregate placement and compaction cycle repeated four additional times? Height of compacted specimen determined and recorded?	Mass of clean dry small mold determined to the nearest 5 g (0.01 lb.)? Mass of coarse aggregate portion determined to the nearest 5 g (0.01 lb.)? Coarse aggregate mass multiplied by 0.025 to determine mass of water to be added? Water and coarse aggregate mixed thoroughly? Each lift tamped lightly with manually operated rammer? Mold cap placed and spacers utilized so the hammers strike near the center of mass in the mold? Initial seating load of approximately 100 lbf applied? Compaction begun and load application rate per Table 3 followed? Compaction cycle repeated four additional times? Height of compacted specimen determined and recorded? Dry density determined? edure 2 Element Mass of clean dry small mold determined to the nearest 5 g (0.01 lb.)? Approximately one fifth of the sample place in mold? Lift tamped lightly with manually operated rammer to consolidate and level? Mold cap placed and spacers utilized so the hammers strike near the center of mass in the mold? Initial seating load of approximately 100 lbf applied? Compaction begun and load application rate per Table 3 followed? Aggregate placement and compaction cycle repeated four additional times? Height of compacted specimen determined and recorded?

Proc	edure Element	Trial 1	Trial 2
App	parent Specific Gravity of the Fine and Coarse Portions According to Annex B		
43.	Appropriate amount of coarse and fine aggregate portions obtained, dried, and cooled?		
44.	Mass of dry test sample(s) determined and recorded?		
45.	Test sample(s) placed in pycnometer and 20°C (68°F) water added to about ¾ full?		
46.	Partial vacuum applied to pycnometer and contents for 20 \pm 1 min. and agitated by mechanical device or manually?		
47.	Vacuum released and pycnometer filled with water without reintroducing air?		
48.	Water stabilized at 20 \pm 0.5°C (68 \pm 1°F), pycnometer cover positioned, and outside dried?		
49.	Mass of pycnometer, sample, and water determined and recorded?		
50.	Specific Gravity determined?		
Com	ments: First Attempt: Pass Fail Second Attempt: Pass F	ail	_
Fxan	niner Signature: WAOTC #:		