


Crack repair plan for Cycle 1 pontoons

Repairs include:

1. Epoxy injections to cracks over .006" in width
2. Transverse post-tensioning at the walls
3. Carbon fiber wrap to portions of the keel slab



Note: Repairs apply to pontoons W, T, U, and V.