



Wall 4: Existing Conditions



Existing conditions at NE 77th Street looking northeast



Wall 4
location

* Photo was taken from this location



Wall 4: Preliminary Concepts

Option A: Ashlar Stone



Option B: Chiseled Limestone with Leaf Pattern





Wall 4: Preliminary Concepts

Option C: Dry Stack Stone



Option D: Random Board

