




### Rural/Agricultural Segment: 180th St SE to 228th Ave SE



**What does this segment look like today?**  
One lane in each direction; occasional transit-only turn outs; a few awkward angled intersections.

**180th Street SE**

**228th Avenue SE**

### What are the problems?

**Safety & Traffic Backups:** School buses making frequent stops create vehicle backups. Unmarked crosswalks and children walking to and from the school bus also create pedestrian safety concerns.

**Safety:** A portion of this segment west of 228th Avenue SE is identified as a high accident corridor. Rear end accidents and vehicles stopped to make left turns at intersections are the most commonly reported accidents. Street lighting and visibility problems have also been identified.