

WSDOT SD Bridges



State Route	Mile-post	County	Bridge Name	Year Built	Bridge Type	SD Problem	Status
2	89.88	Chelan	CHIWAUKUM CR	1936	Steel Girder	Scour	Programmed For Bridge Replacement
2	0.75	Snohomish	EBEY ISLAND VIADUCT	1968	Concrete Girder	Superstructure	Programmed For Bridge Rehabilitation
2	2.06	Snohomish	EBEY SLOUGH BRIDGE	1968	Concrete Box	Superstructure	Programmed For Bridge Rehabilitation
5	114.09	Thurston	MCALLISTER CR	1968	Concrete Slab	Substructure	Programmed for Bridge Repair by contract
5	114.86	Thurston	NISQUALLY RIVER	1937	Steel Thru Truss	Superstructure	Programmed for Bridge Repair by contract
5	18.21	Clark	E FK LEWIS R	1936	Steel Thru Truss	Superstructure	Programmed For Bridge Replacement
5	119.01	Pierce	I-5 OC, DUPONT	1957	Concrete Slab	Deck	Monitor thru Insp - Program Future Repairs
5	153.15	King	I-5 OC, S 178TH ST	1964	Prestress Conc Girder	Superstructure	Programmed for Bridge Repair by contract
5	162.99	King	S-E RAMP WB LANES	1967	Concrete Box	Deck	Programmed for Bridge Repair by contract
5	163	King	EB LANES I-5 OC	1966	Concrete Box	Deck	Programmed for Bridge Repair by contract
5	163.24	King	NB VIADUCT STA 2085	1966	Concrete Slab	Deck	Programmed For Bridge Deck Repair
5	193.63	Snohomish	SR 529 - PACIFIC AVE OC	1966	Prestress Conc Girder	Deck	Monitor thru Insp - Program Future Repairs
5	209.35	Snohomish	STILLAGUAMISH R	1933	Steel Thru Truss	Deck	Programmed For Bridge Deck Repair
5	270.24	Whatcom	I-5 OC, BIRCH BAY	1961	Prestress Conc Girder	Deck	Monitor thru Insp - Program Future Repairs
6	42.62	Lewis	S FK CHEHALIS R	1925	Concrete Arch	Substructure	Programmed For Bridge Replacement
6	50.94	Lewis	CHEHALIS R RIVERSIDE	1939	Steel Thru Truss	Substructure	Programmed for Bridge Repair by contract
7	27.91	Pierce	MASHEL R	1948	Steel Girder	Substructure	Programmed for Bridge Repair by contract
9	34.85	Snohomish	PILCHUCK CR	1916	Concrete Arch	Scour	Programmed for Bridge Repair by contract
9	42.86	Skagit	LAKE CR	1966	Timber Girder	Superstructure	Monitor thru Insp - Program Future Repairs
9	47.29	Skagit	NOOKACHAMPS CR	1952	Timber Slab	Substructure	Monitor thru Insp - Program Future Repairs
10	89.33	Kittitas	TEANAWAY R	1930	Steel Thru Truss	Deck	Monitor thru Insp - Program Future Repairs
10	90.1	Kittitas	BRISTOL FILL	1937	Steel Girder	Deck	Programmed For Bridge Deck Repair
12	0.08	Grays Harbor	WISHKAH R HERON CS1415	1949	Steel Thru Truss	Substructure	Programmed for Bridge Repair by contract
12	176.63	Yakima	TIETON R NO 2	1933	Steel Thru Truss	Superstructure	Programmed For Bridge Replacement
12	177.13	Yakima	TIETON R NO 1	1933	Steel Thru Truss	Superstructure	Programmed For Bridge Replacement
12	372.57	Columbia	WHETSTONE CR	1919	Concrete Slab	Substructure	Monitor thru Insp - Program Future Repairs
12	434.1	Asotin	SNAKE R CLARKSTON	1939	Steel Thru Truss	Deck	Programmed for Bridge Repair by contract
14	24.92	Skamania	HALF BRIDGE	1930	Concrete Girder	Substructure	Programmed for Bridge Repair by contract
18	6.62	King	GREEN R (NEELEY BRIDGE)	1959	Steel Thru Truss	Deck	Programmed For Bridge Deck Repair
20	0.05	Jefferson	SNOW CR	1940	Timber Girder	Substructure	Monitor thru Insp - Program Future Repairs
20	423.75	Pend Oreille	DAVIS CR	1936	Timber Girder	Substructure	Monitor thru Insp - Program Future Repairs
21	130.74	Ferry	SAN POIL R	1931	Concrete Girder	Scour	Monitor thru Insp - Program Future Repairs
21	148.45	Ferry	SAN POIL R	1927	Concrete Girder	Scour	Monitor thru Insp - Program Future Repairs
22	1.39	Yakima	SLOUGH OF YAKIMA R	1935	Concrete Girder	Deck	Programmed For Bridge Replacement
23	23.28	Whitman	ROCK CR	1946	Concrete Girder	Deck	Monitor thru Insp - Program Future Repairs

WSDOT SD Bridges

State Route	Mile-post	County	Bridge Name	Year Built	Bridge Type	SD Problem	Status
25	113.92	Stevens	COLUMBIA R @ NORTHPORT	1948	Steel Thru Truss	Deck	Monitor thru Insp - Program Future Repairs
27	41.02	Whitman	PINE CR	1937	Timber Girder	Substructure	Programmed For Bridge Replacement
82	3.22	Kittitas	SR 821 OC THRALL RD	1970	Prestress Conc Girder	Deck	Monitor thru Insp - Program Future Repairs
82	30.9	Yakima	NACHES R	1932	Steel Thru Truss	Superstructure	Monitor thru Insp - Program Future Repairs
82	11.62	Kittitas	MILITARY RD OC	1971	Prestress Conc Girder	Deck	Programmed For Bridge Deck Repair
82	82.34	Benton	I-82 OC, WINE COUNTRY RD	1978	Prestress Conc Girder	Deck	Monitor thru Insp - Program Future Repairs
90	74.05	Kittitas	LAKE VALLEY RD OC	1962	Prestress Conc Girder	Deck	Monitor thru Insp - Program Future Repairs
90	75.36	Kittitas	BIG CR	1962	Concrete Slab	Deck	Monitor thru Insp - Program Future Repairs
90	75.36	Kittitas	BIG CR	1973	Concrete Slab	Deck	Monitor thru Insp - Program Future Repairs
90	78.81	Kittitas	YAKIMA R	1917	Concrete Arch	Deck	Programmed For Bridge Deck Repair
90	80.31	Kittitas	I-90 OC, BULLFROG RD	1963	Prestress Conc Girder	Deck	Monitor thru Insp - Program Future Repairs
90	80.79	Kittitas	CLE ELUM R	1949	Steel Thru Truss	Deck	Monitor thru Insp - Program Future Repairs
90	97.27	Kittitas	TANEUM CR	1965	Prestress Conc Girder	Deck	Monitor thru Insp - Program Future Repairs
90	100.55	Kittitas	WEST SIDE CANAL	1966	Concrete Slab	Deck	Monitor thru Insp - Program Future Repairs
90	104.71	Kittitas	DRY CR	1967	Concrete Box	Deck	Monitor thru Insp - Program Future Repairs
90	221.95	Adams	SR 261 OC	1952	Concrete Slab	Superstructure	Monitor thru Insp - Program Future Repairs
90	221.95	Adams	SR 261 OC	1958	Concrete Slab	Superstructure	Monitor thru Insp - Program Future Repairs
90	283.03	Spokane	ALTAMONT ST OC	1957	Concrete Slab	Deck	Programmed For Bridge Deck Repair
90	284.35	Spokane	HAVANA ST OC	1957	Concrete Slab	Deck	Programmed For Bridge Deck Repair
97	0	Klickitat	BIGGS RAPIDS-SAM HILL BR	1962	Steel Thru Truss	Deck	Programmed For Bridge Deck Repair
97	45.84	Yakima	SATUS CR 2ND CROSSING	1942	Steel Girder	Scour	Programmed For Bridge Replacement
97	30.8	Klickitat	SATUS CR	1959	Concrete Slab	Superstructure	Programmed for Bridge Repair by contract
97	181.94	Chelan	LARSON CANYON RD BRIDGE	1979	Prestress Conc Girder	Substructure	Monitor thru Insp - Program Future Repairs
99	29.15	King	SPOKANE ST OC	1959	Concrete Box	Substructure	Programmed For Bridge Replacement
99	29.84	King	ALASKAN WAY V NORTHBOUND	1952	Concrete Girder	Superstructure	Programmed For Bridge Replacement
99	29.84	King	ALASKAN WAY V SOUTHBOUND	1952	Concrete Girder	Superstructure	Programmed For Bridge Replacement
101	86.76	Grays Harbor	HOQUIAM R-SIMPSON CS1412	1928	Steel Truss	Superstructure	Programmed for Bridge Repair by contract
101	98.13	Grays Harbor	W FK HOQUIAM R	1934	Timber Girder	Superstructure	Programmed For Bridge Replacement
101	99.49	Grays Harbor	W FK HOQUIAM R	1934	Timber Girder	Substructure	Programmed For Bridge Replacement
101	109	Grays Harbor	HUMPTULIPS R	1950	Steel Thru Truss	Scour	Programmed for Bridge Repair by contract
101	307.16	Jefferson	WALKERS CR	1932	Timber Girder	Substructure	Programmed For Bridge Replacement
101	33.84	Pacific	MIDDLE NEMAH R	1939	Timber Girder	Substructure	Programmed For Bridge Replacement
101	203.15	Clallam	SOL DUC RIVER #2	1941	Steel Thru Truss	Deck	Monitor thru Insp - Program Future Repairs
101	258.21	Clallam	MCDONNELL CR	1939	Timber Girder	Scour	Monitor thru Insp - Program Future Repairs
101	339.3	Mason	PURDY CR	1932	Timber Girder	Substructure	Programmed For Bridge Replacement

WSDOT SD Bridges



State Route	Mile-post	County	Bridge Name	Year Built	Bridge Type	SD Problem	Status
101	45.2	Pacific	BONE R	1935	Timber Girder	Substructure	Programmed For Bridge Replacement
101	362.83	Thurston	MUD BAY	1958	Concrete Slab	Substructure	Programmed for Bridge Repair by contract
101	362.83	Thurston	MUD BAY	1958	Concrete Slab	Substructure	Programmed for Bridge Repair by contract
105	37.23	Grays Harbor	JOHNS R	1952	Steel Girder	Substructure	Programmed for Bridge Repair by contract
105	39.69	Grays Harbor	O LEARY CR	1953	Timber Girder	Substructure	Monitor thru Insp - Program Future Repairs
105	43.99	Grays Harbor	CHAPIN CR	1940	Timber Slab	Substructure	Monitor thru Insp - Program Future Repairs
105	10.07	Pacific	SMITH CR	1959	Prestress Conc Girder	Substructure	Programmed For Bridge Replacement
105	10.42	Pacific	NORTH R	1959	Prestress Conc Girder	Substructure	Programmed For Bridge Replacement
107	6.83	Grays Harbor	CHEHALIS R	1958	Steel Thru Truss	Deck	Programmed for Bridge Repair by contract
107	7.59	Grays Harbor	SLOUGH	1953	Timber Girder	Substructure	Programmed For Bridge Replacement
107	7.79	Grays Harbor	SLOUGH	1953	Timber Girder	Substructure	Programmed For Bridge Replacement
109	6.45	Grays Harbor	GRASS CR	1956	Concrete Slab	Superstructure	Monitor thru Insp - Program Future Repairs
112	23.72	Clallam	GREEN CR	1959	Timber Girder	Substructure	Monitor thru Insp - Program Future Repairs
128	0.22	Asotin	SNAKE R - RED WOLF BR	1979	Steel Box Girder	Deck	Programmed For Bridge Deck Repair
141	23.2	Klickitat	DRAINAGE DITCH	1947	Timber Girder	Substructure	Monitor thru Insp - Program Future Repairs
142	17.55	Klickitat	KLICKITAT R	1954	Prestress Conc Girder	Deck	Monitor thru Insp - Program Future Repairs
162	19.64	Pierce	SR 162 OVER OLD BN RR	1936	Concrete Box	Superstructure	Monitor thru Insp - Program Future Repairs
162	6.81	Pierce	PUYALLUP R	1934	Concrete Truss	Superstructure	Programmed For Bridge Replacement
165	11.93	Pierce	GULCH NO 2	1957	Timber Girder	Substructure	Monitor thru Insp - Program Future Repairs
165	12.03	Pierce	GULCH NO 1	1957	Timber Girder	Substructure	Monitor thru Insp - Program Future Repairs
167	6.4	Pierce	PUYALLUP R	1925	Steel Thru Truss	Superstructure	Programmed For Bridge Replacement
195	37.46	Whitman	SPRING FLAT CR	1920	Concrete Girder	Superstructure	Programmed For Bridge Replacement
203	8.12	King	HARRIS CR	1945	Timber Girder	Substructure	Monitor thru Insp - Program Future Repairs
203	16.5	King	SLOUGH	1945	Timber Girder	Substructure	Monitor thru Insp - Program Future Repairs
203	1.09	King	SLOUGH	1945	Timber Girder	Substructure	Monitor thru Insp - Program Future Repairs
203	1.37	King	SLOUGH	1945	Timber Girder	Substructure	Monitor thru Insp - Program Future Repairs
231	44.65	Stevens	SPOKANE R	1949	Concrete Arch	Deck	Programmed For Bridge Deck Repair
241	23.2	Yakima	DRY CR	1900	Timber Girder	Substructure	Programmed For Bridge Replacement
241	1.34	Yakima	MABTON-SUNNYSIDE #650	1954	Concrete Box	Superstructure	Monitor thru Insp - Program Future Repairs
261	10.27	Columbia	TUCANNON R	1967	Prestress Conc Girder	Deck	Programmed For Bridge Deck Repair
261	57.9	Adams	DRY RUN	1900	Concrete Girder	Substructure	Monitor thru Insp - Program Future Repairs
290	0.82	Spokane	SPOKANE R EAST TRENT	1910	Concrete Arch	Superstructure	Programmed For Bridge Replacement
300	0.28	Mason	MISSION CR	1963	Timber Slab	Scour	Monitor thru Insp - Program Future Repairs
302	15.65	Pierce	PURDY BR	1936	Concrete Box	Substructure	Monitor thru Insp - Program Future Repairs
303	1.47	Kitsap	MANETTE BRIDGE CS1841	1930	Steel Deck Truss	Substructure	Programmed For Bridge Replacement

WSDOT SD Bridges

State Route	Mile-post	County	Bridge Name	Year Built	Bridge Type	SD Problem	Status
395	18.25	Benton	IMNAHA DR OC	1954	Steel Girder	Superstructure	Monitor thru Insp - Program Future Repairs
410	92.76	Yakima	MILK CR	1939	Timber Slab	Substructure	Monitor thru Insp - Program Future Repairs
410	21.8	Pierce	PSPL CO CANAL	1949	Steel Girder	Deck	Programmed For Bridge Deck Repair
502		Clark	MILL CREEK NO 2	1970	Steel Culvert	Superstructure	Monitor thru Insp - Program Future Repairs
506	8.05	Lewis	LACAMAS CR	1951	Timber Girder	Substructure	Programmed For Bridge Replacement
508	13.65	Lewis	S FK NEWAUKUM R	1930	Steel Thru Truss	Deck	Programmed for Bridge Repair by contract
508	22.65	Lewis	ALDER CR	1937	Timber Girder	Substructure	Programmed For Bridge Replacement
508	24.08	Lewis	CREEK	1937	Timber Girder	Superstructure	Programmed For Bridge Replacement
509	0.79	Pierce	PUYALLUP RIVER BRIDGE	1996	Post Tension Conc Box	Superstructure	Programmed for Bridge Repair by contract
509	0.22	Pierce	MURRAY MORGAN BR CS2749	1911	Steel Thru Truss	Superstructure	City/State negotiating removal v. rehabilitation
512	3.09	Pierce	GOLDEN-GIVENS RD OC	1966	Prestress Conc Girder	Superstructure	Monitor thru Insp - Program Future Repairs
512	3.09	Pierce	GOLDEN-GIVENS RD OC	1966	Prestress Conc Girder	Superstructure	Monitor thru Insp - Program Future Repairs
529	5.13	Snohomish	UNION SL	1927	Concrete Girder	Substructure	Monitor thru Insp - Program Future Repairs
529	6.21	Snohomish	EBEY SLOUGH CS3116	1925	Steel Thru Truss	Superstructure	Programmed For Bridge Replacement
542	28.34	Whatcom	BOULDER CR	1952	Concrete Slab	Substructure	Programmed For Bridge Replacement
548	11.54	Whatcom	DAKOTA CR	1930	Steel Girder	Superstructure	Programmed For Bridge Replacement
906	2.98	Kittitas	COAL CREEK	1970	Timber Girder	Substructure	Monitor thru Insp - Program Future Repairs

Local Agency SD Bridges



Bridge Owner	Roadway Carried	Bridge Name	Year Built	Bridge Type	Reason for SD	Status
Adams County	SCHOESSLER ROAD	GEORGE HILZER	1961	Timber Girder	Deck	Monitor through Inspection
Adams County	SACKMAN ROAD	SACKMAN	1953	Timber Girder	Deck	Monitor through Inspection
Adams County	ARLT ROAD	KEYSTONE	1900	Concrete Slab	Deck/Substructure	Monitor through Inspection
Adams County	OLD SR 26	HOOPER STORE	1944	Timber Girder	Deck/Superstructure/Substructure	Monitor through Inspection
Adams County	PROVIDENCE ROAD	BENWARD	1900	Concrete Girder	Substructure	Monitor through Inspection
Adams County	GRIFFITH ROAD	GOTTLIEB HILLE	1929	Concrete Girder	Substructure	Monitor through Inspection
Adams County	DANEKAS ROAD	RICK BURGER	1900	Concrete Arch	Substructure	Monitor through Inspection
Adams County	PAHA-PACKARD RD	PACKARD	1915	Steel Girder	Substructure	Monitor through Inspection
Adams County	Gray Road	HOOPER OVERCROSSING	1913	Timber Girder	Substructure	Monitor through Inspection
Adams County	WAHL ROAD	KLEMMER	1940	Steel Girder	Substructure	Monitor through Inspection
Adams County	HERMAN ROAD	HERMAN	1952	Timber Girder	Superstructure	Monitor through Inspection
Adams County	MCMANAMON ROAD	MCMANAMON	1951	Concrete Girder	Superstructure	Monitor through Inspection
CASHMERE	ANGIER AVENUE	ANGIER AVE BRIDGE	1960	Concrete Girder	Superstructure	Monitor through Inspection
Chelan County	GOODWIN ROAD	WEST CASHMERE	1929	Steel Deck Truss	Deck	Monitor through Inspection
Chelan County	Kingsbury Rd 15400	KINGSBURY ROAD BRIDGE	1973	Steel Girder & Floor System	Deck	Monitor through Inspection
Chelan County	OLD MONITOR ROAD	WEST MONITOR	1907	Steel Through Truss	Deck/Superstructure	Monitor through Inspection
Chelan County	MOE RIDGE ROAD	MOE RIDGE BRIDGE	1930	Timber Girder	Deck/Superstructure/Substructure	Monitor through Inspection
Chelan County	OLD BLEWETT ROAD	OLD BLEWETT #1	1979	Timber Girder	Deck/Superstructure/Substructure	Programmed for Replacement
Chelan County	SUNSET HIGHWAY	MISSION CR-SUNSET HWY	1925	Concrete Slab	Superstructure/Substructure	Monitor through Inspection
Clallam County	WEEL ROAD	WEEL BRIDGE	1969	Steel Girder & Floor System	Deck/Superstructure	Monitor through Inspection
Clallam County	CHARLEY CREEK ROAD	CHARLEY CREEK BRIDGE	1948	Timber Girder	Substructure	Monitor through Inspection
Clallam County	ELWHA RIVER ROAD	ELWHA RIVER BRIDGE	1913	Steel Deck Truss	Superstructure/Substructure	Programmed for Replacement
PORT ANGELES	8TH ST	SR 117 OC, 8TH ST	1935	Timber Girder	Substructure	Monitor through Inspection
PORT ANGELES	8TH ST (OLD SR112)	EIGHTH AND TUMWATER	1935	Timber Girder	Substructure	Programmed for Replacement
PORT ANGELES	8TH ST (OLD SR112)	EIGHTH AND VALLEY	1935	Timber Girder	Substructure	Programmed for Replacement
Clark County	NE HANTWICK RD	LUCIA FALLS	1937	Concrete Girder	Repaired	Programmed for Rehabilitation
Clark County	NE 88TH ST.	FIFTH PLAIN CREEK	1933	Concrete Girder	Substructure	Monitor through Inspection
Clark County	CEDAR CREEK RD	DAYTON	1930	Concrete Girder	Substructure	Monitor through Inspection
Clark County	NE SALMON CREEK AV	BETTS	1935	Timber Girder	Superstructure	Programmed for Replacement
Clark County	NE HWY 99	KLINELINE	1928	Concrete Girder	Superstructure	Programmed for Replacement
Columbia County	KING GRADE	KING	1974	Timber Girder	Deck	Monitor through Inspection
Columbia County	WHISKY CREEK ROAD	NEACE	1963	Steel Girder	Substructure	Monitor through Inspection
Columbia County	BAILEYSBURG ROAD	BAILEYSBURG	1975	Timber Girder	Superstructure	Monitor through Inspection
Cowlitz County	OLD 99 SOUTH	OWL CREEK BRIDGE	1922	Concrete Girder	Deck/Superstructure	Monitor through Inspection

Local Agency SD Bridges



Bridge Owner	Roadway Carried	Bridge Name	Year Built	Bridge Type	Reason for SD	Status
Cowlitz County	MILL CREEK RD	MILL CREEK BRIDGE 3	1960	Concrete Slab	Substructure	Monitor through Inspection
Cowlitz County	TOWER RD	TOWER RD BRIDGE	1981	Concrete Girder	Substructure	Monitor through Inspection
Cowlitz County	PACIFIC AVE NORTH	PACIFIC AVE N 1/2 BRIDGE	1919	Concrete Girder	Superstructure	Monitor through Inspection
Cowlitz County	ROSE VALLEY RD	MULHOLLAND CREEK BRIDGE	1954	Concrete Girder	Superstructure	Programmed for Replacement
LONGVIEW	WASHINGTON WAY	WASHINGTON WAY	1935	Timber Girder	Incorrectly Marked SD	Monitor through Inspection
Douglas County	Road 9.5 SW	BEAVER CREEK (BRETT)	1958	Timber Girder	Substructure	Monitor through Inspection
Douglas County	ELVA WAY	ELVA WAY	1953	Timber Girder	Superstructure	Monitor through Inspection
Ferry County	CURLEW STREET	CURLEW	1908	Steel Through Truss	Superstructure	Programmed for Rehabilitation
Franklin County	COUNTY ROAD	FILBERT ROAD	1954	Timber Girder	Superstructure	Monitor through Inspection
Garfield County	(DRIVEWAY)	KLAVENO M.P. 0.01	1961	Timber Girder	Superstructure/Substructure	Monitor through Inspection
POMEROY	6TH STREET	PATAHA CR-6TH STREET	1940	Steel Girder	Substructure	Monitor through Inspection
Grant County	CRESCENT BAR ROAD	CRESCENT BAR	1963	Steel Girder & Floor System	Deck	Programmed for Replacement
Grant County	F RD NE	F NE Bailey	1948	Steel Through Truss	Structural Adequacy	Programmed for Replacement
Grant County	22.5 RD NE	22.5 Cannawai	1961	Timber Girder	Superstructure	Programmed for Replacement
Grays Harbor County	OCEAN BEACH ROAD	HUMPTULIPS OVFL BR (1)	1966	Timber Girder	Deck/Substructure	Monitor through Inspection
Grays Harbor County	HARP ROAD	GARRARD CREEK BRIDGE	1967	Steel Girder	Deck/Substructure	Programmed for Replacement
Grays Harbor County	FORREST ROAD	GARRARD CREEK BRIDGE	1967	Steel Girder	Substructure	Programmed for Replacement
Grays Harbor County	MATTSON ROAD	GARRARD CREEK BRIDGE	1967	Steel Girder	Substructure	Monitor through Inspection
Grays Harbor County	CAMP CREEK ROAD	CAMP CREEK BRIDGE	1971	Concrete Slab	Substructure	Monitor through Inspection
Grays Harbor County	CHURCH ROAD	WILDCAT CREEK BRIDGE	1966	Concrete Slab	Substructure	Monitor through Inspection
Grays Harbor County	QUINAULT S. SHORE	ZIEGLER CREEK BRIDGE (3)	1971	Concrete Slab	Substructure	Monitor through Inspection
Grays Harbor County	WISHKAH ROAD	CEDAR CREEK BRIDGE	1981	Concrete Slab	Substructure	Monitor through Inspection
Grays Harbor County	CLOQUALLUM CRK RD	BUSH CREEK BRIDGE	1900	Concrete Arch	Substructure	Monitor through Inspection
Grays Harbor County	GEISSLER ROAD	WEDEKIND CREEK BRIDGE	1973	Concrete Slab	Substructure	Monitor through Inspection
Grays Harbor County	O'NEILL ROAD	NEWMAN CREEK BRIDGE (1)	1962	Concrete Girder	Substructure	Monitor through Inspection

Local Agency SD Bridges



Bridge Owner	Roadway Carried	Bridge Name	Year Built	Bridge Type	Reason for SD	Status
Grays Harbor County	STAMPER ROAD	CLOQUALLUM CREEK BRIDGE	1945	Steel Girder	Substructure	Programmed for Rehabilitation
Grays Harbor County	SCHMID ROAD (S)	DRAINAGE BRIDGE	1971	Concrete Slab	Substructure	Programmed for Replacement
Grays Harbor County	SCHMID ROAD (N)	DRAINAGE BRIDGE	1971	Concrete Slab	Substructure	Programmed for Replacement
Grays Harbor County	BROOKLYN ROAD	GARRARD CREEK BRIDGE	1971	Concrete Slab	Substructure	Programmed for Replacement
Grays Harbor County	MIDDLE SATSOP ROAD	TORNOW BRIDGE	1973	Concrete Girder	Substructure	Programmed for Scour
Grays Harbor County	HEISE ROAD	ROBERSON BR (HEISE RD)	1980	Concrete Slab	Superstructure	Monitor through Inspection
OCEAN SHORES	TONQUIN AVE	TONQUIN	1970	Timber Girder	Substructure	Monitor through Inspection
BOTHEL	102ND AVE	102ND AVE UC	1950	Steel Girder	Superstructure	Programmed for Rehabilitation
ISSAQUAH	N.W.DOGWOOD ST	N.W. DOGWOOD BRIDGE	1950	Concrete Girder	Structural Adequacy	Monitor through Inspection
KENMORE	NE 175TH ST	LOWER SWAMP CR.	1951	Concrete Girder	Substructure	Monitor through Inspection
King County	VASHON HWY SW	JUDD CREEK	1953	Concrete Girder	Deck	Programmed for Replacement
King County	14/16TH AVE S	SOUTH PARK BRIDGE	1931	Steel Deck Truss	Deck/Substructure	Monitor through Inspection
King County	S 3RD AVE KENT	ALVORD "T"	1914	Steel Through Truss	Deck/Superstructure	Monitor through Inspection
King County	MOUNT SI ROAD	MT. SI BRIDGE	1955	Steel Through Truss	Structural Adequacy	Programmed for Replacement
King County	UPPER PRESTON RD	UPPER PRESTON	1950	Concrete Girder	Substructure	Monitor through Inspection
King County	KENT-BLCK DIMND	BERRYDALE OX	1931	Timber Girder	Substructure	Monitor through Inspection
King County	SE MAY VALLEY RD	BANDARET	1952	Timber Girder	Substructure	Programmed for Replacement
King County	NE INDEX CK RD	BARING BRIDGE	1930	Timber Suspension	Superstructure/Substructure	Monitor through Inspection
King County	SE LAKE DRTHY RD	LAKE DOROTHY OVERFLOW	1962	Timber Girder	Superstructure/Substructure	Monitor through Inspection
King County	NORTH FORK RD SE	SUNDAY CREEK	1962	Timber Girder	Superstructure/Substructure	Programmed for Replacement
King County	NE 32 ST-CARNATION	TOLT BRIDGE	1922	Steel Through Truss	Superstructure/Substructure	Programmed for Replacement
King County	NORTH FORK RD SE	WAGNERS BRIDGE	1977	Timber Girder	Superstructure/Substructure	Programmed for Replacement
King County	284 AVE NE	SIKES LAKE TRESTLE	1978	Concrete Slab	Superstructure/Substructure	Programmed for Seismic
RENTON	JONES AVE NE	MAY CREEK BRIDGE #1	1950	Concrete Girder	Substructure	Monitor through Inspection
SEATTLE	SW SPOKANE ST	SW SPOK ST VIAD	1941	Concrete Girder	Deck	Monitor through Inspection
SEATTLE	2 AVE EXTEN S	2ND AVE EXTENSION S	1928	Steel Girder	Superstructure	Monitor through Inspection
SEATTLE	15TH AVE NE	COWEN PARK BR	1936	Concrete Arch	Superstructure	Monitor through Inspection
SEATTLE	FREMONT AVE N	FREMONT BR. APPROACHES	1917	Steel Girder & Floor System	Superstructure	Programmed for Replacement
SHORELINE	27TH AVE NW	RICHMOND BEACH OXING	1923	Timber Girder	Superstructure	Programmed for Replacement
TUKWILA	BOEING ACCESS RD	BOEING ACCESS RD	1945	Concrete Girder	Substructure	Monitor through Inspection

Local Agency SD Bridges



Bridge Owner	Roadway Carried	Bridge Name	Year Built	Bridge Type	Reason for SD	Status
Kitsap County	NW STAVIS BAY RD	STAVIS BAY ROAD BRIDGE	1952	Timber Girder	Substructure	Monitor through Inspection
Kitsap County	Southworth Drive	Southworth Drive Bridge	1929	Concrete Girder	Substructure	Monitor through Inspection
Kittitas County	BAR 14 ROAD	BAR 14 RD-HIGHLINE CANAL	1931	Concrete Slab	Substructure	Programmed for Replacement
Kittitas County	CHARLTON ROAD	CHARLTON RD-NANEUM CREEK	1938	Concrete Girder	Substructure	Programmed for Replacement
Kittitas County	SANDERS ROAD	SANDERS RD-WILSON CREEK	1955	Concrete Girder	Superstructure	Monitor through Inspection
Klickitat County	HARMS RD	HARMS	1977	Steel Through Truss	Deck	Programmed for Replacement
Klickitat County	HORSESHOE BEND RD.	WAHKIACUS BIG KLICKITAT	1965	Concrete Girder	Deck/Substructure	Programmed for Replacement
Klickitat County	NORTHWESTERN LK RD	NORTHWESTERN	1957	Concrete Girder	Substructure	Monitor through Inspection
Klickitat County	GOLDENDALE HWY.	OUTLET CREEK	1970	Concrete Girder	Superstructure	Monitor through Inspection
WHITE SALMON	E MARINA WAY	HOOD RIVER BRIDGE	1924	Steel Deck Truss	Superstructure	Monitor through Inspection
CENTRALIA	ALLEY	ROCK ST. ALLEY WEST	1941	Concrete Slab	Superstructure/Substructure	Programmed for Replacement
CHEHALIS	NE EXHIBITOR RD.	SALZER CR (EXHIBITOR ST)	1971	Concrete Slab	Scour	Monitor through Inspection
CHEHALIS	N NATIONAL AVE	NATIONAL AVE. SALZER CR	1936	Concrete Slab	Scour	Monitor through Inspection
CHEHALIS	NE KRESKY RD	SALZER CR (NW KRESKY)	1964	Concrete Slab	Scour	Monitor through Inspection
CHEHALIS	RIVERSIDE DR	RIVERSIDE BRIDGE	1952	Concrete Slab	Scour	Monitor through Inspection
Lewis County	COUGHLIN ROAD	COUGHLIN MP 0.05	1922	Steel Through Truss	Deck/Superstructure	Monitor through Inspection
Lewis County	SILVERBROOK ROAD	SILVERBROOK MP 2.61	1934	Concrete Girder	Deck/Superstructure/Substructure	Programmed for Replacement
Lewis County	SHOREY RD	SHOREY MP 0.73	1960	Concrete Girder	Substructure	Monitor through Inspection
Lewis County	JACKSON HWY	JACKSON HWY MP 4.49	1926	Steel Through Truss	Superstructure	Programmed for Replacement
DAVENPORT	SEVENTH STREET	COTTONWOOD CR-SEVENTH ST	1930	Steel Girder	Superstructure/Substructure	Monitor through Inspection
Lincoln County	ZELLMER ROAD 61240	GERALD ZELLMER BRIDGE	1918	Steel Girder	Substructure	Monitor through Inspection
Lincoln County	COUNTY ROAD 3484	LORDS VALLEY BRIDGE	1959	Steel Girder	Substructure	Monitor through Inspection
Lincoln County	MOHLER ROAD 22250	COAL CREEK BRIDGE	1917	Concrete Arch	Substructure	Monitor through Inspection
Lincoln County	OLD SEDALIA ROAD	KNAFF BRIDGE	1936	Steel Girder	Substructure	Monitor through Inspection
Lincoln County	JOHNSON ROAD 43910	GEIB BRIDGE	1940	Steel Girder	Substructure	Monitor through Inspection
Lincoln County	DUCK LAKE RD 92310	WAGNER BRIDGE	1972	Concrete Girder	Substructure	Monitor through Inspection
Lincoln County	G. KUNZ ROAD 46900	G. KUNZ BRIDGE	1936	Steel Girder	Substructure	Programmed for Replacement
Lincoln County	COUNTY ROAD 13660	EAST PFIEFER BRIDGE	1930	Steel Girder	Substructure	Programmed for Replacement
Lincoln County	BLEND ROAD 45130	BLENZ BRIDGE	1936	Steel Girder	Superstructure	Monitor through Inspection
Mason County	CO. RD. 41640	HUNTER CREEK	1956	Concrete Slab	Substructure	Monitor through Inspection
Pacific County	FALLS CREEK ROAD	HUBER BR.	1949	Timber Girder	Deck	Monitor through Inspection
Pend Oreille County	COUNTY RD.NO 27140	LITTLE MUDDY CK. BR.	1960	Timber Girder	deck	Monitor through Inspection
Pend Oreille County	COUNTY RD NO 93250	IONE BRIDGE	1932	Steel Deck Truss	Deck	Programmed for Rehabilitation

Local Agency SD Bridges



Bridge Owner	Roadway Carried	Bridge Name	Year Built	Bridge Type	Reason for SD	Status
Pend Oreille County	COUNTY RD NO 20220	NORTH FORK CALISPEL CR.	1960	Timber Girder	Deck/Substructure	Programmed for Replacement
Pend Oreille County	COUNTY RD NO 35030	WEST BRANCH NO 3	1956	Timber Girder	Deck/Superstructure/Substructure	Programmed for Replacement
LAKEWOOD	INTERLAAKEN DRIVE	STEILACOOM LAKE	1927	Timber Girder	Structural Adequacy	Monitor through Inspection
Pierce County	288TH ST S	LACAMAS CREEK	1954	Timber Girder	Deck	Monitor through Inspection
Pierce County	8 AVE EAST	NORTH FORK MUCK CREEK	1959	Timber Girder	Deck	Monitor through Inspection
Pierce County	South Vaughn Road	VAUGHN BAY	1966	Concrete Girder	Deck	Programmed for Replacement
Pierce County	CLAY CITY ROAD	CLAY CITY	1963	Concrete Girder	Substructure	Monitor through Inspection
Pierce County	HERRON RD N	HERRON BAY	1929	Concrete Slab	Substructure	Monitor through Inspection
Pierce County	Orville Road East	KAPOWSIN CREEK	1939	Concrete Slab	Substructure	Programmed for Replacement
SUMNER	BRIDGE STREET	STUCK RIVER	1927	Steel Through Truss	Superstructure	Programmed for Rehabilitation
TACOMA	EAST LINCOLN AVE	EAST LINCOLN AVENUE	1929	Steel Through Truss	Deck/Superstructure	Monitor through Inspection
TACOMA	PUYALLUP AVENUE	PUYALLUP RIVER BRIDGE D	1925	Steel Through Truss	Deck/Superstructure	Monitor through Inspection
TACOMA	East 11th Street	HYLEBOS WATERWAY CS2746	1939	Steel Movable	Deck/Superstructure	Programmed for Rehabilitation
TACOMA	STATE ROUTE 509	PUYALLUP R RR OC CS2748	1930	Steel Through Truss	Deck/Superstructure/Substructure	Monitor through Inspection
TACOMA	EAST L STREET	EAST L STREET BRIDGE	1931	Timber Girder	Deck/Superstructure/Substructure	Programmed for Replacement
TACOMA	PUYALLUP AVENUE	PUYALLUP RIVER BRIDGE B	1925	Concrete Girder	Substructure	Programmed for Replacement
TACOMA	PUYALLUP AVENUE	PUYALLUP RIVER BRIDGE	1925	Steel Through Truss	Superstructure	Monitor through Inspection
TACOMA	PUYALLUP AVENUE	PUYALLUP RIVER BRIDGE A	1925	Steel Through Truss	Superstructure	Programmed for Replacement
Skagit County	BURL ALGER ROAD	BURL. ALGER ROAD	1934	Timber Girder	Deck	Monitor through Inspection
Skagit County	BURL.-ALGER RD	FRIDAY CREEK BRIDGE	1956	Concrete Girder	Deck	Monitor through Inspection
Skagit County	BURL-ALGER RD	BURL. ALGER ROAD	1934	Timber Girder	Deck	Programmed for Replacement
Skagit County	OLD HWY 99 NORTH	BURL NORTHERN OVERPASS	1936	Steel Girder	Substructure	Monitor through Inspection
Skagit County	BEST ROAD	NORTH FORK BRIDGE	1959	Steel Girder	Substructure	Programmed for Scour
Skagit County	GUEMES ISLAND ROAD	ANACORTES FERRY DOCK	1925	Steel Girder & Floor System	Superstructure	Monitor through Inspection
Skagit County	PULVER ROAD	DITCH PULVER ROAD	1955	Concrete Girder	Superstructure	Monitor through Inspection
Skagit County	GUEMES ISLAND ROAD	GUEMES ISLAND FERRY DOCK	1981	Steel Girder & Floor System	Superstructure	Programmed for Paint
STEVENSON	CASCADE AVE EXT.	KANAKA CREEK	1920	Timber Girder	Deck	Monitor through Inspection
STEVENSON	Rock Creek Drive	ROCK CREEK BRIDGE 2	1921	Concrete Girder	Scour	Monitor through Inspection
BOTHEL	240TH ST SE	NORTH CREEK #4	1962	Concrete Girder	Substructure	Monitor through Inspection
EVERETT	STATE ROUTE 529	BN RR OC (GN)	1912	Steel Girder	Substructure	Monitor through Inspection
GOLD BAR	FIRST ST	GOLD BAR	1938	Timber Girder	Deck/Substructure	Programmed for Replacement
Snohomish County	MOUNTAIN LOOP HWY	GRANITE FALLS	1934	Steel Deck Truss	Deck	Programmed for Rehabilitation
Snohomish County	MOUNTAIN LOOP HWY.	DEER CREEK #670	1949	Timber Girder	Substructure	Monitor through Inspection

Local Agency SD Bridges



Bridge Owner	Roadway Carried	Bridge Name	Year Built	Bridge Type	Reason for SD	Status
Snohomish County	CRESWELL RD	CARPENTER CREEK #265	1964	Timber Girder	Substructure	Monitor through Inspection
Snohomish County	MOUNTAIN LOOP HWY	BLACK CREEK #547	1952	Concrete Girder	Substructure	Monitor through Inspection
Snohomish County	233RD PL S.E.	BEAR CREEK #625	1973	Concrete Girder	Substructure	Monitor through Inspection
Snohomish County	CARTER RD	SWAMP CREEK #546	1966	Concrete Girder	Substructure	Monitor through Inspection
Snohomish County	208 TH ST SE	SWANSON	1935	Timber Girder	Substructure	Programmed for Replacement
Snohomish County	MOUNTAIN LOOP HWY.	MARTEN CREEK	1949	Timber Girder	Substructure	Programmed for Replacement
Snohomish County	SANDERS RD	CARPENTER CREEK #448	1984	Timber Girder	Superstructure	Monitor through Inspection
Snohomish County	SCHERRER RD	SCHERRER ROAD	1985	Timber Girder	Superstructure	Monitor through Inspection
Snohomish County	MOUNTAIN LOOP HWY.	BUCK CREEK	1960	Concrete Girder	Superstructure	Monitor through Inspection
Snohomish County	PICKLEFARM RD.	MAY CREEK #572	1984	Timber Girder	Superstructure	Programmed for Replacement
Snohomish County	SAUK PRAIRIE RD	SAUK RIVER #414	1930	Steel Through Truss	Superstructure	Programmed for Replacement
Snohomish County	INDEX-GALENA RD	HOWARD CREEK	1976	Timber Girder	Superstructure/Substructure	Monitor through Inspection
SPOKANE	POST STREET	POST ST OC SPOKANE RIVER	1917	Concrete Arch	Deck/Superstructure/Substructure	Programmed for Removal
SPOKANE	FREYA ST	FREYA ST OC BNSF	1928	Concrete Girder	Deck/Superstructure/Substructure	Programmed for Replacement
Spokane County	CHENEY-SPOKANE RD	CHENEY-SPO OVER UP&BN RR	1949	Concrete Girder	Deck	Monitor through Inspection
Spokane County	APPLEWAY AVE	OLD I-90 OVER SPOKANE R.	1939	Concrete Girder	Deck	Programmed for Replacement
Spokane County	SUNSET HIGHWAY	SUNSET HWY OV W BR DEEP	1910	Steel Girder	Deck/Superstructure	Monitor through Inspection
Spokane County	LITTLE SPOKANE DR.	L SPO DR OVER L SPO RIV	1954	Concrete Girder	Structural Adequacy	Programmed for Replacement
SPOKANE VALLEY	SULLIVAN ROAD	SULLIVAN ROAD OVER SPO R	1951	Concrete Girder	Deck	Monitor through Inspection
SPOKANE VALLEY	BARKER ROAD	BARKER RD OVER SPO RIVER	1952	Concrete Girder	Deck/Superstructure	Programmed for Replacement
Stevens County	Greenwood Loop	COLVILLE-ARIS	1963	Steel Girder	Deck/Superstructure	Programmed for Rehabilitation
Thurston County	OLD HWY 99 SE	OLD HIGHWAY 99	1923	Concrete Slab	Substructure	Programmed for Replacement
Wahkiakum County	FERRY RAMP	WAHIAKUM CO FERRY RAMP	1975	Steel Girder	Deck/Substructure	Programmed for Replacement
WALLA WALLA	4TH ST	4TH AT MILL CR	1908	Concrete Girder	Structural Adequacy	Monitor through Inspection
WALLA WALLA	SPOKANE ST	SPOKANE AT MILL CR	1905	Concrete Girder	Superstructure	Monitor through Inspection
WALLA WALLA	OTIS ST	OTIS AT MILL CR	1923	Concrete Girder	Superstructure	Monitor through Inspection
WALLA WALLA	PALOUSE ST	PALOUSE AT MILL CR	1916	Concrete Girder	Superstructure	Programmed for Replacement
Walla Walla County	WOODWARD CANYON RD	GOBLE	1968	Steel Girder	Deck	Monitor through Inspection
Walla Walla County	LOWER HOGEYE RD	SUB STATION	1916	Concrete Arch	Substructure	Monitor through Inspection
Walla Walla County	HOOD RD	HOOD SCHOOL	1969	Steel Girder	Substructure	Programmed for Replacement
Walla Walla County	LOWDEN GARDENA RD	LOWDEN	1920	Concrete Arch	Substructure	Programmed for Replacement
Walla Walla County	MCCOWN RD	McCOWN	1920	Concrete Arch	Substructure	Programmed for Replacement
BELLINGHAM	SQUALLICUM WAY	SQUALLICUM WY BOX CUL #1	1970	Concrete Culvert	Culvert	Monitor through Inspection
BELLINGHAM	JAMES STREET	JAMES STREET @ ABAN RR 1	1945	Timber Girder	Deck	Monitor through Inspection

Local Agency SD Bridges



Bridge Owner	Roadway Carried	Bridge Name	Year Built	Bridge Type	Reason for SD	Status
BELLINGHAM	JAMES STREET	JAMES STREET @ ABAND RR2	1945	Timber Girder	Deck/Superstructure	Monitor through Inspection
BELLINGHAM	ELDRIDGE AVENUE	ELDRIDGE AVE/SQUALLICUM	1937	Concrete Girder	Structural Adequacy	Monitor through Inspection
BELLINGHAM	CHESTNUT ST-BAY ST	CHESTNUT-BAY/RR	1930	Concrete Girder	Substructure	Monitor through Inspection
EVERSON	ROBINSON STREET	NOOKSACK SL-ROBINSON ST	1960	Concrete Girder	Substructure	Monitor through Inspection
LYNDEN	MAIN STREET	FISHTRAP CR - MAIN ST	1970	Steel Culvert	Culvert	Monitor through Inspection
LYNDEN	N 14TH STREET	FISHTRAP CR - N 14TH ST	1970	Concrete Girder	Substructure	Programmed for Replacement
LYNDEN	KOK RD	FISH TRAP CR	1935	Concrete Girder	Superstructure/Substructure	Monitor through Inspection
Whatcom County	MARINE DR	LITTLE SQUALICUM	1933	Concrete Girder	Deck	Monitor through Inspection
Whatcom County	MOSQUITO LK RD	MIDDLE FORK	1915	Steel Through Truss	Deck	Programmed for Rehabilitation
Whatcom County	BAKER LAKE ROAD	SULPHUR CREEK	1963	Concrete Slab	Scour	Monitor through Inspection
Whatcom County	NOON RD	TEN MILE CR	1954	Concrete Girder	Substructure	Monitor through Inspection
Whatcom County	CLEARBROOK RD	JOHNSON CR	1955	Concrete Girder	Substructure	Programmed for Replacement
Whatcom County	HAMPTON RD	KAMM SLOUGH	1960	Concrete Girder	Substructure	Programmed for Replacement
Whatcom County	S BAY DR	BRANNIAN CREEK	1944	Concrete Girder	Superstructure/Substructure	Monitor through Inspection
COLTON	STEPTOE STREET	UNION FLAT CR-STEPTOE	1910	Concrete arch	Substructure	Monitor through Inspection
FARMINGTON	FIRST STREET	S FK PINE CR-FIRST ST	1918	Concrete arch	Superstructure/Substructure	Monitor through Inspection
OAKESDALE	STEPTOE STREET	BR MCCOY CR-STEPTOE ST	1955	Timber Girder	Scour	Monitor through Inspection
PULLMAN	KAMIAKEN STREET	KAMIAKEN STREET	1930	Concrete Girder	Deck/Superstructure	Monitor through Inspection
PULLMAN	SPRING ST	SPRING ST	1915	Concrete Arch	Superstructure	Monitor through Inspection
Whitman County	KILE/3630	KILE APPROACH	1911	Timber Girder	Deck	Monitor through Inspection
Whitman County	CHERRY CREEK/4150	EWAN	1964	Concrete Girder	Deck	Monitor through Inspection
Whitman County	MCNEILLY/6240	MCNEILLY	1948	Timber Girder	Deck	Programmed for Replacement
Whitman County	ZARBACH/3605	ZARBACH	1945	Timber Girder	Deck/Substructure	Programmed for Replacement
Whitman County	GARFLD-FRMGTN/1300	HARLAN	1934	Steel Girder & Floor System	Deck/Superstructure	Programmed for Replacement
Whitman County	PARVIN/5000	FOUR MILE NO. 5	1900	Timber Girder	Deck/Superstructure/Substructure	Programmed for Replacement
Whitman County	CASHUP FLAT/3500	PLEASANT VALLEY	1944	Timber Girder	Deck/Superstructure/Substructure	Programmed for Replacement
Whitman County	BIG ALKALI/7005	NEEL	1920	Timber Girder	Scour	Programmed for Replacement
Whitman County	UNIONTWN EAST/9410	BABINSKI	1960	Concrete Girder	Structural Adequacy	Monitor through Inspection
Whitman County	BIG ALKALI/7005	AUNE	1921	Timber Girder	Substructure	Programmed for Replacement
UNION GAP	PIONEER STREET	PIONEER STREET #807	1961	Timber Girder	Deck/Superstructure	Programmed for Replacement
YAKIMA	YAKIMA AVE., E.	18TH ST UNDERPASS 1311	1979	Concrete Girder	Structural Adequacy	Monitor through Inspection
YAKIMA	40TH AVE.,S.	40TH AVE.,S. #1306	1978	Concrete Girder	Structural Adequacy	Monitor through Inspection
YAKIMA	NOB HILL BLVD	NOB HILL RR #2	1964	Concrete Girder	Substructure	Monitor through Inspection

Local Agency SD Bridges



Bridge Owner	Roadway Carried	Bridge Name	Year Built	Bridge Type	Reason for SD	Status
Yakima County	EVANS RD.	EVANS ROAD #430	1968	Steel Culvert	Culvert	Monitor through Inspection
Yakima County	GREEN VALLEY ROAD	GREEN VALLEY ROAD #621	1957	Timber Girder	Deck	Monitor through Inspection
Yakima County	WIERNAN RD.	WIERNAN ROAD #692	1973	Timber Girder	Deck	Monitor through Inspection
Yakima County	WEST PARKER HEIGHT	PARKER HGHTS RD.,W. #398	1919	Steel Through Truss	Deck	Monitor through Inspection
Yakima County	MARION DRAIN RD. I	MARION DRAIN ROAD #421	1960	Timber Girder	Deck/Substructure	Programmed for Replacement
Yakima County	NORTH FORK RD.	NORTH FORK #109	1953	Timber Girder	Substructure	Monitor through Inspection
Yakima County	OLD NACHES HIGHWAY	OLD NACHES HIGHWAY #460	1922	Concrete Slab	Substructure	Monitor through Inspection
Yakima County	TERRACE HTS DR	TERRACE HTS DR #166	1937	Steel Girder	Substructure	Monitor through Inspection
Yakima County	ROBBINS RD.	ROBBINS ROAD #499	1959	Timber Girder	Substructure	Monitor through Inspection
Yakima County	FORT ROAD	FORT ROAD #1354	1939	Timber Girder	Substructure	Programmed for Replacement
Yakima County	THACKER ROAD	THACKER ROAD #674	1960	Concrete Slab	Superstructure	Monitor through Inspection
Yakima County	PIONEER WAY	PIONEER WAY #70	1958	Concrete Girder	Superstructure	Monitor through Inspection
Yakima County	HUDSON ROAD	HUDSON ROAD #489	1957	Concrete Girder	Superstructure	Monitor through Inspection
Yakima County	ZILLAH HEIGHTS RD	ZILLAH HEIGHTS ROAD #401	1920	Steel Through Truss	Superstructure	Monitor through Inspection
Yakima County	MEYERS RD.,N.	MEYERS RD.,N. #502	1950	Concrete Girder	Superstructure	Monitor through Inspection
Yakima County	POWERHOUSE RD.,W.	POWERHOUSE ROAD, W.#786	1922	Steel Through Truss	Superstructure	Programmed for Replacement
Yakima County	S.L.I. ROAD	S.L.I. ROAD #588	1962	Timber Girder	Superstructure/Substructure	Monitor through Inspection
Yakima County	MEYERS RD.,N.	MEYERS RD.,N. #485	1947	Concrete Girder	Superstructure/Substructure	Programmed for Replacement